


跟一下后端代码,后端代码很简单,直接获取post的文件内容和文件名,然后创建文件并写入内容。正是这里存在任意文件写入漏洞,如果攻击者使用../进行目录穿越,则可以向靶机任意目录写入文件




效果演示

使用bp抓包发送payload




查看目录发现恶意文件成功写入











Sign in to comment

6 gitee

©OSCHINA. All right	s reserved					
Git Resources	Gitee Reward	OpenAPI	About Us	0	777320883	
Learning Git	Gitee Stars	Help Center	Join us	\odot	git@oschina.cn	
CopyCat	Featured Projects	Self-services	Terms of use	知	Gitee	6/11/10
Downloads	Blog	Updates	Feedback	•	+86 400-606-0201	Mini Program
	Nonprofit		Partners			
	Gitee Go					

OpenAtom Foundation Cooperative code hosting platform 🌖 违法和不良信息举报中心 🛮 粵ICP备12009483号

∰简体



