



There is an OS Command Injection vulnerability in the scan engine function configuration of rengine 1.3.0 #2

Open zongdeiqianxing opened this issue on Jul 18 · 0 comments



If you try to reproduce the vulnerability, add the command you want to execute in the scan engine template in the background, then create a target and select the scan engine template for scanning. After a while, you will find that the command is successfully executed.



Labels		
None yet		
Projects		
None yet		
Milestone		
No milestone		
Development		
No branches or pull requests		

1 participant

