Website Performance Audit Report

Ecole Globale International Girls School

Prepared by:

Aditya Raj Singh
Position Applied: Web Development Internship
Date: 1 March 2026

1. Introduction

This performance audit was conducted on the Ecole Globale International Girls School website using Google Lighthouse (Mobile simulation). The objective of this analysis is to evaluate page load performance and suggest technical improvements for better user experience and search engine ranking.

Testing was performed in Google Chrome Incognito mode using Lighthouse Mobile simulation to replicate real-world mobile user conditions.

---

2. Performance Metrics Summary

The Lighthouse mobile performance score for the tested page is **58/100**, indicating moderate optimization with significant improvement potential.

Metric	Observed Value	Ideal Value
Performance Score	58	90+
First Contentful Paint (FCP)	3.0 s	< 1.8 s
Largest Contentful Paint (LCP)	11.9 s	< 2.5 s
Total Blocking Time (TBT)	280 ms	< 200 ms
Cumulative Layout Shift (CLS)	0.03	< 0.1
Speed Index	6.5 s	< 3.4 s



---

3. Key Performance Issues Identified

3.1 High Largest Contentful Paint (11.9s)

The LCP is significantly above the recommended threshold. This indicates that the main visual element (likely the hero background image) is loading very late.

Probable Causes:

- Large background hero image
- Lack of image compression
- No preload for critical image
- Heavy CSS and JavaScript execution

3.2 Render-Blocking Resources

Lighthouse identified render-blocking CSS and JavaScript files, causing delayed content display.

Impact:

- Delayed FCP

- Increased Speed Index
- Slower initial user perception

Figure 3: Lighthouse Identified Performance Optimization Opportunities



3.3 Font Loading Delay

Font display issues indicate potential savings of over 1 second.

This suggests that custom web fonts are blocking text rendering and increasing perceived load time.

3.4 Heavy Use of Elementor (WordPress Page Builder)

The website appears to be built using WordPress + Elementor.

This typically results in:

- Large CSS bundles
- Multiple JavaScript files
- Increased DOM size
- Reduced mobile performance

---

4. Recommended Technical Improvements

4.1 Optimize Largest Contentful Paint

- Convert hero images to WebP format
- Reduce image resolution
- Compress images using TinyPNG/Squoosh
- Preload hero image
- Use proper image sizing

Expected improvement:
LCP reduction from 11.9s to below 3s.

4.2 Eliminate Render Blocking Resources

- Add defer to non-critical JS
- Inline critical CSS
- Remove unused CSS
- Combine CSS files

Expected improvement:
1–2 second faster rendering.

4.3 Optimize Font Loading

- Use font-display: swap
- Preload important fonts
- Reduce font families

4.4 Reduce JavaScript Execution Time

- Minify JS
- Remove unused Elementor widgets
- Reduce third-party scripts

4.5 Implement CDN and Caching

- Use Cloudflare CDN
- Enable Gzip/Brotli compression
- Configure browser caching headers

---

5. Expected Performance Improvement

If the above optimizations are implemented:

- Performance Score can improve from 58 → 85+
- LCP can potentially be reduced from 11.9 seconds to under 3 seconds with proper image and resource optimization.
- Overall load time can reduce by 30–50%

Conclusion

The website demonstrates strong SEO practices and good visual stability (CLS score). However, mobile performance optimization is required, particularly for Largest Contentful Paint (LCP) and render-blocking resources. Implementing the suggested optimizations would significantly enhance user experience, search ranking potential, and overall performance efficiency.

Overall, the website has a solid technical foundation, but performance optimization is required to meet modern Core Web Vitals standards.