
Solution

Use olevba tool to analyze




Analysis shows string addition functions and calls to powershell

Perform debugging of the program and print out the ChBEP variable



Or use msgbox to print the message



Decode tthe powershell shows that this is a reverse shell to the attacker's machine and sends a message containing the flag

