INSPECTION REPORT

NAME OF REQUESTER	LOCATION	DESCRIPTION OF REQUESTED MATERIAL	QUANTITY REQUESTED	NAME AND DATE OF INSPECTION
Residents	Prk. Quezon, Brgy. Rotonda	Concrete Pipe (No. 36)	6 Pieces	SEVERINO JOHNROME USERO JANUARY 19,2026
		Cement	6 Bags	
		Sand	1 Load	
		Gravel	1 Load	

DOCUMENTATION



INSPECTION REPORT



REMARKS:

The requested materials are needed to ensure safety and convenience. The area is already wet during the dry season, and conditions are expected to worsen during the rainy season, making passage unsafe. Upon inspection, the originally requested pipe culvert was found to be oversized. An **18-inch pipe culvert** is sufficient and is recommended, as agreed by the area resident representative.