






C FLASHING ALONG EXISTING WALL @ FLAT ROOF SADDLE
SCALE: HALF SIZE





B FLASHING AT FLAT ROOF AT NORTH WALL OF AUDITORIUM
SCALE: 3/4" = 1'-0"




A FLASHING AT FLAT ROOF AT EAST WALL OF AUDITORIUM







D DORMER VENTS (8 OF THESE)
SCALE: HALF SIZE



E VENT @ NORTH WALL OF EAST ENTRANCE



F FLASHING AT INTERSECTION OF SADDLE & PITCHED ROOF
SCALE: HALF SIZE



REVISIONS		PARISH HALL ADDITION	
1	3-31-66	FOR	ST. EDMUND'S EPISCOPAL CHURCH
2	4-1-66	1775 SAN GABRIEL BLVD., SAN MARINO, CALIFORNIA	
3	4-1-66		
4	4-1-66		
5	4-1-66		
6	4-1-66		
7	4-1-66		
8	4-1-66		
9	4-1-66		
10	4-1-66		
11	4-1-66		
12	4-1-66		
13	4-1-66		
14	4-1-66		
15	4-1-66		
16	4-1-66		
17	4-1-66		
18	4-1-66		
19	4-1-66		
20	4-1-66		
21	4-1-66		
22	4-1-66		
23	4-1-66		
24	4-1-66		
25	4-1-66		
26	4-1-66		
27	4-1-66		
28	4-1-66		
29	4-1-66		
30	4-1-66		
31	4-1-66		
32	4-1-66		
33	4-1-66		
34	4-1-66		
35	4-1-66		
36	4-1-66		
37	4-1-66		
38	4-1-66		
39	4-1-66		
40	4-1-66		
41	4-1-66		
42	4-1-66		
43	4-1-66		
44	4-1-66		
45	4-1-66		
46	4-1-66		
47	4-1-66		
48	4-1-66		
49	4-1-66		
50	4-1-66		
51	4-1-66		
52	4-1-66		
53	4-1-66		
54	4-1-66		
55	4-1-66		
56	4-1-66		
57	4-1-66		
58	4-1-66		
59	4-1-66		
60	4-1-66		
61	4-1-66		
62	4-1-66		
63	4-1-66		
64	4-1-66		
65	4-1-66		
66	4-1-66		
67	4-1-66		
68	4-1-66		
69	4-1-66		
70	4-1-66		
71	4-1-66		
72	4-1-66		
73	4-1-66		
74	4-1-66		
75	4-1-66		
76	4-1-66		
77	4-1-66		
78	4-1-66		
79	4-1-66		
80	4-1-66		
81	4-1-66		
82	4-1-66		
83	4-1-66		
84	4-1-66		
85	4-1-66		
86	4-1-66		
87	4-1-66		
88	4-1-66		
89	4-1-66		
90	4-1-66		
91	4-1-66		
92	4-1-66		
93	4-1-66		
94	4-1-66		
95	4-1-66		
96	4-1-66		
97	4-1-66		
98	4-1-66		
99	4-1-66		
100	4-1-66		