

Tyre Audit Summary

for KDG LOGISTICS,
KDG




Location KDG Durban

Date Range 01/01/2025 - 31/01/2025


Locations Summary by Vehicle Class

KDG Durban


Vehicle Class	No. of Vehicles Inspected	No. of Vehicles in Location	% of Vehicles Inspected	No. of Tyres Inspected	No. of Tyres in Location	% of Tyres Inspected
Airport vehicle	3	9	33%	18	72	25%
Dustcart	1	3	33%	8	28	29%
Rigid truck	4	8	50%	34	82	41%
Semi-Trailer	54	89	61%	364	875	42%
Surface mining and/or construction vehicle	7	12	58%	56	120	47%
Tractor Unit	27	75	36%	194	702	28%
Trailer	0	1	0%	0	11	0%
TOTAL	96	197	49%	674	1890	36%

Pressure Analysis by**Steer Axle****Drive Axle****2nd Steer/Lift/Carry Axles****Trailer Axle**

Tread Depth Analysis - All Axles



Tyre Manufacturer Analysis



Notifiable Observations (Top 10)

Tyre Life Analysis

