
Main experiment: same bridge
ILOS 0.7 m/s, GNSS outage
Vessel centre at contact (48.64 s)
Full method, GNSS outage
ILOS 0.7 m/s, GNSS available
Bridge walls
Admission gate
East (m)
North (m)
Actual hull clearance (m)
North (m)