

VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V.

September 21, 2026

EQ R LINEA 2

Inspection Result / Fiber Name:

File Name: S45194-132648930A1

Serial Number. S45194-132648930

Lot Number: 020263 48930

IL: <0.20dB

RL: >65.0dB


Profile: SM,Post Polish (IEC-61300-3-35 Table 4)

Inspection Summary:


Zone Name	Diameter		Result	Defects		Scratches	
	Inner	Outer		Count	Area (μ2)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	0	0	PASS	0
Zone E	250	1000	PASS	0	0	PASS	0
Epoxy Gap:	PASS	Fiber Type:	Simplex	Core Size:	9		

****PASS****

LOW Magnification



High Magnification



VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V.

September 21, 2026

EQ R LINEA 2

Inspection Result / Fiber Name:

File Name: S45194-132648930B1

Serial Number. S45194-132648930

Lot Number: 020263 48930

IL: <0.20dB

RL: >65.0dB


Profile: SM,Post Polish (IEC-61300-3-35 Table 4)

Inspection Summary:

Zone Name	Diameter		Result	Defects		Scratches	
	Inner	Outer		Count	Area (μ2)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	0	0	PASS	0
Zone E	250	1000	PASS	0	0	PASS	0
Epoxy Gap:	PASS	Fiber Type:	Simplex	Core Size:	9		

****PASS****

LOW Magnification



High Magnification

