

LOOK MUM **FLYING CAN**

ESERO-Poland CanSat 2021 Competition Team

The Team



Miłosz
Project Lead



Jakub
Software Engineer




Mikołaj
Backend Engineer



Sebastian
AERO Engineer

The mission



Objectives

- create first SDR-based CanSat platform
- data relay / range extender device for rescue workers
- create tiny linux-based platform capable of operating in space
- improve aerospace safety by expanding range of ADS-B system

Mission description


Primary mission

- Monitor thermal performance (SDR, BAT, STM32, RPi, ext)
- Measure current altitude (pressure)

Secondary mission


- Relay ADS-B data
- Localize Cospas-Sarsat beacon
- Over-the-horizon propagation test

Mission description



Secondary mission / ADS-B

LOOK MUM
FLYING CAN



Limited ADS-B coverage → ADS-B satellite platform

Our Cansat aims to increase worldwide ADS-B coverage, by working as a signal relay station


We also planned to integrate our CanSat to Cospas-Sarsat system but due to the clock generator IC failure we were unable to receive data.

Hardware & Software




CanSat's modules & subsystems

LOOK MUM
FLYING CAN



CanSat's modules & subsystems



```
while (1)
{
    State_OnFrameStart(&state);

    printf(" --- Frame %d ---\n", state.frameNumber);

    switch (state.phase) {
        case Phase_Armed:
            ExecuteTasks_Armed();
            break;
        case Phase_Liftoff:
            ExecuteTasks_Liftoff();
            break;
        case Phase_Deployed:
            ExecuteTasks_Deployed();
            break;
        case Phase_Recovery:
            ExecuteTasks_Recovery();
            break;
        case Phase_Off:
            Shutdown();
            break;
        case Phase_Test:
            break;
    }

    State_OnFrameEnd(&state, true);
}
```

```
pressureTriggers += pressureTrigger( );

if ((pressureTriggers >= 10 && HAL_GetTick( ) - startTick > 600000) {
    RPi_SetPower(&rpi, 0);
    Buzzer_PlayMelody(&buzzer, &melody_barka);
    State_ChangePhase(&state, Phase_Recovery);
}
```

```
uint8_t pressureTrigger() {
    pressureVariation[2] = pressureVariation[1];
    pressureVariation[1] = pressureVariation[0];
    pressureVariation[0] = lastPressure - telemetry_sensor.pressure;

    double pressureVariationAvg = (pressureVariation[2] + pressureVariation[1] + pressureVariation[0]) / 3;
    double pressureToGround = (lastPressure + telemetry_sensor.pressure) / 2 - groundPressure;

    lastPressure = telemetry_sensor.pressure;

    if (pressureVariationAvg < 0.01 && pressureVariationAvg > -0.01)
        return 0;

    if (pressureVariationAvg < 30.0 && pressureVariationAvg > -30.0)
        return pressureToGround < 1500.0 && pressureToGround > -1500.0

    return 0;
}
```

```
Initializing HAL
[8353] Initializing peripherals
> SD: OK
> BMP280: OK
> INA3221: OK
> DS18B20: OK (7)
> LoRa: OK
[9270] Init completed!
[9270] SYS STATUS: OK
...
```





Poligon Wojskowy


Telemetry

Temp:	PCB	SDR	ENV1	ENV2	RPI
	44.23	31.331	20.233	21.973	60.111
Pres:	Pa				
	9998.13				
Acc:	X	Y	Z		
	0.12	0.001	-1.623		
Psu_V:	Bat	5V	3V3		
	7.853	5.41	3.293		
Psu_A:	Bat	5V	3V3		
	0.32	0.41	0.203		
Rpi:	Status				
	[68, 63]				

GNSS

Latitude	50.34189
Longitude	19.53296
Speed	8.123
Altitude	723.11



A photograph of several young men at a rocket launch site. In the foreground, a boy with short brown hair and a black t-shirt is looking up at a rocket. He has a blue lanyard around his neck with white text that is partially visible. Behind him, another boy in a white shirt is also looking up at the rocket. To the right, a man with a beard and a dark t-shirt is partially visible, also looking towards the sky. The background shows a clear sky and some buildings or tents in the distance.

Launch results

Launch results


- primary mission systems operational
- radio link established
- recovery system worked as predicted
- SBC did not boot - suspected voltage transient during power on

Additional data gathering




Data analysis


Data analysis



Data analysis




Data analysis




Data analysis (system idle)

LOOK MUM
FLYING CAN




Data analysis (system operational)

LOOK MUM
FLYING CAN





Data analysis




Data analysis

LOOK MUM
FLYING CAN








A photograph of three young men on a sandy beach under a cloudy sky. The man on the left is seen from behind, wearing a black t-shirt and holding a laptop. The man in the middle is also seen from behind, wearing a dark vest over a plaid shirt. The man on the right is facing towards the camera, holding a white cylindrical device connected to a large Yagi antenna. In the background, there's a line of trees and some small bushes.

Mission result

(PARTIAL) SUCCESS


Mission result




LOOK MUM **FLYING CAN**

ESERO-Poland CanSat 2021 Competition Team


CanSat's modules & subsystems



Secondary mission / ADS-B



Secondary mission / ADS-B



Example log

[109292] 2A5E100000C5A4F700102A8E100000990001802000005108EB7.080000
[109667] [94][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[109908] [95][B]: IN:31.812500C|29.875000C ENV:26.937500C|27.080000C RPI:42.355000C PRES:98011.687500hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.736001@0.419512) 5V(4.904000@0.326341) 3V3(3.320000@0.088800) SDR:DI0 FLAG:127
[110361] 2A8E100000990001802000005108EB00102A8E100000990001802000005108EB42.35500
[110731] [95][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[110993] [96][B]: IN:31.875000C|29.937500C ENV:26.875000C|27.080000C RPI:42.355000C PRES:98010.617188hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.720000@0.480000) 5V(4.896000@0.364390) 3V3(3.312000@0.120000) SDR:DI0 FLAG:127
[111446] 2A8E100000900914D2A8224840CBA300C ENV:26
[111816] [96][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[112057] [97][B]: IN:31.937500C|29.937500C ENV:26.937500C|27.090000C RPI:41.868000C PRES:98012.054688hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.728000@0.458537) 5V(4.904000@0.351707) 3V3(3.320000@0.088800) SDR:DI0 FLAG:127
[112510] [96][A]:
[112880] [97][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[113121] [98][B]: IN:32.000000C|30.000000C ENV:26.875000C|27.090000C RPI:41.868000C PRES:98008.562500hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.736001@0.454146) 5V(4.904000@0.321463) 3V3(3.320000@0.088000) SDR:DI0 FLAG:127
[113574] 2A8E100000990001802000005108EB00102A8E100000990001802000005108EB41.86800
[113944] [98][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[114189] [99][B]: IN:32.062500C|30.000000C ENV:26.937500C|27.090000C RPI:41.868000C PRES:98008.230469hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.736001@0.454634) 5V(4.904000@0.326341) 3V3(3.320000@0.091200) SDR:DI0 FLAG:127
[114642] [98][A]:
[115012] [99][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[115253] [100][B]: IN:32.125000C|30.062500C ENV:26.937500C|27.090000C RPI:41.868000C PRES:98010.667969hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.728000@0.449268) 5V(4.904000@0.348780) 3V3(3.320000@0.089600) SDR:DI0 FLAG:127
[115706] 2A8E100000990001802000005108EB000C ENV:26
[116076] [100][G]: 0.000000 0.000000 V:0.000m/s H:0.000m TIME: 0:0:0 SAT:0
[116317] [101][B]: IN:32.187500C|30.125000C ENV:26.937500C|27.100000C RPI:41.868000C PRES:98009.312500hPa ACC:0.000000X
0.000000Y 0.00000Z, PSU: BAT(7.728000@0.429756) 5V(4.904000@0.345366) 3V3(3.320000@0.088000) SDR:DI0 FLAG:127
[116770] 2A8E10000090091161123EE35B2CA300102A8E100000990001802000005108EB:41.86800

Data analysis

```
*5d4ca2d468fe2f;  
*a0000290805b7317e00c5e4cdaf9;  
*5d4ca2d468fe2f;  
*8d4ca2d4990cba8558400ca98692;  
*8d4ca2d4f8230006004878dfa184;  
*8d4ca2d4ea07e86ecd1c08a3c52b;  
*8d4ca2d46013f1672437abfd1f92;  
*8d4ca2d4990cba8558440c91b092;  
*8d4ca2d46013e4d89a1b37ce83ee;  
*8d4ca2d4990cba8558400ca98692;  
*5d4ca2d468fe2f;  
*8d4ca2d4990cb98538400b9ccd9f;  
*8d4ca2d46013e1671a379716b9f7;  
*0281823e18f693;  
*a000023effdb7517bff45cfdf3c6;  
*a000023e87d40d30b80000b2c747;  
*2000023ed1aaa2;  
*8d4ca2d4990cb98538400b9ccd9f;  
*8d4ca2d4f8230006004878dfa184;  
*8d4ca2d4e1149f00000000b7067e;  
*8d4ca2d4990cb98538400c631dbb;  
*5d4ca2d468fe2f;
```