Autocannon Load Test Report

Test run on 5/19/2025, 3:17:50 AM


Test Configuration

URL: https://jimbo.int.aws.jims.net/api/services/fectch


Method: GET Connections: 30 Duration: 30 seconds

Test Results Summary

Latency Metrics



Requests Timeline



Detailed Test Results

Latency: Min: 158 ms Max: 763 ms

Average: 184.78 ms Std Dev: 70.73 ms

Percentiles: p1: 159 ms p50: 167 ms p75: 171 ms p90: 175 ms p99: 538 ms

Requests: Total: 4855

Average: 161.84 req/sec

Throughput: Total: 1.86 MB

Average: 63.53 KB/sec

Errors and Status Codes:

Errors: 0

Status Codes:

200: [object Object]