Autocannon Load Test Report


Test run on 5/19/2025, 4:49:49 AM

Test Configuration

URL: https://jimbo.int.aws.jims.net/api/services/fectch


Method: GET Connections: 30 Duration: 30 seconds

Test Results Summary



Test Results Summary (continued)

Requests Timeline



Status Code Distribution

200

Detailed Test Results

Latency: Min: 159 ms Max: 607 ms

Average: 185.29 ms Std Dev: 69.87 ms

Percentiles: p1: 159 ms p50: 167 ms p75: 173 ms p90: 176 ms p99: 536 ms

Requests: Total: 4848

Average: 161.60 req/sec

Throughput: Total: 1.86 MB

Average: 63.44 KB/sec

Errors and Status Codes:

Errors: 0

Status Codes:

200: [object Object]