





Dust blocking heat dissipation
[By courtesy of TUV Rheinland].



Installation in direct sun light [By
courtesy of TUV Rheinland].



Distance to bottom, top or to the
sides too low [By courtesy of
TUV Rheinland].



Presence of inflammable mate-
rial [By courtesy of SUPSI
PVLab].

