






Multiple bubbles in the centre and edge of the backsheet [Köntges16].



Cracked backsheet in combination with yellowing under a hot cell [Eder19].



Deep scratch on backsheet [By the courtesy of TUV Rheinland].



Finger with white powder [By the courtesy of TUV Rheinland].

