





Uniform light soiling, which in ideal conditions is self-cleaning when raining [By the courtesy of SUPSI PVLab].

Uniform heavy soiling caused by rail way station [By the courtesy of SUPSI PVLab].

Non-uniform soiling caused by low inclination and close mounting to roof [By the courtesy of SUPSI PVLab].

Soiling pattern on a system in the Atacama desert [By the courtesy of ISE FhG].

