






Corroded connector due to cross-mating [By the courtesy of Stäubli].




Not fully inserted or interlocked connector [Yang19].



Burned connector [Köntges17].



Corroded Cable [Köntges17].



Animal bite on cable [Köntges17].

