🖥️ SHIBA INSIDER TECHNICAL REPORT



📌 Attack Summary

The investigation identified an attack involving insecure transmission of credentials over HTTP and the use of steganography to conceal data within an image file. The attacker's identity was successfully determined through analysis of extracted hidden data.

⏱️ Timeline

1. PCAP file analyzed
2. HTTP stream inspected
3. Password discovered in plaintext
4. ZIP archive accessed
5. Image metadata analyzed
6. Steganography identified
7. Hidden ID extracted

8. Attacker profile identified

🔍 IOCs

-
-
- HTTP traffic artifacts
- Steganographic image file

🛠️ Tools Used

- Wireshark
- ExifTool
- Steghide
- OSINT tools (search engines)

🛡️ EXTRACT

🔍 Indicators of Compromise (IOCs)

- ID Hash: **0726ba878ea47de571777a**
- Password exposed in traffic: **redforever**
- Protocol: **HTTP (plaintext communication)**
- File artifact: **Steganographic image file (sislo/image)**
- Attacker profile: **bluetiger**

⚔️ Attack Techniques

- Use of **unencrypted HTTP communication**

- **Credential exposure in network traffic**
- **Steganography** (data hiding in image file)
- Use of **metadata as a hinting mechanism**
- OSINT-based attacker traceability

🧭 IDENTIFY

🚪 Entry Point

- Initial entry via **network communication captured in PCAP**
- Password transmitted in **plaintext over HTTP**

🔄 Lateral Movement

- **No evidence** of lateral movement
- Activity limited to a **single communication flow**

📤 Data Exfiltration

- Data hidden within an image using **steganography**
- Extracted using:
  - Steghide
- Hidden ID used for attribution

🧾 DELIVERABLE (TECHNICAL)

📌 Explanation of Findings

Analysis of the PCAP file revealed that sensitive information, specifically a password, was transmitted over HTTP in plaintext. This password was used to access a ZIP archive containing an image file. Examination of the image metadata indicated the use of steganography. Further analysis using steganographic extraction techniques revealed a hidden ID, which was then used to identify the attacker's profile.

🔗 Attack Chain Breakdown

1. HTTP traffic captured in PCAP
2. Plaintext password (**redforever**) identified
3. ZIP file accessed using recovered credentials
4. Image file extracted from archive
5. Metadata analysis reveals steganography
6. Hidden data extracted from image
7. ID traced to attacker → **bluetiger**

📊 Findings

- Sensitive credentials transmitted insecurely via HTTP
- Metadata provided key insight into hidden data technique
- Steganography successfully used for concealment
- Attacker identity traceable via extracted identifier