F12: Visual Inspection of Extraction Regimes (Success, Partial Loss, and Failure)

Original Cover (512x512)

Watermarked Stego (512x512)

Attacked Image (512x512)

Extracted Payload (32x32)

Row 1: Robust Success (LL, JPEG Q=70)









Result: BER = 0.000

Row 2: Partial Degradation (HL, Crop 15%)










Result: BER = 0.129

Row 3: Catastrophic Failure (LL, Contrast 2.2)









Result: BER = 0.500