

12396 Edgewater Drive, Unit/Lot 23

Hampton, GA 30228

Vacant residential lot · 1.3313 acres · Waterpointe subdivision · Clayton County, Georgia · Parcel 05050A A003 · Zoned RS180

1.3313 ac 57,993 SQ FT (GIS-COMPUTED)	148 × 419 ft WIDTH × DEPTH	80.2 ft ELEVATION RELIEF ON LOT
18.3% AVERAGE SLOPE (10.4°)	Zone X FEMA — MINIMAL FLOOD HAZARD	\$125,000 ASKING · COUNTY APPRAISAL \$60,000

How to read this report

Every finding carries a provenance tag. This distinction is the core discipline of the report: a lidar-derived contour is *not* a legally reliable survey, and nothing here substitutes for a licensed professional or a county confirmation.

OFFICIAL recorded/published source (county GIS, FEMA, USDA, county resolution)	GIS-DERIVED computed by this analysis from public lidar/GIS — an estimate
NEEDS PROFESSIONAL requires surveyor, engineer, soil scientist or county sign-off	UNVERIFIED document not obtained / data unavailable at time of writing

Five findings that change the picture

1. The property is in Clayton County — not Henry County

OFFICIAL

The "Hampton, GA 30228" address leads nearly everyone to assume Henry County. The U.S. Census geocoder returns **Clayton County (FIPS 13063)**, the parcel is served by the **Clayton County** tax assessor, and the HOA describes itself as a Clayton County community. This determines zoning, permitting, property tax millage, and **school assignment** — all Clayton County, not Henry.
2. The lot does not touch the water

OFFICIALGIS-DERIVED

Listings market this as a "lakefront" lot with "direct access to the water." The county parcel polygon tells a different story: Lot 23's south boundary adjoins parcel 05045 051001, owned by the **Clayton County Water Authority (CCWA)** and appraised at \$5.48M. The reservoir's edge lies roughly **59–80 ft inside CCWA land**. Lot 23 contains **zero** water. It is lake-*adjacent* with a view, **not riparian**, and carries no apparent water frontage rights.
3. The lake is a public drinking-water reservoir — expect no private dock

OFFICIAL

The water body is **J.W. Smith Reservoir**, a CCWA public water-supply reservoir. CCWA sells access **permits** (\$5 day / \$25 annual), restricts hours, **closes J.W. Smith entirely from November through February**, and prohibits **swimming and wading**. A private dock would have to be built on and over land and water the buyer does not own, belonging to a public water utility. Treat dock, motorized boating and swimming as **not available** until CCWA says otherwise in writing.
4. The terrain is materially steeper than advertised

GIS-DERIVED

A 2021 listing called this a "perfect gentle rolling lot." USGS 3DEP lidar measures **80.2 ft of fall** across the lot and an **18.3% average grade**, reaching **23.5% over the steepest 50 ft**. Independently, USDA maps the soil as the **10–25% slope** phase with a representative slope of **18%** — two unrelated sources agreeing. This is a **moderate slope** lot (locally steep), which drives foundation type, driveway design, retaining walls and cost.
5. Two Clayton County moratoriums are active right now

OFFICIAL

Resolution 2026-153 suspends acceptance of applications for **short-term rentals** (plus boarding/group/personal-care homes) through **31 December 2026**. **Resolution 2026-120** suspends applications for new single-family **subdivision** development on the same timeline. The STR moratorium directly contradicts any Airbnb/VRBO investment thesis for now; the development moratorium needs a direct answer from the county as to whether a single home on an existing platted lot is caught by it.
- What is genuinely good here

FEMA **Zone X** (minimal flood hazard) with the lot's low point ~10 ft above normal pool; **well-drained** soil with **low shrink-swell**; a permanently undeveloped CCWA buffer behind the lot that protects the view; a fire station **0.19 mi** away; Hartsfield-Jackson ~16 mi; and a built-out neighbourhood of \$300k–\$860k homes that supports the value of a well-built house.

1 · Property identification OFFICIAL

Street address	12396 Edgewater Drive, Hampton, GA 30228
Unit designation "#23"	Corresponds to LOT 23 in the county record — confirmed, not an apartment unit
Subdivision / community	Waterpointe (four phases); Waterpointe Community Association
County / state	Clayton County , Georgia (FIPS 13063) — <i>not</i> Henry County
Parcel / APN	05050A A003
Zoning	RS180 (single-family residential)
Lot area	57,993 sq ft = 1.3313 acres GIS-DERIVED — computed from the county parcel polygon in UTM 16N/NAD83; matches the listing's "1.33 acre" claim
Perimeter	1,112.6 ft
Dimensions	▮ 148 ft wide × 419 ft deep (minimum rotated rectangle)
Owner of record	MCKNIGHT DESMOND · deed year 2021
County appraised value	\$60,000 (land fair market value \$60,000; no structure)
County floodplain flag	NO
Centroid (WGS84)	33.41612601, -84.36982169
Legal description	UNVERIFIED Not obtained. The recorded deed and plat legal description must be pulled from the Clayton County Clerk of Superior Court.

Surveyed corner coordinates GIS-DERIVED

Converted from the county parcel polygon. **These are GIS coordinates, not survey monuments** — county parcel fabric routinely differs from a field survey by several feet.

Corner	Latitude	Longitude	Position
V0	33.41565614	-84.36937280	SE corner (lake end)
V1	33.41553600	-84.36983654	SW corner (lake end)
V2	33.41663119	-84.37025320	NW corner (road end)
V3	33.41671759	-84.36988479	North boundary jog
V4	33.41672798	-84.36984213	NE corner (road end)

Boundary line	Length (ft)	Bearing	Notes
V0 ▮ V1 (south / rear)	148.2	251.4°	Adjoins CCWA reservoir parcel
V1 ▮ V2 (west side)	418.5	340.9°	Adjoins Lot 24 (12402)
V2 ▮ V3 (north / front)	116.8	72.9°	Edgewater Dr frontage
V3 ▮ V4 (north / front)	13.6	72.4°	Continuation — total frontage ▮ 130.4 ft
V4 ▮ V0 (east side)	415.6	158.4°	Adjoins Lot 22 (12390)

2 · Listing information OFFICIAL IMAGES UNAVAILABLE

Current asking price	\$125,000 (1.33-acre lot, marketed as lakefront)
County appraisal	\$60,000 — 52% below asking. Note every other vacant lot on Edgewater Dr is also appraised at exactly \$60,000, so this is the assessor's standard vacant-lot figure rather than a property-specific opinion.
Earlier marketing (2021)	Described as "1.33 acre lake front lot... nicely wooded, perfect gentle rolling lot" — the "gentle rolling" characterisation is not supported by lidar (see Section B).
Neighbourhood sales	Waterpointe: 4 recorded sales in the 12 months to 20 Sep 2026, median \$454,950, \$120/sq ft , median 34 days on market, sellers accepting ~99% of original ask.

Why there are no listing photographs in this report

The checklist requests Zillow hero and surrounding-area images. Listing photographs on Zillow, Redfin and realtor.com are **copyrighted** by the brokerage or photographer and are not licensed for redistribution in a derivative report. Embedding or hot-linking them here would infringe those rights, so they are deliberately omitted. Open the source listings directly to view them:

- Redfin — redfin.com/GA/Hampton/12396-Edgewater-Dr-30228/home/25184182
- realtor.com — realtor.com/realestateandhomes-detail/12396-Edgewater-Dr_Hampton_GA_30228_M65547-02384

All imagery in this report is instead generated from public-domain federal data (USGS 3DEP lidar, FEMA, USDA) and county GIS, which carry no such restriction.

3 · Official recorded plat & boundary

UNVERIFIEDNEEDS PROFESSIONAL

The recorded plat has not been obtained — this is the single most important missing document

Everything in this report's boundary analysis derives from the **county parcel fabric**, which is a tax-mapping product, not a legal instrument. The recorded plat is what actually governs, and it is the only place you will find:

- **Easements** — drainage, utility, sanitary-sewer and access easements. On a 419 ft deep lot draining toward a public reservoir, a rear drainage easement is plausible and would directly reduce buildable area.
- **Building setback lines** as platted (which may be stricter than zoning).
- Whether any **reservoir buffer or no-build strip** was dedicated when Waterpointe was platted.
- The **legal description** and the true bearing/distance calls on each line.

Obtain from: **Clayton County Clerk of Superior Court** (recorded plats) and the **Tax Assessor Mapping Department**, (770) 477-3276.

Comparison of county GIS against the listing: the GIS-computed area (**1.3313 ac**) agrees with the advertised 1.33 ac to within 0.1%, which is reassuring on size. The county's own `ACERAGE` attribute is populated as `0.0` for this parcel — a database gap, not a zero-acreage lot. Discrepancies found are catalogued in Section M.

4 · GIS / parcel map & adjoining ownership

OFFICIAL

Queried live from the Clayton County Tax Assessor ArcGIS service (`gis.claytoncountyga.gov/server/rest/services/TaxAssessor/Parcels`). The decisive result is the first row.

Parcel	Address / owner	Zone	Lot	Appraised	Relationship to Lot 23
05045 051001	275 Hampton Rd — CLAYTON COUNTY WATER AUTHORITY	AG	—	\$5,480,100	Adjoins rear boundary. Contains the entire reservoir (all 362 lidar water samples fall inside it).
05050A A002	12390 Edgewater Dr — Hickson	RS180	22	\$519,400	East neighbour, improved
05050A A004	12402 Edgewater Dr — Wilson	RS180	24	\$60,000	West neighbour, vacant
05050A A001	12382 Edgewater Dr — Chastain	RS180	21	\$60,000	134 ft away, vacant
05050A A005	12408 Edgewater Dr — McGuffie Trust	RS180	25	\$60,000	135 ft away, vacant
05050C B001	12554 Panhandle Rd — Clayton County Fire Station	ER	—	\$859,100	652 ft away — Station 10

Reading the ownership pattern

Four of the nine nearest lots are still vacant and appraised at \$60,000 each. Waterpointe has been building out since 1988 and these lots have not sold — on a street where finished homes appraise at \$300k–\$860k. That is worth asking about directly: slow absorption of the *steeper, lake-end* lots is consistent with the terrain and dock findings in this report. It is also a negotiating data point against the \$125,000 ask.

Discrepancies between sources

GIS-DERIVED

Item	Source A	Source B	Assessment
Acreage	Listing: 1.33 ac	GIS polygon: 1.3313 ac	Agree
County acreage field	GIS <code>ACERAGE</code> = 0.0	Computed 1.3313 ac	County field is blank/zero — data gap
Waterfront status	Listing: "lakefront", "direct access to the water"	Parcel contains no water; CCWA land intervenes	Material conflict — see item 24
Terrain	Listing: "gentle rolling"	Lidar 18.3% avg; USDA 10–25% slope unit	Material conflict — see Section B
County	Mailing address "Hampton"	Census + assessor: Clayton County	Hampton address spans counties; parcel is Clayton
FEMA panel returned	Flood polygon DFIRM <code>13063C</code> (Clayton)	Panel query returned <code>13151C0140D</code> (Henry)	Near a county line; confirm the governing panel with the county floodplain administrator




Figure 1 — True-scale plan. Horizontal scale is 1:1 (equal aspect); the scale bar is valid in both axes. Contours at 5 ft (labelled every 25 ft) derived from USGS 3DEP lidar sampled on a lot-aligned 10 ft grid (3,149 points, 583 of them inside the boundary). Blue arrows show computed down-gradient drainage direction. The lot has been rotated so the road-to-lake axis is vertical; the north arrow shows true north at 20.4° from the page vertical. **Contours are lidar-derived estimates, not a surveyed topographic map.**

891 ft
HIGHEST POINT (AT ROAD)

811 ft
LOWEST POINT (AT REAR)

801 ft
RESERVOIR NORMAL POOL

Note how the contours run **almost perpendicular** to the lot's long axis and are **evenly spaced** — the signature of a uniform, planar hillside rather than a lot with a flat building pad and a drop at the back. The fall is continuous from road to rear boundary, and that is the central constraint on this site.

The brief specifically requires that any vertically exaggerated profile be shown **side by side with a true 1:1 model**, because exaggeration is the most common way a slope diagram misleads. Both are below, from the same lidar data along the lot centreline.




Figure 2 — Road → lake section. Panel (a) uses 6.1× vertical exaggeration, the conventional map presentation: the hillside looks severe. Panel (b) is the identical data at true 1:1 — the honest profile. The land reads as a steady, uniform grade rather than a cliff, but it never flattens: there is no natural level building pad anywhere on the lot.

Slope metrics as specified **GIS-DERIVED**

Metric	Value	Interpretation
Length of lot (road → rear, centreline)	410 ft	Measured run used for grades
Height (fall) across that run	75.1 ft	889.99 ft → 814.94 ft
Total relief anywhere on lot	80.2 ft	891.19 ft max - 811.03 ft min
Average slope	18.3% / 10.37°	Moderate slope class
Maximum slope over any 50 ft	23.5% / 13.25°	Occurs 60–110 ft in from the road — i.e. right where a house would go
Direct rising angle from shoreline to lot high point	18.4% / 10.42°	90.1 ft rise over 490 ft
Rising angle over the last 50 ft toward the water	18.5% / 10.47°	Grade does not ease at the lake end
Lowest ground vs normal pool	+9.9 ft	Freeboard above the reservoir surface
Gap between rear boundary and water's edge	59–80 ft	CCWA-owned land, not purchasable with the lot

The steepest ground is in the worst possible place

The 23.5% maximum occurs between 60 ft and 110 ft from the road frontage. After a front setback (RS180 front setback still to be confirmed), that band is exactly where the house footprint and driveway approach would normally sit. A driveway on 23.5% grade is unusable — residential driveways are generally kept at or below about 15%, with many jurisdictions stricter. Expect the design to require cutting into the slope, a stepped or daylight-basement foundation, and retaining structure.

3D TERRAIN MODEL — lot boundary in red, reservoir in blue
USGS 3DEP lidar, 10 ft sampling · vertical scale exaggerated for visibility




Figure 3 — 3D terrain surface. Lot boundary in red, reservoir plane in blue. Vertical scale is exaggerated to make the surface legible (see Figure 2b for the true profile). The surface is a smooth, consistently dipping hillside with no bench or plateau inside the boundary.

7 · Terrain classification **GIS-DERIVED**

Classification band	Grade	Applies?
Flat	< 2%	No
Nearly flat	2–5%	No
Gentle slope	5–10%	No — contradicts the "gentle rolling" marketing
Moderate slope	10–20%	YES — lot average 18.3%
Steep slope	20–30%	YES locally — 23.5% over the steepest 50 ft
Very steep slope	> 30%	No

Two independent sources agree, which materially raises confidence: **(a)** USGS 3DEP lidar measured by this analysis □ 18.3% average; **(b)** USDA-NRCS maps the entire parcel as soil unit **GwE2, the "10 to 25 percent slopes, eroded" phase**, with a representative slope of **18%**. Neither derives from the other.

Construction earthwork implications **GIS-DERIVED** **NEEDS PROFESSIONAL**

Requirement	Likelihood	Basis
Minimal grading	Very unlikely	No natural level pad exists on the lot
Significant grading	Likely	Creating any level pad on an 18% grade requires substantial earthwork
Cut-and-fill	Very likely	Balanced cut/fill is the standard approach on a uniform hillside
Retaining walls	Likely	Needed to hold cut faces and create usable flat yard
Extensive site engineering	Probable	Grading plan, drainage design and possibly a geotechnical report
Stepped / daylight-basement foundation	Strongly indicated	80 ft of fall is well suited to a daylight basement — the neighbourhood already has these (e.g. 12328 Edgewater's "huge partially finished basement")

The slope is not only a cost — it is also the view
An 18% fall toward a permanently protected reservoir is precisely what produces an elevated, unobstructable water view, and it lends itself naturally to a daylight-basement design that yields a large, well-lit lower level at modest marginal cost. Neighbouring homes with water views appraise at the top of the street (\$519k–\$737k). The terrain is best read as "expensive to start, valuable when finished" rather than simply a defect.

9 · FEMA flood-zone determination OFFICIAL

Queried directly from the FEMA National Flood Hazard Layer at the parcel location.

Flood zone	Zone X
Zone subtype	AREA OF MINIMAL FLOOD HAZARD
Special Flood Hazard Area (SFHA)	No (SFHA_TF = F)
Static BFE published	None (-9999 = not applicable in Zone X)
Depth	None
DFIRM ID	13063C (Clayton County countywide)
Panel returned by panel-layer query	13151C0140D , effective 6 Oct 2016 — a Henry County panel CONFLICT

Reconcile the panel before relying on it

The flood-zone polygon is unambiguously Clayton County's (13063C) and returns Zone X. The separate panel-index query returned a Henry County panel, which happens near county lines where panel polygons overlap. The **zone determination is the operative answer and it is favourable**, but for a lender or an elevation certificate you want the governing panel number in writing from the Clayton County floodplain administrator.

Not Zone A, AE, AO, AH or VE

The lot is in none of the Special Flood Hazard Areas. Mandatory federal flood insurance does not apply. This is one of the strongest objective positives on the property, and it is explained by geometry: the lot's lowest ground sits ~10 ft above the reservoir's normal pool and ~59–80 ft back from the water.

10 · First Street / forward-looking flood risk UNVERIFIED

First Street Foundation's Flood Factor is a proprietary model behind terms that do not permit redistribution of its scores in a derivative report, and no score was retrieved for this parcel. It is worth checking yourself at riskfactor.com because it models pluvial (rainfall) and future climate risk that FEMA's map does not. Given Zone X status, ~10 ft of freeboard, and well-drained Hydrologic Group B soil, a low score is the expected outcome — but that is a reasoned expectation, not a retrieved value.

11 · Site elevations GIS-DERIVED

Highest natural ground	891.2 ft NAVD88 (at the road frontage)
Lowest natural ground	811.0 ft (at the rear/lake boundary)
Average site elevation	849.9 ft
Reservoir normal pool	801.1 ft — the lidar flat-water plane (362 concordant samples)
Lot low point above pool	+9.9 ft
Lot high point above pool	+90.1 ft

Spot-check: the independent USGS Elevation Point Query Service returned 895.9 ft at the road-interpolated address point, against 896.0 ft from the 3DEP grid at the same location — agreement to 0.1 ft. Reservoir level is a *single-epoch* lidar observation and will vary seasonally and with CCWA operations.

12 · Base Flood Elevation (BFE) OFFICIAL

No BFE exists for this parcel. FEMA publishes base flood elevations only inside Special Flood Hazard Areas; in Zone X there is no regulatory BFE, so the checklist's "difference between lowest ground and BFE" is undefined here. The nearest meaningful datum is the reservoir normal pool (801.1 ft), against which the lot's low point has 9.9 ft of freeboard.

13 · Minimum finished-floor elevation NEEDS PROFESSIONAL

With no BFE, no FEMA-driven freeboard requirement is triggered, and the usual "BFE + freeboard = minimum finished floor" calculation does not apply. Finished-floor elevation will instead be set by the grading and drainage design, not by floodplain rules. Confirm with Clayton County Community Development whether any **local** reservoir-watershed or drainage ordinance imposes a minimum elevation or buffer independent of FEMA.

Question	Finding
Existing terrain adequate?	Yes with respect to flooding — the whole lot sits above the reservoir with no mapped flood hazard
Is fill necessary to escape flood risk?	No. Any earthwork here is for buildability on the slope, not flood avoidance
Must the house be elevated?	No flood-driven elevation requirement
Crawlspace / pier / slab restrictions?	No flood-zone restriction. Choice will be governed by slope and soil — see items 15 and 43

The brief rightly warns against assuming fill is permitted merely because it raises a house above a BFE. That trap does not arise here — but the inverse caution does: do not assume unlimited grading freedom just because there is no floodplain rule. Earth disturbance adjacent to a **public drinking-water reservoir** is exactly the situation where state and local water-supply-watershed buffer rules and erosion-control permits bite. Verify before designing.

45 · Drainage GIS-DERIVED

Computed flow direction is uniformly from the road frontage toward the reservoir — i.e. the lot drains across its full depth into a public water supply. Every blue arrow in Figure 1 points the same way. Practical consequences: (a) roof and driveway runoff must be managed so it does not discharge sediment downslope onto CCWA land; (b) upslope runoff from Edgewater Dr and the properties opposite arrives at the front boundary and must be intercepted; (c) erosion risk during construction is elevated on an 18% grade in an "eroded"-phase soil. Natural swales, culverts, neighbouring runoff and the lake outfall all require field verification. NEEDS PROFESSIONAL

14 · Soil characteristics OFFICIAL

USDA-NRCS Soil Survey, queried via Soil Data Access for the parcel polygon. The entire lot falls in a **single map unit** (a consociation, 100% one component) — unusually clean, which makes the data more useful than typical.

Map unit	GwE2 (mukey 125527) — Gwinnett sandy clay loam, 10 to 25 percent slopes, eroded
Soil series / component	Gwinnett, 100% of unit
Taxonomic class	Fine, kaolinitic, thermic Rhodic Kanhapludults — classic deep red Georgia Piedmont clay
Representative slope	18% (range 10–25%) — independently corroborates the lidar
Drainage class	Well drained
Hydrologic soil group	B — moderate infiltration, moderate runoff
Saturated hydraulic conductivity (Ksat)	9.0 μm/s □ 1.3 in/hr — moderately high
Depth to restrictive layer	127 cm (50 in) — paralithic bedrock, "moderately coherent"
Depth to groundwater	No water table reported within the profile — deep
Shrink-swell (linear extensibility)	LEP 1.5% — LOW (values under ~3% are low)
Erosion factor T	4
Flooding / ponding	None reported

Soil profile by horizon

Horizon	Depth	Sand %	Silt %	Clay %	Org. matter %	pH
H1 (topsoil)	0–13 cm / 0–5 in	55.5	14.5	30.0	2.0	5.8
H2 (argillic B)	13–91 cm / 5–36 in	23.3	29.2	47.5	0.25	5.8
H3	91–163 cm / 36–64 in	34.8	33.2	32.0	0.25	5.8

What this profile actually means

Good news for foundations: well drained, no shallow water table, and **low** shrink-swell. Expansive-clay heave — the classic foundation-cracking mechanism — is not the risk here, because kaolinitic Piedmont clays are relatively inert compared with the smectitic clays that cause trouble.

The catch: the B horizon from 5 to 36 inches is **47.5% clay**. That is the layer every footing, trench and drainfield will sit in. It holds water, drains more slowly than the sandy surface suggests, and is slick when wet — which matters for trench stability on an 18% grade.

"Eroded" is a warning in the map unit name. Only 5 inches of topsoil remain at 2% organic matter, and below that organic matter collapses to 0.25%. Historic erosion has already stripped this hillside once. Expect to import topsoil for any lawn or garden, and expect aggressive erosion-control obligations during construction.

15 · Foundation suitability GIS-DERIVED NEEDS PROFESSIONAL

Foundation type	Assessment on this lot
Slab-on-grade	Poor fit as-is. Would require a large level pad cut into an 18% grade, with the resulting cut face retained. Technically possible, economically wasteful here.
Crawlspace	Workable. Accommodates moderate grade with stepped stem walls.
Pier / beam	Workable for decks and projections; less common for the main structure locally.
Daylight basement	Best fit. 80 ft of fall lets the lower level open at grade on the downhill (lake) side. Converts the site's main liability into finished square footage and a water view. Matches existing homes on the street.
Stepped foundation	Likely required in combination with any of the above.
Retaining walls	Likely required for driveway cut, pad edges and usable yard.

A geotechnical investigation is advisable — and the reason is specific

Not boilerplate. Two site-specific triggers: **(1)** paralithic bedrock at a reported **50 inches**. If you cut 6–10 ft into the hillside for a basement or driveway, you may well reach rock, and rock excavation is a major cost variable that can swing a budget by tens of thousands. **(2)** Footings bearing in a 47.5%-clay layer on a slope raise both bearing-capacity and slope-stability questions that only borings can answer. Commission test borings *before* closing if possible, or make the contract contingent on them.

16 · Septic suitability GIS-DERIVED NEEDS PROFESSIONAL

Question	Finding
Is public sewer available?	UNVERIFIED Not confirmed. Strong indicators point to septic : 1–2 acre lots throughout Waterpointe, RS180 zoning, and a build-out spanning 1988–2025. Must be confirmed with CCWA.
Soil suitability for septic	Moderate, with real constraints. Well-drained Gwinnett with Ksat 1.3 in/hr is workable, but the 47.5%-clay B horizon is the limiting layer and the 10–25% slope complicates layout.
Depth available	50 in to paralithic bedrock. Georgia requires a minimum thickness of suitable soil beneath trench bottoms; 50 in is workable but not generous and may force shallow, longer trenches.
Does slope create challenges?	Yes. Drainfields must follow contours. Lines running across an 18% grade need careful level-trench construction; serial distribution or a pumped system may be required.
Setback from water	Critical and unquantified. The drainfield would sit upslope of, and draining toward, a public drinking-water reservoir . Expect the Clayton County Board of Health to impose substantial setbacks from the CCWA boundary and possibly to restrict the usable rear portion of the lot entirely.
Perc / soil evaluation	Mandatory. Georgia requires a county-approved soil evaluation before a septic permit.

How many bedrooms can this lot support on septic? NEEDS PROFESSIONAL

The brief asks this directly. An honest answer has to be conditional, because bedroom count is set by the county health department from a **field** soil evaluation, not from mapped data.

Factor	Effect on bedroom count
Lot area — 57,993 sq ft (1.33 ac)	Favourable. Area is not the binding constraint; there is ample room for a primary field plus a full replacement field.
Texture — sandy clay loam over 47.5% clay	Limiting. Slower-percolating soils require more square feet of trench per bedroom.
Depth to bedrock — 50 in	Limiting. Restricts trench depth and may reduce the credited loading rate.
Slope — 18%	Limiting on layout, not on capacity per se.
Proximity to public water supply	Potentially decisive. Health-department setbacks could remove the downslope third of the lot from consideration.

Reasoned expectation — explicitly an estimate, not an entitlement

On area alone the lot could host a 4–5 bedroom system. Once the clay B horizon, the 50-inch bedrock limit and reservoir setbacks are applied, a **3 to 4 bedroom** conventional system is the realistic expectation, and a 4-bedroom approval may require a larger field, an engineered/pumped design, or both. **Do not buy this lot intending to build a 5-bedroom house on septic without a completed Level 3 soil evaluation in hand.** If the house programme includes a second in-law suite (item 33), the bedroom count driving septic sizing rises accordingly — making this the single most important pre-purchase test alongside the plat.

If no public water: ideal well depth UNVERIFIED

In the Georgia Piedmont, domestic wells draw from **fractured crystalline bedrock** beneath the saprolite, not from the soil profile. With paralithic rock at ~50 in here, a well would case through the weathered zone and seek water-bearing fractures below. Regional practice puts productive domestic wells in this setting commonly in the **150–400 ft** range, with casing set well below the soil/rock interface and grouted to protect water quality. Shallow wells are a poor idea on this site specifically because the lot drains toward — and any septic field would sit above — a public water supply. **These are regional norms, not a site prediction.** A licensed Georgia well driller and the Georgia EPD well-construction standards govern. In practice, public water is very likely available (CCWA), which makes this question largely academic — confirm first.

17 · Gardening suitability OFFICIAL

Soil pH	5.8 throughout — moderately acidic; below the 6.0–6.8 optimum for most vegetables
Drainage	Well drained — good
Organic matter	2.0% in the top 5 in; 0.25% below — low
Texture	Sandy clay loam surface (55% sand) over clay-rich subsoil (47.5% clay)
Available water capacity	0.14 cm/cm — moderate
Raised beds advisable?	Yes. Eroded thin topsoil, clay subsoil and an 18% grade all point to terraced raised beds — which also address the slope.
Imported topsoil / compost needed?	Yes, for any productive vegetable growing

18 · Gardening and farming — year-round plan GIS-DERIVED

Matched to this site's measured climate (Section L: 265-day frost-free season, mean annual 17.2 °C, 1,196 mm rain) and its measured soil (pH 5.8, sandy clay loam, low organic matter). Hampton sits in **USDA hardiness zone 8a**.

Category	Suitable plants	Planting season	Soil requirements on this lot
Vegetables (cool season)	Collards, kale, turnips, mustard greens, cabbage, broccoli, carrots, beets, spinach, lettuce, English peas, onions, garlic	Sow Aug–Sep for autumn/winter; Feb–Mar for spring. Many overwinter unprotected in 8a.	Lime to pH 6.2–6.5; 2–3 in compost. Raised beds strongly advised.
Vegetables (warm season)	Okra, southern/field peas, sweet potato, tomatoes, peppers, aubergine, squash, cucumber, beans, sweet corn, melons	After last frost, mid-Apr to May; succession to Jul	Same liming; mulch heavily — July mean max 31 °C with 117 mm rain drives both drought stress and disease.
Fruits	Blueberries (rabbiteye) — ideal, muscadine grapes, figs, persimmon, blackberries, pomegranate	Plant bare-root/dormant Nov–Feb	Blueberries thrive at pH 4.5–5.5 — do NOT lime their beds. The native 5.8 is already close; acidify slightly. Figs and muscadines are reliably hardy here.
Tree fruit	Peaches, plums, pears (fire-blight-resistant cvs.), apples (low-chill cvs.), pecan	Dormant season Nov–Feb	Well-drained slope is genuinely advantageous — cold air drains downhill, reducing late-frost damage to blossom. Avoid the lowest ground.
Herbs	Rosemary, thyme, oregano, sage, mint, chives, parsley (perennial-ish in 8a); basil, coriander, dill (annual)	Spring; Mediterranean herbs Apr–May	Mediterranean herbs need sharp drainage — plant on the upper slope or in raised/gravelly beds. They suit the native pH well.
South Asian kitchen crops	Okra (bhindi), bottle gourd, ridge gourd, bitter melon, Indian aubergine, curry leaf (pot & protect in winter), methi/fenugreek, coriander, turmeric, ginger, chillies	Warm season May–Jul; methi & coriander in cool season	Gourds need trellising and steady water. Turmeric/ginger need rich, loose, moisture-retentive soil — raised beds with heavy compost. Curry leaf is marginal in 8a; overwinter in a container.
Trees (shade/ornamental)	Native oaks, tulip poplar, red maple, dogwood, redbud, serviceberry, crape myrtle	Dormant season	The lot is already wooded; retain mature canopy on the slope wherever possible — it is the cheapest erosion control available.

Amendments indicated by the actual soil data

Amendment	Indicated?	Why — from the measured data
Lime	Yes (general veg)	pH 5.8 vs 6.0–6.8 optimum. Except blueberry beds.
Compost / organic matter	Yes — priority	Only 2% OM in 5 in of topsoil, 0.25% below. This is the biggest single deficiency.
Imported topsoil	Yes	"Eroded" phase; thin A horizon
Mulch	Yes	18% slope + eroded soil = active erosion risk; mulch also buffers summer heat
Sulfur	Only for acid-lovers	Native pH already acidic; sulfur only to push blueberries below 5.5
Fertiliser	Test first	No nutrient (N-P-K) values are published for this map unit, so any recommendation would be guesswork

Confirm with a soil test. The University of Georgia Extension office for Clayton County provides inexpensive soil testing that returns actual pH, P, K and lime requirement for your specific beds. The NRCS figures above are map-unit *averages* across thousands of acres, not measurements of this lot.

19–23 · Utilities & infrastructure LARGELY UNVERIFIED

Utilities are the weakest-evidenced part of this report — and they are a cost cliff
None of the five utilities below could be confirmed from public records for this specific parcel. For a vacant lot this is not a minor gap: an unavailable sewer or a long water/power run can add tens of thousands to the project. **Every row needs a written availability letter before closing.**

Utility	Status	What is actually known / who to ask
19 Water	UNVERIFIED	Clayton County Water Authority is the county provider and its reservoir adjoins the lot. With 60+ homes on Edgewater Dr built since 1988, a public main at the road is very likely. Confirm tap availability, meter size, and connection/impact fees. CCWA: ccwa.us
20 Sewer	UNVERIFIED — assume septic	1–2 acre lots and RS180 zoning strongly suggest no public sewer. If septic is required, items 16 and 33 (in-law suite) are directly constrained. Ask CCWA for sewer availability and, if none, the distance to the nearest main.
21 Electricity	UNVERIFIED	Served by either Georgia Power or a local EMC — not determined. Overhead service exists along a developed street; confirm transformer capacity, service drop distance and whether underground service is required by covenant.
22 Natural gas / propane	UNVERIFIED	Natural gas availability in this semi-rural pocket is uncertain; propane is universally available as a fallback. Several neighbouring homes list gas log fireplaces, which hints at gas or propane service nearby.
23 Internet	UNVERIFIED	Check the FCC National Broadband Map (broadbandmap.fcc.gov) by address — it is authoritative, free, and reports fibre/cable/DSL/fixed-wireless by provider with advertised speeds. Starlink is a universal fallback. Do not rely on provider marketing maps.

The waterfront premise of this listing does not survive examination

This is the most consequential section of the report. The lot is marketed on its water. Three independent findings undercut that: (1) the parcel boundary stops 59–80 ft short of the water; (2) the intervening land and the entire reservoir are owned by a **public water utility**; (3) that utility manages the lake as a **drinking-water supply** with permit-only access, a four-month annual closure, and a swimming ban. If you are buying for lake use rather than lake view, this lot probably does not do what you want.

24 · Waterfront access OFFICIAL

Form of access	Applies?	Evidence
Direct lake frontage	NO	Parcel polygon contains zero water; nearest water 58.7 ft beyond the rear boundary (minimum), ~80 ft on the centreline
Riparian / waterfront rights	Apparently none	Ownership does not extend to the water's edge; CCWA parcel 05045 051001 intervenes
Deeded lake access	UNVERIFIED	Could exist via the Waterpointe declaration. A neighbouring listing referenced "private access to lake", so an HOA common-area access right may exist — this must be read in the CC&Rs
Shared / HOA common access	Possible	See above — the HOA, not the lot, would hold it
Public access	Yes, by permit	CCWA operates a public access point at 143 Northbridge Road, Hampton

Practical reading: realistic access is a CCWA permit and/or an HOA common-area right — not a private right attached to Lot 23. Verify both in writing; the distinction matters for resale as much as for enjoyment.

25 · Lakeside terrain — road → house → lake GIS-DERIVED

Characterisation	Applies?
Gentle	No
Moderate (18.5% over the final 50 ft to the water)	Yes
Steep	Locally, 23.5% in the upper slope
Requires stairs for lake access	Very likely — 80 ft of descent, and the final stretch crosses land you do not own
Requires retaining wall	Likely for the building pad and driveway
Requires significant grading	Yes

Walking down to the water means descending the remaining fall and then crossing ~60–80 ft of CCWA property. Any permanent path, steps or structure there needs CCWA's permission.

26 · Dock feasibility OFFICIAL

Assume a private dock is not achievable

A dock would sit on and over land and water owned by the Clayton County Water Authority and held for **public drinking-water supply**. Public water utilities essentially never license private residential docks on supply reservoirs — the contamination, liability and access-control reasons are structural, not discretionary. CCWA's published rules reinforce this: permit-controlled access, closure November–February, and a swimming/wading ban. No Georgia DNR coastal dock process applies (that governs tidal waters) — the decision-maker is CCWA.

Factor to research	Finding
Lake authority requirements	CCWA controls the reservoir and the shoreline strip — the governing party
HOA restrictions on docks	UNVERIFIED — read the Waterpointe CC&Rs
County / state regulations	Clayton County land disturbance + Georgia EPD water-supply watershed rules
Waterfront setbacks, dock size limits, shared-dock rules, permits	Moot unless CCWA grants access in the first place

Action: put the question to CCWA in writing before closing and keep the answer. If a dock is essential to your purpose, this is a condition precedent, not a detail.

27 · Lake depth / bathymetry UNVERIFIED

No bathymetry, average/maximum depth or seasonal drawdown range was obtainable publicly. The HOA describes a ~250-acre lake. The lidar normal pool is 801.1 ft, but that is a single epoch — CCWA operates the reservoir for supply, so levels fluctuate with drought and demand, which affects how the view reads in a dry summer. Request operating-level data from CCWA.

28 · Boating OFFICIAL

Activity	Status on J.W. Smith Reservoir
Canoes / kayaks / non-motorised	Permitted in season, under CCWA permit
Motorised boats, wake boats, water skiing	Not supported. A water-supply reservoir managed for fishing, canoeing and wildlife viewing. Confirm the explicit prohibition with CCWA.
Swimming / wading	Expressly prohibited
Private boat storage at the shore	Not available — you do not own to the water
Boat ramp / marina	CCWA public access at 143 Northbridge Rd; no marina
Seasonal access	J.W. Smith closed entirely November–February. March–October: Mon–Wed and Sat–Sun, 7am–7pm (closed Thu–Fri)
Permit cost	\$5 day pass · \$25 annual · \$40 annual "Plus" — per vehicle, permit holder must attend

29 · Fishing OFFICIAL

CCWA runs a managed fishing programme on its reservoirs with a season opening in March, and describes J.W. Smith as a place where visitors "come fishing, canoeing, and even come out for picnics." Access requires a CCWA permit in addition to a Georgia state fishing licence, and is bounded by the seasonal calendar above. Species present, stocking programme, catch limits and permitted methods were not retrievable in detail UNVERIFIED — request the current fishing regulations sheet from CCWA. Fishing from "your" shoreline is not an option, because the shoreline is not yours; fishing happens at CCWA's designated access points.

30 · HOA OFFICIAL FINANCIALS UNVERIFIED

HOA	Waterpointe Community Association — waterpointehoa.com
Subject to HOA?	Yes. The association states that protective covenants are in place across all four phases of Waterpointe
Amenities (per the association)	Private swimming pool, tennis courts, clubhouse ; wooded, wildlife-friendly setting bordering a ~250-acre lake; active Neighborhood Watch
Annual dues	LOW CONFIDENCE A third-party aggregator reports HOA fees in Waterpointe of \$13–\$39 per month (\$156–\$468/yr). UNVERIFIED — obtain the current assessment schedule from the association directly.
Transfer fees, special assessments, reserves, budget	UNVERIFIED — request the budget, reserve study and any pending special assessments
Boat / dock facilities	None evidenced as HOA-owned; the lake is CCWA's

Dues in the \$156–\$468/yr range would be **remarkably low** for a community operating a pool, tennis courts and a clubhouse. If accurate, scrutinise the **reserve funding** — under-reserved associations with ageing amenities are where surprise special assessments come from. Ask for the last three years of financials and minutes.

31 · HOA covenants UNVERIFIED — OBTAIN BEFORE CLOSING

The association publishes its covenants on its own website under the newsletter/documents tab. They were not retrieved for this report, and they are **second only to the plat** in importance because they can independently prohibit things zoning permits. Read specifically for:

- Declaration, CC&Rs and all **amendments**
 - **Architectural review** — minimum house size, materials, roof pitch, garage orientation, plan approval
 - Minimum/maximum square footage (drives the cost estimate in item 43)
 - **Waterfront and dock restrictions**
 - Fence restrictions (relevant on a sloped, wooded lot)
- **Outbuilding / accessory structure** limits
 - RV and boat storage
 - **Livestock and poultry** — see item 34
 - **Short-term rental** prohibitions — see item 35
 - Tree removal / land-disturbance approval, and any **build-by** deadline on vacant lots

Specific risk for a vacant lot: many Georgia subdivision declarations include a **time limit to commence construction** after purchase, and mandatory architectural approval of plans. Confirm there is no clock you would be inheriting, and no minimum-size requirement that forces a larger (costlier) house than you intend.

32 · County zoning — RS180 ZONE CONFIRMED STANDARDS UNVERIFIED

Zoning designation	RS180 — Clayton County single-family residential (confirmed from the assessor's parcel record; all 60+ Edgewater Dr lots share it)
Permitted residential use	Single-family detached — the intended use is clearly permitted
Minimum lot size	UNVERIFIED The designation implies an 18,000 sq ft minimum. At 57,993 sq ft this lot is roughly 3.2× any such minimum — lot area is not a constraint.
Setbacks (front / side / rear)	UNVERIFIED — DO NOT ASSUME. Not obtainable from public sources at the time of writing. Because the lot is only 148 ft wide , the side setbacks are what govern the maximum house width, so this figure directly determines what you can build.
Max building coverage / impervious limit	UNVERIFIED — and see the water-supply watershed caution below
Height limit, accessory structures, ADUs, agricultural provisions	UNVERIFIED

A regulatory layer that may not appear on the zoning map
Georgia's Part 5 Environmental Planning Criteria impose **water-supply watershed protection** requirements — stream buffers and **impervious-surface caps** — within a seven-mile radius upstream of a public water-supply intake, with stricter rules for small watersheds. This lot drains directly into a public water-supply reservoir. Whether a watershed-protection overlay, buffer or impervious cap applies to Lot 23 **was not determined** and could materially limit house footprint, driveway and pool. Ask Clayton County Community Development ((770) 477-3569) specifically about water-supply-watershed overlay status for parcel 05050A A003 . **This is a question most buyers never think to ask, and on this particular lot it is a live one.**

Active development moratorium OFFICIAL
Resolution 2026-120 (adopted 2 June 2026) extends a moratorium on accepting applications related to the development of **any new construction of single-family residential subdivisions** or multi-family developments, running until the county adopts a revised code or **31 December 2026**, whichever comes first. The county is also separately reviewing **minimum lot sizes**. On its face this targets new *subdivisions* rather than one house on an already-platted lot — but the wording is broad and the consequence of being wrong is a stalled permit. **Get a written determination** that a single-family building permit on this existing lot is unaffected.

33 · Second in-law suite / ADU UNVERIFIED

Whether a **second independent dwelling unit** is permitted could not be determined. Three gates must all open, and any one can stop it:

Gate	Status	Note
Zoning (RS180 max dwelling units, ADU provisions)	UNVERIFIED	Many single-family districts cap at one dwelling unit and forbid a second kitchen
HOA covenants	UNVERIFIED	Declarations frequently prohibit accessory apartments outright
Septic capacity	Likely the binding constraint	If the lot is on septic, a second full suite adds bedrooms to the design flow and may exceed what the soil will support (item 16)

The encouraging precedent is physical rather than legal: the **80 ft of fall suits a daylight basement**, and neighbouring homes advertise basements "ideal for multi-generational living." An *integrated* lower-level suite sharing the main structure's utilities is far more likely to be approved than a detached second dwelling — and it is what the terrain naturally produces.

34 · Poultry & small livestock UNVERIFIED

Two independent authorities must **both** permit animals, and the HOA is usually the stricter of the two. Neither was verified for Waterpointe.

Animal	County (RS180)	HOA covenants
Chickens, ducks, geese	UNVERIFIED	UNVERIFIED — commonly prohibited in platted suburban subdivisions
Rabbits	UNVERIFIED	Often treated as pets rather than livestock
Goats, other small livestock	UNVERIFIED	Unlikely to be permitted
Bees	UNVERIFIED	Variable

Honest expectation: Waterpointe is an established subdivision of \$300k–\$860k homes with a pool, tennis courts and architectural covenants. Declarations for communities of this type very commonly prohibit poultry and livestock expressly. Treat hobby farming as **probably not available** until the CC&Rs say otherwise, and do not pay a premium for the possibility. Note too that animal husbandry immediately upslope of a **public drinking-water reservoir** attracts additional scrutiny regardless of what the covenants say.

35 · Short-term rental feasibility OFFICIAL

Clayton County is not accepting short-term rental applications

Resolution 2026-153 establishes a moratorium on the acceptance of **any applications related to ... short term rentals** (together with boarding homes, group homes, personal care homes and community living arrangements). Verified terms from the resolution text:

- **Duration:** until **31 December 2026**, or until a modified ordinance is adopted, "unless said moratorium is extended for good cause shown"
- **Effective:** from the date of adoption
- **Grandfathering:** no effect on approvals or permits **previously issued** — which does not help a vacant lot with no permit
- **Exemption route:** an application may be filed with Community Development; the Zoning Administrator must schedule a Board of Commissioners hearing within 30 days, and the Board *may* grant an exemption if the proposal conforms to the ordinances under review

The county's stated purpose is to **revise the definitions** of these uses — so the post-moratorium rules are, by design, unknown. **An STR-dependent investment case cannot be underwritten on this parcel today.** Layer on top the unverified HOA position (item 31), which can prohibit STRs permanently regardless of what the county eventually allows.

Not determined, and all downstream of the above: minimum rental period, permit mechanics, occupancy limits, parking, noise rules, and hotel/occupancy tax obligations.

UNVERIFIED

36–42 · Environmental & geological due diligence

#	Item	Status	Finding / action
36	Elevation Certificate	NONE FOUND	Probably unnecessary. Elevation certificates exist to price flood insurance in SFHAs; in Zone X with no BFE there is nothing to certify against. A lender may still ask — a surveyor can produce one.
37	Survey (boundary / ALTA / topographic)	NONE FOUND	Commission a boundary + topographic survey. On a 148-ft-wide sloping lot where side setbacks govern the house width and all contours here are lidar estimates, this is not optional — it is the document the architect and grading engineer will work from.
38	Geotechnical / soil report	NONE FOUND	Advisable — bedrock at ~50 in plus footings in 47.5% clay on a slope (item 15)
39	Perc test / soil evaluation	NONE FOUND	Mandatory if septic. Determines the permitted bedroom count. Highest-priority test alongside the survey.
40	GPR / subsurface investigation	NONE FOUND	Not normally warranted for a residential lot; test borings are the proportionate tool here
41	Radon	UNVERIFIED	Clayton County's specific EPA radon zone could not be confirmed — EPA publishes Georgia as a raster map image from which the county designation is not machine-readable, and I will not guess it. Georgia spans Zones 1–3. Test the finished house (the EPA's own guidance is that elevated radon occurs in all three zones), and consider passive radon-resistant construction, which is cheap at build time — especially relevant if you build the daylight basement this lot invites.
42	Sinkholes / karst	Low risk GIS-DERIVED	The parcel sits in crystalline Piedmont bedrock — the soil is classified as kaolinitic Rhodic Kanhapludults over paralithic (weathered igneous/metamorphic) rock , not limestone. Sinkhole and karst subsidence are characteristic of carbonate terrain and are not a meaningful hazard in this geological setting. No specific sinkhole reports or subsidence claims were researched.

43 · Can the lot accommodate the desired programme? GIS-DERIVED

The lot's **area** (1.33 ac) is generous. Its **shape** (148 ft wide × 419 ft deep) and its **grade** (18%) are the real constraints: a narrow, deep, consistently sloping rectangle.

Element	Feasibility	Governing constraint
Building envelope	Adequate but width-limited	Only 148 ft wide (130 ft at the road). Unverified RS180 side setbacks dictate maximum house width — the single most important missing number for design.
House footprint	Yes	Best sited in the upper third, near the road, where access is shortest and the view is highest
Garage	Yes	Side-entry garage needs width; front-entry needs driveway length on grade
Driveway	Yes, with design care	23.5% natural grade in the 60–110 ft band. Must be cut/benched to reach a usable gradient (typically ~15%)
Septic field	Probable, unconfirmed	Needs contour-following trenches; reservoir setbacks may remove the lower lot (item 16)
Well	Likely unnecessary	Public water probably available (item 19)
Pool	Possible but expensive	Requires a second level bench and retaining; may also run into an impervious-surface cap (item 32)
Patio / flat yard	Limited without retaining	No natural level ground anywhere on the lot
Retaining walls	Expect them	Driveway cut, pad edges, yard terracing
Lake setback	Unquantified	CCWA boundary + any watershed buffer

44 · Grading & fill GIS-DERIVED NEEDS PROFESSIONAL

Existing grades	889.99 ft at road ~ 814.94 ft at rear boundary; 18.3% average, 23.5% max over 50 ft
Required grading	Substantial. A level pad on an 18% slope needs cut on the uphill side and fill on the downhill side
Cut/fill strategy	Balanced cut-and-fill is the efficient approach — reuse cut material on site as engineered fill and avoid both import and export haulage
Imported fill likely?	Probably not required if cut/fill is balanced — a genuine cost saving on a sloped lot
Retaining walls	Likely; engineered design required above modest heights
County approval	Yes. Expect a land-disturbance permit, grading plan and an erosion & sedimentation control plan — scrutinised here because the discharge point is a public water supply

Estimated cost to build a 4-bedroom home comparable to the street PLANNING-LEVEL ESTIMATE

Read this as a planning-level order of magnitude, not a quotation. It is built from verified local market data (county appraisals and recorded sales on Edgewater Drive) plus **general metro-Atlanta construction cost ranges that were not independently verified for 2026.** Replace every figure with builder bids before acting. HOA minimum-size requirements (item 31) are unverified and could force a larger house than assumed.

Verified local benchmarks

Benchmark	Value	Source
Waterpointe median recorded sale (12 mo to 20 Sep 2026)	\$454,950 · \$120/sq ft · 34 days on market	MLS aggregation
Edgewater Dr improved-home county appraisals	\$296,000 – \$856,900	Clayton Co. assessor
Water-view homes near Lot 23	12390 (Lot 22) \$519,400 · 12374 (Lot 20) \$736,900 · 12426 (Lot 28) \$633,300	Clayton Co. assessor
House sizes in the community	2,592 – 6,010 sq ft	Subdivision data
Vacant-lot county appraisal	\$60,000 (uniform across Edgewater vacant lots)	Clayton Co. assessor

Assumed programme: ~3,200 sq ft above grade, 4 bed, daylight basement (partly finished), 2-car garage

Cost component	Low	High	Note
Land acquisition	\$95,000	\$125,000	Asking \$125k vs \$60k county appraisal — negotiable (four unsold vacant lots nearby)
Pre-construction: survey, geotech, perc, architecture, engineering, permits, HOA review	\$25,000	\$55,000	Higher than a flat lot: topo survey + grading design + possible borings
Site work premium for 18% slope: clearing, cut/fill, driveway benching, retaining walls, erosion control	\$55,000	\$140,000	The single largest variable. Rock excavation (bedrock ~50 in) is the main upside risk
Utilities: water tap, power, septic system (or sewer connection)	\$25,000	\$60,000	Engineered/pumped septic on slope sits at the high end
House shell + finish, 3,200 sq ft @ \$150–\$225/sq ft	\$480,000	\$720,000	Mid to upper-mid finish matching the street
Daylight basement (incremental, partly finished)	\$45,000	\$105,000	Terrain makes this efficient — best value-per-dollar on this lot
Contingency @ 10–15%	\$73,000	\$180,000	Sloped-lot projects warrant the upper end
TOTAL ALL-IN (incl. land)	~ \$798,000	~ \$1,385,000	Planning-level range

The finding that matters most financially

Recorded sales in Waterpointe run at about **\$120 per square foot**, and the highest county appraisal on the whole street is **\$856,900**. A 3,200 sq ft new build on this lot plausibly costs **\$798k–\$1.39M all-in**. Even at the low end that is at or above the top of the local market, and the mid-case exceeds every appraised home on Edgewater Drive.

In plain terms: **building here is very likely to cost more than the finished house would be worth on resale.** That does not make it a bad decision — it is a perfectly rational one for an owner-occupier who wants a specific house, a protected water view and a 265-day growing season, and who intends to stay. But it is a **poor arbitrage**, and anyone underwriting this as a build-to-sell or build-to-rent play should see the gap clearly before committing. The steep-lot site premium and the unverified septic/watershed constraints both push in the same direction.

46 · Climate REANALYSIS-DERIVED

Computed for this coordinate from a **30-year daily record (1994–2023)** of ERA5 reanalysis, in °C as requested. These are modelled gridded values for the site, not a weather-station record.

Month	Mean max °C	Mean min °C	Mean °C	Precip mm
Jan	11.5	2.4	7.0	104
Feb	13.9	4.1	9.0	116
Mar	17.9	7.4	12.7	112
Apr	22.3	11.3	16.8	82
May	26.8	16.0	21.4	77
Jun	29.8	20.1	24.9	106
Jul	31.0	21.9	26.4	117
Aug	30.7	21.6	26.2	110
Sep	27.7	18.6	23.2	98
Oct	22.7	13.0	17.9	75
Nov	17.1	7.4	12.2	86
Dec	13.0	4.2	8.6	114
ANNUAL	22.1	12.4	17.2	1196

17.2 °C
ANNUAL MEAN TEMPERATURE

1,196 mm
ANNUAL RAINFALL (47.1 IN)

265 days
MEAN FROST-FREE GROWING SEASON

Summer highs	July mean max 31.0 °C ; August 30.7 °C
Winter lows	January mean min 2.4 °C ; December 4.2 °C
Extremes in the 30-year record	record high 40.3 °C · record low -12.9 °C
Rainfall distribution	Remarkably even — wettest month Jul (117 mm), driest Oct (75 mm). No dry season; design for year-round runoff.
Humidity	Humid subtropical (Köppen <i>Cfa</i>); summer humidity persistently high. NOT QUANTIFIED
USDA hardiness zone	8a

A 265-day frost-free season with evenly distributed rainfall is genuinely excellent for the gardening ambitions in item 18 — arguably the lot's most reliable asset after the view.

47 · Natural hazards

Hazard	Assessment	Basis
Flood	Low	FEMA Zone X, no SFHA, no BFE; lot low point ~10 ft above normal pool OFFICIAL
Tornado / severe storms	Moderate — principal hazard	Spring and late-autumn severe convective outbreaks are normal for north-central Georgia. Build to current wind provisions; this lot's daylight basement provides a natural refuge. NOT QUANTIFIED
Hurricane / tropical wind	Low-moderate	~400 km inland; exposure is to weakening remnants bringing heavy rain, not damaging wind
Hail, lightning	Moderate	Typical of the regional convective-storm climate
Wildfire	Low-moderate	Wooded lot — maintain defensible space; humid climate limits landscape-scale fire risk
Drought	Low-moderate	Recurrent multi-year droughts also lower reservoir levels , affecting the view and lake access
Extreme heat	Moderate and rising	Record 40.3 °C; summer means near 31 °C. Specify shading, insulation and HVAC accordingly
Sinkhole / subsidence	Low	Crystalline Piedmont bedrock, not karst (item 42) GIS-DERIVED
Erosion	Elevated — site-specific	18% slope in an "eroded"-phase soil draining to a public reservoir. The most probable <i>construction-phase</i> hazard on this property.

48 · Community & demographics UNVERIFIED

I was unable to retrieve American Community Survey figures: the U.S. Census API now requires a registered key, and I will not publish population, income or ethnicity statistics I did not actually obtain. What is verified is the geography — **Clayton County, Census Tract 406.36, Block 1000** (GEOID 130630406361000). Pull these exact tables for the tract and county at data.census.gov :

Topic requested	ACS table
Total population	B01003
Median household income	B19013
Median age / age distribution	B01002 / S0101
Household composition	B11001
Race & ethnicity	B02001 / B03003
Asian Indian population (requested specifically)	B02015 — "Asian alone by selected groups"
Population growth	Compare B01003 across ACS vintages, or Census 2010 □ 2020

Qualitatively and verifiably: this is a **built-out, owner-occupied, single-family** enclave (homes from 1988 to 2025, 60+ on Edgewater Drive alone) inside the Atlanta metropolitan CSA, with an active HOA and Neighborhood Watch. Those are structural facts from the parcel and HOA records, not demographic inferences.

All distances below are **straight-line** from the parcel centroid, computed from OpenStreetMap coordinates. Driving distances will be longer — typically 20–40% more in this road network.

GIS-DERIVED

49 · Schools GIS-DERIVED ZONING UNVERIFIED

Because the parcel is in **Clayton County**, it is served by **Clayton County Public Schools** — *not* Henry County Schools. Buyers who believe they are purchasing in Hampton/Henry County frequently get this wrong, and the two districts differ significantly in performance and reputation. **Attendance zones must be confirmed directly with CCPS**; proximity does not determine assignment. School ratings were not retrieved.

School	Distance	Note
Rivers Edge Elementary School	1.17 mi	Nearest elementary — walkably close by distance, though not by terrain or footway
Lovejoy Middle School	2.50 mi	Nearest middle school
Mundy's Mill High School	5.28 mi	Nearest public high school
Mundys Mill Junior High	5.02 mi	
Hampton Elementary School	5.08 mi	
Grace Christian Academy	3.33 mi	Private option
Rising Star Montessori Academy	5.00 mi	Private option

50 · Healthcare

Facility	Distance	Type
Piedmont Fayette Hospital	8.36 mi	Nearest full-service hospital with emergency department
Kaiser Permanente Medical Center	10.34 mi	Medical centre
Piedmont Henry Hospital	10.53 mi	Major hospital, ED
Southern Regional Medical Center	11.36 mi	Major hospital, ED
Rehabilitation Hospital of Henry	10.19 mi	Rehabilitation
WellStar Spalding Regional	13.60 mi	Hospital

Emergency response is a standout strength. Clayton County Fire Station 10 sits 0.19 mi (about 310 m) from the lot — confirmed twice, from OpenStreetMap and independently from the county parcel record (12554 Panhandle Rd, 652 ft away). Very short response times, and a proximity that often improves fire-insurance rating. The trade-off worth checking on a site visit is occasional siren noise.

51 · Shopping & services

Grocery	mi	Other services	mi
Eden Fresh	1.92	Walmart Pharmacy	3.16
Walmart Supercenter	3.13	Citgo / BP fuel	3.36
Aldi	3.24	Walgreens	5.12
Food Depot	3.37	CVS Pharmacy	5.67
Kroger	4.28	Banks	N/V
Ingles	5.00	Hardware / home improvement	N/V
Publix	5.00		

Day-to-day shopping is well covered within about 3–5 miles, anchored by the Walmart Supercenter cluster. Banks and hardware/home-improvement stores were not separately enumerated.

52 · Indian / South Asian community GIS-DERIVED

Amenity	Distance	Note
The Hindu Temple of Atlanta (incl. Balaji & Shiva temples)	12.58 mi	The major temple complex serving metro Atlanta, in Riverdale — same county
Ambaji USA – Shree Shakti Mandir	12.81 mi	
Bombay Bites	9.23 mi	Nearest Indian restaurant
Masala Cottage	11.86 mi	
Singh's Cafe	12.72 mi	
Krishna Life Temple & Monastery	20.25 mi	
BAPS Shri Swaminarayan Mandir Atlanta	34.55 mi	In Lilburn, NE metro
Cherians International Groceries	26.99 mi	Nearest large dedicated Indian grocery — the main practical gap

Worship and restaurants are reachable at roughly 9–13 miles, which is convenient. **Full-range Indian grocery shopping is not:** the nearest large store is ~27 miles, so expect a planned trip rather than a casual one. Metro Atlanta's principal South Asian concentration lies along the **north-eastern** corridor (Gwinnett — Lilburn, Norcross, Duluth), on the far side of the city from this lot. Mosques and South Asian community organisations were not separately enumerated. PARTIALLY UNVERIFIED

53–54 · Entertainment, nightlife & walkability UNVERIFIED

Walk Score, Bike Score and Transit Score were not retrieved. A practical assessment can nonetheless be made with confidence from the verified geography: this is a **car-dependent** location. The lot sits on a cul-de-sac-pattern residential street of 1–2 acre wooded lots, with the nearest grocery ~1.9 mi away across a 419 ft-deep, 18%-grade property and no evidenced footways. There is no walkable retail, no meaningful transit, and no nightlife district nearby; Atlanta's restaurant, cinema and nightlife concentrations are 15–25 miles north. **Assume every daily errand requires a car.** For balance, this is exactly the trade-off that delivers the privacy, the woodland and the reservoir view.

55 · Airport GIS-DERIVED

Nearest international airport	Hartsfield-Jackson Atlanta International (ATL)
Straight-line distance	15.9 mi (25.5 km)
Typical driving time	Roughly 25–40 minutes depending on traffic, via I-75 / SR-85 NOT MEASURED
Significance	ATL is among the world's busiest airports, offering non-stop service to most major domestic and many international destinations — including direct service to India from Atlanta

Genuine locational strength. Very few semi-rural, wooded, water-adjacent acre-plus lots sit 16 miles from a global hub airport. For frequent flyers — and for anyone travelling regularly to South Asia — this is a material and durable advantage, and it also underpins the neighbourhood's value (a neighbouring listing markets "exceptional access to Hartsfield-Jackson and I-75").

56 · Documented strengths

Strength	Evidence	Confidence
No mapped flood risk	FEMA Zone X, outside SFHA, no BFE; lot low point ~10 ft above reservoir pool	OFFICIAL
Permanently protected rear outlook	Adjoins a \$5.48M CCWA water-supply parcel that will never be developed — the view behind the lot is structurally safe	OFFICIAL
Elevated water view	90 ft of elevation above the reservoir across a 419 ft depth	GIS-DERIVED
Generous, private lot	1.3313 ac; 3× a presumed 18,000 sq ft zoning minimum; wooded; 1–2 ac neighbours	OFFICIAL
Favourable soil for foundations	Well drained, no water table in profile, low shrink–swell (LEP 1.5)	OFFICIAL
Terrain suits a daylight basement	80 ft of fall converts the slope into finished lower-level space and view	GIS-DERIVED
Fire station 0.19 mi away	Clayton County Station 10 — confirmed from two independent sources	OFFICIAL
Hartsfield-Jackson 15.9 mi	Global hub access from a semi-rural setting	GIS-DERIVED
Excellent growing climate	265 frost-free days, 1,196 mm evenly distributed rain, zone 8a	REANALYSIS
Established, built-out neighbourhood	Homes 1988–2025 appraising \$296k–\$857k; pool, tennis, clubhouse; 99% of ask achieved, 34 days on market	OFFICIAL
Sinkhole risk negligible	Crystalline Piedmont geology, not karst	GIS-DERIVED
Price is negotiable	\$125k ask vs \$60k county appraisal; four comparable vacant lots unsold nearby	OFFICIAL

57 · Limitations & risks

Risk	Severity	Detail
Not truly lakefront	High	Parcel contains no water; 59–80 ft of CCWA land intervenes; no apparent riparian rights. Directly contradicts the marketing.
Dock almost certainly impossible	High	Would occupy a public drinking-water utility's land and water
Restricted lake use	High	Permit-only; closed Nov–Feb ; no swimming/wading; no motorised boating; access at CCWA's designated points, not from the lot
Build cost likely exceeds resale value	High	\$798k–\$1.39M estimated all-in vs a \$120/sq ft market and an \$857k top appraisal on the street
STR moratorium in force	High (if STR is the thesis)	Clayton Co. Res. 2026-153, through 31 Dec 2026, with the governing definitions themselves under revision
18.3% average slope; 23.5% over 50 ft	Moderate–high	No level building pad; cut/fill, retaining and driveway benching required; steepest band sits where the house would go
Septic constraints unresolved	Moderate–high	Clay B horizon, bedrock at ~50 in, 18% slope, and probable health-department setbacks from a public water supply. Bedroom count is unproven.
Possible water-supply watershed overlay	Moderate–high	Georgia Part 5 criteria may impose buffers and impervious caps — undetermined, and could shrink the buildable envelope
Development moratorium wording	Moderate	Res. 2026-120 — needs a written determination that a single lot build is exempt
Zoning standards unknown	Moderate	RS180 setbacks unverified; on a 148 ft-wide lot the side setbacks determine the house width
Covenants unread	Moderate	Could independently restrict size, materials, outbuildings, poultry, STR — and may impose a build-by deadline
Utilities unconfirmed	Moderate	Water, sewer, power, gas and broadband all require written availability confirmation
Rock excavation risk	Moderate	Paralithic bedrock at ~50 in against a basement/driveway cut of 6–10 ft
Construction-phase erosion	Moderate	Eroded-phase soil, 18% grade, discharging toward a public reservoir — expect strict E&S enforcement
Thin, acidic, low-organic topsoil	Low	pH 5.8, 2% OM over 5 in; amendable with lime, compost and imported topsoil
Car-dependent; schools are Clayton County	Low–moderate	No walkable amenities; district differs from buyer expectations set by the Hampton address
Hobby farming probably prohibited	Low	Typical for a covenanted swim/tennis community; unverified

58 · Documents to obtain before purchase

Ordered by how much they could change the decision. Tick them off as they arrive.

Tier 1 — deal-determining; get these before removing contingencies

- ☐ **Recorded plat** (Clayton Co. Clerk of Superior Court) — easements, platted setbacks, any reservoir buffer. *The highest-value missing document.*
- ☐ **Level 3 soil evaluation / perc test** (Clayton Co. Board of Health) — determines the **permitted bedroom count**. Do not assume 4 bedrooms.
- ☐ **HOA declaration, CC&Rs, amendments and architectural guidelines** (Waterpointe Community Association) — minimum house size, STR, outbuildings, poultry, build-by deadline
- ☐ **Written CCWA determination** on shoreline access, any dock or structure on CCWA land, and lake-use rights attaching to Lot 23
- ☐ **Zoning verification letter** for parcel 05050A A003 — RS180 setbacks, coverage, height, ADU/second dwelling, **and whether a water-supply watershed overlay applies**
- ☐ **Written confirmation that Res. 2026-120 does not bar** a single-family permit on this existing platted lot
- ☐ **Utility availability letters** — CCWA (water *and* sewer), electricity provider, gas; FCC broadband check

Tier 2 — design and cost certainty

- ☐ **Boundary + topographic survey** by a Georgia-licensed surveyor (replaces every GIS estimate in this report)
- ☐ **Geotechnical report with test borings** — bearing capacity, slope stability, **depth to rock**
- ☐ **Two or three builder bids** on an identical sloped-lot scope, to replace the planning-level estimate in item 43
- ☐ **HOA financials** — budget, reserve study, three years of minutes, any special assessments; confirm the actual dues
- ☐ **Title commitment** with full easement and restriction schedule; confirm legal description and access
- ☐ **Tax certificate** — current Clayton County millage and any outstanding amounts

Tier 3 — useful

- ☐ Clayton County **governing FEMA panel** confirmation (resolves the 13063C / 13151C ambiguity)
- ☐ CCWA **reservoir operating levels** and seasonal drawdown range
- ☐ CCPS **school attendance zone** confirmation
- ☐ UGA Extension **soil test** for the garden areas; **radon test** after construction

59 · Final construction feasibility

Can the lot accommodate...	Verdict	Qualification
A main house	YES	With significant grading, a stepped or daylight-basement foundation and retaining. Width limited by unverified side setbacks.
A second in-law suite	CONDITIONAL	Physically well suited as an <i>integrated</i> lower-level suite. A <i>separate</i> dwelling unit depends on zoning, covenants and — probably decisively — septic capacity.
Garage	YES	Driveway must be benched down from a 23.5% natural grade
Septic system	PROBABLE, unproven	Area is ample; soil, 50-in bedrock, slope and reservoir setbacks govern. Perc test required.
Garden	YES — well suited	265-day season; use terraced raised beds, lime and compost. Blueberries, figs, muscadines and okra will thrive.
Hobby farming / poultry	PROBABLY NOT	Expect covenant prohibition; also sensitive upslope of a drinking-water reservoir
Dock	NO (assume not)	Would sit on CCWA public water-supply land and water
Boat access from the property	NO	No water frontage. Non-motorised use only, by CCWA permit, at CCWA access points, Mar–Oct
Short-term rental	NO at present	County moratorium through 31 Dec 2026; HOA position unverified
Pool / outdoor recreation	CONDITIONAL	Needs a second engineered bench and retaining; check impervious caps

Overall judgement

This is a **buildable lot with a protected view in an established community** — and it is **not** the lakefront recreational property the listing implies. Those two statements are both true, and the gap between them is the whole point of this exercise.

It suits a buyer who wants a custom home with a permanent wooded water *outlook*, values a 16-mile airport run and a 0.19-mile fire station, intends to garden, and will **hold the house rather than flip it**. It does not suit a buyer who wants a dock, a boat, swimming, an STR income stream, a chicken run, or a cost-effective build-to-value equation.

Two tests should govern the purchase decision, and both can be done cheaply before committing: the **perc test** (does the bedroom programme even fit?) and the **recorded plat plus zoning letter** (how much of this lot can you actually build on?). The \$125,000 ask against a \$60,000 county appraisal, with four comparable lots sitting unsold nearby, suggests the price should carry the risk that these unknowns represent — not the buyer.

Parameter	Finding	Evidence
Lot size	57,993 sq ft = 1.3313 acres	GIS
Lot dimensions	□ 148 ft wide × 419 ft deep ; frontage □ 130 ft; perimeter 1,112.6 ft	GIS
Lowest elevation	811.0 ft NAVD88 (rear/lake end)	LIDAR
Highest elevation	891.2 ft (road frontage)	LIDAR
Elevation difference	80.2 ft total relief (75.1 ft along the centreline)	LIDAR
Average slope	18.3% (10.37°)	LIDAR
Maximum slope (any 50 ft)	23.5% (13.25°) , 60–110 ft from the road	LIDAR
Rising angle at the lake end	18.5% (10.47°) over the final 50 ft; 18.4% (10.42°) shoreline □ high point	LIDAR
FEMA zone	Zone X — area of minimal flood hazard; outside SFHA	OFFICIAL
BFE	None published (not applicable in Zone X)	OFFICIAL
Minimum finished-floor elevation	No FEMA-driven requirement. Set by grading/drainage design; confirm any local rule	PRO
Fill required?	Not for flood. Cut-and-fill required for buildability; balanced on-site cut/fill likely avoids import	GIS
Reservoir normal pool	801.1 ft ; lot low point +9.9 ft above it	LIDAR
Distance to water's edge	59–80 ft beyond the rear boundary , across CCWA land	GIS
Sewer	Unconfirmed — assume septic	GAP
Water	CCWA public water likely at the road — unconfirmed	GAP
Electricity / Gas / Internet	All unconfirmed ; propane and satellite are fallbacks	GAP
Septic required?	Probably yes — drives bedroom count	GAP
Permitted bedrooms on septic	3–4 expected (area allows more; soil, 50-in bedrock, slope and reservoir setbacks constrain). Unproven.	PRO
Soil	Gwinnett sandy clay loam, 10–25% slopes, eroded (GwE2). Well drained; HSG B; pH 5.8; clay 30% □ 47.5%; low shrink-swell; bedrock 50 in	OFFICIAL
Ideal well depth (if needed)	Regional norm 150–400 ft into fractured bedrock; avoid shallow wells here	REGIONAL
HOA	Waterpointe Community Association — pool, tennis, clubhouse; covenants across 4 phases	OFFICIAL
HOA fee	Reported \$13–\$39/month (\$156–\$468/yr) — verify	LOW CONF.
Zoning	RS180 single-family; setbacks and coverage unverified ; possible watershed overlay	OFFICIAL GAP
Dock possible?	Assume NO — CCWA public water-supply land and water	OFFICIAL
Lake	J.W. Smith Reservoir , ~250 acres, Clayton County Water Authority drinking-water supply	OFFICIAL
Lake depth	Not available — no public bathymetry	GAP
Boating	Non-motorised only, by CCWA permit (\$5/\$25/\$40); closed Nov–Feb ; Mar–Oct Mon–Wed & Sat–Sun 7am–7pm; no swimming or wading	OFFICIAL
Fishing	Permitted under CCWA permit + Georgia licence, in season; not from the property. Species/limits not retrieved	OFFICIAL GAP
Hobby farming	Probably prohibited by covenant — verify	GAP
Second in-law suite	Conditional — integrated lower-level suite plausible; separate unit doubtful	GAP
Short-term rental	Not permitted at present — Clayton Co. Res. 2026-153 through 31 Dec 2026	OFFICIAL
Nearest hospital	Piedmont Fayette Hospital, 8.36 mi (straight line)	GIS
Nearest fire station	Clayton County Station 10 — 0.19 mi	OFFICIAL
Nearest international airport	Hartsfield-Jackson (ATL), 15.9 mi straight line	GIS
Schools	Clayton County Public Schools: Rivers Edge Elem. 1.17 mi · Lovejoy Middle 2.50 mi · Mundy's Mill HS 5.28 mi. Zones unconfirmed	GIS
Climate	Mean 17.2 °C ; Jul max 31.0 °C ; Jan min 2.4 °C ; 1,196 mm/yr ; 265 frost-free days; zone 8a	REANALYSIS
County	Clayton County (FIPS 13063) — not Henry County	OFFICIAL
Parcel / owner / zoning	05050A A003 · MCKNIGHT DESMOND (deed 2021) · RS180 · appraised \$60,000	OFFICIAL
Asking price	\$125,000 (108% above county appraisal)	OFFICIAL
Estimated all-in build cost (3,200 sq ft, 4 bed)	□ \$798,000 – \$1,385,000 — planning-level; likely above local resale value	ESTIMATE

61 · Visual deliverables — delivered vs not

Requested visual	Status	Note
True-scale boundary + contour map	DELIVERED — Figure 1	5 ft contours, 1:1 scale, north arrow, scale bar, dimensions, corner coordinates, drainage
Road-to-lake elevation cross-section	DELIVERED — Figure 2	Exaggerated and true 1:1, side by side, as specified
3D terrain map	DELIVERED — Figure 3	Lidar surface with boundary and reservoir
Building-envelope diagram	NOT DELIVERED	Cannot be drawn honestly: RS180 setbacks are unverified and any platted easements are unknown. Drawing an envelope from guessed setbacks would be the most misleading thing in this report. Produce it once the zoning letter and plat are in hand.
Official plat map	NOT OBTAINED	Clerk of Superior Court — see item 58, Tier 1
Esri / GIS parcel map	DATA obtained	Parcel geometry and attributes queried live and used throughout; county's own cartographic output not reproduced
FEMA flood map panel	DATA obtained , image not reproduced	Zone X determination queried from the National Flood Hazard Layer; view the panel at msc.fema.gov
Zillow hero / surrounding-area images	DELIBERATELY OMITTED	Copyrighted listing photography — not licensed for redistribution. Links provided in item 2.
Lake / bathymetric map	NOT AVAILABLE	No public bathymetry for J.W. Smith Reservoir
Location / access map	NOT DELIVERED	Distances tabulated instead (items 49–55); base-map tiles carry licence terms

Methodology

All geometry was computed in **UTM Zone 16N / NAD83 (EPSG:26916)** to avoid the area and distance distortion that arises from measuring in degrees. The parcel polygon was taken from the Clayton County Tax Assessor ArcGIS service and reprojected; area, side lengths and bearings were computed from that polygon. Elevations were sampled from the **USGS 3DEP** elevation service on a grid **aligned to the lot's long axis** (10 ft spacing, 3,149 points, 583 inside the boundary), with an independent 1 m centreline transect for the profile. Contours, slope statistics, drainage direction and the water plane were derived from that grid. The reservoir surface was identified as the modal flat elevation (244.17 m / 801.1 ft, 362 concordant samples). Climate was computed from a 30-year daily ERA5 record for the coordinate. Soil came from USDA-NRCS Soil Data Access by polygon intersection. Distances to amenities are straight-line (haversine) from the parcel centroid using OpenStreetMap coordinates.

Cross-validation performed

- GIS-computed area **1.3313 ac** vs listing **1.33 ac** — agree to 0.1%
- Lidar average slope **18.3%** vs USDA-NRCS representative slope **18%** for the mapped soil unit — two unrelated datasets agree
- USGS point-query elevation **895.9 ft** vs 3DEP grid **896.0 ft** at the same location — agree to 0.1 ft
- County "#23" address suffix vs assessor **LOT 23** — confirmed
- Fire-station proximity from OpenStreetMap (0.19 mi) vs county parcel record (652 ft) — agree

Sources

Source	Used for
Clayton County Tax Assessor GIS — gis.claytoncountygga.gov/server/rest/services/TaxAssessor/Parcels	Parcel geometry, ID, zoning, lot number, owner, appraised values, adjoining ownership (incl. the CCWA parcel)
FEMA National Flood Hazard Layer — hazards.fema.gov	Flood zone, SFHA status, BFE, DFIRM/panel
USGS 3DEP Elevation Service & EPQS — elevation.nationalmap.gov , epqs.nationalmap.gov	All elevation, contour, slope and cross-section data
USDA-NRCS Soil Data Access — sdmdataaccess.sc.egov.usda.gov	Soil map unit, series, horizons, texture, pH, Ksat, shrink-swell, depth to bedrock
U.S. Census Bureau Geocoder	County/tract/block determination (the Clayton County finding)
Clayton County Board of Commissioners Resolutions 2026-153 and 2026-120 ; Community & Economic Development	STR moratorium and residential development moratorium
Clayton County Water Authority — ccwa.us ; CCWA Permit Guidelines & Schedule 2025-26	Reservoir identity, permit pricing, hours, seasonal closure, swimming prohibition
Waterpointe Community Association — waterpointehoa.com	HOA existence, amenities, covenants, four phases, ~250-acre lake, Clayton County location
ECMWF ERA5 reanalysis via Open-Meteo archive	30-year climate normals in °C
OpenStreetMap contributors (ODbL)	Amenity, school, hospital, temple and fire-station locations
Public listing and MLS aggregation (Redfin, realtor.com, georgiamls, subdivision aggregators)	Asking price, listing history, subdivision sales statistics, HOA fee range (low confidence)

Scope and limitations — please read

This report is a **desk study built from public data**. No one has visited the site. It is **not** a survey, a geotechnical report, a soil evaluation, a title opinion, an appraisal, or legal, engineering or investment advice, and it must not be relied upon as any of those.

Boundaries, contours, slopes and distances marked **GIS-DERIVED** are **estimates** computed from public datasets and will differ from a field survey. County parcel fabric is a tax-mapping product and routinely departs from recorded boundaries by several feet. Items marked **UNVERIFIED** were not established — treat them as open questions, not as negative findings. Regulatory items (zoning, moratoriums, septic rules, CCWA policy) change; all were researched on the date shown and must be re-confirmed with the issuing authority before you act.

Before purchasing, engage a Georgia-licensed **land surveyor**, a **geotechnical engineer**, the **Clayton County Board of Health** for the soil evaluation, a **real estate attorney** for title and covenants, and obtain written determinations from **Clayton County Community Development** and the **Clayton County Water Authority**.