
Two lakefront lots on Richland-Chambers Reservoir, Texas

Long-term land hold and future 5-bedroom lake home · Navarro County · summary of both lots · 8 Nov 2026

$190k combined asking | **1.15 ac** combined | **272 ft** lake frontage



7.2 / 10 — A · 11 Bayview Cir

Corsicana, TX 75109 · 0.65 ac · 158 ft lake frontage · $89,900 asking · CAD $88,808

Better hold of the two. Priced at its appraisal, with public water and HOA sewer, in a gated upscale enclave with a bulkheaded, protected cove. Watch: $3,530/yr HOA dues while you hold; narrow, shallow cove; costly 2,500 sf / 60% masonry minimum; long time on the market.

6.3 / 10 — B · 5001 Arrowhead Pt

Streetman, TX 75859 · 0.50 ac · 115 ft lake frontage · $99,900 asking · CAD $68,849

Cheap to hold ($144–644/yr POA, ≈$1.2k tax) and easy to build on, but the asking price is 45% over the appraisal, it needs an aerobic septic + drip field, the cove is shallow, POA rules are strict (no poultry) and it is rural (99 min to Dallas). Negotiate toward the $70–80k range.

Bottom line

- Both lots can take a 5-bedroom house and garage; neither needs fill for flooding. The house pads sit 4–6 ft above a conservative floor level (Zone-A edge + 2 ft).
- Both sit on expansive Crockett/Axtell clay. Budget an engineered foundation and a geotechnical report.
- Both coves are only 7–10 ft deep at full pool and would be nearly dry in a 2006-type drought (lake 11 ft low).
- Neither lot shows sinkhole, karst or wildfire concern; tornado and wind are the main hazards.

Key measurements	A · 11 Bayview Cir (White Rock)	B · 5001 Arrowhead Pt (Rustling Oaks)
Price & value		
Asking price	$89,900 ($138,308/ac) · MLS 21146775	$99,900 ($199,800/ac) · MLS 21298338
CAD 2026 value	$88,808 · asking +1%	$68,849 · asking +45%
Property tax / yr	$1,397	$1,178 (now $972, capped)
5-BR build (est.)	≈$1.03–1.31M (custom, 3,600 sf)	≈$0.68–0.89M (3,000 sf)
Land & terrain		
Lot size	0.65 ac legal · 27,722 sf GIS	0.50 ac legal · 23,577 sf GIS
Lot dimensions	road 190 · lake 158 · sides 298/247 ft (wedge)	road 131 · lake 115 · sides 255/181 ft
Lowest / highest	313.0 / 333.6 ft	319.5 / 330.2 ft
Elevation difference	20.6 ft	10.6 ft
Average slope	8.5% (house area 5.6%)	6.6% (house area 5.3%)
Max slope (50 ft)	26% / 14.5° at the bank	18% / 10.0° at the bank
Soil	Crockett: sandy loam over high-shrink clay	Axtell: sandy loam over high-shrink clay
Flood		
FEMA zone	X + Zone A on 13% (shore) · 48349C0450D	X + Zone A on 2% (shore) · 48349C0600D
BFE	none published (Zone A); TRWD 100-yr 318 ft	none published (Zone A); TRWD 100-yr 318 ft
Min finished floor	≥324.4 ft (est.) · pad ≈329 ft	≥322.6 ft (est.) · pad ≈328 ft
Fill required?	**No**	**No**
Utilities		
Water / sewer	M.E.N. WSC / White Rock HOA sewer plant	Winkler WSC / **none**
Septic required?	**No**	**Yes** — aerobic + drip; 5–6 BR fit
Electric / gas / internet	NCEC co-op / propane / 5G, fixed wireless, Starlink	NCEC co-op / propane / 5G, fixed wireless, Starlink
Rules		
HOA & fee	White Rock HOA (gated) · **$3,530/yr** incl. sewer (listing)	Rustling Oaks POA · $144/yr handbook, $644/yr MLS CONFIRM
Min house / zoning	2,500 sf, 60% stone & glass · likely SF-3	1,600 sf · likely SF-3
In-law suite	≤40% of main house (county) + HOA	≤40% of main house (county) + ACC
Hobby farming	**No** poultry/livestock (needs ≥3 ac)	**No** — POA bans fowl & livestock
Short-term rental	unclear — confirm county & HOA	unclear — confirm county & POA
Lake		
Dock possible?	**Yes**, TRWD ≤1,230 sf · bulkhead exists	**Yes**, TRWD ≤918 sf · steel wall exists
Lake depth off lot	8 ft mean / 10 ft max at full pool	7 ft mean / 8.5 ft max at full pool
Boating / fishing	all craft · marina 0.2 mi · catfish, hybrids, bass, crappie	all craft · POA ramp & pier · same fishery
Main house, garage, pool, garden	fit (envelope 12,800 sf); raised-bed garden	fit (envelope 14,300 sf); raised-bed garden
Access		
Nearest hospital	Navarro Regional 20 mi · 32 min	Freestone Medical 23 mi · 36 min
Intl. airport	DFW 92 mi · 111 min	DFW 103 mi · 126 min
Dallas / schools	72 mi · 84 min · Mildred ISD (B)	82 mi · 99 min · Fairfield ISD (C)


Before you buy

1. **A:** get the White Rock CC&Rs and HOA budget; confirm what the $3,530/yr dues cover. **B:** confirm the POA fee ($144 or $644/yr).
2. **Both:** boundary + topographic survey showing the 315/318/320 ft lines; Elevation Certificate.
3. **Both:** Navarro County zoning district and floodplain freeboard in writing.
4. **B:** OSSF site evaluation by a sanitarian/engineer (TRWD permit) before closing.
5. **Both:** water, electric and (A) sewer will-serve letters; geotechnical report; TRWD permit history for the existing bulkheads.

A · 11 Bayview Cir, Corsicana, TX 75109

White Rock Sub. (W0305) Lot 11 · Navarro County · gated community off US-287

$89,900	0.65 ac	158 ft	313–334	7.2
asking	27,722 sf GIS	lake frontage	ground ft msl	/10 hold




Listing photo: lot 11 and the main lake · LakeHouse.com / RE/MAX



Lot outline on Esri imagery (Nov 2025)



Fly-around view from the east (lidar 3-D)



Texas location · 63 mi SE of Dallas

Evidence: OFFICIAL recorded source · GIS computed from lidar/GIS, not a survey · ESTIMATE this report's estimate · CONFIRM needs surveyor/engineer/county/HOA. Elevations: ft NAVD88 (≈ msl).

1 · Identification, listing & value

Address	11 Bayview Cir, Corsicana, TX 75109 OFFICIAL
Legal	W0305 WHITE ROCK SUB LOT 11 .65 ACRES OFFICIAL
CAD parcel	ID 63254 · Geo W0305-00-00110-000-00-0
Owner / deed	Jason Hamad (Dallas) · warranty deed 15 Jul 2022, Vol 2022 p 7656
Lot size	**0.65 ac** legal (28,314 sf) · GIS 0.636 ac (27,722 sf) GIS
Dimensions	road 190 ft · lake 158 ft · sides 298 / 247 ft GIS
Asking	**$89,900** · $138,308/ac · $570/lake-ft *MLS 21146775 · RE/MAX LakeSide Dreams (Teel) · LakeHouse.com ad 7100373, Nov 2026*
CAD 2026	**$88,808** (land $85,197 + steel retaining wall (bulkhead) $3,611) OFFICIAL
Value history	2022: $57k → 2023: $81k → 2024: $86k → 2025: $91k → 2026: $89k
Property tax	1.5730% → **$1,397/yr** on full value
Listing history	on portals since ≥Dec 2022; current listing since 8 Jan 2026 (304 days): long time on market
Links	LakeHouse · Zillow · Realtor.com · Redfin

2 · Plat, GIS boundary & corners

lat, lon (NAD83)

Recorded plat is not online (Navarro County Clerk) CONFIRM. Boundary = Navarro CAD GIS parcel (TxGIO StratMap 2026) GIS; GIS area is -2% vs the legal acreage. Listing's "~158 ft platted water frontage" matches GIS 158 ft. Neighbours: Lot 12 .53 Acres, Lot 9-R 1.28 Acres.

P1 32.000454, -96.216493	P2 31.999641, -96.216383
P3 31.999697, -96.216471	P4 31.999778, -96.216535
P5 31.999986, -96.216642	P6 31.999998, -96.216653
P7 32.000630, -96.216942	P8 32.000720, -96.216824
P9 32.000550, -96.216621	

3 · Terrain, slope & grading

Ground	low **313.0** · high **333.6** · mean 327.1 ft (NAVD88 ≈ msl) GIS
Relief	20.6 ft · 89% of the lot is above the 320 ft TRWD line
vs lake	house pad ≈329 ft = 14 ft above full pool, 17 ft above today's lake
Average slope	8.5% (4.8°) whole lot · 5.6% in the building area
Max 50-ft run	**26% (14.5°)** anywhere (lake bank) · 12.5% in building area
Road → lake	340 ft to the 315 ft shoreline · fall 18.2 ft · direct angle **3.1°** (5.4%)
At the lake	last 20 ft rise 7.4° (13%) · steepest 10 ft 21° (bulkhead/bank)
Drainage	sheet flow to the SSW into the cove; no channel crosses the lot
Class	**Moderate slope** overall; gentle-to-moderate where the house goes
Grading	Significant: cut-and-fill pad, stem wall or stepped slab · 60×46 ft pad: ground 327.4–330.1 ft, ≈32 cy cut / 48 cy fill (balanced) ESTIMATE

4 · Lake, dock, boating & fishing

Frontage	direct, 158 ft on a cove ≈100 ft wide GIS · existing steel bulkhead with step-down walk (listing, CAD)
Dock	TRWD permit ($300): max **1,230 sf** (8 sf/ft of shoreline); ≥5 ft from side lines (20 ft if >1,200 sf); ≤2 storeys; no toilets or living space; lower deck ≥18 in above the 320 ft flowage line OFFICIAL
Depth	8 ft mean / 10 ft max at full pool within 300 ft (TWDB 2018) OFFICIAL · ≈5 ft today · the 2006 low (303.6 ft) would leave the cove dry
Lake level	since 2000: mean 312.9 ft; below 312 ft 27% of days; high May–Jun, low Nov–Dec · now 312.17 ft (89% full)
Boating	all craft incl. ski/wake boats; 200 ft safe distance for towed sports (TRWD 2026) · Oak Cove Marina 0.2 mi
Fishing	blue catfish (excellent), hybrid striped & white bass, largemouth, crappie; hybrids stocked 10–14/ac/yr (TPWD) · licence required · bag: catfish 25, white bass 25 (10 in), hybrid 5 (18 in), bass 5 (14 in), crappie 25 (10 in) · fishing from own dock/shore allowed

5 · Flood zone, BFE & finished floor

FEMA zone	**Zone X** (minimal) on 87% · **Zone A** (1%/yr, no BFE) on 13% along the shore OFFICIAL
FIRM panel	48349C0450D, effective 5 Jun 2012 · no LOMR/LOMA on file OFFICIAL
BFE	none published for Zone A OFFICIAL · TRWD 100-yr lake level 318.0 ft; flowage easement to 320.0 ft OFFICIAL
Zone A edge	lies on ground 320.6–324.6 ft (median 322.4) GIS
Min floor	322.4 ft (proxy BFE) + 2 ft freeboard = **324.4 ft** ESTIMATE · county freeboard rule not published CONFIRM
Verdict	**Terrain adequate**: pad ≈329 ft is 4.6 ft above that → no fill, no elevated house; slab, pier-and-beam or crawlspace all allowed outside Zone A. No work below 320 ft without a TRWD permit.
First Street	not retrieved (site blocks automated access) CONFIRM
Elev. cert.	none on file CONFIRM

6 · Soil & foundation (USDA NRCS SSURGO)

Map units	CtC2 Crockett soils, 2 to 5 percent slopes, eroded (94%); CrB Crockett fine sandy loam, 1 to 3 percent slopes (6%) OFFICIAL
Profile	8 in sandy loam (pH 6.5, OM 1.25%) over **46% clay** to 72+ in; dense clay-loam 'bedrock' at 53 in
Shrink-swell	**high** (LEP 9.0% in the clay) · permeability very slow (Ksat 0.91 µm/s) · moderately well drained · HSG C · no water table < 6.5 ft
NRCS ratings	dwellings **very limited** (shrink-swell) · septic fields very limited · shallow excavation somewhat limited · steel corrosion high
Foundation	engineered post-tensioned slab, or pier-and-beam on drilled piers below the active clay zone; no basement; stepped slab/stem wall where the pad falls >2 ft · **geotechnical report required** CONFIRM

7 · Sewer, septic & water quality

Sewer	**available**: White Rock HOA's private sanitary plant (HOA-owned Lot C, 'Sanitary Plant & Reserve Area', 0.58 ac) OFFICIAL; included in HOA dues (listing) · no septic needed · tap fee CONFIRM
If no sewer	TRWD zone allows only an aerobic unit + subsurface drip (spray banned); drip area ≈11,312 sf vs 3,600 sf needed for 5 BR (360 gpd ÷ 0.10 gal/sf/day, clay) → soil/area would allow **5–6 BR** ESTIMATE
Water well	only if public water failed: USGS-logged wells nearby are 16–342 ft deep (Wilcox Group). Shallow wells (<100 ft) are surface-influenced and often iron-rich; **target ≈250–350 ft**, sealed casing, ≥100 ft from a drip field; test for bacteria, iron, TDS ESTIMATE

8 · Utilities

Water	M.E.N. WSC (TX1750015) service area OFFICIAL · listing: utilities in place
Sewer	White Rock HOA plant (see 7)
Electric	Navarro County Electric Co-op (903-874-7411; Oncor overlaps) OFFICIAL · service at the street per listing CONFIRM
Gas	no natural-gas main found → propane (W & J Propane yard 0.2 mi away on CR 3190)
Internet	5G/fixed wireless (AT&T Internet Air, T-Mobile, Nextlink), Starlink (≤~400 Mbps), HughesNet; cable/fiber (Vyve, Vero, Rise) mainly inside Corsicana CONFIRM

9 · HOA, zoning, in-law suite, animals, STR

HOA	White Rock Homeowners Assoc. Inc. — gated; owns common area Lot A (1.2 ac) and the sewer plant OFFICIAL. Dues **$3,530/yr**, private sewer included (MLS listing) CONFIRM; transfer fee and special assessments not published
Restrictions	site-built only, ≥2,500 sf heated & cooled, ≥60% stone & glass exterior (listing) · full CC&Rs not online CONFIRM
Zoning	Navarro Co. Richland-Chambers Lakeshore Zoning (≤5,000 ft from shore) OFFICIAL; district map not online — likely **SF-3**: front 35 / rear 15 / side 10 ft, ≤40% coverage, ≤2½ storeys CONFIRM · permit $0.25/sf + 3 third-party inspections
In-law suite	county allows an accessory dwelling ≤40% of the main house's floor area (no plumbing until the house is occupied); a duplex is not allowed in SF districts · HOA approval
Animals	county: ≤4 dogs/cats; poultry/livestock count as 'farm or ranch' use (≥3 ac) → not on this lot
STR	county lists only owner-occupied B&B (1 room; 2–4 by SUP); whole-house rentals not addressed CONFIRM; 6% state hotel tax for stays <30 days

10 · Location & living

Schools	Mildred ISD (TEA **B** 2026): Mildred Elementary 10 mi · 16 min
Hospital	Navarro Regional (ER) 20 mi · 32 min · Level-I trauma Baylor Dallas 72 mi · 86 min · urgent care 19 mi · 30 min
Shopping	store & gas at the gate 0.1 mi · H-E-B 17 mi · 27 min · Walmart 20 mi · 32 min · Home Depot 15 mi · 24 min
Indian	Food Belly (Indian), Corsicana ~27 min · Patel Bros / India Bazaar Irving 84 mi · 98 min · DFW Hindu Temple 84 mi · 99 min · Islamic Center of Waco 72 mi · 88 min
Airport	DFW 92 mi · 111 min (AA hub, 200+ nonstops) · Love Field 78 mi · 96 min
Getting out	Corsicana 18 mi · 27 min · Dallas 72 mi · 84 min · car needed (store, gas, grill ≤0.2 mi)
People	Navarro Co. 57,181 (2025, +8.6% since 2020); income $63,111 (TX $78,476); tract median age 55, 30% 65+; Asian Indian 74 in county (0.1%) OFFICIAL
Climate	mean 19.7 °C · Jul–Aug highs 34.5 °C · Jan lows 4.5 °C · extremes 42.6/-14.5 °C · 1,036 mm · RH 69% · 39 days ≥35 °C
Hazards	FEMA NRI: tornado & wind relatively high; hail, lightning, ice, heat moderate; flood, drought, wildfire low · no karst/sinkholes · EPA radon zone 3 CONFIRM

11 · Cost to build a 5-bedroom home

5 BR, ≈3,600 sf heated + 3-car garage, ≥60% stone/glass: **$260–320/sf** → house $0.94–1.15M; foundation engineering & pad $45–80k; taps & HOA review $10–25k; design, survey, geotech, permits $35–55k → **≈$1.03–1.31M** ESTIMATE (+ boathouse $60–150k). Benchmark: 218 White Rock Rd (3,929 sf, built 2022) CAD improvements $1.16M ≈ $295/sf. Built White Rock homes: CAD $640k–$1.53M (median $1.18M) → **in line**.

2026 Texas guides: $180–280/sf builder-grade, $280–400+/sf custom (homeguide.com). Get two bids.

12 · Holding-investment score 7.2/10

Price vs appraisal **1.3**/1.5 · Value trend **0.9**/1.0 · Water frontage & use **1.0**/1.5 · Buildability **1.1**/1.5 · Utilities **1.0**/1.0 · HOA / holding cost **0.4**/1.0 · Location & access **0.7**/1.0 · Liquidity / exit **0.5**/1.0 · Risk **0.3**/0.5

Reasons for each point: page 6.

A · 11 Bayview Cir — maps, terrain & views

Pictures ≥3.8 in wide · true-north arrows · scale bars in feet · imagery © Esri, Maxar, Earthstar

3.1°	14.5°	7.4°
road-to-lake angle	max over 50 ft	rise at lake edge




Fly-around 1 — from the cove; lidar 3-D at true vertical scale (replaces realtor.com Fly Around)




Fly-around 2 — from the road side, looking toward the lake




True-scale plan (A→A′ = road→lake): 1-ft lidar contours, CAD lot lines, corners, high/low points



3-D terrain model, vertical ×3 (fly-arounds above are true 1:1): lot line, 5-BR massing, fall to lake




Section A–A′, road→lake: left TRUE 1:1 (whole section + lakeside 90 ft, real angles); right exaggerated. Length 340 ft, height 18.2 ft, direct angle 3.1°, max over 50 ft 14.5° on the lot



Building envelope: SF-3 setbacks + ground ≥322 ft; 5-BR footprint placed for least grading



FEMA flood map (NFHL): Zone A strip on the shore, rest Zone X



Lake-bottom contours (TWDB Dec-2018 survey), depth below the 315 ft full pool



Listing drone photo — lot lines drawn by the broker (approximate) · LakeHouse.com / RE/MAX

B · 5001 Arrowhead Pt, Streetman, TX 75859

Rustling Oaks Estates Ph II (R1550.02) Blk 1 Lot 33 · Navarro County · south shore

$99,900	0.50 ac	115 ft	320–330	6.3
asking	23,577 sf GIS	lake frontage	ground ft msl	/10 hold



Listing photo: the cove from the lot · LakeHouse.com / NTREIS



Lot outline on Esri imagery (May 2025)



Fly-around view from the south (lidar 3-D)



Texas location · 65 mi SE of Dallas

Evidence: OFFICIAL recorded source · GIS computed from lidar/GIS, not a survey · ESTIMATE this report's estimate · CONFIRM needs surveyor/engineer/county/HOA. Elevations: ft NAVD88 (≈ msl).

1 · Identification, listing & value

Address	5001 Arrowhead Pt, Streetman, TX 75859 OFFICIAL
Legal	R1550.02 RUSTLING OAKS ESTATES PHASE II BLK 1 LOT 33 .5 ACRES OFFICIAL
CAD parcel	ID 56587 · Geo R1550-02-00010-033-00-0
Owner / deed	Danny & Leanna Pitts (own the adjoining home, 5003) · deed 10 Apr 2015, Vol 2015 p 2509
Lot size	**0.50 ac** legal (21,780 sf) · GIS 0.541 ac (23,577 sf) GIS
Dimensions	road 131 ft · lake 115 ft · sides 255 / 181 ft GIS
Asking	**$99,900** · $199,800/ac · $870/lake-ft *MLS 21298338 · Laura Smith, Keller Williams · LakeHouse.com ad 7885360, Nov 2026*
CAD 2026	**$68,849** (land $65,340 + steel retaining wall $3,509) OFFICIAL
Value history	2022: $44k → 2023: $48k → 2024: $48k → 2025: $47k → 2026: $69k
Property tax	1.7117% → **$1,178/yr** on full value (now $972: 20% circuit-breaker cap, resets on sale)
Listing history	active since 15 Jun 2026 (145 days): 100+ ft lake frontage on a private cul-de-sac
Links	LakeHouse · Realtor.com · Zillow search · HAR

2 · Plat, GIS boundary & corners

lat, lon (NAD83)

Recorded plat is not online (Navarro County Clerk) CONFIRM. Boundary = Navarro CAD GIS parcel (TxGIO StratMap 2026) GIS; GIS area is +8% vs the legal acreage. Listing's "100+ ft frontage" matches GIS 115 ft. Neighbours: Blk 1 Lot 32 .5 Acres, Blk 1 Lot 34 .5 Acres.

P1 31.951876, -96.272943	P2 31.951758, -96.272996
P3 31.951720, -96.273137	P4 31.951662, -96.273165
P5 31.952127, -96.273782	P6 31.952141, -96.273730
P7 31.952187, -96.273479	P8 31.952214, -96.273374

3 · Terrain, slope & grading

Ground	low **319.5** · high **330.2** · mean 327.4 ft (NAVD88 ≈ msl) GIS
Relief	10.6 ft · 100% of the lot is above the 320 ft TRWD line
vs lake	house pad ≈328 ft = 13 ft above full pool, 16 ft above today's lake
Average slope	6.6% (3.8°) whole lot · 5.3% in the building area
Max 50-ft run	**18% (10.0°)** anywhere (lake bank) · 10.9% in building area
Road → lake	283 ft to the 315 ft shoreline · fall 14.2 ft · direct angle **4.0°** (7.1%)
At the lake	last 20 ft rise 17.5° (32%) · steepest 10 ft 22° (bulkhead/bank)
Drainage	sheet flow to the E into the cove; no channel crosses the lot
Class	**Moderate slope** overall; gentle-to-moderate where the house goes
Grading	Significant: cut-and-fill pad, stem wall or stepped slab · 60×46 ft pad: ground 327.3–329.4 ft, ≈32 cy cut / 35 cy fill (balanced) ESTIMATE

4 · Lake, dock, boating & fishing

Frontage	direct, 115 ft on a cove ≈170 ft wide GIS · existing steel retaining wall (CAD)
Dock	TRWD permit ($300): max **918 sf** (8 sf/ft of shoreline); ≥5 ft from side lines (20 ft if >1,200 sf); ≤2 storeys; no toilets or living space; lower deck ≥18 in above the 320 ft flowage line OFFICIAL
Depth	7 ft mean / 8 ft max at full pool within 150 ft (TWDB 2018) OFFICIAL · ≈4 ft today · the 2006 low (303.6 ft) would leave the cove dry
Lake level	since 2000: mean 312.9 ft; below 312 ft 27% of days; high May–Jun, low Nov–Dec · now 312.17 ft (89% full)
Boating	all craft incl. ski/wake boats; 200 ft safe distance for towed sports (TRWD 2026) · POA ramp & pier in the subdivision
Fishing	blue catfish (excellent), hybrid striped & white bass, largemouth, crappie; hybrids stocked 10–14/ac/yr (TPWD) · licence required · bag: catfish 25, white bass 25 (10 in), hybrid 5 (18 in), bass 5 (14 in), crappie 25 (10 in) · fishing from own dock/shore allowed

5 · Flood zone, BFE & finished floor

FEMA zone	**Zone X** (minimal) on 98% · **Zone A** (1%/yr, no BFE) on 2% along the shore OFFICIAL
FIRM panel	48349C0600D, effective 5 Jun 2012 · no LOMR/LOMA on file OFFICIAL
BFE	none published for Zone A OFFICIAL · TRWD 100-yr lake level 318.0 ft; flowage easement to 320.0 ft OFFICIAL
Zone A edge	lies on ground 319.7–322.5 ft (median 320.6) GIS
Min floor	320.6 ft (proxy BFE) + 2 ft freeboard = **322.6 ft** ESTIMATE · county freeboard rule not published CONFIRM
Verdict	**Terrain adequate**: pad ≈328 ft is 5.8 ft above that → no fill, no elevated house; slab, pier-and-beam or crawlspace all allowed outside Zone A. No work below 320 ft without a TRWD permit.
First Street	not retrieved (site blocks automated access) CONFIRM
Elev. cert.	none on file CONFIRM

6 · Soil & foundation (USDA NRCS SSURGO)

Map units	AxE Axtell fine sandy loam, 5 to 12 percent slopes (100%) OFFICIAL
Profile	4 in sandy loam (pH 5.8, OM 0.75%) over **45% clay** to 80+ in
Shrink-swell	**high** (LEP 7.5% in the clay) · permeability very slow (Ksat 0.91 µm/s) · moderately well drained · HSG C · no water table < 6.5 ft
NRCS ratings	dwellings **very limited** (shrink-swell) · septic fields very limited · shallow excavation somewhat limited · steel corrosion high
Foundation	engineered post-tensioned slab, or pier-and-beam on drilled piers below the active clay zone; no basement; stepped slab/stem wall where the pad falls >2 ft · **geotechnical report required** CONFIRM

7 · Sewer, septic & water quality

Sewer	**none**: septic (OSSF) required (subdivision listings) OFFICIAL
System	clay = TCEQ Class IV → no trenches; **aerobic unit + subsurface drip** (TRWD bans spray near the lake); RS/PE design, TRWD permit $400, quarterly maintenance OFFICIAL · TRWD's 1-ac minimum applies only to post-2011 plats
Bedrooms	drip field ≥50 ft from the pool, ≥5 ft from lines/house: ≈11,928 sf vs **3,600 sf for 5 BR** (360 gpd), 4,200 sf for 6 BR → **5–6 BR fit** ESTIMATE · site evaluation CONFIRM
Water well	only if public water failed: USGS-logged wells nearby are 16–342 ft deep (Wilcox Group). Shallow wells (<100 ft) are surface-influenced and often iron-rich; **target ≈250–350 ft**, sealed casing, ≥100 ft from a drip field; test for bacteria, iron, TDS ESTIMATE

8 · Utilities

Water	Winkler WSC (TX1750023) service area OFFICIAL · tap fee CONFIRM
Sewer	none — septic (see 7)
Electric	Navarro County Electric Co-op OFFICIAL · neighbours served; short extension CONFIRM
Gas	no natural-gas main → propane
Internet	5G/fixed wireless (AT&T Internet Air, T-Mobile, Nextlink), Starlink, HughesNet; Windstream Kinetic in parts of Streetman CONFIRM

9 · HOA, zoning, in-law suite, animals, STR

POA	Rustling Oaks Estates POA, mandatory: **$12/month** ($144/yr) in the POA handbook OFFICIAL; the MLS flyer says **$644/yr** CONFIRM · ACC approves all building; $500 road fee + $0.85/sf of slab; pool $1,000; boathouse $750 · amenities: entrance, boat ramp, dock & pier, picnic area
Rules	≥1,600 sf heated on waterfront; RVs temporary only; shed ≤12×16 ft, no metal buildings; no screening fences; no firearms; no 'for sale' signs on vacant lots
Zoning	Navarro Co. Richland-Chambers Lakeshore Zoning (≤5,000 ft from shore) OFFICIAL; district map not online — likely **SF-3**: front 35 / rear 15 / side 10 ft, ≤40% coverage, ≤2½ storeys CONFIRM · permit $0.25/sf + 3 third-party inspections
In-law suite	county allows an accessory dwelling ≤40% of the main house's floor area (no plumbing until the house is occupied); a duplex is not allowed in SF districts · ACC: outbuildings only after the house slab
Animals	county: ≤4 dogs/cats; poultry/livestock count as 'farm or ranch' use (≥3 ac) · POA bans fowl, goats, hogs, sheep, horses, cattle
STR	county lists only owner-occupied B&B (1 room; 2–4 by SUP); whole-house rentals not addressed CONFIRM; 6% state hotel tax for stays <30 days

10 · Location & living

Schools	Fairfield ISD (TEA **C** 2026): elementary 23 mi · 37 min, high school 25 mi · 40 min
Hospital	Freestone Medical Center (ER) 23 mi · 36 min · Navarro Regional 30 mi · 47 min · Baylor Dallas 83 mi · 101 min
Shopping	Winkler store/gas/cafe 5.8 mi · 15 min · bank 7.4 mi · 18 min · H-E-B 27 mi · 42 min · Walmart 28 mi · 46 min
Indian	Food Belly (Indian), Corsicana ~42 min · Patel Bros Irving 95 mi · 113 min · DFW Hindu Temple 94 mi · 114 min · Islamic Center of Waco 81 mi · 103 min
Airport	DFW 103 mi · 126 min (AA hub, 200+ nonstops) · Love Field 88 mi · 111 min
Getting out	Corsicana 28 mi · 42 min · Dallas 82 mi · 99 min · car needed (store 5.8 mi)
People	Navarro Co. 57,181 (2025, +8.6% since 2020); income $63,111 (TX $78,476); tract median age 55, 30% 65+; Asian Indian 74 in county (0.1%) OFFICIAL
Climate	mean 19.9 °C · Jul–Aug highs 34.6 °C · Jan lows 4.6 °C · extremes 42.3/-13.3 °C · 1,044 mm · RH 69% · 41 days ≥35 °C
Hazards	FEMA NRI: tornado & wind relatively high; hail, lightning, ice, heat moderate; flood, drought, wildfire low · no karst/sinkholes · EPA radon zone 3 CONFIRM

11 · Cost to build a 5-bedroom home

5 BR, ≈3,000 sf heated + 2-car garage, brick/stone/fiber-cement: **$200–250/sf** → $0.60–0.75M; aerobic septic + drip $18–30k; pad & foundation $25–45k; water/electric $8–20k; POA fees ≈$4k; design, survey, geotech, permits $25–40k → **≈$0.68–0.89M** ESTIMATE (+ boathouse $50–120k). Built Rustling Oaks homes: CAD $198k–$965k (median $488k) → **a 5-BR would top the street**; a 4-BR ≈2,600 sf fits the market better.

2026 Texas guides: $180–280/sf builder-grade, $280–400+/sf custom (homeguide.com). Get two bids.

12 · Holding-investment score 6.3/10

Price vs appraisal **0.7**/1.5 · Value trend **0.7**/1.0 · Water frontage & use **0.9**/1.5 · Buildability **1.2**/1.5 · Utilities **0.6**/1.0 · HOA / holding cost **0.7**/1.0 · Location & access **0.5**/1.0 · Liquidity / exit **0.6**/1.0 · Risk **0.4**/0.5

Reasons for each point: page 6.

B · 5001 Arrowhead Pt — maps, terrain & views

Pictures ≥3.8 in wide · true-north arrows · scale bars in feet · imagery © Esri, Maxar, Earthstar

4.0°	10.0°	17.5°
road-to-lake angle	max over 50 ft	rise at lake edge




Fly-around 1 — from the cove; lidar 3-D at true vertical scale (replaces realtor.com Fly Around)




Fly-around 2 — from the road side, looking toward the lake




True-scale plan (A→A′ = road→lake): 1-ft lidar contours, CAD lot lines, corners, high/low points




3-D terrain model, vertical ×3 (fly-arounds above are true 1:1): lot line, 5-BR massing, fall to lake




Section A–A′, road→lake: left TRUE 1:1 (whole section + lakeside 90 ft, real angles); right exaggerated. Length 283 ft, height 14.2 ft, direct angle 4.0°, max over 50 ft 10.0° on the lot



Building envelope: SF-3 setbacks + ground ≥322 ft; 5-BR footprint placed for least grading; dots = drip field



FEMA flood map (NFHL): Zone A strip on the shore, rest Zone X



Lake-bottom contours (TWDB Dec-2018 survey), depth below the 315 ft full pool



Listing drone photo — lot lines (estimated by the broker), cove and main lake · LakeHouse.com / NTREIS

Construction feasibility · gardening · documents · glossary · sources

Shared notes for both lots

Final construction feasibility

	A · 11 Bayview Cir	B · 5001 Arrowhead Pt
Main house (5 BR)	**Yes** — envelope 12,800 sf; 60×46 ft pad on 2.7 ft of fall	**Yes** — envelope 14,300 sf; 60×46 ft pad on 2.1 ft of fall
In-law suite	**Conditional** — ≤40% of house (county) + HOA approval	**Conditional** — ≤40% of house + ACC approval
Garage	**Yes** — attached 3-car within setbacks	**Yes** — attached; detached only after the house slab
Septic system	not needed — HOA sewer	**Yes** — aerobic + drip, 5–6 BR, after site evaluation
Garden	**Conditional** — raised beds over clay	**Conditional** — raised beds; lime per soil test
Hobby farming	**No** — poultry/livestock need ≥3 ac	**No** — POA bans fowl & livestock
Dock	**Yes** — TRWD ≤1,230 sf; narrow cove	**Yes** — TRWD ≤918 sf
Boat access	**Conditional** — 5–7 ft today; dry in a deep drought	**Conditional** — 4–6 ft today; POA ramp & pier
Short-term rental	**Conditional** — not addressed by county; HOA rules unknown	**Conditional** — not addressed; ask POA
Pool / outdoor	**Yes** — room behind the house; TRWD permit below 320 ft	**Conditional** — must share space with the drip field; POA fee $1,000

Holding-investment score — points and reasons

Criterion (max)	A · 7.2/10	B · 6.3/10
Price vs appraisal (1.5)	**1.3** asking $89.9k = CAD $88.8k + 1%	**0.7** asking $99.9k = 45% over CAD $68.8k
Value trend (1.0)	**0.9** CAD value +57% since 2022	**0.7** CAD land +50% in one year (2026)
Water frontage & use (1.5)	**1.0** 158 ft, bulkheaded, protected; cove only 8–10 ft deep	**0.9** 115 ft, steel wall, POA ramp & pier; cove 7–8.5 ft deep
Buildability (1.5)	**1.1** pad 4–5 ft above flood proxy; clay; 12.5% max grade in envelope	**1.2** gentle house area (5%), 99.8% above 320 ft; clay
Utilities (1.0)	**1.0** public water + HOA sewer: no septic	**0.6** public water; aerobic septic + drip required
HOA / holding cost (1.0)	**0.4** dues $3,530/yr (sewer incl.) + $1.4k tax; 2,500 sf minimum	**0.7** POA $144–644/yr, strict ACC rules, no poultry
Location & access (1.0)	**0.7** on US-287: 27 min Corsicana, 84 min Dallas	**0.5** rural: 15 min store, 42 min Corsicana, 99 min Dallas
Liquidity / exit (1.0)	**0.5** marketed on and off since 2022; 304 days on this listing	**0.6** fresh listing; priced above peers' land values
Risk (0.5)	**0.3** 13% in Zone A; cove shallow in droughts; expansive clay	**0.4** 2.5% Zone A; cove shallow in droughts; expansive clay

A holding score rewards a fair price, appreciation, usable frontage, cheap and easy building, low carrying cost and an easy resale. A's $3,530/yr dues cost it 0.3 points; it still ranks first. If B's POA fee is $644, B's score is unchanged.

Gardening & farming (same climate, similar clay)

Category	Suitable plants	Plant	Soil needs
Vegetables	warm: tomato, pepper, okra, southern peas, squash, sweet potato, eggplant · cool: broccoli, cabbage, short-day onion, lettuce, spinach, carrot	warm Mar 15–May & Jul–Aug (fall crop) · cool Sep–Oct & Feb	raised beds 10–12 in, 50:50 topsoil/compost
Fruits	blackberry (thornless), fig, pear, persimmon, pomegranate, low-chill peach, muscadine grape	bare-root Dec–Feb	mounded beds; avoid wet clay pockets
Herbs	rosemary, oregano, thyme, sage, Mexican mint marigold; basil (summer); cilantro, dill, parsley (cool)	Mar–Apr; Oct for cool herbs	well drained, raised
Trees	pecan, cedar elm, bur oak, live oak, Shumard oak, redbud, Mexican plum	Nov–Feb	plant ≥15 ft from the foundation (clay shrink-swell)

Amendments, from SSURGO and to be confirmed by a $15 Texas A&M soil test: compost 2–3 in and mulch on both lots. Lot A topsoil pH 6.5 needs no lime or sulfur. Lot B topsoil pH 5.8 may need light lime. Use balanced or N-only fertilizer as the test directs. The clay subsoil starts at 4–8 in and drains very slowly, so **raised beds are advised**. Growing season ≈297 frost-free days (ERA5; lake-moderated, verify locally); USDA zone 8a.

Documents to obtain before purchase

- **Both:** recorded subdivision plat; boundary + topographic survey with 315/318/320 ft lines; Elevation Certificate; title commitment; geotechnical report; zoning-district & floodplain letter from Navarro County Planning & Development (601 N 13th St, Corsicana; 903-875-3312); TRWD permit history for the existing steel walls; will-serve letters (water co-op, NCEC electric); seller disclosures and listing photos.
- **A (White Rock):** declaration & CC&Rs, architectural guidelines, HOA budget, dues, transfer fee, special assessments, sewer tap fee and plant capacity.
- **B (Rustling Oaks):** full recorded Declaration of CC&Rs (only the ACC handbook is online); OSSF site evaluation & perc/soil test; Winkler WSC tap fee.

Data sources

- Navarro Central Appraisal District records (parcels 63254, 56587 and neighbours) · TxGIO StratMap 2026 parcels
- USGS 3DEP 1 m lidar DEM (TX 2022 North-Central; 2018 Red River check) · USGS NWIS well records
- FEMA National Flood Hazard Layer; FEMA National Risk Index (Dec 2025)
- USDA NRCS SSURGO via Soil Data Access
- TWDB Dec-2018 volumetric survey & Water Data for Texas lake levels · TPWD Richland-Chambers survey report (2022)
- TRWD General Ordinance (Dec 2025) & 2026 Residential Improvement / OSSF guidelines; TRWD Waste Control Order (2011) · TCEQ 30 TAC 285 (RG-472)
- Navarro County Richland-Chambers Lakeshore Area Zoning Ordinance (rev. 2017; 2022 amendment) & 2025 building-permit package
- Rustling Oaks Estates POA ACC handbook & fee schedules (2009–2024)
- LakeHouse.com listings 7100373 (MLS 21146775) and 7885360 (MLS 21298338): price, dues, listing photos · Zillow, Realtor.com, Redfin, HAR search snippets (pages block automated access) · The Teel Team
- US Census ACS 2020–24 (Census Reporter), QuickFacts V2025 · TEA 2026 ratings (Texas Tribune)
- Esri World Imagery & World Geocoder · OpenStreetMap / OSRM routes · HIFLD electric territories · TWDB water-service areas · ERA5 via Open-Meteo

Glossary

BFE	Base Flood Elevation: water level of the 1%-annual-chance (100-yr) flood
Zone A / X	FEMA 1%-chance floodplain without a BFE / area of minimal flood hazard
FIRM	Flood Insurance Rate Map panel
Freeboard	extra height above the BFE for the lowest floor
NAVD88 / msl	vertical datums for elevations (here within 0.03 ft of NGVD29/msl)
Normal pool	full lake level, 315.0 ft; TRWD flowage easement runs to 320.0 ft
TRWD	Tarrant Regional Water District — owns the lake; permits docks, walls, septic near it
Lidar / DEM	laser-scanned bare-earth elevation grid (1 m) used for contours and slopes
Vertical exaggeration	vertical scale stretched vs horizontal; ×1 = true shape
CAD	Central Appraisal District — tax parcel and value records
GIS parcel	digital tax-map lot outline; not a survey
OSSF / ATU	on-site sewage facility (septic) / aerobic treatment unit
Drip field	subsurface drip lines that disperse treated effluent; sized by Ra (gal/sf/day)
Class IV soil	clay, the slowest-draining septic soil class (Ra 0.1)
Shrink-swell (LEP)	clay volume change with moisture; LEP >6% is high
HSG	hydrologic soil group (runoff potential, A low – D high)
SF-3 / SUP	county ½-acre single-family district / Specific Use Permit
HOA / POA / ACC	home- or property-owners' association / architectural control committee
WSC / NCEC	water supply corporation / Navarro County Electric Cooperative
Circuit breaker	Texas 20%/yr cap on appraisal rises for non-homestead property ≤$5M
STR	short-term rental (<30 days)
ERA5	global weather reanalysis used for climate normals

Method & limits

Desk study from public records — no site visit. Not a survey, appraisal, flood determination, soil evaluation, title opinion or legal/engineering advice. Lidar elevations carry about ±0.5 ft error and GIS lot lines can differ from the recorded plat by several feet. Both HOA documents and the county zoning district were not obtainable online and are marked CONFIRM. Zillow, Redfin and realtor.com (including its Fly Around views) refuse automated access (HTTP 403/429), so listing photos come from LakeHouse.com (same MLS photos) and the fly-around views are generated from lidar.

End note

Date of creation: 08 November 2026 · **Prepared by AI model:** Claude Opus 5.5 (Anthropic), working in Kiro · **File:** Richland-Chambers-2-Lots-Due-Diligence_08-Nov-26_Claude-Opus-5.5.pdf

Data, scripts and figures to rebuild this report are in the GitHub repository MMS-ITS/Corsicana_3lots.