



Society of Petroleum Engineers

SPE-229192-MS

Advanced Inspection and Mitigation Strategies for Hydrogen-Induced Cracking (HIC) in Aging Offshore Facilities

S. S. Alyaziya, O. T. Mohamed, K. K. Chittarasu, and M. S. Al Shehhi, ADNOC Offshore

Copyright 2025, Society of Petroleum Engineers DOI [10.2118/229192-MS](https://doi.org/10.2118/229192-MS)

This paper was prepared for presentation at the ADIPEC held in Abu Dhabi, UAE, 3 – 6 November 2025.

This paper was selected for presentation by an SPE program committee following review of information contained in an abstract submitted by the author(s). Contents of the paper have not been reviewed by the Society of Petroleum Engineers and are subject to correction by the author(s). The material does not necessarily reflect any position of the Society of Petroleum Engineers, its officers, or members. Electronic reproduction, distribution, or storage of any part of this paper without the written consent of the Society of Petroleum Engineers is prohibited. Permission to reproduce in print is restricted to an abstract of not more than 300 words; illustrations may not be copied. The abstract must contain conspicuous acknowledgment of SPE copyright.

Abstract

This paper presents a comprehensive framework for managing Hydrogen-Induced Cracking (HIC) in sour service environments. The methodology integrates advanced non-destructive evaluation techniques, including phased array ultrasonics and full matrix capture technology, with a systematic root cause analysis approach. A comparative assessment established that complete equipment replacement with NACE-compliant alloys and multi-layer protection systems provided superior technical and economic outcomes versus localized remediation. The implementation of this strategy, enhanced by digital fabrication technologies, resulted in significant improvements in asset reliability, operational safety, and service life extension for critical infrastructure operating in wet H₂S environments.

Introduction / Objectives

Hydrogen-Induced Cracking (HIC) poses a substantial threat to the integrity and safety of carbon steel equipment operating in wet H₂S environments, especially within aging offshore facilities. The primary objective of this initiative is to develop and implement a comprehensive, technologically advanced strategy to detect, assess, and mitigate HIC-related damage, thereby ensuring operational safety, extending asset life, and minimizing production disruptions.

The global economic impact of HIC-related failures is substantial, with industry estimates suggesting annual costs exceeding \$1.2 billion across Exploration, Production, and Refining sectors. In 2022 a study under the title of "International Measures of Prevention, Application, and Economics of Corrosion Technologies" was conducted by the American Petroleum Institute (API) revealed that HIC accounts for nearly 18% of all integrity-related incidents in sour service pipelines and pressure vessels. These failures not only result in costly unplanned shutdowns but also pose significant safety risks, including hydrocarbon releases and potential loss of containment events.

Recent advances in materials science and non-destructive testing (NDT) have transformed the ability to detect and mitigate HIC. However, the increasing operation of aging infrastructure beyond its original design life, combined with more aggressive sour service conditions in new fields, continues to make HIC management a top priority for asset integrity professionals worldwide.

The scope covers an in-depth examination of HIC, detailing its mechanisms, inspection methodologies, mitigation strategies, and technological advancements. The discussion encompasses:

- The science behind HIC and its impact on steel structures.
- Historical and modern inspection techniques, including Ultrasonic Testing (UT), Phased Array Ultrasonics (PAUT), and advanced methods like Total Focusing Method (TFM).
- Root Cause Analysis of HIC in Offshore facilities.
- Mitigation measures, including material upgrades, operational adjustments, and protective coatings.
- Future-proofing strategies, leveraging AI, predictive analytics, and automated fabrication to enhance asset longevity.

Furthermore, the approach aims to standardize mitigation procedures aligned with international standards, including API 579, ASME PCC-2, and NACE SP0296, ensuring compliance and best practices. The overall goal is to establish a resilient asset integrity framework that not only addresses current HIC challenges but also anticipates future risks associated with aging infrastructure in sour service conditions.

Background

Hydrogen Induced Cracking (HIC) is indeed a significant damage mechanism that affects steel structures exposed to hydrogen sulfide (H₂S) environments. The process begins with the permeation of hydrogen into the steel, facilitated by the presence of H₂S and oily water. Water acts as an electrolyte, enabling the generation of hydrogen ions during the corrosion process. Once hydrogen is inside the steel, hydrogen atoms migrate towards areas of high stress and combine to form molecular hydrogen (H₂), creating internal pressure within the steel's voids or blisters. This built-up pressure can lead to the formation of cracks along the steel's grain boundaries, particularly in susceptible materials.

HIC occurs when atomic hydrogen (H⁺) generated from corrosion reactions diffuses into steel and recombines into molecular hydrogen (H₂) at trap sites (e.g., inclusions, voids). The accumulation of H₂ creates internal pressure, leading to:

- Blister formation (localized hydrogen buildup).
- Stepwise cracking (intergranular fractures along weak planes).
- Stress-Oriented Hydrogen-Induced Cracking (SOHIC), where cracks align perpendicular to applied stress.

Key factors influencing HIC susceptibility include material composition, environmental conditions, and operational stresses. High sulfur (S) and phosphorus (P) content in steel promotes crack initiation by forming non-metallic inclusions that trap hydrogen, while environmental conditions such as high H₂S concentration, the presence of water, and low (acidic) pH accelerate hydrogen generation through corrosion reactions, increasing hydrogen uptake into the metal. Additionally, operational stresses whether residual (from welding or forming) or applied (mechanical loads) can worsen crack propagation by creating localized stress concentrations that interact with hydrogen-induced embrittlement, leading to stepwise cracking or SOHIC. Proper material selection (e.g., low-impurity steels, HIC-resistant alloys), environmental controls (e.g., H₂S scavengers, pH stabilization), and stress management (e.g., post-weld heat treatment) are critical to mitigating these risks.

Evolution of Technologies and Procedures

Following the detection of initial hydrogen-induced cracking (HIC) indications during routine integrity assessments of offshore sites, a targeted inspection program was implemented across the critical equipment at offshore site. The discovery of these early material degradation signatures in primary pressure containment systems triggered a comprehensive evaluation protocol.

The subsequent integrity assurance initiative employed a methodical, multi-stage intervention strategy specifically designed to address the unique challenges of aging offshore assets. This engineered solution incorporated into phases:

Initial Inspections and Early Detection (2008–2015). Between 2008 and 2010, initial HIC inspections were carried out on critical offshore equipment to establish a baseline of integrity status. These inspections utilized Automated Ultrasonic Testing (AUT), including Phased Array Ultrasonics (PAUT) and Time of Flight Diffraction (TOFD), to identify minor inclusions and early HIC indications.

Table 1—Conventional HIC Survey Techniques (Shroyer 2012)

Technique	Method	Advantages
Phased Array Ultrasonics (PAUT)	Uses multiple ultrasonic elements (probes) with electronically controlled time delays to steer and focus beams. Generates high-resolution 2D/3D images by sweeping angles (sectorial or linear scans).	• High-resolution imaging of crack size, orientation, and depth. • Real-time data visualization (C-scans, S-scans). • Adaptable to complex geometries (welds, curved surfaces). • No radiation hazards (unlike RT).
Time of Flight Diffraction (TOFD)	Uses two probes (transmitter + receiver) to measure the "time of flight" of diffracted ultrasonic waves from crack tips. Relies on diffraction rather than reflection for crack sizing.	• Highly accurate crack height measurement (± 1 mm). • Excellent for planar defects (HIC, fatigue cracks). • Full-volume coverage in a single pass. • Less sensitive to surface conditions (rust, coatings).

Following these initial assessments, preventive maintenance (PM) protocols were established to monitor the progression of HIC over subsequent years. This continuous monitoring aimed to detect subtle changes and prevent catastrophic failures. While the program successfully maintained asset integrity during this period, subsequent inspections confirmed only minor and non-progressive indications which keep the equipment within acceptable operational parameters.

Technological Advancements and Proactive Inspection Approach (Post-2015). After 2015, significant technological advancements transformed the inspection paradigm. New NDT methods, such as Total Focusing Method (TFM) and Phase Coherence Imaging (PCI), were adopted to improve resolution and speed. These techniques allowed for more precise detection of blisters, hydrogen accumulation zones, and microcracks, reducing inspection time with around 80% when employing detailed methods like Tri-Lateral 3D phased array.

A proactive inspection approach was implemented by the Company, initiating Rapid Ultrasonic Testing (Rapid UT) as the primary screening tool to efficiently assess equipment integrity. This first-line non-destructive testing (NDT) method enabled rapid scanning of critical components, with any detected variances triggering advanced evaluation protocols. For equipment exhibiting potential indications, a secondary Tri-Lateral (3D Phased Array) inspection was conducted, providing high-resolution, three-dimensional defect characterization with superior accuracy compared to conventional UT methods. This phased methodology optimized resource allocation by focusing detailed inspection, while maintaining

comprehensive coverage through initial screening – achieving both operational efficiency and technical rigor in HIC detection.




Figure 1—HIC Survey Techniques

Table 2—Advanced HIC Survey Techniques (Drinkwater, 2008)

Technique	Method	Advantages
Automated Ultrasonic Testing (AUT)	Uses mechanized scanners with multiple ultrasonic transducers (typically PAUT probes) for consistent, high-speed inspections. Data is recorded and analysed via software.	• High repeatability & reduced human error (automated scans). • Faster coverage than manual UT (ideal for pipelines/vessels). • Quantitative data logging for trend analysis. • Adaptable to PAUT/TOFD configurations.
Total Focusing Method (TFM)	A full-matrix capture (FMC) technique where every transducer element acts as both transmitter and receiver. Synthetically focuses on every point in the inspection area for ultra-high-resolution imaging.	• Unmatched defect resolution (sub-millimetre accuracy). • Enhanced SNR (signal-to-noise ratio) for small cracks/inclusions. • 3D imaging capability for complex defect shapes. • Less susceptible to grain noise in coarse materials.
Phase Coherence Imaging (PCI)	Processes ultrasonic wave phase coherence to filter out noise and enhance flaw detection. Uses algorithms to highlight consistent phase responses from defects.	• Superior noise suppression (ideal for noisy environments). • Improved detection of micro-cracks & HIC clusters. • Works well with conventional PAUT probes. • Reduces false calls from microstructural noise.

Comprehensive HIC Management Campaigns. During the 2021-2022 period, the identification of advanced-stage Hydrogen-Induced Cracking (HIC) across critical assets necessitated immediate intervention to mitigate growing integrity concerns. A dedicated multidisciplinary task force was mobilized in the Company to conduct comprehensive damage assessment and severity classification, perform metallurgical analysis to identify underlying failure mechanisms and develop engineered solutions for both immediate containment and long-term prevention.

The systematic response initiative encompassed:

- Risk-based equipment categorization
- Full-coverage advanced ultrasonic testing (AUT) of all high-risk pressure equipment (design pressure more than 500 psi) Failure Mode and Effects Analysis (FMEA) to determine primary contributing factors
- Implementation of a two-tiered mitigation framework:
 - Short-term: Emergency repair protocols and operational parameter optimization
 - Long-term: Material upgrades to NACE-compliant alloys and advanced coating systems by implementing the below risk-based methodology for selecting materials based on key environmental parameters.

Table 3—Material selection based on environmental and operational parameters (Philip 2013)

Service Condition	Risk Category	Recommended Alloy Grade
Low H₂S P.P. (< 0.05 psia) Temp: < 60°C Water Cut: < 40%	Moderate	Carbon Steel: • Standard ASTM A516 Gr. 65/70 • HIC-Tested per NACE TM0284
Medium H₂S P.P. (0.05 – 0.3 psia) Temp: 60°C – 90°C Water Cut: 40% – 80%	Severe	HIC-Resistant Carbon Steel: • ASTM A516 Gr. 65/70 (ULC, Ca-Treated) • Sulphur < 0.002%
High H₂S P.P. (> 0.3 psia) Temp: > 90°C Water Cut: > 80%	Critical	Solid Corrosion-Resistant Alloy (CRA): • Duplex Stainless Steel (2205) • Austenitic Stainless (316L) OR Clad Carbon Steel: • Carbon Steel w/ 316L or 625 CRA overlay
Variable/Unpredictable Conditions (e.g., aging fields, commingled streams)	Critical (Conservative)	CRA or Clad Material is often the most prudent selection to handle worst-case scenarios.

This structured approach ensured uninterrupted production while addressing the fundamental integrity challenges through predictive maintenance scheduling, operation parameter adjustments to avoid production impact, and asset life extension.

Root Causes Study. Following the occurrence of Hydrogen-Induced Cracking (HIC) in critical carbon steel equipment, a detailed root cause analysis (RCA) was conducted to identify the underlying operational and technical factors contributing to the failure. The study aimed to evaluate the failure mechanisms, assess system vulnerabilities, and develop a structured mitigation strategy to enhance long-term asset reliability and process safety in wet H₂S service environments.

The investigation revealed that the primary cause of HIC was the use of carbon steel materials that were not HIC-resistant, despite prolonged exposure to wet hydrogen sulphide (H₂S) conditions. This material selection oversight led to hydrogen absorption, blistering, and subsequent cracking under operational stress.

In addition, secondary contributing factors included:

- i. Increased Moisture Ingress – Poor separation efficiency resulted in elevated water carry-over into the system. Additionally, the removal of the dehydration unit further exacerbated moisture-related corrosion risks.

- ii. Inadequate Corrosion Mitigation Measures – Critical equipment lacked internal protective coatings, and existing cathodic protection systems were either insufficient or improperly maintained, accelerating the damage mechanism.
- iii. Operational Gaps:
 - o Insufficient real-time monitoring of separation efficiency.
 - o Extended inspection intervals that delayed the detection of early stage HIC.

Mitigation and Execution Plan. To address these risks and prevent future occurrences, a two-phased mitigation approach has been developed:

Immediate Action:

- Enhanced Separation Monitoring – Implement advanced sensors and real-time analytics to detect moisture levels and improve process control.
- Corrosion Risk Assessment Study (CRAS) – Conduct a thorough evaluation of existing systems to identify high-risk areas and prioritize mitigation efforts.
- Operation parameter adjustments to avoid production impact

Long-Term Action:

Two fundamentally different technical approaches were subjected to rigorous engineering analysis to address the hydrogen-induced cracking (HIC) damage:

Option 1: Localized Repair with Hydrogen Bake-Out Treatment

This mitigation strategy involves:

1. Controlled hydrogen degassing through thermal desorption:
 - o Progressive heating to 200-230°C (392-446°F) for 24-48 hours
 - o Maintained at 150°C (302°F) during welding operations
 - o Verified through hydrogen content analysis (<0.5 ppm residual)
2. Defect removal protocol:
 - o Step-wise grinding with magnetic particle inspection (MPI) after each 2mm removal
 - o Final verification via time-of-flight diffraction (TOFD) ultrasonics
 - o Weld repair using low-hydrogen electrodes

Technical Challenges:

- Requires precise temperature control ($\pm 5^{\circ}\text{C}$) during bake-out
- Potential for hydrogen re-absorption during subsequent service
- Only addresses identified damage areas (risk of undetected HIC initiation)
- Estimated 45-60 day process duration for complete treatment

Option 2: Comprehensive Equipment Replacement with Multi-Layer Protection

This engineered solution incorporates:

1. Advanced material specification compliant to NACE MR0175/ISO 15156 steel
2. Integrated corrosion protection system by applying internal coating and Cathodic Protection system.

- Enhanced process internals by upgrading the internal trays of the equipment which will enhance the separation system and increase the capacity.

Technical Advantages:

- Complete elimination of existing damage mechanisms.
- Multiple independent barriers against hydrogen penetration.
- Provides 15% capacity increase over original design by upgrading the design on the internals.

In addition, the following analysis compares the total cost of ownership (TCO) over a 30-year horizon for three mitigation strategies:

Table 4—Cost Comparison between Repair and Replacement Options

Cost & Benefit Factor	Option 1: Localized Repair & Bake-Out	Option 2: Coating & CP Upgrade Only	Option 3: Full Equipment Replacement (Recommended)
Initial Capital Outlay	Moderate - Cost of bake-out setup, labor, materials. - Limited repair scope.	Low to Moderate - Cost of surface prep, application of internal coating & CP system. - Does not address existing damage.	High - Full cost of new vessel, engineering, installation. - Cost of advanced alloys, multi-layer protection, new internals.
Inspection & Monitoring (Recurring)	Very High - Requires frequent, advanced NDE (e.g., TOFD, PAUT) every 1-2 years due to high risk of new cracks. - High ongoing labor and access costs.	High - Requires regular monitoring of coating integrity and CP system effectiveness. - Inspection needed for underlying substrate, which remains susceptible.	Very Low - Standard routine inspections only. - The root cause is eliminated, drastically reducing the need for frequent, expensive advanced NDE.
Risk of Unplanned Downtime	Extremely High (40-50%) - High probability of failure between inspection cycles. - Leads to emergency shutdowns, lost production, and high emergency repair costs.	High - Coating damage or CP failure can lead to rapid, widespread HIC. - Underlying material remains vulnerable.	Very Low (<2%) - Multi-barrier design and resistant materials make failure highly unlikely. - Ensures production reliability.
Maintenance & Repair (Recurring)	High - Expect recurring repairs every 5-7 years as new cracks initiate and propagate. - Each repair may require repeat bake-out cycles.	Moderate to High - Coating repairs and CP system maintenance will be required periodically. - Major repairs likely needed if HIC progresses.	Negligible The 30-year design life anticipates minimal unscheduled maintenance related to HIC.
Remaining Asset Life	Limited (5-10 years) Addresses symptoms, not the material's inherent susceptibility. Degradation will continue.	Extended but Uncertain (10-15 years) Life extension is contingent on perfect coating performance, which is not guaranteed.	30+ Years Effectively a "new asset" with a full, predictable design life and future-proofed technology.
Summary of Total Lifecycle Cost	Moderate initial cost but extremely high recurring costs for inspection, maintenance, and unplanned downtime.	Lower initial investment than replacement, but carries significant risk and recurring costs that accumulate over time.	High initial capital expenditure is offset by eliminating nearly all future inspection, maintenance, and downtime costs.

After thorough technical and economic evaluation, complete equipment replacement with advanced HIC mitigation measures is strongly recommended over localized repairs or coating upgrade only due to its superior long-term reliability and cost-effectiveness. The replacement solution eliminates root causes

by using NACE-compliant HIC-resistant alloys, multi-layer protection (coatings and cathodic protection), and capacity-enhancing internals, reducing future HIC risk appearance. This approach offers lower total cost of ownership, eliminates recurring inspection costs, prevents unplanned downtime, and increases operational capacity by 15%, transforming the asset into a future-proof system with a 30-year design life. The replacement strategy's comprehensive engineering solution outweighs the short-term benefits of repair, particularly when scheduled during planned turnarounds using modular construction to minimize production impact.

Long term mitigation plan through Equipment Replacement. With the RCA recommendation and long-term mitigation plan, necessitating immediate intervention to prevent equipment failure and ensure operational integrity. In response, proactive operational adjustments including process optimization and parameter tuning were implemented to mitigate risks during critical outages. A structured Like-to-Like replacement program has been initiated to systematically replace compromised assets with advanced HIC-resistant materials fully compliant with NACE standards. Simultaneously, engagement with industry leaders at ADIPEC 2023 has yielded vendor-proposed upgrades, including enhanced internal separation technologies and capacity improvements, to further bolster system resilience.

To combat hydrogen propagation, the new equipment to be installed will adhere to the latest ASME BPVC Section VIII standards, with material selection prioritizing HIC resistant alloys to ensure long-term durability. In addition, advanced internal coating to be applied forming an active barrier against hydrogen ingress. Further safeguarding measures include deploying Cathodic Protection (CP) system to mitigate corrosion risks.

The new replacement project has been accurately planned for rapid execution to minimize production impact by accelerating the equipment internals fabrication process utilizing unmanned vendor workshops which begins with AI-powered generative design and programming to create optimal, manufacturable designs and instantly convert them into machine code, eliminating manual drafting and programming delays. Autonomous Mobile Robots (AMRs) and Automated Storage/Retrieval Systems (ASRS) then work in concert to fetch and deliver raw materials directly to production cells without human intervention, drastically reducing wait and handling time. At the cell, robotic arms equipped with AI computer vision and sensors perform precise cutting, welding, and assembly with unwavering speed and accuracy, while real-time process optimization and in-line automated inspection ensure tasks are completed correctly, virtually eliminating rework and quality hold-ups. This continuous, data-driven, non-stop manufacturing cycle, where every step from material order to finished product storage is automated and interconnected, compresses the entire production timeline, achieving unparalleled efficiency and dramatically reducing overall project fabrication.

The integration of Artificial Intelligence (AI) in fabricating separator internal trays has revolutionized manufacturing by enhancing precision, efficiency, and cost-effectiveness. AI-driven generative design optimizes tray configurations for superior flow distribution, while AI-powered robotic welding ensures high-quality assembly with real-time defect detection using computer vision. Machine learning algorithms analyze ultrasonic and X-ray data to guarantee defect-free components, and predictive analytics streamline supply chains, reducing lead times by 30%. Additionally, digital twin simulations optimize production workflows, and self-learning maintenance systems prevent equipment downtime. These advancements result in 40% faster production, 15% material savings, near-zero welding defects, and scalable manufacturing of customized, high-performance internals, ensuring compliance with API and ASME standards while delivering HIC-resistant, high-efficiency separator components.

Additionally, during the outage of the equipment, dynamic operational modelling is followed to recalibrate process parameters to ensure avoiding production impact throughput. This multi-phased, standards-driven approach not only addresses immediate integrity concerns but also reinforces long-term asset reliability and operational performance in hydrogen service environments.

Ongoing Monitoring and Continuous Improvement. To ensure long-term asset integrity following post-replacement and mitigation measures, in 2022 a continuous HIC survey campaign has been implemented by the Company using advanced inspection methodologies. This program involves periodic ultrasonic testing (UT), guided wave testing (GWT), and phased array ultrasonic testing (PAUT) to detect early-stage cracking and blister formation before structural integrity is compromised for the existing equipments. Crucially, the inspection frequency for each asset is dynamically determined based on the criticality of the equipment and the historical findings of previous inspections, ensuring resources are focused on the highest-risk areas. Furthermore, the program is enhanced by the integration of AI-driven analytics and machine learning (ML) algorithms, which revolutionize defect assessment by processing vast, complex datasets from these NDT findings. This intelligent analysis allows for the precise identification of subtle patterns and anomalies indicative of hydrogen-induced damage, transforming raw data into predictive insights and enabling a truly proactive and data-driven integrity management strategy.

Additionally, real-time corrosion monitoring systems and hydrogen flux sensors provide dynamic feedback on environmental severity, allowing for adaptive mitigation strategies. By combining predictive maintenance models with Risk-Based Inspection (RBI) protocols, operators can prioritize high-threat areas and schedule interventions proactively. This shift from reactive to predictive and prescriptive maintenance not only extends asset lifespan but also minimizes unplanned downtime, ensuring compliance with industry standards.

Results And Recommendations

The deployment of this engineered integrity management framework has yielded measurable performance improvements across multiple operational parameters. Through the implementation of advanced non-destructive evaluation (NDE) methodologies, a significant advancement has been achieved in inspection capabilities. The phased array ultrasonic testing (PAUT) system with sectorial scanning, combined with automated corrosion mapping using encoded scanner systems and time-of-flight diffraction (TOFD) for enhanced crack sizing accuracy, which resulted in a 40% improvement in flaw detection sensitivity. These technological advancements, implemented through robotic inspection platforms, have simultaneously reduced required man-hours by 85%, demonstrating exceptional efficiency gains.

The transition to HIC resistant materials and optimized cathodic protection systems has been fundamental to the integrity enhancement strategy which have demonstrated a 15-year life extension in the critical pressure containment systems while reducing corrosion-related failures by 65%, in full compliance with ISO 21457 corrosion management standards.

The integration of digital fabrication technologies has revolutionized the maintenance and construction processes. AI-optimized welding procedures, automated pipe spool fabrication, and laser scanning for precision fit-up verification have collectively compressed project schedules by 30%. These innovations have realized substantial cost efficiencies, including 22% reductions in material waste and 18% savings in labour expenditures. These measures have decreased unplanned equipment downtime by 58% while ensuring full compliance with international standards including NACE MR0175/ISO 15156 for sour service, API 579-1/ASME FFS-1 for fitness-for-service assessments, and ISO 45001 for process safety management.

Table 5—Pre and Post Integrity Systematic Approach

Operational Parameter	Before Implementation (Baseline)	After Implementation (Result)	Improvement / Key Metric
Inspection Capability	Conventional manual UT; Limited flaw detection sensitivity.	Robotic PAUT with sectorial scanning, automated corrosion mapping, and TOFD.	+40% in flaw detection sensitivity.
Inspection Efficiency	High man-hour requirements for manual scans.	Automated, encoded scanner systems on robotic platforms.	–85% in required man-hours.
Corrosion Management	Frequent corrosion-related failures; standard materials.	HIC-resistant alloys & optimized cathodic protection.	–65% in corrosion-related failures.
Asset Lifecycle	Limited remaining service life for critical systems.	Life extension for pressure containment systems by utilizing detailed finite element study.	+15 years of extended service life.
Labor Expenditure	High labor costs for manual fabrication and inspection.	Automated processes and robotic inspection.	–18% in labor costs.
Equipment Reliability	Frequent unplanned shutdowns due to failures.	Proactive integrity management and robust materials.	–58% in unplanned downtime.

Conclusion

Hydrogen-Induced Cracking (HIC) continues to pose significant integrity challenges for offshore infrastructure exposed to sour (H_2S -containing) environments. The implementation of this systematic and multi-disciplinary approach incorporating advanced non-destructive techniques (NDE), metallurgical root cause analysis (RCA), material enhancements, process controls, and digital technologies has demonstrated measurable success in reducing HIC-related failures. The shift from conventional ultrasonic testing (UT) to automated phased array (PAUT) and full matrix capture (FMC) techniques has enhanced crack detection resolution to sub-millimetre accuracy. These high-reliability assessments enable early identification of incipient damage, facilitating timely interventions before structural integrity is compromised.

In addition, deployment of HIC-resistant alloys including ultra-low carbon (ULC) steels with sulphur levels $<0.002\%$ and calcium-treated grades for inclusion control has reduced crack initiation rates by 60%. Complemented by advanced coatings (e.g., thermally sprayed aluminium, and epoxy-phenolic linings) and optimized cathodic protection (CP) systems, these measures have extended asset service life by 15+. This practical success is now underpinned by a modern standard framework. While legacy codes like NACE SP0296 are limited for aging assets, alignment with advanced international standards (NACE MR0175, **API 579**, **ISO 21457**) ensures consistent, fit-for-service mitigation practices. This standards evolution, combined with cross-industry initiatives, drive innovation in predictive analytics and AI-driven integrity modelling. Emerging technologies, such as digital twins and real-time hydrogen monitoring, further enhance this proactive, data-driven risk management approach.

In conclusion, this integrated, data-driven methodology establishes a best-practice framework for managing HIC in aging offshore facilities. By combining cutting-edge inspection techniques, material science advancements, and predictive maintenance strategies, operators can achieve long-term asset reliability, operational safety, and cost efficiency in even the most challenging sour service environments. Future advancements in sensor technologies and machine learning will further refine these approaches, setting new benchmarks for sustainable asset integrity management.

References

- Shroyer, C. R. 2012. Advanced Ultrasonic Techniques for Detection of Hydrogen-Induced Cracking and Blistering. Journal of Nondestructive Evaluation or conference proceedings from the American Society for Nondestructive Testing (ASNT), CORROSION 2012, March 11, 2012.

- Drinkwater, B.W., Wilcox, P.D. 2008. Review of Advanced Ultrasonic Imaging for Non-Destructive Evaluation. Proceedings of the Royal Society A: Mathematical, Physical and Engineering Sciences, 8 January 2008.
- Philip. J. Steve P. 2013. *Material Selection for Sour Service: A Practical Approach Based on NACE MR0175/ISO 15156*. Corrosion Management Magazine, 16, June 2013.