

[UQBA-4] [Collision] Player character falls through SM_Rock_Large terrain mesh due to missing collision primitives

Created: 22/Aug/26 Updated: 24/Aug/26 Due: 27/Aug/26 Resolved: 24/Aug/26

Status:	Done		
Project:	UE5 QA BSC Amalis		
Components:	None		
Affects versions:	None		
Fix versions:	None		

Type:	Bug	Priority:	Medium
Reporter:	Oleksandr Doroshkevych	Assignee:	Oleksandr Doroshkevych
Resolution:	Done	Votes:	0
Labels:	collision, geometry, level_design, out_of_bounds		
Remaining Estimate:	Not Specified		
Time Spent:	Not Specified		
Original estimate:	Not Specified		

Attachments:

FinalMapOne.png

NEW1.png

FinalMapSecond.png

FinalMapTriangle.png

Rank:	0 hzzzzb:
Start date:	24/Aug/26

Description

Steps to Reproduce:

1. Launch the game and load Level_01.

2. Navigate to the waterfall location.

3. Attempt to jump onto the large decorative rock (SM_Rock_Large) positioned at the water's edge.

Expected Result:

The player character lands solidly on the surface of the rock and can walk across it.

Actual Result:

The player character falls entirely through the rock mesh and through the landscape geometry, dropping out of the playable map area.

Severity: Critical

Environment: UE 5.8

Comments

Comment by Oleksandr Doroshkevych [24/Aug/26]


Fix Applied:

Generated custom simplified collision via **DOP 18** in Static Mesh Editor for SM_Rock_Large.

Set Collision Complexity preset to Use Complex Collision As Simple for critical terrain walkable surfaces.

Tested character ground-trace detection on sloped faces.

Attached: collision_wireframe_check.png



Comment by [Oleksandr Doroshkevych](#) [24/Aug/26]

QA Verified:

- Character cannot fall through rock bounds or clip into under-terrain void. Walking, jumping, and vaulting collision surface is solid.
- Verified on Build: v0.4.1-dev. **Closed.**

Generated at Mon Aug 24 21:43:48 UTC 2026 by Oleksandr Doroshkevych using Jira 1001.0.0-SNAPSHOT#100293-rev:0def82f81a0ac3b909733c71c33f756f28d12358.