

SME10756 — Brook Park Imaging Center MRI

Network Imaging Associates LLC · Siemens MRI · Brook Park, OH · Jul 7 – Aug 6 monitor data (1,478 captures)

COMPRESSOR

ON

running · 3 brief dropouts — likely sensor flickers

SHIELD NOW

52.0 K

52% of the 100 K line · rising

EVENT PEAK

52.0 K

Aug 3 18:45Z · 48.0 K under threshold

CABINET

21.9 °C


15.8–22.4 °C in window · warn 38 · alarm 43 °C

HELIUM


55.5%

below the 60% warning level

SHIELD TEMP — JUL 7 → AUG 6 (daily range, K)



HELIUM LEVEL — JUL 7 → AUG 6 (daily reading, %)



Timeline (UTC): No compressor events, alarms, or threshold breaches detected across 1,478 captures. The compressor signal dropped for a single reading 3 times (Jul 21 17:45Z, Jul 24 16:45Z, Jul 27 15:45Z) with no shield temp response — **likely sensor flickers, not true stops**. Helium fell to **55.5%** (–4.80 vs baseline). No quench. Shield temp now reads 52.0 K (Aug 6 18:45Z) — 52% of the line.

CURRENT — AUG 6 (last readings)

Compressor ON. Shield temp 52.0 K (18:45Z). Helium 55.5%.

RATES

Shield temp +3.0 K vs baseline (49.0 → 52.0); peak 52.0. Helium –4.80 points.

DATA NOTES

1,478 captures · 1,478 valid pressure · 1,478 valid helium readings. Charts show the daily min-max range with the daily last value. EDU (1,478 captures): room 71.1–78.1 °F · probes –196.6–60.0 / 54.8–68.7 °F · humidity 33–65%.