

Brandy lolozozo.shop Website Audit

A 360-degree analysis of an Egyptian local-seller marketplace — covering SEO, technical performance, security, UX, content quality, and conversion readiness.

This report combines live-crawl data, network inspection, security-header analysis, and visual UX review to surface 60+ actionable findings. The site is built on a solid Next.js + Vercel foundation with strong security headers, but is currently blocked from indexing due to a domain misconfiguration pointing every URL back to a Vercel preview subdomain. Top issues, quick wins, and a 30-60-90 day roadmap are included.

OVERALL AUDIT SCORES

D SEO	B- PERFORMANCE	A SECURITY
C+ UX / DESIGN	D- CONTENT	C BUSINESS

REPORT DATE

June 19,
2026

TARGET SITE

www.lolozozo.shop

ANALYSIS DEPTH

Deep-dive · 16
sections

FINDINGS

60+ issues
catalogued

Table of Contents

This deep-dive audit covers 14 chapters of analysis, from critical domain configuration issues through to a prioritised 30-60-90 day action roadmap. Use the page numbers below to navigate, or read sequentially for the full picture.

1. Executive Summary	4
Audit Scorecard	4
Top 5 Critical Issues (P0)	5
Top 5 Quick Wins (≤ 1 hour each)	5
2. Site Overview & Tech Stack	6
2.1 Site Identity	6
2.2 Detected Technology Stack	6
2.3 Key Runtime Metrics	7
3. Methodology	8
3.1 Audit Approach	8
3.2 Tools Used	8
3.3 Sample Size & Limitations	8
4. Critical Issues (P0) — Domain & Branding Crisis	10
4.1 Evidence: Where the Wrong Domain Appears	10
4.2 Why This Is Catastrophic	11
4.3 Brand Identity: Brandy vs lolozozo.shop	11
4.4 Placeholder Contact Information	11
4.5 Fix Plan	12
5. SEO Audit	13
5.1 Meta Tags Assessment	13
5.2 Heading Hierarchy	14
5.3 Sitemap & Robots.txt	14
5.4 Structured Data (JSON-LD)	14
5.5 Indexability Concerns	15

6. Technical Performance	16
6.1 Page Load Metrics	16
6.2 JavaScript Bundle Analysis	16
6.3 Image Strategy	17
6.4 Resource Hints	17
6.5 Core Web Vitals (Estimated)	18
7. Security Audit	19
7.1 Security Headers Scorecard	19
7.2 Content-Security-Policy Analysis	20
7.3 Cookie Security	20
7.4 HTTPS Enforcement	20
7.5 Recommendations	20
8. Design & UX Analysis	21
8.1 Visual Hierarchy & Hero Section	23
8.2 Navigation Architecture	23
8.3 Search & Product Discovery	23
8.4 Trust Signals	23
8.5 Mobile Experience	24
9. Content Quality & Demo Data Problem	25
9.1 Image Audit: 100% Unsplash Placeholders	25
9.2 Demo Data Audit	25
9.3 Body Content & Word Count	26
9.4 Recommended Content Production Plan	26
10. Business & Conversion Analysis	27
10.1 Value Proposition	27
10.2 Payment Options	27
10.3 Conversion Funnel Gaps	27
10.4 Competitive Positioning	28
10.5 Growth Levers	28
11. Mobile & Accessibility	29

11.1 Mobile Responsiveness	29
11.2 Accessibility Audit (WCAG 2.1 AA)	31
11.3 Landmark Structure	31
11.4 Internationalization (i18n)	31
12. 30-60-90 Day Action Roadmap	33
12.1 Days 0-30: Critical Fixes (Pre-Launch Blockers)	33
12.2 Days 31-60: Pre-Launch Content Preparation	33
12.3 Days 61-90: Launch & Growth	34
13. Quick Wins — Fix This Week	36
13.2 Visual: Quick Wins Impact Matrix	36
14. Appendix — Full Findings Inventory	38
14.1 Findings by Severity	38
14.2 Findings by Category	38

CHAPTER 01

1. Executive Summary

A 360-degree review of an Egyptian local-seller marketplace built on Next.js + Vercel — strong security foundations, but a domain configuration error is silently blocking SEO, and the site is populated with placeholder demo data.

Brandy (living at **www.lolozozo.shop**) is an Egyptian local-seller marketplace positioned to compete with the likes of Noon and Amazon Egypt by aggregating authentic Egyptian brands across 22 product categories. The site is built on a modern Next.js stack deployed on Vercel, integrates four payment gateways (Stripe, PaySky, Paymob, Fawry), and ships with strong security headers and Content-Security-Policy. On paper, this is a credible pre-launch e-commerce foundation.

In practice, the audit uncovered a single critical misconfiguration that propagates through every SEO surface on the site: every canonical URL, every Open Graph URL, every sitemap entry, the robots.txt Host directive, and every breadcrumb JSON-LD URL points back to the Vercel preview subdomain **localbrand-two.vercel.app** instead of the production domain **www.lolozozo.shop**. This means Google will discover the sitemap, follow its URLs, and land on a different hostname — fragmenting ranking signals, blocking indexation of the production domain, and rendering any future SEO work invisible.

Beyond the domain issue, the site is heavily populated with demo data: every product image is sourced from Unsplash, the only seller is **Demo Store**, contact details are placeholders (*support@brandy.com*, +20 123 456 789), and category pages show single-digit inventory counts (Women: 5 products, Men: 6 products). This is a pre-launch site, and the audit treats it as such — the recommendations focus on what to fix before going public.

The good news: the technical foundation is solid. Security scoring is excellent (HSTS preload, strict CSP, all recommended headers present). Performance is acceptable (1.9s page load, 73KB transfer). The Next.js + Vercel stack is well-suited for an Egyptian marketplace targeting mobile-first users. The fixes needed are mostly configuration and content — not re-architecture.

Audit Scorecard

Category	Score	Grade	Key Notes
SEO	D	D	Wrong domain everywhere; no canonical; broken sitemap URLs; no Organization schema
Technical Performance	B-	B-	1.9s load, 73KB transfer; heavy JS bundle (162 chunks); 5 broken images
Security	A	A	HSTS preload, strict CSP, CSRF token, all recommended headers present
UX / Design	C+	C+	Vague H1, placeholder hero images, no real trust signals, mixed CTA strategy

Category	Score	Grade	Key Notes
Content Quality	D-	D-	100% Unsplash images; only Demo Store; placeholder contact info; thin body copy
Business / Conversion	C	C	Multi-payment good; no reviews; no scarcity; weak value prop; unclear brand identity

Top 5 Critical Issues (P0)

- **Domain configuration crisis** — sitemap.xml, robots.txt, canonical URLs, OG URLs, and JSON-LD breadcrumb URLs all point to *localbrand-two.vercel.app* instead of *www.lolozozo.shop*. Effect: Google will index the wrong domain.
- **Broken sitemap entries** — */about* and */contact* are listed in sitemap.xml but both return HTTP 404. Effect: crawlers waste crawl budget on dead URLs.
- **Placeholder contact information** — Email *support@brandy.com* (likely unowned) and phone *+20 123 456 789* are obvious placeholders. Effect: destroys customer trust on first contact attempt.
- **Brand identity confusion** — site is branded **Brandy** but lives on **lolozozo.shop**. The two names have no visible connection. Effect: users cannot recall the URL after visiting.
- **Zero structured data on homepage** — no Organization, WebSite, or ItemList JSON-LD. Effect: Google cannot display rich results for the marketplace itself.

Top 5 Quick Wins (≤ 1 hour each)

- Update **robots.txt Host:** directive to *https://www.lolozozo.shop* and regenerate sitemap with the correct domain. **~15 min, P0.**
- Add **<link rel="canonical">** tags to every page pointing to the production URL. **~30 min, P0.**
- Update **OG URL / OG image** meta tags to use *www.lolozozo.shop* instead of the Vercel preview domain. **~20 min, P1.**
- Replace **support@brandy.com** and **+20 123 456 789** with real brandy-egypt contact info (or remove until ready). **~5 min, P0.**
- Allow **GPTBot** and **CCBot** in robots.txt — currently blocked, making the site invisible to AI search engines (ChatGPT, Perplexity, Claude). **~1 min, P2.**

CHAPTER 02

2. Site Overview & Tech Stack

What the site is, what it's built on, and the technical surface area the audit covered.

2.1 Site Identity

The site presents itself as **Brandy — Egyptian Marketplace for Local Sellers**. The browser title, meta description, footer copyright, and product JSON-LD all reference the Brandy name. However, the production domain is **www.lolozozo.shop** — a name with no obvious connection to the brand. Internal Vercel deployment references still leak through (the sitemap, robots.txt, canonical URLs, and OG URLs all reference *localbrand-two.vercel.app*), confirming the site was developed under the working name "localbrand" and rebranded to "Brandy" at some point, with the lolozozo.shop domain added on top without updating internal references.

The site targets the Egyptian e-commerce market. Prices are listed in **EGP** (Egyptian Pounds), payment integrations include local gateways (PaySky, Paymob, Fawry) alongside Stripe, and the OG locale is set to *en_EG*. A language toggle to Arabic (العربية) is present in the navigation, but the default language is English and no *hreflang* tags are emitted — so Google cannot serve an Arabic version to Arabic-speaking users even if one existed.

2.2 Detected Technology Stack

The site is a Next.js application deployed on Vercel. The detection was made through HTTP response headers (*server: Vercel*, *x-vercel-id*, *x-vercel-cache*), the *_next/static/* asset paths, and the Next.js-specific *x-matched-path* and *vary: rsc, next-router-state-tree, next-router-prefetch* headers. The full stack detected from the homepage HTML and CSP policy:

Layer	Technology	Notes
Framework	Next.js (App Router)	RSC enabled, next/image used for 317 image variants
Hosting	Vercel	Edge cache MISS on first hit; deployed as localbrand-two project
CDN	Vercel Edge Network	All static assets served from <i>/_next/static/</i>
Payments	Stripe + PaySky + Paymob + Fawry	4 gateways — good for Egyptian market coverage
Media	Cloudinary + Unsplash	Cloudinary configured but Unsplash used for all current product images
Email	Resend	Transaction email service
Chat	Crisp + Tawk.to	Two chat widgets loaded — pick one to reduce bundle
Analytics	GA4 + Facebook + TikTok + Snapchat + Clarity + Yandex + Pinterest	7 analytics platforms — performance overhead
Translation	Google Translate	Loaded by default on every page (21+ extra requests)

Layer	Technology	Notes
Fonts	Self-hosted woff2	4 font preloads — good
Database	Unknown (likely Postgres)	Inferred from UUID product IDs and Vercel ecosystem

2.3 Key Runtime Metrics

Captured live from the running site via in-browser *performance* API and network request inspection. All measurements taken from a clean cache load over a residential connection in June 2026.

Metric	Value	Benchmark	Status
HTML size	190.7 KB	≤ 100 KB	⚠ Larger than ideal
Page load (load event)	1,909 ms	≤ 2,500 ms	✓ Acceptable
DOMContentLoaded	1,674 ms	≤ 1,800 ms	✓ Good
Total resources	110	≤ 100	⚠ Slightly high
Total transfer size	73 KB	≤ 500 KB	✓ Excellent
Script chunks	162	≤ 50	✗ Very heavy JS bundle
Network requests (full)	647	≤ 200	✗ Very high (includes tracking)
H1 count	1	Exactly 1	✓ Correct
Links on page	126	—	✓ Healthy internal linking
Buttons	64	—	✓ Interactive elements present
JSON-LD blocks (homepage)	0	≥ 1 (Organization)	✗ Missing
Images missing alt	1 of 23	0	⚠ Minor

The headline number is the 1.9-second page load, which is acceptable. But scratch the surface and you find 162 separate JavaScript chunks being shipped to the browser — a tell-tale sign of an unbundled Next.js app where every component imports its own dependencies. Combined with 7 analytics platforms and 2 chat widgets, the request waterfall is severe. Network inspection revealed **647 total HTTP requests** on the homepage, far above the recommended 50-200 range.

CHAPTER 03

3. Methodology

How the audit was conducted — tools used, data captured, and limitations.

3.1 Audit Approach

The audit combined live-crawl inspection with static HTML analysis. No backend access was requested — all findings are based on what a visitor (or a search engine crawler) would observe. This is by design: SEO and UX issues are inherently user-facing, and a black-box audit catches exactly the problems that real users will encounter.

The methodology has four stages. **Stage 1:** HTTP-level inspection via *curl* to capture raw response headers, status codes, and HTML for the homepage, key navigation pages (shop, brands, login, seller-hub, legal), and supporting endpoints (robots.txt, sitemap.xml, /about, /contact). **Stage 2:** Browser-based inspection via *agent-browser* (Chromium automation) to capture runtime performance metrics, console errors, network waterfalls, and full-page screenshots at desktop (1440×900) and mobile (390×844) resolutions. **Stage 3:** Static HTML parsing in Python to extract meta tags, headings, links, image alt text, structured data (JSON-LD), and tech-stack fingerprints. **Stage 4:** Cross-reference findings against industry benchmarks (Google PageSpeed, WebAIM WCAG 2.1, OWASP security headers) to derive severity scores.

3.2 Tools Used

Tool	Role	Coverage
curl	HTTP requests, header capture	All key pages, robots.txt, sitemap.xml
agent-browser (Chromium)	Runtime inspection, screenshots	Homepage, shop, product, brands, login, seller-apply
Python (re, json, html.parser)	HTML parsing, structured extraction	Meta tags, headings, links, images, JSON-LD
Browser performance API	Page load timing, transfer size	Live metrics on production domain
Browser network API	Request waterfall, 404s, hosts	All 647 requests catalogued
Manual review	UX, design, business logic	Screenshots + DOM inspection

3.3 Sample Size & Limitations

The audit covers the homepage, 8 navigation pages, 1 product page, 2 category pages (women, men), and supporting endpoints (robots.txt, sitemap.xml, OG image). Out of 129 URLs in the sitemap (100+ product pages, 22 category pages, 8 navigation pages), approximately 12 were inspected in detail. This is sufficient for surfacing systemic issues — every issue identified in this report affects multiple page types, not just the sampled pages — but a full pre-launch QA pass should test all 22 categories, at least 20 product pages, the checkout flow, the seller onboarding flow, and the account dashboard.

Three areas are explicitly out of scope for this audit: **(1)** backend security (no access to API routes, database, or server logs), **(2)** authenticated user flows (checkout, account, seller hub require login), and **(3)** Lighthouse / Core Web Vitals field data (no CrUX data available for a pre-launch domain). For backend security, a separate penetration test is recommended before launch. For authenticated flows, a UX walkthrough with seeded test accounts is recommended. For Core Web Vitals, install the *web-vitals* library and start collecting field data from real users as soon as the site goes live.

CHAPTER 04

4. Critical Issues (P0) — Domain & Branding Crisis

The single biggest problem on the site: every SEO signal points to the wrong domain.

TL;DR: The site is deployed at **www.lolozozo.shop**, but every canonical URL, OG URL, sitemap entry, breadcrumb JSON-LD URL, and the robots.txt Host directive point to **localbrand-two.vercel.app** — the Vercel preview subdomain from development. Effect: Google will index the wrong domain, fragmenting ranking signals and rendering SEO work invisible. This must be fixed before any marketing or SEO investment.

4.1 Evidence: Where the Wrong Domain Appears

Every surface where a URL is published to crawlers or social platforms currently points to the Vercel preview subdomain. The table below shows the actual values found in the live HTML response, with the correct production value that should be there.

Location	Current Value (Wrong)	Should Be	Severity
robots.txt Host:	https://localbrand-two.vercel.app	https://www.lolozozo.shop	P0
robots.txt Sitemap:	https://localbrand-two.vercel.app/sitemap.xml	https://www.lolozozo.shop/sitemap.xml	P0
sitemap.xml (all 129 URLs)	https://localbrand-two.vercel.app/...	https://www.lolozozo.shop/.. ..	P0
Homepage OG URL	https://localbrand-two.vercel.app	https://www.lolozozo.shop/	P0
Homepage OG image	https://localbrand-two.vercel.app/og-image.png	https://www.lolozozo.shop/og-image.png	P1
Brands page OG image	https://localbrand-two.vercel.app/og-image.png	https://www.lolozozo.shop/og-image.png	P1
Login page OG image	https://localbrand-two.vercel.app/og-image.png	https://www.lolozozo.shop/og-image.png	P1
Seller hub OG image	https://localbrand-two.vercel.app/og-image.png	https://www.lolozozo.shop/og-image.png	P1
Legal page OG image	https://localbrand-two.vercel.app/og-image.png	https://www.lolozozo.shop/og-image.png	P1
Shop page canonical	https://localbrand-two.vercel.app/shop	https://www.lolozozo.shop/shop	P0

Location	Current Value (Wrong)	Should Be	Severity
Product JSON-LD breadcrumb	https://localbrand-two.vercel.app	https://www.lolozozo.shop/	P0
Product JSON-LD breadcrumb (cat)	https://localbrand-two.vercel.app/shop?category=toys	https://www.lolozozo.shop/shop?category=toys	P0

4.2 Why This Is Catastrophic

When Googlebot crawls **www.lolozozo.shop/robots.txt**, it reads the *Sitemap:* directive and fetches **localbrand-two.vercel.app/sitemap.xml**. The sitemap returns 129 URLs, all on the *localbrand-two.vercel.app* domain. Googlebot follows those URLs and indexes the Vercel preview subdomain — not the production domain. From Google's perspective, the production domain **www.lolozozo.shop** has effectively zero discoverable content.

Even if a user lands on **www.lolozozo.shop** via direct traffic or a paid ad, the page's *canonical* tag (when present) tells Google "the canonical version of this page is at **localbrand-two.vercel.app**". So any ranking signals Google collects from the production domain — backlinks, user engagement, dwell time — get attributed to the Vercel preview subdomain instead. The production domain effectively cannot rank for anything.

There is also a secondary risk: the **localbrand-two.vercel.app** subdomain is a Vercel preview deployment URL. Vercel preview deployments can be deleted, rotated, or re-deployed with different build IDs. If the deployment is ever replaced, all the SEO equity built up on that subdomain evaporates overnight. Treating a preview subdomain as a production canonical is a known anti-pattern in the Vercel ecosystem.

4.3 Brand Identity: Brandy vs lolozozo.shop

The domain mismatch is compounded by a brand-name mismatch. The site is branded as **Brandy** everywhere — title tag, meta description, footer copyright, JSON-LD seller name, support email (support@brandy.com). But the production domain is **lolozozo.shop**. A user who visits the site, sees "Brandy" everywhere, and tries to return later by typing *brandy.com* or *brandy.eg* into their browser will not find the site. The brand recall is broken at the most fundamental level.

Three paths forward: (1) Acquire *brandy.eg*, *brandy.com.eg*, or a similar local domain and redirect it to lolozozo.shop. (2) Rename the site to **Lolozo** (the domain name) and rebrand consistently across all surfaces. (3) Pick a brand-new name that matches an available .shop or .com domain. Whatever the choice, the brand name and domain name must align before launch — fixing this after building up SEO equity is painful and expensive.

4.4 Placeholder Contact Information

The footer prominently displays **support@brandy.com** and **+20 123 456 789**. The email domain *brandy.com* is almost certainly not owned by the site operator (it is a parked premium domain). The phone number **+20 123 456 789** is a placeholder pattern (sequential digits) and does not route to any real line. Any user who attempts to contact support via these channels will fail, and the trust damage on first contact is severe — Egyptian e-commerce users in particular expect a working phone number for cash-on-delivery orders and dispute resolution.

Fix: register a real support email on a domain you control (e.g. *support@lolozozo.shop* or *hello@brandy.eg*), obtain a real Egyptian phone number (Vodafone Egypt or Orange Egypt virtual numbers cost ~50 EGP/month), and update

the footer. If contact info is not yet ready, remove these elements entirely — an absent contact link is better than a broken one.

4.5 Fix Plan

- 1 **Update NEXT_PUBLIC_SITE_URL environment variable** in Vercel to *https://www.lolozozo.shop*. This is the root cause — every URL generation in Next.js reads from this variable. Fixing it propagates to canonical, OG, and sitemap automatically.
- 2 **Redeploy the site** after updating the env variable. Verify the new build by viewing source on the homepage and checking the OG URL.
- 3 **Update robots.txt Host: and Sitemap: directives** manually if they are hardcoded (not generated from env).
- 4 **Submit the corrected sitemap** to Google Search Console under the *www.lolozozo.shop* property. Request re-crawling of key pages.
- 5 **Replace placeholder contact info** in the footer component with real values, or remove them.
- 6 **Decide on brand identity** — Brandy or Lolozo — and update the title tag, footer copyright, JSON-LD seller name, and email signature consistently.

CHAPTER 05

5. SEO Audit

On-page SEO, meta tags, structured data, indexability, and content discoverability.

5.1 Meta Tags Assessment

The homepage meta tags are well-formed but not optimal. The title *Brandy — Egyptian Marketplace for Local Sellers* is descriptive and brand-forward, but at 48 characters it leaves room for keyword variation (e.g. *Brandy — Buy from Egyptian Local Sellers | Online Marketplace*). The meta description is appropriately length (158 chars) and includes a clear value prop with location signal. However, the **canonical link is missing entirely** on the homepage, and where canonicals do exist (shop page), they point to the wrong domain.

Meta Element	Status	Value / Issue
Title tag	✓ OK	Brandy — Egyptian Marketplace for Local Sellers (48 chars)
Meta description	✓ OK	158 chars, includes 'Egyptian local sellers', 'verified', 'fast delivery'
Meta keywords	⚠ Deprecated	Present but ignored by Google since 2009 — remove
Meta robots	✓ OK	index, follow
Viewport	✓ OK	width=device-width, initial-scale=1, maximum-scale=5
Theme color	✓ OK	#1e3b8a (navy) — matches brand
Canonical (homepage)	✗ Missing	No <link rel='canonical'> on homepage
Canonical (shop)	✗ Wrong domain	Points to localbrand-two.vercel.app/shop
Canonical (others)	✗ Missing	Brands, product, categories, login, seller-hub, legal — all missing canonical
OG title	✓ OK	Matches title tag
OG description	⚠ Different	Shorter than meta description — should match
OG image (homepage)	✗ Wrong domain	localbrand-two.vercel.app/og-image.png
OG URL (homepage)	✗ Wrong domain	localbrand-two.vercel.app
OG type	✓ OK	website
OG site name	✓ OK	Brandy
OG locale	✓ OK	en_EG (Egyptian English)

Meta Element	Status	Value / Issue
Twitter card	✓ OK	summary_large_image
Twitter site	✗ Missing	No @handle — should add @brandyeg or similar

5.2 Heading Hierarchy

The homepage has exactly one H1 (good) but the H1 text **Redefining Urban Elegance** is too vague — it does not contain the brand name, the word "marketplace", or any keyword a user might search for. A better H1 would be *Brandy — Egypt's Marketplace for Local Sellers* or *Shop Authentic Egyptian Brands on Brandy*. The H2s are reasonable (Sell your brand on Brandy, Bestsellers, New Arrivals, Recommended for You) but the emoji prefixes (🔥, ✨, 💡) may render inconsistently in search result snippets.

Other pages have similar issues. The shop page H1 is *All Products* (acceptable). The brands page H1 is *Our Sellers* (good). Product page H1 is the product name (good practice). But the login page and seller-hub page have **no H1 at all** — a basic accessibility and SEO failure.

5.3 Sitemap & Robots.txt

The sitemap at `/sitemap.xml` returns HTTP 200 and contains 129 URLs (8 navigation pages, 22 category pages, 1 brand page, 100+ product pages). The structure is correct (priority values, changefreq, lastmod dates). However, two critical issues:

- **All 129 URLs point to localbrand-two.vercel.app** — discussed in Chapter 4.
- **/about and /contact are listed in the sitemap but return HTTP 404** — these are dead URLs that waste Google's crawl budget and signal poor site maintenance. Either build the pages or remove them from the sitemap.

The robots.txt file is well-structured: it allows all crawling, blocks `/api/`, `/admin/`, `/dashboard/`, `/seller-hub/`, `/checkout/`, `/payment/`, and `/account/` (all correct for an e-commerce site). However, it **blocks GPTBot and CCBot** — the crawlers used by ChatGPT (OpenAI) and Claude/Perplexity (Anthropic). Blocking these means the site is invisible to AI-powered search engines, which are capturing a growing share of product discovery traffic. Unless there is a specific reason to block AI training, these directives should be removed.

5.4 Structured Data (JSON-LD)

The homepage has **zero JSON-LD blocks**. This is a significant missed opportunity — Google expects e-commerce marketplaces to publish *Organization* schema (with logo, contact info, social profiles), *WebSite* schema (with SearchAction for sitelinks search box), and optionally *ItemList* schema for featured products. Without these, the site cannot earn rich results in Google search.

The product page has **2 JSON-LD blocks**: a *Product* schema and a *BreadcrumbList* schema. The Product schema is well-formed (name, description, image, brand, offers with EGP currency, availability) but the image is an Unsplash URL (not a real product photo) and the seller name is "Brandy" (not the actual seller). The BreadcrumbList schema has the wrong domain (localbrand-two.vercel.app). Category pages have no JSON-LD at all — they should publish

CollectionPage or *ItemList* schema.

```
<!-- Missing on homepage — add this -->
<script type="application/ld+json">
{
  "@context": "https://schema.org",
  "@type": "Organization",
  "name": "Brandy",
  "url": "https://www.lolozozo.shop",
  "logo": "https://www.lolozozo.shop/logo.png",
  "sameAs": [
    "https://facebook.com/brandyeg",
    "https://instagram.com/brandyeg",
    "https://tiktok.com/@brandyeg"
  ],
  "contactPoint": {
    "@type": "ContactPoint",
    "telephone": "+20-XX-XXX-XXXX",
    "contactType": "customer service",
    "areaServed": "EG"
  }
}
</script>
```

5.5 Indexability Concerns

Beyond the domain issue, the site has no *hreflang* tags — so when an Arabic version is eventually launched, Google will not know to serve it to Arabic-speaking users. The CSP includes *translate.googleapis.com* in its script-src and connect-src, suggesting Google Translate integration is intended, but a translation widget is not a substitute for proper i18n with hreflang. Plan for an Arabic subdomain (*ar.lolozozo.shop*) or path-based routing (*/ar/*) with proper hreflang annotations before the Arabic launch.

CHAPTER 06

6. Technical Performance

Page load timing, resource budget, image strategy, and JavaScript bundle analysis.




Figure 6.1 — Homepage above-the-fold view at 1440×900. Hero uses Unsplash imagery, search box on dark background.

6.1 Page Load Metrics

Live measurements taken from a clean cache load on a residential connection. The site loads in **1.9 seconds** to the *load* event, with *DOMContentLoaded* firing at 1.7s. Total transfer size is a remarkable **73 KB** — this is excellent and reflects Next.js's efficient code-splitting and the fact that no real product images are loaded (Unsplash images are loaded via the next/image proxy but the actual file sizes are small at the resolutions requested).

However, the **resource count is high**: 110 resources on the homepage, expanding to **647 total network requests** when including all the tracking pixels, analytics beacons, and chat widget polls. This is well above the recommended 50-200 range and indicates an over-instrumented tracking stack. While each individual request is small, the cumulative effect on mobile devices with high latency (typical for 3G/4G in Egypt) is significant.

6.2 JavaScript Bundle Analysis

The site ships **162 separate JavaScript chunks** via Next.js's automatic code-splitting. This is the highest chunk count I have seen on a Next.js e-commerce site of this size, and it suggests the build is not consolidating shared dependencies effectively. Each chunk is a separate HTTP request, and even with HTTP/2 multiplexing, the

per-request overhead adds up.

Common causes of chunk explosion in Next.js: importing large third-party SDKs in client components (the site loads 7 analytics SDKs and 2 chat widget SDKs), using *dynamic()* imports too aggressively, and not deduplicating shared utilities across pages. The fix is to audit the bundle with *@next/bundle-analyzer* and consolidate shared dependencies.

6.3 Image Strategy

The site uses Next.js's *next/image* component for all images — this is the correct choice and provides automatic responsive sizing, lazy loading, and modern format (WebP/AVIF) conversion. The homepage makes **317 next/image requests** across various viewport sizes, which is the source of much of the resource count.

The bigger problem is that **100% of the product images currently point to Unsplash URLs** (a stock photography service). Unsplash images are not owned by the marketplace, do not represent the actual products being sold, and create an external dependency on a third-party service that could change its URL structure or rate limits at any time. Five Unsplash URLs returned HTTP 404 in the live test — broken product images that show a blank placeholder to users.

***Recommendation:** migrate all product images to Cloudinary (already configured in the CSP) once real product photos are available. The next/image component will continue to optimize them, but the source URLs will be owned by the marketplace. Until then, the Unsplash images are acceptable for development but must be replaced before launch.*

6.4 Resource Hints

The homepage includes 8 *preload* directives (4 fonts, 1 stylesheet, 3 images) — good for critical-path optimization. However, it has **zero preconnect or dns-prefetch directives** for the many external domains the site connects to. Adding these would shave 100-300ms off the perceived load time on mobile.

External Domain	Purpose	Recommended Hint
images.unsplash.com	Product images (current)	preconnect
res.cloudinary.com	Product images (future)	preconnect
fonts.gstatic.com	Google Fonts (if used)	preconnect
translate.googleapis.com	Google Translate widget	preconnect
www.googletagmanager.com	GA4 tag manager	preconnect
connect.facebook.net	Facebook Pixel	preconnect
analytics.tiktok.com	TikTok Pixel	preconnect
client.crisp.chat	Crisp chat widget	preconnect
embed.tawk.to	Tawk.to chat widget	preconnect (or remove one widget)

6.5 Core Web Vitals (Estimated)

No field data is available for this pre-launch domain. Lab estimates based on the resource waterfall suggest:

Metric	Estimated	Good Threshold	Likely Status
LCP (Largest Contentful Paint)	~2.5s	≤ 2.5s	⚠ Borderline
FID/INP (Interaction)	~150ms	≤ 200ms	✓ Probably OK
CLS (Cumulative Layout Shift)	~0.05	≤ 0.1	✓ Probably OK
TTFB (Time to First Byte)	~400ms	≤ 800ms	✓ Good (Vercel edge)
Total Blocking Time	~300ms	≤ 200ms	⚠ Above target

CHAPTER 07

7. Security Audit

HTTP security headers, CSP, transport security, and cookie configuration.

This is the strongest area of the site. Security headers are exemplary — HSTS with preload, strict CSP with nonce-based script-src, all OWASP-recommended headers present. The only minor improvements are removing the deprecated X-XSS-Protection header and adding COOP/COEP for defense-in-depth against Spectre-class attacks.

7.1 Security Headers Scorecard

Header	Value	Status	Notes
Strict-Transport-Security	max-age=31536000; includeSubDomains; preload	✓ Excellent	1 year + preload — best practice
Content-Security-Policy	default-src 'self'; script-src 'self' 'nonce-...' 'strict-dynamic' + allowlist	✓ Excellent	Nonce-based with strict-dynamic — modern CSP
X-Frame-Options	SAMEORIGIN	✓ OK	Prevents clickjacking; consider CSP frame-ancestors instead
X-Content-Type-Options	nosniff	✓ OK	Prevents MIME sniffing
Referrer-Policy	strict-origin-when-cross-origin	✓ Excellent	Best practice
Permissions-Policy	camera=(), microphone=(), geolocation=()	✓ Excellent	Locks down sensitive APIs
X-XSS-Protection	1; mode=block	⚠ Deprecated	Removed from modern browsers; can introduce vulnerabilities
Cross-Origin-Opener-Policy	Missing	⚠ Recommended	Add 'same-origin' for Spectre defense
Cross-Origin-Embedder-Policy	Missing	⚠ Recommended	Add 'require-corp' if third-party resources are CORS-protected
Cross-Origin-Resource-Policy	Missing	⚠ Recommended	Add 'same-site' for resource isolation

7.2 Content-Security-Policy Analysis

The CSP is one of the most well-configured I have seen on a Next.js site. It uses a **nonce-based script-src** with *'strict-dynamic'*, which is the modern recommended approach — nonces are rotated per request and *'strict-dynamic'* allows trusted scripts to load their own dependencies without explicit allowlisting. The CSP allows the necessary third-party services (Stripe, PaySky, Paymob, Fawry for payments; Cloudinary for media; Resend for email; Google Translate; the 7 analytics platforms; the 2 chat widgets; the social pixel networks) without being overly permissive.

One concern: the *connect-src* directive allows a large number of third-party domains, which means a compromised script could exfiltrate data to any of these endpoints. This is unavoidable for a site with this many integrations, but it is worth periodically auditing whether all the allowed domains are still actively used. The *frame-src* directive correctly restricts which domains can be embedded as iframes (Stripe, PaySky, Paymob, Tawk.to, Hotjar).

7.3 Cookie Security

The site sets a **csrf-token** cookie with the following attributes: *Secure* (only sent over HTTPS — good), *SameSite=Lax* (prevents CSRF for top-level navigations — good), *Max-Age=86400* (24 hours — reasonable). The cookie does **not** have the *HttpOnly* attribute, which means JavaScript can read it — this is intentional if the cookie is used by client-side CSRF protection, but should be verified. Session cookies (if any) should always be *HttpOnly*.

7.4 HTTPS Enforcement

HSTS is enabled with a 1-year max-age, includeSubDomains, and preload. This means browsers will refuse to connect to the site over HTTP after the first visit, and the site is eligible for the Chrome HSTS preload list (a hardcoded list of HTTPS-only domains shipped with browsers). The site is already serving exclusively over HTTPS, and Vercel automatically redirects HTTP to HTTPS at the edge. No issues here.

7.5 Recommendations

- 1 **Remove X-XSS-Protection header.** It is deprecated, no longer supported in modern browsers, and can introduce cross-site information leakage vulnerabilities. The CSP already provides superior XSS protection.
- 2 **Add Cross-Origin-Opener-Policy: same-origin** to isolate the browsing context group, mitigating Spectre-class side-channel attacks.
- 3 **Add Cross-Origin-Resource-Policy: same-site** to prevent cross-origin resources from being loaded without explicit opt-in.
- 4 **Audit CSP connect-src allowlist** quarterly — remove any domains that are no longer used by the corresponding third-party SDK.
- 5 **Verify HttpOnly attribute** on all session-related cookies. The csrf-token cookie should be *HttpOnly* unless there is a specific client-side reason to read it.
- 6 **Conduct a backend penetration test** before launch — this audit only covers client-side security. The API routes, database queries, and authentication flows need separate review.

CHAPTER 08

8. Design & UX Analysis

Visual hierarchy, navigation, calls-to-action, trust signals, and mobile experience.




Figure 8.1 — Mobile view at 390×844 (iPhone 14 Pro). The hero text and search box are readable, but the dark hero image dominates the small screen.

8.1 Visual Hierarchy & Hero Section

The homepage opens with a full-bleed hero section featuring a fashion model photograph (from Unsplash), overlaid with the kicker *SEASONAL COLLECTION 2026*, H1 *Redefining Urban Elegance*, and two CTAs: **Shop Now** and **Explore Lookbook**. The visual treatment is editorial and fashion-forward — appropriate for the stated positioning — but the H1 text does not communicate what the site is. A first-time visitor seeing *Redefining Urban Elegance* would not immediately know this is a multi-seller Egyptian marketplace.

The two CTAs compete for attention. *Shop Now* routes to /shop (good — clear shopping intent), but *Explore Lookbook* routes to /lookbook, which is a single page that does not appear to be a primary user task. Lookbooks are typically used by fashion brands to showcase collections — they are less relevant on a multi-seller marketplace where the user task is to discover and buy products across categories. Recommend replacing the second CTA with *Browse Categories* or *Become a Seller* (since seller acquisition is a stated goal).

8.2 Navigation Architecture

Top navigation: **Flash Sales | Top Brands | Track Order | Help | يبرع | Start Selling | Sign in**. This is a reasonable information architecture for a marketplace, but it is missing two key e-commerce elements: a **Cart** icon (users have to add items and then look for cart access — currently no visible cart link in the header) and a **Categories** dropdown (the 22 categories are only accessible via the footer or by browsing /shop). Adding these would significantly improve discoverability.

The footer navigation is more complete: **Shop All Products | Categories | Flash Sales | Lookbook | Brands | Sell (Start Selling, Seller Hub, Seller Terms, Affiliate Program) | Help (Help Center, Track My Order, Returns & Refunds, Shipping Policy, Contact Us) | Legal (Privacy Policy, Terms of Service, Seller Terms, Returns Policy)**. The footer is well-organized but the *Contact Us* link points to /contact which returns 404.

8.3 Search & Product Discovery

The header includes a search box with the placeholder *Search products, brands...*. The styling uses white text on a semi-transparent white background (*bg-white/10 border-white/20*), which on the dark hero provides low contrast — approximately 2.1:1, well below the WCAG AA threshold of 4.5:1. This is an accessibility failure and also a usability issue on mobile devices in bright sunlight. Recommend using a solid background or higher-contrast border.

Product discovery happens via three sections on the homepage: **Bestsellers**, **New Arrivals**, and **Recommended for You**. Each shows product cards in a horizontal scrolling layout. The product cards include image, seller name (currently *Local Demo Store* for all), product name, price (in EGP), and an **Add to Cart** button with a cart emoji (🛒). The button text *Add to Cart* + emoji is unusual for Western e-commerce but acceptable in the Egyptian market where emoji usage in commerce is more common.

8.4 Trust Signals

Trust signals are weak across the site. The homepage does not display: a customer count, a seller count (the copy says *Join 100+ Egyptian local brands* but only 1 seller — Demo Store — is visible on the brands page), trust badges (Verisign, McAfee Secure, etc.), payment method icons (Visa, Mastercard, Meeza, Fawry), customer reviews or ratings, or media mentions. For a new marketplace entering a market dominated by Noon and Amazon Egypt, trust

signals are critical — users will not enter payment details on an unknown site without visual proof of legitimacy.

Trust Signal	Status	Recommendation
Customer count badge	✗ Missing	Add once real customers exist (e.g. 'Trusted by 10,000+ Egyptian shoppers')
Seller count badge	⚠ Misleading	Copy says '100+' but only 1 visible seller — fix copy or recruit sellers
Payment method icons	✗ Missing	Add Visa, Mastercard, Meeza, Fawry, InstaPay icons in footer
Security badges	✗ Missing	Add SSL/TLS badge, ideally a third-party trust seal
Customer reviews	✗ Missing	Implement after launch — critical for conversion
Star ratings on products	✗ Missing	No rating UI on product cards or product pages
Media mentions / press	✗ Missing	Add 'As seen in' strip once any press coverage exists
Return policy summary	✗ Missing	Add '7-day returns' badge near Add to Cart buttons
Satisfaction guarantee	✗ Missing	Add 'Authentic Egyptian sellers, verified by Brandy' messaging

8.5 Mobile Experience

The mobile screenshot (Figure 8.1) shows a reasonable mobile layout — the hero text scales down appropriately, the search box collapses to a reasonable size, and the navigation appears to switch to a mobile menu (not directly testable in this audit). The viewport meta tag is correctly set with *width=device-width*, *initial-scale=1*, *maximum-scale=5*, *viewport-fit=cover* — the *maximum-scale=5* allows pinch-to-zoom (good for accessibility, avoids the common anti-pattern of disabling zoom).

The product cards on mobile appear to switch to a single-column layout, which is appropriate. The *Add to Cart* buttons remain tappable. However, the horizontal scrolling product carousels on the homepage (Bestsellers, New Arrivals, Recommended) may have usability issues on mobile — horizontal scroll requires a clear visual indicator (arrows, dots, or partial card peek) which was not visible in the screenshot. Recommend adding visible scroll indicators.

CHAPTER 09

9. Content Quality & Demo Data Problem

The site is heavily populated with placeholder content. This is acceptable for development but must be replaced before launch.

Bottom line: Every product image is from Unsplash. The only seller is Demo Store. Contact details are placeholders. Categories have single-digit inventory. This is a pre-launch site — schedule 2-4 weeks of content population before any marketing push.

9.1 Image Audit: 100% Unsplash Placeholders

The homepage loads 23 images, and **all 23 are sourced from Unsplash** via the next/image proxy. The product detail page (Classic Plush Teddy Bear) loads an Unsplash image of an actual teddy bear, but it is a stock photo — not a photo of the actual product being sold. The brands page shows a single seller (Demo Store) with no logo. The hero image is a fashion model photo from Unsplash — not an Egyptian model, not Brandy-branded, not shot for this marketplace.

This is the single biggest content problem. Stock photography on an e-commerce site destroys trust — users can immediately tell that the product photos are not real, and they will assume the products themselves may not be real either. For a marketplace asking users to enter payment details and wait for delivery, this is fatal.

Furthermore, **5 Unsplash URLs returned HTTP 404** in the live test. The next/image proxy at `/_next/image?url=...` returned 404 for these URLs, which means users see broken image placeholders. The cause is likely that the Unsplash photo IDs were rotated or removed by Unsplash, or the URL parameters changed. This is the inherent risk of depending on a third-party image service for production content.

9.2 Demo Data Audit

Element	Demo Value	Should Be
Seller name (all products)	Local Demo Store / Demo Store	Real Egyptian brand names
Brand name in JSON-LD	Demo Store	Real brand name
Brands page count	1 (Demo Store)	20+ real Egyptian sellers
Women category product count	5	50+ before launch
Men category product count	6	50+ before launch
Other categories (20)	Unknown, likely 0-5 each	20-100+ each
Product names	Classic Plush Teddy Bear, Lavender Pet Grooming Shampoo, High-Speed Power Blender, Electric Drip Coffee Maker	Real products from real sellers

Element	Demo Value	Should Be
Contact email	support@brandy.com	support@lolozozo.shop or similar
Contact phone	+20 123 456 789	Real Egyptian phone number
Hero image	Unsplash fashion model	Brandy-branded hero, ideally Egyptian model
Footer copyright	© 2026 Brandy	© 2026 <actual brand name>
Partner Since badge	PARTNER SINCE 2026	Real partner since dates

9.3 Body Content & Word Count

The homepage body text is approximately **397 words** — short for an e-commerce marketplace homepage. Industry benchmarks suggest 600-1,200 words for a homepage that needs to rank for category keywords like "Egyptian marketplace", "local sellers Egypt", "buy Egyptian products". The current copy is dominated by navigation labels and product names — there is no introductory paragraph explaining what Brandy is, no value proposition statement, no SEO-targeted body content.

The product detail page (Classic Plush Teddy Bear) has the product description *Super soft, huggable classic plush teddy bear made with hypoallergenic materials* — a single sentence. E-commerce product pages should have 100-300 words of description, specifications, materials, care instructions, and shipping info. The current description is too thin to rank for product-name searches and too thin to convince a buyer.

Category pages (Women, Men) have almost no body content — just the category name as H1, a short subtitle, and the product grid. Adding 100-200 words of introductory copy per category would help with SEO and would help users understand what they can expect to find.

9.4 Recommended Content Production Plan

- Seller recruitment sprint (Weeks 1-4):** Recruit 20+ real Egyptian sellers via direct outreach, social media, and partnership with local brand incubators. Each seller should bring 5-20 products.
- Product photography (Weeks 3-6):** Either require sellers to provide product photos (with style guidelines) or set up a centralized photography service. Photos should be on white/neutral backgrounds, multiple angles, and at least 1000×1000px.
- Product description writing (Weeks 4-6):** Either require sellers to write 100-300 word descriptions or hire a copywriter to do so. Include materials, dimensions, care instructions, shipping info.
- Category page copywriting (Week 5):** Write 150-250 words of introductory copy for each of the 22 category pages. Include keywords like "Egyptian", "local sellers", "authentic".
- Homepage content expansion (Week 6):** Add a 200-word "About Brandy" section, a seller spotlight carousel, a customer testimonial section (once reviews exist), and a value proposition block.
- Blog/content marketing (Week 8+):** Start publishing seller stories, Egyptian brand spotlights, and shopping guides. Aim for 2-4 blog posts per month for SEO.

CHAPTER 10

10. Business & Conversion Analysis

Value proposition, conversion funnel, payment options, and growth levers.

10.1 Value Proposition

The site's value proposition is scattered across multiple surfaces and not stated clearly in one place. The meta description says *Discover authentic Egyptian local sellers on Brandy. Shop fashion, electronics, home goods and more from verified Egyptian sellers. Fast delivery across Egypt.* — this is good. But the homepage H1 (*Redefining Urban Elegance*) and hero copy do not reinforce this. A first-time visitor would not know this is a marketplace for **authentic Egyptian sellers** with **verified** status and **fast delivery** from reading the hero section alone.

The strongest value-prop statement on the homepage is the seller pitch: *Join 100+ Egyptian local brands already growing their business. Zero upfront costs — just sign up and start selling.* This is clear and compelling — but it is below the fold and aimed at sellers, not buyers. The buyer-facing value prop needs similar clarity: *Shop authentic Egyptian brands, verified by Brandy, delivered to your door in 2-3 days.*

10.2 Payment Options

The site integrates **four payment gateways**: Stripe (international cards), PaySky (Egyptian gateway), Paymob (Egyptian gateway supporting Meeza, InstaPay, mobile wallets), and Fawry (Egyptian cash-payment network with 30,000+ kiosks). This is excellent coverage for the Egyptian market — Egyptian shoppers use Fawry heavily for cash payments, Paymob for mobile wallets, and card payments are growing but still a minority of e-commerce transactions. Having all four options is a competitive advantage versus smaller Egyptian e-commerce sites that only support one or two.

The CSP also references *accept.paymob.com* in frame-src, confirming Paymob iframe integration. Stripe is referenced in script-src (*js.stripe.com*) and frame-src (*js.stripe.com*) — standard Stripe Checkout or Elements integration. PaySky is similarly referenced. The payment stack appears to be properly configured at the CSP level.

10.3 Conversion Funnel Gaps

Funnel Stage	Status	Gap / Recommendation
Awareness (SEO)	✗ Critical gap	Site cannot rank due to domain config issue (see Ch.4)
Awareness (Social)	✓ Tracking in place	Facebook, TikTok, Snapchat, Pinterest pixels all loaded
Consideration (Product page)	△ Weak	Thin product descriptions, no reviews, no related products visible
Consideration (Trust)	✗ Critical gap	No trust badges, no seller ratings, no security seals
Decision (Cart)	△ Unclear	No visible cart icon in header — users may not know how to view cart
Decision (Checkout)	— Not tested	Requires login; /checkout blocked from crawlers (correct)

Funnel Stage	Status	Gap / Recommendation
Payment	✓ Strong	4 payment gateways including Fawry (cash) — excellent for Egypt
Retention (Reviews)	✗ Missing	No review system visible — critical for repeat purchases
Retention (Loyalty)	✗ Missing	No loyalty program, no wishlist feature visible
Referral (Affiliate)	✓ Exists	Affiliate Program link in footer — good growth lever

10.4 Competitive Positioning

Brandy is entering a market with established players: **Noon Egypt** (regional giant, broad catalog), **Amazon Egypt** (launched 2021, fast delivery), **Jumia Egypt** (Pan-African marketplace), **B.TECH** (electronics specialist), and various category-specific players. To win, Brandy needs to differentiate on the **local seller** angle — authentic Egyptian brands that are not available on the global marketplaces. This is a strong positioning if executed well, but it requires a critical mass of unique sellers and unique products that cannot be found elsewhere.

The current catalog (Demo Store only, ~100 products across 22 categories) is far below the threshold needed to compete. A realistic pre-launch target would be: **50 sellers, 1,000 products, 5+ products in every category**. Below this, the site will feel empty and users will bounce back to Noon or Amazon.

10.5 Growth Levers

- **Affiliate Program:** Already linked in the footer. Activate this with Egyptian content creators (fashion bloggers, TikTok creators) for low-CAC customer acquisition.
- **Seller-driven acquisition:** Each seller brings their own audience. Make it easy for sellers to share their Brandy storefront on social media with a tracked link.
- **WhatsApp Business integration:** Egypt has ~50M WhatsApp users. Add a WhatsApp share button on product pages and consider a WhatsApp Business API for customer support.
- **Cash-on-Delivery (COD):** Egyptian e-commerce is 60%+ COD. Confirm COD is offered at checkout (Paymob and Fawry both support it) and display the COD option prominently on product pages.
- **Instagram Shopping integration:** Connect the product catalog to Instagram Shopping for taggable product posts — free distribution to Instagram's Egyptian user base.
- **Google Shopping feed:** Generate a Google Merchant Center feed from the product catalog for Shopping ads (once the domain config is fixed and products are populated).

CHAPTER 11

11. Mobile & Accessibility

Mobile responsiveness, WCAG 2.1 compliance, keyboard navigation, and screen-reader support.

11.1 Mobile Responsiveness




Figure 11.1 — Mobile viewport at 390×844. The layout adapts but the search box contrast is poor on the dark hero.

The site is built mobile-first with Tailwind CSS (inferred from the class names like *bg-white/10* and the responsive grid layouts). The viewport meta tag is correct, allowing pinch-to-zoom up to 5x. The mobile layout for the homepage stacks the hero text, search box, and CTA buttons vertically — appropriate for one-handed use. The product carousels switch to touch-scroll on mobile, though visible scroll indicators are missing.

Specific mobile concerns: (1) the search box's white-on-translucent styling has poor contrast in bright sunlight (common in Egypt), (2) the *Add to Cart* button with cart emoji (🛒) may render differently on Android vs iOS — verify the emoji renders consistently, (3) the horizontal product carousels need visible scroll affordance (partial card peek or arrow indicators), (4) the mobile menu (hamburger) was not directly testable in this audit but should be verified to contain all key navigation links.

11.2 Accessibility Audit (WCAG 2.1 AA)

WCAG Criterion	Status	Evidence / Fix
1.1.1 Non-text Content	⚠ Partial	1 image missing alt out of 23 — minor; all others have alt text
1.3.1 Info and Relationships	✗ Failed	0 <header> elements; 2 <nav>, 1 <main>, 1 <footer> — missing header landmark
1.4.3 Contrast (Minimum)	✗ Failed	Search box white-on-translucent $\approx$ 2.1:1 contrast (need 4.5:1)
1.4.4 Resize Text	✓ OK	maximum-scale=5 allows zoom up to 500%
2.1.1 Keyboard	— Not tested	Requires manual keyboard walkthrough
2.4.1 Bypass Blocks	✓ OK	Skip to main content link present at top of page
2.4.2 Page Titled	✓ OK	All pages have descriptive <title> tags
2.4.6 Headings and Labels	⚠ Partial	Login and seller-hub pages have no H1
3.1.1 Language of Page	✓ OK	<html lang='en'> set correctly
3.1.2 Language of Parts	✗ Missing	Arabic toggle button 'يبرع' has no lang='ar' attribute
4.1.2 Name, Role, Value	⚠ Partial	20 aria-labels, 0 role attributes — buttons rely on text content
4.1.3 Status Messages	— Not tested	Requires interaction testing

11.3 Landmark Structure

The page has **0 <header> elements** — the top navigation bar is likely wrapped in a <div> instead of a semantic <header> element. This is an accessibility failure: screen readers use landmark elements to navigate pages, and a missing header landmark means screen reader users cannot quickly jump to the navigation. The page does have 2 <nav> elements (good — likely one for main nav, one for footer nav), 1 <main> (good), 1 <footer> (good), and 5 <section> elements (good). Fix: wrap the top navigation bar in a <header> element.

11.4 Internationalization (i18n)

The site has a language toggle button labeled العربية (Arabic for "Arabic") in the top navigation, but no actual Arabic content or routing is implemented — clicking the button likely activates Google Translate (the CSP allows `translate.googleapis.com`). This is a poor user experience for Arabic speakers: machine translation is visibly low-quality, breaks layout, and does not translate images or screenshots.

Recommendation: Implement a proper Arabic localization with RTL layout support. Next.js has excellent *i18n* support via the App Router. Use path-based routing (`/ar/` for Arabic, `/en/` or default for English), add `hreflang` tags, set `dir='rtl'` on the element for Arabic pages, and translate all UI strings and product content. Egyptian Arabic (*ar-EG*) is the target dialect.

CHAPTER 12

12. 30-60-90 Day Action Roadmap

A prioritised plan: fix critical issues in 30 days, prepare for launch in 60, drive growth in 90.

12.1 Days 0-30: Critical Fixes (Pre-Launch Blockers)

These are the issues that must be fixed before the site can be indexed by Google, trusted by users, or competitively positioned. None require significant engineering effort — they are configuration, content, and copywriting fixes.

#	Action	Owner	Effort	Impact
1	Update NEXT_PUBLIC_SITE_URL env var to <code>https://www.lolozozo.shop</code>	Dev	15 min	P0 — fixes domain propagation
2	Redeploy site, verify canonical/OG/sitemap use production domain	Dev	30 min	P0 — confirms fix
3	Update robots.txt Host and Sitemap directives	Dev	5 min	P0 — fixes crawler hints
4	Fix /about and /contact 404s (build pages or remove from sitemap)	Dev/Content	4 hours	P0 — removes dead URLs
5	Replace support@brandy.com and +20 123 456 789 placeholders	Founder	5 min	P0 — user trust
6	Add JSON-LD Organization schema on homepage	Dev	30 min	P1 — rich results
7	Add JSON-LD WebSite schema with SearchAction	Dev	30 min	P1 — sitelinks search box
8	Add canonical tags to all pages	Dev	1 hour	P0 — duplicate content
9	Remove GPTBot/CCBot block in robots.txt	Dev	1 min	P2 — AI search visibility
10	Decide on brand name (Brandy vs Lolozo) and apply consistently	Founder	2 hours	P0 — brand identity
11	Set up Google Search Console for <code>www.lolozozo.shop</code>	Founder	30 min	P0 — indexation tracking
12	Submit corrected sitemap to GSC	Founder	5 min	P0 — discovery
13	Add preconnect hints for external domains	Dev	15 min	P1 — performance
14	Remove deprecated X-XSS-Protection header	Dev	1 min	P3 — code hygiene
15	Add Cross-Origin-Opener-Policy header	Dev	5 min	P2 — security

12.2 Days 31-60: Pre-Launch Content Preparation

With the critical fixes in place, focus shifts to populating the site with real content. This is the work that turns a development site into a launchable marketplace. Plan for 4 weeks of dedicated content work — seller recruitment,

product photography, copywriting, and category page development.

#	Action	Owner	Effort	Impact
1	Recruit first 20 real Egyptian sellers (direct outreach, social media)	Founder/BD	4 weeks	P0 — catalog critical mass
2	Onboard 200+ real products across 22 categories	Sellers + Ops	4 weeks	P0 — catalog depth
3	Replace all Unsplash images with real product photos	Sellers + Dev	4 weeks	P0 — trust
4	Write 100-300 word descriptions for every product	Sellers + Copywriter	3 weeks	P1 — conversion + SEO
5	Write 150-250 word intro copy for each of 22 category pages	Copywriter	1 week	P1 — SEO
6	Add 200-word 'About Brandy' section to homepage	Copywriter	2 hours	P2 — value prop clarity
7	Implement cart icon in header with item count badge	Dev	4 hours	P1 — UX
8	Add 'Categories' dropdown in header navigation	Dev	3 hours	P1 — UX
9	Add payment method icons (Visa, Mastercard, Meeza, Fawry) in footer	Dev/Designer	2 hours	P1 — trust
10	Improve search box contrast (fix WCAG failure)	Dev/Designer	1 hour	P1 — accessibility
11	Wrap top nav in <header> element	Dev	30 min	P2 — accessibility
12	Consolidate to one chat widget (Crisp or Tawk.to)	Dev	2 hours	P3 — performance
13	Audit and reduce analytics stack (remove unused pixels)	Dev	4 hours	P3 — performance
14	Set up @next/bundle-analyzer, identify largest chunks	Dev	2 hours	P2 — performance
15	Replace hero image with Brandy-branded Egyptian-model photo	Designer	1 day	P2 — brand

12.3 Days 61-90: Launch & Growth

With a populated, accessible, and trustworthy site, the focus shifts to growth — getting real users, collecting feedback, and iterating. By Day 60 the site should be soft-launched (sellers notified, small paid social campaign). By Day 90 the site should be ready for a public launch with a marketing push.

#	Action	Owner	Effort	Impact
1	Implement product review system (post-purchase email + review form)	Dev	1 week	P0 — trust + SEO
2	Add star rating UI to product cards and product pages	Dev	3 days	P1 — conversion
3	Implement related products on product pages	Dev	3 days	P1 — AOV
4	Implement wishlist feature	Dev	3 days	P2 — retention

#	Action	Owner	Effort	Impact
5	Implement Arabic localization (path-based /ar/, RTL, hreflang)	Dev + Translator	3 weeks	P1 — market coverage
6	Activate Affiliate Program, recruit 10 Egyptian creators	BD	2 weeks	P1 — acquisition
7	Set up Google Shopping feed for product ads	Dev + Founder	1 week	P2 — paid acquisition
8	Connect Instagram Shopping catalog	Dev + Founder	3 days	P2 — social commerce
9	Add WhatsApp share button on product pages	Dev	1 day	P2 — viral
10	Start blog/content marketing (2-4 posts per month)	Copywriter	ongoing	P2 — SEO
11	Set up Core Web Vitals field data collection (web-vitals lib)	Dev	1 day	P2 — performance monitoring
12	A/B test hero CTAs (Shop Now vs Browse Categories vs Become Seller)	Dev + Founder	2 weeks	P2 — conversion
13	Implement post-purchase email flows (Resend)	Dev	1 week	P2 — retention
14	Soft launch: notify sellers, small paid social campaign (~\$500)	Founder	1 week	P0 — first traffic
15	Public launch: PR, influencer campaign, paid ads (~\$5,000)	Founder + Marketing	2 weeks	P0 — scale

CHAPTER 13

13. Quick Wins — Fix This Week

The top 10 actions ranked by impact-to-effort ratio. Each can be completed in under 1 hour.

If you only have time for 10 fixes this week, do these. Combined, they would take roughly 6-8 hours of developer time and would resolve the most visible issues on the site. Total estimated impact: site becomes indexable by Google, contact information is real, structured data is present, AI search engines can crawl, and basic performance hints are in place.

#	Quick Win	Effort	Impact	How
1	Update NEXT_PUBLIC_SITE_URL to <code>https://www.lolozozo.shop</code> in Vercel env vars, redeploy	15 min	P0	Vercel dashboard → Project Settings → Environment Variables
2	Update robots.txt Host: and Sitemap: to lolozozo.shop (if hardcoded)	5 min	P0	Edit app/robots.ts or public/robots.txt
3	Fix /about and /contact 404s — either build placeholder pages or remove from sitemap.xml	1 hour	P0	Add app/about/page.tsx and app/contact/page.tsx OR remove from sitemap
4	Replace support@brandy.com with support@lolozozo.shop (or remove)	5 min	P0	Edit footer component
5	Replace +20 123 456 789 with real phone number (or remove)	5 min	P0	Edit footer component
6	Add Organization JSON-LD schema to homepage layout	30 min	P1	Add script tag in app/layout.tsx
7	Add WebSite JSON-LD schema with SearchAction for sitelinks search box	30 min	P1	Add to homepage page.tsx
8	Remove GPTBot and CCBot disallow from robots.txt	1 min	P2	Edit robots.txt
9	Add preconnect hints for images.unsplash.com, fonts.gstatic.com, googletagmanager.com	5 min	P1	Add <code><link rel='preconnect'></code> in
10	Remove deprecated X-XSS-Protection header	1 min	P3	Edit next.config.js headers()

Bonus quick win: decide on the brand name (Brandy or Lolozo) and update the title tag, footer copyright, JSON-LD seller name, and email signature consistently. This is a 30-minute decision that prevents months of confusion.

13.2 Visual: Quick Wins Impact Matrix

The matrix below plots each quick win by impact (vertical) and effort (horizontal). Items in the top-left quadrant (high impact, low effort) should be done first — items 1, 2, 4, 5, 8 from the table above all sit in this quadrant.

	Low Effort (<30 min)	Medium Effort (30-60 min)	High Effort (>1 hour)
High Impact (P0/P1)	#1, #2, #4, #5, #9 (env + robots + contact + preconnect)	#6, #7 (JSON-LD Organization + WebSite)	#3 (build /about + /contact pages)
Medium Impact (P2)	#8 (unblock GPTBot)	—	—
Low Impact (P3)	#10 (remove X-XSS-Protection)	—	—

CHAPTER 14

14. Appendix — Full Findings Inventory

Complete catalogue of all 60+ findings identified in this audit. Use the accompanying Excel file for filterable, sortable issue tracking.

The full findings inventory is provided as a companion Excel file: **brandy_lolozozo_audit_checklist.xlsx**. The Excel file contains four sheets:

- **Summary** — overall scores per category, P0/P1/P2/P3 issue counts, completion tracker.
- **Issue Tracker** — every finding with ID, category, severity, impact, effort, evidence, recommended fix, and status. Filterable by category and severity; sortable by impact/effort.
- **Quick Wins** — top 15 issues sorted by impact-to-effort ratio (high impact + low effort first).
- **Roadmap** — 30-60-90 day plan with owner, effort estimate, and target completion date.

14.1 Findings by Severity

Severity	Count	Description	Examples
P0 (Critical)	12	Site-breaking issues that block launch or indexing	Wrong domain config, placeholder contact, broken sitemap URLs
P1 (High)	18	Significant issues that hurt SEO, conversion, or UX	No JSON-LD on homepage, no canonical, weak trust signals, demo images
P2 (Medium)	22	Important issues to fix before/shortly after launch	No hreflang, low inventory, missing cart icon, performance hints
P3 (Low)	12	Code hygiene and minor optimizations	Deprecated headers, duplicate chat widgets, redundant analytics

14.2 Findings by Category

Category	P0	P1	P2	P3	Total
SEO & Meta	5	6	3	1	15
Technical Performance	0	2	4	3	9
Security	0	0	2	1	3
Design & UX	1	3	4	1	9
Content Quality	3	4	2	0	9
Business / Conversion	2	2	4	3	11

Category	P0	P1	P2	P3	Total
Mobile / Accessibility	0	1	2	2	5
Branding / Identity	1	0	1	1	3
Total	12	18	22	12	64

Next step: Open *brandy_lolozozo_audit_checklist.xlsx* and work through the *Issue Tracker* sheet in priority order. Update the *Status* column as you fix each issue. Re-run this audit in 30 days to verify progress and capture any new issues introduced by the fixes.

End of report. Generated on June 19, 2026 by automated website audit pipeline. All findings are based on live-crawl data captured from www.lolozozo.shop on the audit date.