



AssetProof AUDIT

PHOTOGRAPHIC CONDITION INSPECTION

Sample Property B — Two-bedroom house, City Bowl

Room by room, surface by surface, with the photographic evidence — including everything that is wrong with it.

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

FINDINGS CARRIED

230 across 11 areas



AssetProof

Turning physical assets into structured, defensible digital evidence.
www.AssetProofSolutions.com · WhatsApp +27 82 221 4313



1 About this record

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

This is a **Photographic Condition Inspection**: a room-by-room, surface-by-surface record of a two-bedroom house made on one date, before a long-term letting and for the insurance file. It covers **every surface, not only the contents** — walls, ceilings, cornices, floors, skirtings, window surrounds, doors, blinds, joinery, sanitaryware, fittings and the external fabric — and it carries **every one of the 230 findings** recorded across 11 areas, with the photographic plate that supports each one.

It is deliberately unflattering. A condition record that only shows a property at its best is worthless to the person who has to rely on it later. The pool in this house was severely green and algae-affected with sediment on the submerged steps; the leather sofa is heavily worn; the dishwasher door seal is torn. All of that is in here, in the same detail as everything that is sound. That is the point of the document: at the end of the tenancy, or at a claim, both sides are arguing from the same page.

2 Property profile

Property	Sample Property B — two-bedroom house	Reference	SAMPLE-B
Location	City Bowl, Cape Town	Type	House — 2 bedroom / 2 bathroom, part-furnished
Purpose of record	Long-term letting baseline and insurance evidence	Furnishing at inspection	Part-furnished — mattresses bare, most wardrobes and cupboards empty
Inspection date	20 July 2026	Prepared by	AssetProof
Owner	Private owner — details withheld for publication	Basis	Visual inspection supported by the photographic record

3 At a glance

11 AREAS INSPECTED	118 SURFACES SCHEDULED	230 FINDINGS RECORDED	148 PLATES IN THIS RECORD
------------------------------	----------------------------------	---------------------------------	-------------------------------------

4 How to read this record

Every finding carries a severity. Severity describes the **consequence** of the observation, not the cost of putting it right.

SEVERITY	WHAT IT MEANS	COUNT
CRITICAL	A safety risk or an immediate threat to the fabric. Act before occupation.	0
HIGH	Safety, health or urgency. Treat before the property is let, photographed or occupied.	13
MEDIUM	Functional. It works, or nearly works, but it needs attention and then monitoring.	57
LOW	Cosmetic, or fair wear and tear. Recorded so that it cannot later be called damage.	105
SOUND	Inspected and found in good order. A negative finding remains a finding.	29
RE-CHECK	Inspected, but the detail was not established with confidence. Listed for closer inspection.	26
Total findings carried		230

5 Findings by area

Where the record is thickest is where the property needs the most attention.

AREA	ITEMS	SURFACES	HIGH	MEDIUM	LOW	ALL FINDINGS
Exterior, boundary & entrance	28	14	1	8	8	17
Pool courtyard	23	12	9	5	5	23
Outdoor courtyard & braai	35	12	0	12	14	28
Garage, laundry & storage	84	12	2	14	14	36
Kitchen	54	12	0	6	20	36
Lounge & dining	46	9	1	7	22	36
Main bedroom suite & en-suite	40	13	0	3	3	14
Bedroom 2	13	10	0	1	9	17
Second bathroom	17	12	0	0	4	13
Guest powder room	4	12	0	0	0	0
Rooms whose attribution is not resolved	14	0	0	1	6	10
Total	358	118	13	57	105	230

6 Priority findings

Everything assessed as a safety, health or urgency matter, in one place. Each is repeated in its area below with the surrounding detail.

REF	AREA	FINDING	SEVERITY	PLATE
F012	Pool courtyard	Pool water appears green/algae-affected, not clear	HIGH	Plate 005

REF	AREA	FINDING	SEVERITY	PLATE
F014	Pool courtyard	Pool water green/algae-tinted (visible in background)	HIGH	Plate 006
F016	Pool courtyard	Pool water severely green and murky, algae bloom	HIGH	Plate 007
F017	Pool courtyard	Dark sediment/algae buildup visible on submerged pool steps and floor	HIGH	Plate 007
F020	Exterior & entrance	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section	HIGH	Plate 004
F022	Pool courtyard	Pool water green/algae-tinted	HIGH	Plate 008
F024	Pool courtyard	Pool water is green/algae-affected, not clear	HIGH	Plate 009
F025	Pool courtyard	Dark staining/algae marks on pool wall and floor	HIGH	Plate 009
F107	Lounge	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone	HIGH	Plate 095
F116	Laundry / utility & storage	Exposed orange and black cabling around the alarm control box, not fully enclosed	HIGH	Plate 045
F151	Laundry / utility & storage	Scattered small dark speckled marks (possible dirt or mould) on left interior panel	HIGH	Plate 050
F228	Pool courtyard	Pool water is green and murky, indicating algae growth or neglected water treatment	HIGH	Plate 010
F230	Pool courtyard	Pool water is green/murky, consistent with algae or lack of maintenance	HIGH	Plate 011

7 The pool, stated plainly

The pool, stated plainly

At inspection the plunge pool water was **severely green and murky with an active algae bloom**, and dark sediment had settled on the submerged steps and floor. The white pool surround carried water staining and hairline cracking. The pool is **not swimmable and must not be presented as ready for use** until it has been treated, cleared and re-inspected. The pump, filtration and backwash equipment do not appear anywhere in the record and remain to be documented separately.

8 Exterior, boundary & entrance

The corner plot, its boundary walls, the motorised entrance gate, the driveway paving, the garden and the external elevations of the house.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Boundary walls, fencing & electric perimeter	GOOD	Clean	Inspected; no defect observed.
Gates, trellis & security installation	GOOD	Clean	Muddy/bare patches in lawn between stepping stones; One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel; Wall paint appears slightly scuffed near gate track. (F146, F147, F149)
Facade, parapet & roofline	ATTENTION	Clean	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section; Visible plaster/render texture patchiness on wall surface. (F020, F011)
Paths, driveway & paving	FAIR	Clean	Driveway paving stained and weathered with dark patches; Driveway paving stained/weathered; Driveway paving stained/weathered. (F162, F175, F176)
Garden	FAIR	Clean	Patchy/thin lawn areas; Hairline crack in concrete riser near planter; Muddy/bare patches in lawn between stepping stones. (F007, F145, F146)
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	ATTENTION	Clean	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section; Rough, unpainted/unfinished concrete patch contrasting with surrounding painted walls; Visible plaster/render texture patchiness on wall surface. (F020, F021, F011)
Floor	GOOD	Clean	Inspected; no defect observed.
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	GOOD	Clean	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel; Wall paint appears slightly scuffed near gate track; Gate surface shows scuffed/worn patina. (F147, F149, F163)
Windows — sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	GOOD	Clean	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel; Wall paint appears slightly scuffed near gate track. (F147, F149)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Power points, switches & wiring	GOOD	Clean	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel. (F147)

9 Exterior, boundary & entrance — findings

17 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F020	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section	HIGH	Plate 004
F007	Patchy/thin lawn areas	MEDIUM	—
F021	Rough, unpainted/unfinished concrete patch contrasting with surrounding painted walls	MEDIUM	Plate 004
F144	Dark algae/moisture staining on concrete steps	MEDIUM	Plate 002
F145	Hairline crack in concrete riser near planter	MEDIUM	Plate 002
F162	Driveway paving stained and weathered with dark patches	MEDIUM	—
F175	Driveway paving stained/weathered	MEDIUM	—
F176	Driveway paving stained/weathered	MEDIUM	—
F177	Paving stones heavily stained with dark patches/discolouration throughout	MEDIUM	Plate 001
F011	Visible plaster/render texture patchiness on wall surface	LOW	Plate 003
F146	Muddy/bare patches in lawn between stepping stones	LOW	Plate 002
F147	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel	LOW	—
F148	Driveway pavers show uneven weathering/staining across squares	LOW	—
F149	Wall paint appears slightly scuffed near gate track	LOW	—
F163	Gate surface shows scuffed/worn patina	LOW	—
F178	Retaining wall shows surface staining	LOW	Plate 001
F179	Paving stained/discoloured with dark patches	LOW	—

10 Exterior, boundary & entrance — items and fittings recorded

28 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Street-frontage boundary wall, sage-green painted plaster/render	1	Good - render intact and evenly painted, no cracks or stains visible from street distance; wall paint appears slightly scuffed near the sliding gate track	
Electric fence system to boundary wall - multiple black strand wires on white/black insulator standoff brackets, running the full length of the wall, with a small yellow warning sign	1	Good - wires taut and standoffs in place; no broken strands or leaning brackets visible. Yellow warning sign text not legible at inspection resolution	
White satellite dish mounted on roof pillar	1	Good - dish and arm intact, no visible corrosion at this distance	
Motorised sliding driveway gate - dark-brown horizontal wood-slat panels in a galvanised steel surround, four bays divided by galvanised vertical posts, running on a ground track	1	Fair - the top-left bay is a distinctly lighter, newer-looking wood tone than the uniformly dark-stained panels beside it, suggesting a repaired or replaced panel; gate surface shows scuffed/worn patina	
Sliding gate motor unit, mounted at the base of the gate at its right end	1	Good - housing in place, no damage or corrosion visible	
Driveway paving - large square exposed-aggregate/textured concrete pavers laid in a grid	1	Poor - paving stones heavily stained with dark patches and algae-type staining throughout, with marked colour variation and uneven weathering between squares	Plate 001
Concrete steps from the paved driveway area down to the lawn - three risers, grooved anti-slip nosing strips, with a wood-look tiled bench/step ledge at the base	1	Fair - dark algae/moisture staining across the steps, hairline crack in the concrete riser near the planter, steps stained and worn	Plate 002, Plate 001
Low sage-green rendered retaining wall / raised planter ledge cast into the boundary wall alongside the driveway	1	Fair - surface staining on the retaining wall render	Plate 002, Plate 001
Driveway planter display - terracotta and plastic pots holding aeonium/echeveria-type succulents and aloes, with driftwood/root decor pieces	1	Good - plants in leaf, pots intact	
Prickly-pear (Opuntia) cactus and a small green succulent in metal/ceramic pots on the low wall beside the steps, with loose driftwood pieces set in beside them	2	Good - plants healthy, pots intact	Plate 002
Small teal-blue plant pots with seedlings, placed on the edges of the concrete steps	2	Good - pots intact, seedlings in leaf	Plate 001

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Front garden bed and lawn - aloe/agave succulents, a large aeonium-type plant with dark maroon rosettes on bare woody stems, and potted succulents on a low stone/brick planter	1	Fair - patchy/thin lawn areas; planted material otherwise in leaf	
Teal-green wheelie-bin-style container standing beside the front garden planter	1	Good - body intact, no damage visible	
Dark grey plastic wheelie bins standing on the driveway paving, the right-hand one hand-painted in white lettering 'the property [locality redacted]'	2	Good - bodies and lids intact, no cracks visible	
Side passage exterior wall, sage/pale-green painted plaster	1	Fair - visible plaster/render texture patchiness across the wall surface	Plate 003
Green plastic cylindrical rainwater/water storage tank standing in the side passage against the wall	1	Good - tank body intact, no splits or leaks visible	Plate 003
White PVC downpipes and surface plumbing running down the side passage wall	1	Good - pipework in place and secured, no visible breaks	Plate 003
Black wrought-iron side gate in the side passage	1	Good - gate in place, no rust or damage noted	Plate 003
Corrugated metal roof over the lean-to/shed structure at the far end of the side passage	1	Fair - sheeting in place; surface condition not assessable at the distance and angle available	Plate 003
Small white wall-mounted sensor/box on the side passage wall	1	Good - housing intact, no damage visible	Plate 003
Flat rooftop terrace - floor coated in grey waterproofing paint beneath an overhanging grey-painted concrete slab	1	Poor - dark damp-like staining with moss/algae discolouration on the unfinished concrete wall section, and a rough, unpainted/unfinished concrete patch contrasting with the surrounding painted walls	Plate 004
Roof-level pipe manifold - cluster of blue and copper-coloured pipes with valves and fittings mounted at the ceiling/wall junction under the overhang	1	Good - pipework and valves in place, no leaks or corrosion visible	Plate 004
Black wall-mounted light fixture and adjacent electrical junction/inspection cover on the roof terrace	1	Good - fixture and cover in place, no damage visible	Plate 004
Pale-green access hatch/door in the roof-terrace wall, standing open over a recessed water meter or valve assembly	1	Good - hatch and recessed assembly intact; hatch found standing open at inspection	Plate 004
Folding clothes-drying rack standing on the roof terrace	1	Good - surround intact, no damage visible	Plate 004

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Washing-line wires strung across the roof terrace, with a TV aerial/satellite mount alongside	1	Good - lines in place, no sagging or breaks visible	Plate 004
Black burglar bars to the window in the cream/beige wall at roof-terrace level	1	Good - bars secure in the surround, no rust noted	Plate 004
Boundary outlook from the roof terrace – mature planting and rooflines beyond the boundary wall, recorded for context	1	Good - no defect observed to anything within the property boundary	

11 Exterior, boundary & entrance – photographic plates



Plate 001 Driveway paving - large square exposed-aggregate/textured concrete pavers laid in a grid



Plate 002 Concrete steps from the paved driveway area down to the lawn




Plate 003 Side passage exterior wall, sage/pale-green painted plaster




Plate 004 Flat rooftop terrace

12 Pool courtyard

The enclosed courtyard holding the plunge pool, its surround, the loungers and the rainwater tank.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Pool shell, coping & water	ATTENTION	Clean	Pool water appears green/algae-affected, not clear; Pool water green/algae-tinted (visible in background); Pool water severely green and murky, algae bloom. (F012, F014, F016)
Paving, deck & steps	ATTENTION	Clean	Dark sediment/algae buildup visible on submerged pool steps and floor; Hairline cracks in the white pool-surround paving; Grime/staining on paving surface. (F017, F018, F019)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Boundary walls	GOOD	Clean	Inspected; no defect observed.
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	ATTENTION	Clean	Dark staining/algae marks on pool wall and floor; Scuff marks and dirt on white lounge chair surfaces; General grime and weathering to the metal body of the exterior wall lantern. (F025, F015, F029)
Floor	ATTENTION	Clean	Dark sediment/algae buildup visible on submerged pool steps and floor; Dark staining/algae marks on pool wall and floor. (F017, F025)
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	FAIR	Clean	Dust/grime buildup on the white security gate bars. (F009)
Windows – sashes, sills & surrounds	GOOD	Clean	Small debris/insect nest clump inside one glass pane of the lantern; Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection; Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection. (F028, F218, F219)
Blinds & window coverings	GOOD	Clean	Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection; Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection. (F218, F219)
Light fittings & ceiling roses	GOOD	Clean	Small debris/insect nest clump inside one glass pane of the lantern; General grime and weathering to the metal body of the exterior wall lantern. (F028, F029)
Power points, switches & wiring	GOOD	Clean	Inspected; no defect observed.

13 Pool courtyard – findings

23 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F012	Pool water appears green/algae-affected, not clear	HIGH	Plate 005
F014	Pool water green/algae-tinted (visible in background)	HIGH	Plate 006
F016	Pool water severely green and murky, algae bloom	HIGH	Plate 007

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F017	Dark sediment/algae buildup visible on submerged pool steps and floor	HIGH	Plate 007
F022	Pool water green/algae-tinted	HIGH	Plate 008
F024	Pool water is green/algae-affected, not clear	HIGH	Plate 009
F025	Dark staining/algae marks on pool wall and floor	HIGH	Plate 009
F228	Pool water is green and murky, indicating algae growth or neglected water treatment	HIGH	Plate 010
F230	Pool water is green/murky, consistent with algae or lack of maintenance	HIGH	Plate 011
F009	Dust/grime buildup on the white security gate bars	MEDIUM	Plate 012
F013	Water staining/discolouration on the white pool surround	MEDIUM	Plate 005
F018	Hairline cracks in the white pool-surround paving	MEDIUM	Plate 007
F019	Grime/staining on paving surface	MEDIUM	Plate 007
F023	Hairline crack visible in paved step/platform near water butt	MEDIUM	Plate 008
F010	Dry needles/debris scattered on the artificial turf	LOW	Plate 012
F015	Scuff marks and dirt on white lounge chair surfaces	LOW	Plate 006
F026	General grime marks on paving stones	LOW	Plate 009
F028	Small debris/insect nest clump inside one glass pane of the lantern	LOW	Plate 016
F029	General grime and weathering to the metal body of the exterior wall lantern	LOW	Plate 016
F218	Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection	RE-CHECK	Plate 013
F219	Exterior wall and step surfaces beyond the window not established through the glazing and blind; listed for closer inspection	RE-CHECK	Plate 014

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F229	Window glass is heavily covered in dust/grime spots, reducing visibility	RE-CHECK	Plate 011
F027	Textured wall render reads rough and uneven — a cast finish rather than a defect	SOUND	Plate 015

14 Pool courtyard — items and fittings recorded

23 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Small octagonal plunge pool - shell, submerged steps and water	1	Poor - pool water severely green, murky and opaque, an algae bloom; dark sediment/algae buildup visible on the submerged steps and pool floor; dark algae staining on the pool walls. Water was not clear at any point in the record	Plate 005, Plate 006, Plate 007, Plate 008, Plate 009, Plate 010, Plate 011
Pool coping and paved surround - white-painted concrete coping with white stone/tile paving	1	Poor - hairline cracks visible in the white pool-surround paving, grime and dark staining on several paving stones, and water-staining discolouration on the white coping	Plate 007, Plate 009, Plate 010, Plate 011
Artificial turf (astro turf) ground covering to the pool courtyard	1	Fair - turf laid flat and complete; dry pine needles and loose debris scattered across the surface at inspection	Plate 005, Plate 006, Plate 008, Plate 012, Plate 009, Plate 013, Plate 014
White plastic sun-lounger chairs with adjustable slatted backrests, one fitted with caster wheels on its front legs	2	Fair - scuff marks and light dirt visible on the white plastic surfaces of both loungers	Plate 006, Plate 008, Plate 012, Plate 013, Plate 014
White-painted concrete steps leading up from the courtyard to the side door	1	Good - three to four risers, edges intact, no cracking noted	Plate 005, Plate 006, Plate 008, Plate 013, Plate 014
Courtyard side door/gate - dark wood-toned vertical planks in a galvanized metal surround, set into the boundary wall	1	Good - planks and surround intact, no rot or rust noted	Plate 005, Plate 006, Plate 013, Plate 014
Dark grey wall-mounted post box/mailbox beside the courtyard gate	1	Good - housing intact, no damage visible	Plate 005, Plate 006
Courtyard boundary walls - sage-green painted render enclosing two sides, with small drain/weep holes near the base	1	Good - render intact and evenly painted, no cracks or staining recorded on these wall faces	Plate 005, Plate 006, Plate 008, Plate 012
Electric fence strand wires running along the top of the courtyard boundary wall	1	Good - wires in place along the full run, no broken strands or leaning brackets visible	Plate 005, Plate 006, Plate 008, Plate 012

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Black wrought-iron lantern wall lights on the courtyard-facing house wall - square frosted-glass shades divided into a 3x3 grid by black metal muntins, on curled scroll brackets, one larger and one smaller	2	Fair - a small brown debris clump (possibly an insect nest) is adhered to the inside of one frosted glass pane, and there is general grime and weathering on the metal surround	Plate 005, Plate 008, Plate 009, Plate 015, Plate 016
White-painted expandable concertina security gate covering the sliding glass door onto the courtyard	1	Fair - dust and grime buildup on the white security gate bars; gate fully extended and latched at inspection	Plate 005, Plate 008, Plate 016, Plate 012
Sliding glass door from the house onto the courtyard, white aluminium surround	1	Good - glazing and surround intact, no cracks noted; door standing open at inspection	Plate 005, Plate 008
Black plastic water butt/rainwater container standing on the raised paved step beneath the downpipe	1	Good - container body intact, no splits visible	Plate 008
Rainwater downpipe serving the courtyard - black plastic hopper box on the wall feeding a white PVC pipe run	1	Good - hopper and pipe in place and connected	Plate 008, Plate 009
White-painted low step/platform running along the base of the house in the courtyard	1	Fair - hairline crack visible in the paved step/platform near the water butt	Plate 005, Plate 008
Dark ceramic/stone garden ornaments standing on the paving at the base of the courtyard wall - one vase and one lantern-shaped ornament	2	Good - both ornaments intact, no chips or cracks visible	Plate 005, Plate 006, Plate 007
White PVC pool pipe (skimmer/equipment line) lying across the corner of the pool surround	1	Fair - pipe lying loose across the paved surround rather than fixed or buried	Plate 007, Plate 009
Small yellow plastic pool test-kit vial floating at the pool edge	1	Good - vial intact	Plate 007, Plate 010
White security/burglar bars to the courtyard-facing windows - vertical bars and a white diamond-pattern panel	1	Good - bars secure in their surrounds, no rust or distortion noted	Plate 009, Plate 016, Plate 010
Courtyard-facing window glazing behind the security bars	1	Poor - the window glass is heavily covered in dozens of dust and grime specks across the pane, giving a hazy appearance and materially reducing visibility through it	Plate 011
White-framed window with white-painted expandable concertina security gate on the courtyard elevation	1	Good - window surround and gate intact; lattice fully extended	Plate 016
Tiled pitched roof edge with white fascia and gutter trim above the courtyard	1	Good - tiles and fascia trim in place, no sagging or missing sections visible	Plate 009

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Small rectangular grey wall-mounted light fixture above the courtyard door	1	Good - fixture in place, no damage visible	Plate 013

15 Pool courtyard – photographic plates



Plate 005 Small octagonal plunge pool - shell, submerged steps and water



Plate 006 Small octagonal plunge pool - shell, submerged steps and water



Plate 007 Small octagonal plunge pool - shell, submerged steps and water



Plate 008 Small octagonal plunge pool - shell, submerged steps and water



Plate 009 Small octagonal plunge pool - shell, submerged steps and water




Plate 010 Small octagonal plunge pool - shell, submerged steps and water



Plate 011 Small octagonal plunge pool - shell, submerged steps and water



Plate 012 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 013 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 014 Artificial turf (astroturf) ground covering to the pool courtyard



Plate 015 Black wrought-iron lantern wall lights on the courtyard-facing house wall



Plate 016 Black wrought-iron lantern wall lights on the courtyard-facing house wall

16 Outdoor courtyard & braai

The covered deck, the built-in braai and prep counter, the outdoor lounge suite and the security trellis to the rear entrance.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Braai, flue & prep counter	FAIR	Clean	Rust on wire grill basket; Interior of wall niches left as bare unpainted cement/plaster, unfinished look; Soot and ash residue built up inside firebox and on flip-down shelf. (F136, F140, F137)
Paving, deck & steps	FAIR	Clean	Weathered, discoloured/algae-stained wood on the step edging below the deck; Concrete paver steps stained and worn; Worn/rough concrete texture on the paving/step base. (F003, F170, F004)
Boundary walls	FAIR	Clean	Visible horizontal crack or joint line in the low boundary wall render. (F128)
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	FAIR	Clean	Visible horizontal crack or joint line in the low boundary wall render; Interior of wall niches left as bare unpainted cement/plaster, unfinished look; Dirt/scuff mark on green painted pillar beside braai. (F128, F140, F138)
Floor	GOOD	Clean	Dirt/staining in patio slab grout lines; Staining on paved tiles; Floor tiles appear wet/reflective near doorway. (F001, F129, F172)
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	FAIR	Clean	General soiling and creasing on cushion covers consistent with outdoor weathering; Floor tiles appear wet/reflective near doorway. (F131, F172)
Windows — sashes, sills & surrounds	GOOD	Clean	Distinct circular amber/orange stain (resin or spill residue) on/under the glass table top corner; Glass tabletop has light dust/smudging. (F134, F143)
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	GOOD	Clean	Light general wear on wicker weave visible but no breaks; Glass tabletop has light dust/smudging. (F133, F143)
Power points, switches & wiring	GOOD	Clean	Inspected; no defect observed.

17 Outdoor courtyard & braai — findings

28 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F002	Patchy/thin grass in lawn area	MEDIUM	—
F003	Weathered, discoloured/algae-stained wood on the step edging below the deck	MEDIUM	Plate 018
F127	Patchy, weedy, unmown lawn with bare soil patches	MEDIUM	—
F128	Visible horizontal crack or joint line in the low boundary wall render	MEDIUM	—
F130	Dark stain/soiling on seat cushion fabric	MEDIUM	Plate 020
F131	General soiling and creasing on cushion covers consistent with outdoor weathering	MEDIUM	Plate 020
F136	Rust on wire grill basket	MEDIUM	Plate 017
F139	Exposed unconnected plumbing pipe with no fixture attached	MEDIUM	Plate 026
F140	Interior of wall niches left as bare unpainted cement/plaster, unfinished look	MEDIUM	Plate 026
F142	Dark stain/weathering at one wooden corner joint of the coffee table	MEDIUM	Plate 022
F170	Concrete paver steps stained and worn	MEDIUM	—
F171	Patchy lawn with bare/muddy areas	MEDIUM	—
F001	Dirt/staining in patio slab grout lines	LOW	—
F004	Worn/rough concrete texture on the paving/step base	LOW	Plate 018
F129	Staining on paved tiles	LOW	—
F132	Mild creasing/wrinkling on cushion covers	LOW	Plate 021
F133	Light general wear on wicker weave visible but no breaks	LOW	Plate 021
F134	Distinct circular amber/orange stain (resin or spill residue) on/under the glass table top corner	LOW	Plate 025
F135	Adjacent whitish-green residue patch near the same corner	LOW	Plate 025
F137	Soot and ash residue built up inside firebox and on flip-down shelf	LOW	Plate 017
F138	Dirt/scuff mark on green painted pillar beside braai	LOW	Plate 017

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F141	Visible dirt/grime staining on the seat cushion of the central armchair	LOW	Plate 022
F143	Glass tabletop has light dust/smudging	LOW	Plate 022
F164	Lawn has visible bare and muddy patches	LOW	—
F169	Wooden step edging shows heavy weathering/staining, dark patches	LOW	—
F172	Floor tiles appear wet/reflective near doorway	LOW	Plate 023
F173	Surface condition at this position not established; listed for closer inspection	RE-CHECK	—
F174	Patio surface detail not established in fine detail; listed for closer inspection	RE-CHECK	Plate 019

18 Outdoor courtyard & braai — items and fittings recorded

35 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Built-in Jetmaster braai - black steel firebox with an oval 'Jetmaster' badge above the opening, black flip-down front cooking surface/shelf, black chimney hood/flue, cast-iron adjustable grate-height hook/lever, and a grey metal ash/wood box drawer embossed 'Jetmaster'	1	Fair - soot and ash residue built up inside the firebox and on the flip-down shelf, with a light dust film over the unit	Plate 017, Plate 018
Wire mesh grill basket with folding handle, sitting on the braai grate	1	Poor - visible rust across the wire grill basket	Plate 017
Built-in outdoor kitchen counter - sage-green painted masonry with a white/pale grey countertop	1	Fair - counter and top intact; light scuff/dirt mark on the painted pillar to the left of the braai opening	Plate 017, Plate 018, Plate 019
Round stainless-steel undermount bar sink in the braai counter, with a single chrome wall-mounted tap and chrome U-bend plumbing beneath	1	Good - bowl, tap and trap intact, no leaks or corrosion visible	Plate 019, Plate 017, Plate 018
Braai chimney/flue - tall rectangular rendered stack with a dark metal cap and small finial above the patio roof	1	Good - render, cap and finial intact, no cracking visible	Plate 018
Covered patio roof (flat roof) with grey square structural support columns	1	Good - roof and columns intact, no cracking or water marking visible	Plate 018

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Patio flooring - wood-look ceramic/porcelain plank tile in a brown tone with a raised step	1	Good - consistent plank pattern with intact grout lines, no cracks or lifted tiles visible; tiles appeared wet/reflective near the doorway at inspection	Plate 020, Plate 021, Plate 022, Plate 023
Grey synthetic rattan/wicker outdoor two-seater sofa with cream/off-white cushions (two back cushions and a long seat cushion split into two sections)	1	Poor - dark smudge stain on the seat cushion fabric near its centre-right, with visible dirt marks, dark staining and creasing across the cushion covers, consistent with outdoor weathering	Plate 020
Grey synthetic rattan/wicker outdoor three-seat sofa with grey/beige cushions	1	Fair - cushion covers show general soiling and creasing; wicker weave shows light wear but no breaks	Plate 022, Plate 023
Grey synthetic rattan/wicker outdoor armchairs with cream/off-white seat and back cushions and large beige scatter cushions	2	Fair - visible dirt/grime staining on the seat cushion of the central armchair; mild creasing and wrinkling across the other cushion covers; light general wear on the wicker weave but no breaks	Plate 021, Plate 024
Grey synthetic rattan/wicker coffee table with a tempered glass top set into a rattan-wrapped surround with exposed circular wooden corner joints	1	Poor - a distinct circular amber/orange resin-like stain roughly 4-5cm across at the front-left corner of the glass top, with an adjacent whitish-green residue patch; dark stain/ weathering at one wooden corner joint; light dust and smudging across the glass	Plate 021, Plate 025, Plate 022
Green woven fabric cover or cushion laid over the patio coffee table	1	Good - fabric intact, no tears visible	Plate 024
Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio kitchenette unit, with a manufacturer sticker on its lower left corner	1	Good - screen and housing intact, no cracks visible; unit was off throughout the record	Plate 026, Plate 024, Plate 027
Built-in outdoor kitchenette wall unit with two recessed niches/shelves, sage-green painted face	1	Fair - the interiors of the wall niches are left as bare, unpainted grey cement/plaster, an unfinished finish contrasting with the painted sage-green facing	Plate 026
Exposed copper/brass plumbing pipe with a P-trap bend and isolation valve protruding from the lower kitchenette niche	1	Poor - pipe is exposed and unconnected, with no fixture attached; appears to be a tap or future sink connection point left incomplete	Plate 026
Cream-coloured electrical socket/switch plates on the patio and kitchenette walls	1	Good - plates in place, no scorching or cracking visible	Plate 026, Plate 027, Plate 019
White concertina/trellis security gates across the doors from the patio into the house interior, with diagonal bracing and a door lock/latch mechanism	2	Good - lattice, bracing and latches intact and fully extended across the openings	Plate 018, Plate 022, Plate 023, Plate 024, Plate 027

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Solid dark wood door at the far right of the covered patio	1	Good - leaf and surround intact, no visible damage	Plate 018
Wall-mounted lantern-style light fixture centred above the patio opening	1	Good - fixture and glazing in place, no damage visible	Plate 018
White wooden slatted balustrade/railing at the patio edge	1	Good - slats and rail intact, paint sound	Plate 021
Wooden venetian blinds/shutters behind the glazed patio doors	1	Good - slats intact and hanging level where visible	Plate 024, Plate 027
Built-in alcove with a light-coloured bench/shelf seat in the patio nook, with white cornice moulding at the ceiling	1	Good - bench, alcove and cornice intact, no cracking or staining visible	Plate 027
Steps from the lawn up to the covered patio - grey concrete paver steps with dark-stained wooden step edging	1	Poor - the wooden step edging below the deck is weathered, discoloured and algae-stained with heavy dark patches and grain wear; the concrete paver steps are stained and worn with a rough surface texture	Plate 018
Grey paving stepping stones set across the rear lawn leading to the patio	1	Fair - stones in place; surrounding lawn muddy and worn between them	Plate 018
Rear garden paved patio - large square textured concrete slabs	1	Fair - dirt and staining in the slab grout lines, with further staining across the paved tiles	
Rear and side garden lawn	1	Poor - patchy, weedy and unmown, with bare soil and muddy patches and thin grass throughout	
Garden beds and planting to the rear and side yard - succulents, agave, aloes, cacti including prickly pear, small ornamental trees and three bare deciduous trees, edged with a wooden timber border	1	Good - planting established and in leaf; deciduous trees bare at the time of inspection (winter)	
Potted plants in terracotta, concrete and metal planters through the rear garden and patio bed - including a large potted aloe, agave, cactus and a small cactus/succulent in a metal planter box	1	Good - plants in leaf, pots intact with no chips or cracks noted	Plate 018, Plate 019
Weathered grey driftwood/root decor - a sculpture piece on the patio and a large driftwood log used as a planter display, plus a driftwood piece at the base of the patio wall	1	Good - pieces sound and intact; naturally weathered grey surface	Plate 018
Garden hose, coiled and lying across the rear lawn	1	Good - hose intact, no splits or kinks visible	
Light grey-blue rendered boundary and low retaining wall to the side/back yard	1	Fair - visible horizontal crack or construction-joint line running through the render partway up the low wall	

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Grey horizontal-slat timber-style fence/wall to the rear of the side yard	1	Good - slats and posts intact, no leaning or rot visible	
Grey precast concrete panel boundary/screen wall to the rear garden, with electric fence wires along the top	1	Good - panels seated and upright, no cracking or displacement visible	Plate 018
Small teal/turquoise planter with greenery on the patio	1	Good - planter intact, plant in leaf	Plate 023
Patio walls and pillars - sage-green painted render	1	Fair - light scuff/dirt mark on the pillar beside the braai opening; render otherwise sound and evenly painted	Plate 017, Plate 023, Plate 019

19 Outdoor courtyard & braai — photographic plates



Plate 017 Built-in Jetmaster braai



Plate 018 Built-in Jetmaster braai



Plate 019 Built-in outdoor kitchen counter



Plate 020 Patio flooring



Plate 021 Patio flooring



Plate 022 Patio flooring




Plate 023 Patio flooring



Plate 024 Grey synthetic rattan/wicker outdoor armchairs with cream/off-white seat and back



Plate 025 Grey synthetic rattan/wicker coffee table with a tempered glass top set into a rattan-wr



Plate 026 Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio



Plate 027 Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio

20 Garage, laundry & storage

The single garage with its motorised door, the laundry bay, the fitted storage joinery, the distribution board and the household plant.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Garage slab & motorised door	FAIR	Clean	Crack/joint line across concrete floor near garage door threshold; Concrete floor unfinished/bare; Slight water staining at base of wall near garage entrance. (F005, F124, F126)
Laundry plumbing & connections	FAIR	Clean	Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue; Light scuff marks on top surface of the washing machine; Washing machine door area shows scuffing/grime around the door surround. (F113, F008, F119)
Fitted storage units	GOOD	Clean	General scuffing and wear on cabinet interior surfaces; Cluttered/disorganised storage typical of utility space; Multiple small dark specks/marks scattered on the interior surfaces of the cabinet, possibly dirt or insect debris. (F120, F121, F190)
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	FAIR	Clean	Hairline crack in wall near floor corner; Slight water staining at base of wall near garage entrance; Light scuff marks on top surface of the washing machine. (F122, F126, F008)
Floor	FAIR	Clean	Crack/joint line across concrete floor near garage door threshold; Floor finish appears worn/patchy in places; Hairline crack in wall near floor corner. (F005, F112, F122)
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	FAIR	Clean	Crack/joint line across concrete floor near garage door threshold; Ladder shows heavy paint splatter and surface wear, rust at hinge joints; Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue. (F005, F181, F113)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Windows — sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	FAIR	Clean	Slight water staining at base of wall near garage entrance; Light scuff marks on top surface of the washing machine; Light smudging/fingerprints on the mirrored door surface (minor, cosmetic). (F126, F008, F115)
Power points, switches & wiring	ATTENTION	Clean	Exposed orange and black cabling around the alarm control box, not fully enclosed; Scattered small dark speckled marks (possible dirt or mould) on left interior panel; Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue. (F116, F151, F113)

21 Garage, laundry & storage — findings

36 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F116	Exposed orange and black cabling around the alarm control box, not fully enclosed	HIGH	Plate 045
F151	Scattered small dark speckled marks (possible dirt or mould) on left interior panel	HIGH	Plate 050
F005	Crack/joint line across concrete floor near garage door threshold	MEDIUM	—
F006	Weathered/stained driveway paving	MEDIUM	—
F112	Floor finish appears worn/patchy in places	MEDIUM	—
F113	Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue	MEDIUM	Plate 039
F117	Unpainted, unfinished timber strip at the head of the door opening	MEDIUM	Plate 045
F118	Bare, unfinished concrete floor with dark staining	MEDIUM	Plate 040
F122	Hairline crack in wall near floor corner	MEDIUM	Plate 031
F124	Concrete floor unfinished/bare	MEDIUM	Plate 031

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F125	Moss/algae staining on stone steps and paving	MEDIUM	Plate 028
F126	Slight water staining at base of wall near garage entrance	MEDIUM	Plate 028
F150	Brownish/tan smear stains on white interior back panel	MEDIUM	Plate 050
F152	General grime/dust build-up on interior surfaces	MEDIUM	Plate 050
F166	Concrete floor has multiple dark stains/patches	MEDIUM	Plate 032
F181	Ladder shows heavy paint splatter and surface wear, rust at hinge joints	MEDIUM	Plate 030
F008	Light scuff marks on top surface of the washing machine	LOW	Plate 038
F059	Small dark speckled marks/residue on the lower countertop surface (left of centre)	LOW	Plate 044
F111	Various stains and scuff marks across the concrete garage floor	LOW	—
F114	General surface wear/dirt on appliance fronts	LOW	Plate 039
F115	Light smudging/fingerprints on the mirrored door surface (minor, cosmetic)	LOW	Plate 043
F119	Washing machine door area shows scuffing/grime around the door surround	LOW	Plate 040
F120	General scuffing and wear on cabinet interior surfaces	LOW	Plate 047
F121	Cluttered/disorganised storage typical of utility space	LOW	Plate 047
F123	Scuff/dirt marks at wall base	LOW	Plate 031
F155	Scattered small brownish marks/smudges in a rough horizontal band across the wall	LOW	—
F167	Wooden ladder shows visible wear on rungs	LOW	Plate 032
F180	Concrete floor shows faint stains/patch marks	LOW	Plate 033
F190	Multiple small dark specks/marks scattered on the interior surfaces of the cabinet, possibly dirt or insect debris	LOW	Plate 048

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F191	Multiple small dark specks/marks on interior cabinet walls across two shelf levels	LOW	Plate 049
F060	Wall finish above the counter could not be read with confidence under the light falling on it; listed for closer inspection	RE-CHECK	Plate 044
F156	Wall finish in this section not established in fine detail; listed for closer inspection	RE-CHECK	—
F165	Garage wall and floor surfaces not established in fine detail; listed for closer inspection	RE-CHECK	Plate 035
F168	Garage interior recorded under low light; fine surface detail not established, listed for closer inspection	RE-CHECK	Plate 032
F182	Garage surface detail not established in fine detail; listed for closer inspection	RE-CHECK	Plate 034
F183	Surface condition at this position not established; listed for closer inspection	RE-CHECK	—

22 Garage, laundry & storage — items and fittings recorded

84 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Sectional garage door to the double garage, with floor track/threshold	1	Good - door panels intact and operating on the track; standing open at inspection	Plate 028
Garage door operator - navy-blue plastic motor housing with red LED display mounted on a grey metal rail fixed to the ceiling, red twisted release cord running to a red plastic emergency-release pull toggle on the wall, with a wall-mounted motor control box	1	Good - motor, rail, release cord and control box all in place; no damage or marks visible, surrounding walls freshly painted	Plate 029
Wall-mounted control unit branded 'DRUID', black housing with digital display and multiple labelled buttons	1	Good - housing and display intact, no damage visible	Plate 030
Grey electrical distribution box mounted on the garage wall below the DRUID control unit	1	Good - enclosure closed and intact, no damage visible	Plate 030
Garage floor - bare grey concrete/screed	1	Poor - various stains and scuff marks across the floor, finish worn and patchy in places, multiple dark stains/patches, and a crack/joint line running across the concrete near the garage door threshold	Plate 031, Plate 032, Plate 033
Garage internal walls - taupe/beige and grey painted plaster	1	Fair - diagonal hairline crack running down from the corner near floor level, and scuff/dirt marks along the base of the wall	Plate 031, Plate 030, Plate 034

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Built-in white cabinetry to the back and side walls of the garage - overhead and floor units with hinged doors	1	Good - carcasses and doors intact, hinges in place, no water damage or swelling noted	Plate 028, Plate 035, Plate 032, Plate 036, Plate 037
Tall white open-shelf cubby storage units	1	Good - shelving upright and intact, mostly empty	Plate 033, Plate 034
DEFY front-loading washing machine - dark graphite/ anthracite body, round glass porthole door, digital display, single control dial, energy-rating sticker affixed to the door glass	1	Good - light scuff marks on the top surface; door, dial and display all intact	Plate 038, Plate 036
DEFY tumble dryer - silver-grey body, round door, dial control, with a yellow sticky note attached to the front panel	1	Good - body and door intact, no damage noted	Plate 038
Stainless-steel microwave oven standing at floor level beside the laundry appliances	1	Fair - door found slightly ajar; casing otherwise intact	Plate 038
Laundry sink/basin with two taps, set beside the washer and dryer	1	Good - bowl and taps intact, no cracks or staining noted	Plate 032, Plate 033
Laundry basket on a small rolling stand	1	Good - basket and stand intact	Plate 028, Plate 033
White fold-up ironing board	1	Good - surround and cover intact	Plate 028, Plate 035
Manual push reel lawnmower, black body with red wheels	1	Good - blades, handle and wheels in place, no rust noted	Plate 028, Plate 035, Plate 032, Plate 033
Electric push lawnmower, orange and black, with black grass-catcher box and a red coiled extension cord wrapped around the handle	1	Good - body, catcher box and cord intact; a black plastic bucket was standing upside-down on the engine housing at inspection	Plate 031
Black plastic bucket	1	Good - no cracks or damage visible	Plate 031
Wooden ladder (extension type) leaning against the garage wall	1	Poor - heavily paint-splattered and weathered, visible surface wear on the rungs and rust staining at the hinge joints	Plate 032, Plate 030
Aluminium step ladder leaning against the garage back wall	1	Good - rails and steps intact, no bends or corrosion noted	
Wall-mounted fire extinguisher	1	Good - cylinder and bracket in place	Plate 028
Folded wooden clothes airer/drying rack leaning against the garage wall	1	Good - surround intact, no breaks visible	Plate 028

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Wooden slatted bed base and headboard stored upright against the garage wall, with two grey/beige bath mats or rugs draped over the top rail	1	Good - slats and surround intact where visible	Plate 031, Plate 033
Long-handled garden and cleaning tools stored upright in the shelving - broom with red-and-silver handle, mop, red-headed garden rake, orange-tined leaf rake, spade and a black extendable pole	1	Good - handles and heads intact, no breakages noted	Plate 028, Plate 035, Plate 032, Plate 033, Plate 036
Red-and-black vacuum cleaner or steam mop stored in the garage cupboard	1	Good - housing intact, no damage visible	Plate 036
Cleaning supplies in a grey plastic basin on the cupboard shelf - white spray bottle, part-used yellow-labelled bottle, blue washing-up liquid bottle and other containers	1	Good - containers intact	Plate 036
Capsule coffee machine, black body with white/chrome accent ring and stainless steel drip tray, stored on a cupboard shelf	1	Good - body and drip tray intact, no damage visible	Plate 037
Orbital/disc sander power tool stored on the cupboard shelf	1	Good - housing intact, no damage visible	Plate 037
Blue strap/tie-down stored on the cupboard shelf	1	Good - webbing intact, no fraying visible	Plate 037
Small red-and-blue boxes stacked at the front of the cupboard shelf	1	Good - boxes intact	Plate 037
Grey plastic wheelie/pedal bin marked 'C.C.C.' standing inside the garage	1	Good - body and lid intact	Plate 032, Plate 030
Mop bucket with mop handle, and dustpan	1	Good - bucket and handle intact	Plate 033, Plate 030, Plate 034
Small white waste/pedal bin standing near the garage side door	1	Good - body and lid intact	
White side door with round knob, leading from the garage into the house	1	Good - door leaf, surround and handle intact, no scuffing noted	Plate 033
Wall-mounted key hook	1	Good - fitting secure	
White wall-mounted electrical box/socket with surface cable run	1	Good - cover plate in place, cable secured	Plate 034
Small trolley/hand-truck	1	Good - surround and wheels intact	
Wooden-framed panel or mirror leaning against the garage wall	1	Good - surround intact where visible	
Wooden workbench top in the garage cupboard run	1	Good - top intact, no splits or burns noted	Plate 036

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Wooden bamboo-look board/shelf panel wedged between the laundry appliances	1	Good - board intact	Plate 038
Aluminium folding table stored beside the laundry appliances	1	Good - leg and surround intact where visible	Plate 038
Yellow-handled long tool and stacked grey/black plastic buckets	1	Good - handle and buckets intact	Plate 038
Assorted stored goods on the garage shelving - shoes, storage boxes, tins and cans, a plastic bowl, a small plant pot and a brown paper bag	1	Good - items stored and intact where visible	Plate 028, Plate 034, Plate 036, Plate 037
Stored cardboard boxes and flattened cardboard on the garage floor	1	Fair - flattened and stacked, some boxes bowed	Plate 031, Plate 032, Plate 033
Black lantern-style wall light fixture mounted on the exterior wall above the garage opening	1	Good - fixture and glazing in place, no damage visible	Plate 028, Plate 035, Plate 032
Concrete drainage channel with metal grate running along the base of the wall at the garage threshold	1	Fair - channel and grate in place; slight water staining at the base of the wall near the garage entrance, and moss/algae staining on the adjoining stone steps and paving	Plate 028
DEFY front-loading washing machine, dark grey/black front, round glass door, rotary programme dial (On/Off, Cotton 20/40/60+Prewash/90/Eco, Synthetics 20, Delicate/Hand Wash 40, Downwear 40, Spin+Drain, Rinse, Drum Clean) and small digital display, green 'ENERGY A+++' label on the door glass	1	Poor - heavy dark staining/streaking down the front panel, concentrated below and around the door (possibly rust, mould or detergent residue); scuffing and grime around the door surround	Plate 039, Plate 040, Plate 041, Plate 042
DEFY tumble dryer, silver front-loader with round porthole door and timer dial, carrying a yellow 'Autodryer Operations' instruction sticker, a red/white 'DO NOT OVERLOAD THE DRUM - RECOMMENDED LOAD' warning sticker and a green energy-rating sticker	1	Fair - general surface wear and dirt on the appliance front	Plate 039, Plate 040, Plate 041, Plate 042
DEFY microwave oven, silver/mirrored finish, standing on the timber shelf above the laundry appliances; labelled preset panel (BAKED POTATO, POPCORN, PIZZA, BEVERAGE, FROZEN DINNER, REHEAT, POWER, TIMER, CLOCK, RESET, COOK, COOK BY WEIGHT, START/STOP, DEFROST BY WEIGHT, SPEED DEFROST) and numeric keypad	1	Good - no dents, cracks or major wear; light smudging/fingerprints on the mirrored door surface (cosmetic)	Plate 043, Plate 039, Plate 040, Plate 041, Plate 042
Timber-topped laundry counter/shelf spanning the washer and dryer, with a black plastic wall-mount bracket fixed to the wall behind	1	Fair - general utility-area wear; no structural damage observed	Plate 039, Plate 040, Plate 043

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Utility recess joinery - white floating shelf/wall cabinet unit over a white appliance-height countertop, with a loose thin metal/plastic trim strip lying on the counter	1	Fair - small dark speckled marks/residue on the lower countertop surface left of centre; a trim strip is detached and lying loose on the counter	Plate 044, Plate 041
Switched wall socket outlet and a second switch/isolator box in the utility recess	2	Good - no damage observed	Plate 044
Chrome double wall hook, utility recess side wall	1	Good - no damage observed	Plate 044
Wooden venetian blind to the utility area window	1	Good - no defects observed (partially visible at the edge of the view)	Plate 044
Electrical distribution board - white cover panel with two rows of circuit breakers labelled LIGHTS, LIGHTS, LIGHTS, GEYSER, TIMER, STOVE, EARTH LEAKAGE, PLUGS x5 (top row) and MAIN SWITCH, EARTH LEAKAGE, POOL, PLUGS x3, SHAVER (bottom row); Riken RKH-225 breakers; bilingual English/Afrikaans WARNING/WAARSKUWING label	1	Good - board and labelling intact, surrounding wall paint sound with no cracks or damage	
Prepaid electricity metering installation - ECON keypad unit (numeric keypad 1-9, 0, CLR) with LCD display reading 847, PT1 three-phase breaker switches, and a Plessey meter panel marked '800 imp/kWh 20(80)A 3 x 230/400V 50Hz', serial 06 6354 6540 1, with bilingual WARNING/ISILUMKISO anti-tamper label	1	Good - meter and labelling intact, no tamper damage observed	
Alarm and security installation in the service cupboard - beige/cream metal alarm control box with orange and black wiring, a blue circuit board/relay module, a white 'FIDELITY ADT' module with green circuit board and LED indicators, and a vented wall-mounted device plugged into a red-covered socket	1	Fair - exposed orange/black wiring around the alarm control box, not fully enclosed	Plate 045
Built-in service cupboard housing the alarm equipment - white cabinet door on chrome hinges, plain white walls and ceiling	1	Fair - unpainted/unfinished timber strip visible at the top of the door lining opening; otherwise sound	Plate 045
Built-in white storage cupboard with three shelves and brown/bronze-toned hinges	1	Good - plain white laminate shelves, no visible damage	Plate 046
Large white melamine built-in storage cupboard system with multiple full-height compartments, doors, and a section of small square/rectangular cubby shelving	1	Fair - general scuffing and wear on the cabinet interior surfaces; no major structural damage observed	Plate 047, Plate 041
Empty built-in cabinet with two shelf compartments, cream/beige interior, metal hinges	1	Fair - multiple small dark specks/marks scattered across the interior back and side walls and shelf (at least four visible in one view, at least six across two shelf levels in another); possibly dirt or insect debris	Plate 048, Plate 049

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Built-in white melamine cupboard compartment with sloped ceiling panel following the roofline, soft-close hinge and a small round fitting at the top of the sloped panel	1	Poor - brownish/tan smear stains across the centre of the sloped white back panel; scattered small dark speckled marks (dirt or possible mould) on the left interior panel; general grime/dust build-up on interior surfaces	Plate 050
Laundry sink/trough with two exposed chrome tap fittings above and visible P-trap plumbing beneath (recorded as a white plastic rectangular basin in one view and a stainless-steel wall-mounted trough in another)	1	Fair - exposed pipework beneath, no leaks or damage observed	Plate 040, Plate 042
Ironing board with green-and-cream / green-and-blue checked patterned cover	1	Good - cover intact, no scorch marks observed	Plate 040, Plate 047, Plate 042
Black dustpan and brush set	1	Good - no damage observed	Plate 040
Yellow-handled mop with grey plastic mop bucket	2	Fair - bucket contains water and what appears to be cleaning solution or debris; general utility wear	Plate 040, Plate 042, Plate 041
Black plastic bucket containing small metal fittings/hardware	1	Fair - general utility wear	Plate 040
Genesis CycloVac cyclonic vacuum cleaner (Verimark), boxed - 'The ideal compact & powerful cyclonic vacuum'	1	Excellent - stored unused in original packaging	Plate 046
Red canister-style handheld cleaning appliance (vacuum or steam cleaner), stored in the utility cupboard	1	Fair - general storage wear; not powered up or tested	Plate 047, Plate 041
Steam iron, blue and white, with woven/braided cord	1	Good - no damage observed	Plate 046
Boxed DEFY-branded item (black box, appears to be a small appliance), stored on a cupboard shelf	1	Good - box intact	Plate 046
White plastic multi-hook organiser	1	Good - no damage observed	Plate 046
Clear plastic bag containing folded white/blue fabric items with blue text (possibly aprons or linens)	1	Good - bagged and stored	Plate 046
Brown plastic 'Coconut Oil' toiletry bottles (shampoo/conditioner pair)	2	Good - part-used consumables	Plate 046
Cleaning consumables on the lower cupboard shelf - purple spray bottle, green/white bottle, blue-capped spray bottle, an aerosol can with red cap, a clear bottle with black cap, an orange bottle, and a pack labelled 'DRY CARPET & FABRIC CLEANER'	7	Good - part-used consumables	Plate 046
Assorted stored items on the cupboard middle shelf - black shoe stretcher/boot form, round grey lid/pan, and navy and brown/tan fabric belts or straps	3	Fair - stored, general wear	Plate 046

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Black pod-style (Nespresso-type) coffee machine, stored on a utility cupboard shelf	1	Fair - stored among cleaning supplies; not tested	Plate 047
Long-handled cleaning and garden tools stored in the cupboard - black wet/dry mop system with red handle, orange plastic leaf rake, and further mop and broom handles	4	Fair - general utility wear	Plate 047, Plate 041
Utility cupboard contents - grey plastic basin, cleaning spray bottles and bottles of liquid on the lower shelf, a brown paper bag, a coiled blue cable/strap and a black drawstring bag	1	Fair - cluttered/disorganised storage typical of a utility space	Plate 047
Red toolbox stored on the shelf above the laundry counter	1	Fair - stored, general wear; contents not visible	Plate 047
Clear plastic laundry basket	1	Good - no cracks or damage observed	Plate 041, Plate 042
Metal-legged side table in the laundry nook	1	Good - no damage observed	Plate 041
Beige stone/marble-look stool or side table	1	Good - no chips or damage observed	Plate 039
Utility/garage floor - bare grey concrete screed	1	Poor - unfinished bare concrete with dark staining and marks across the surface	Plate 040, Plate 047
Glade Secrets 'Ocean Escape' air freshener can and a HellermannTyton TOP Tronic instruction leaflet stored at the distribution board	2	Good - consumable and documentation, intact	

23 Garage, laundry & storage — photographic plates



Plate 028 Sectional garage door to the double garage, with floor track/threshold



Plate 029 Garage door operator




Plate 030 Wall-mounted control unit branded 'DRUID'



Plate 031 Garage floor - bare grey concrete/screed



Plate 032 Garage floor - bare grey concrete/screed



Plate 033 Garage floor - bare grey concrete/screed



Plate 034 Garage internal walls - taupe/beige and grey painted plaster



Plate 035 Built-in white cabinetry to the back and side walls of the garage



Plate 036 Built-in white cabinetry to the back and side walls of the garage




Plate 037 Built-in white cabinetry to the back and side walls of the garage



Plate 038 DEFY front-loading washing machine



Plate 039 DEFY front-loading washing machine



Plate 040 DEFY front-loading washing machine



Plate 041 DEFY front-loading washing machine



Plate 042 DEFY front-loading washing machine



Plate 043 DEFY microwave oven




Plate 044 Utility recess joinery




Plate 045 Alarm and security installation in the service cupboard




Plate 046 Built-in white storage cupboard with three shelves and brown/bronze-toned hinges




Plate 047 Large white melamine built-in storage cupboard system with multiple full-height



Plate 048 Empty built-in cabinet with two shelf compartments, cream/beige interior, metal hinges



Plate 049 Empty built-in cabinet with two shelf compartments, cream/beige interior, metal hinges



Plate 050 Built-in white melamine cupboard compartment with sloped ceiling panel following the

24 Kitchen

The fitted kitchen — joinery, hardwood counters, the Smeg range and hob, the integrated dishwasher, the Samsung refrigeration and the full loose contents of every drawer and cupboard.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	FAIR	Clean	Diagonal crack or open seam at the wall corner beside the door architrave; Small dark mark/dot on interior cabinet side wall, possibly a screw hole or blemish; Light dust and fingerprint smudges on toaster's stainless steel body. (F201, F050, F052)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Floor	FAIR	Clean	Metal transition strip on floor at left edge appears slightly raised/ uneven; Metal threshold strip appears slightly raised where it meets the timber floor; Floorboard gap and open seam running across the kitchen floor. (F204, F205, F072)
Skirtings, cornices & trim	FAIR	Clean	Diagonal crack or open seam at the wall corner beside the door architrave. (F201)
Doors, linings & ironmongery	FAIR	Clean	Torn or lifting rubber door seal/gasket visible at top of door opening; Diagonal crack or open seam at the wall corner beside the door architrave; Light fingerprint/smudge marks on stainless steel door surface (minor, cosmetic). (F064, F201, F061)
Windows — sashes, sills & surrounds	GOOD	Clean	Light water spot/residue marks on the glass lid of the front pot; Glassware not inspected individually for chips; listed for closer inspection; Wall and sill condition beside the kitchen window not established under the light falling on it; listed for closer inspection. (F076, F209, F211)
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	FAIR	Clean	Metal transition strip on floor at left edge appears slightly raised/ uneven; Metal threshold strip appears slightly raised where it meets the timber floor; Light dust and fingerprint smudges on toaster's stainless steel body. (F204, F205, F052)
Power points, switches & wiring	GOOD	Clean	Faint vertical mark/shadow on painted wall near the emergency button; Surface detail of the appliance door panel not established with confidence; listed for closer inspection. (F053, F062)
Built-in joinery & counters	GOOD	Clean	Small dark mark/dot on interior cabinet side wall, possibly a screw hole or blemish; Dark mark/smudge on white laminate shelf surface; Cabinet interior shows general wear consistent with under-sink storage. (F050, F056, F057)
Sink, taps & waste	GOOD	Clean	Cabinet interior shows general wear consistent with under-sink storage. (F057)
Splashback & wall tiling	GOOD	Clean	Inspected; no defect observed.

25 Kitchen — findings

36 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F054	Green/dark tarnish or residue build-up around bases of several control knobs on the right side	MEDIUM	Plate 068
F063	Wire rack tines appear bent/splayed out of alignment in places	MEDIUM	Plate 071

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F064	Torn or lifting rubber door seal/gasket visible at top of door opening	MEDIUM	Plate 071
F201	Diagonal crack or open seam at the wall corner beside the door architrave	MEDIUM	Plate 074
F204	Metal transition strip on floor at left edge appears slightly raised/uneven	MEDIUM	Plate 058
F205	Metal threshold strip appears slightly raised where it meets the timber floor	MEDIUM	Plate 059
F050	Small dark mark/dot on interior cabinet side wall, possibly a screw hole or blemish	LOW	Plate 052
F051	Small brown/orange stain on the top square saucer in the stacked pile	LOW	Plate 053
F052	Light dust and fingerprint smudges on toaster's stainless steel body	LOW	Plate 067
F053	Faint vertical mark/shadow on painted wall near the emergency button	LOW	Plate 066
F055	Light dust/residue build-up around the brand badge	LOW	Plate 069
F056	Dark mark/smudge on white laminate shelf surface	LOW	Plate 060
F057	Cabinet interior shows general wear consistent with under-sink storage	LOW	Plate 060
F058	Staining/residue marks on black oven grill tray surface (ridged section)	LOW	Plate 057
F061	Light fingerprint/smudge marks on stainless steel door surface (minor, cosmetic)	LOW	Plate 072
F065	Water spot residue and minor food debris specks on interior walls	LOW	Plate 071
F071	Surface shows glossy sheen with some scuff/wear marks in high-traffic area near cabinets	LOW	—
F072	Floorboard gap and open seam running across the kitchen floor	LOW	—
F073	Wooden spoon heads show dark staining and wear consistent with heavy use	LOW	Plate 075
F076	Light water spot/residue marks on the glass lid of the front pot	LOW	Plate 076
F153	Visible colour/tone mismatch seam between two different wood sections of the countertop	LOW	Plate 062

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F154	Light general wear/patina on hob's stainless surface	LOW	Plate 062
F159	Diagonal scuff/scrape mark on wall surface	LOW	—
F160	Scattered small dark specks (dirt or insect marks) across the wall	LOW	—
F202	Fridge door surface shows reflected glare and minor smudging	LOW	Plate 074
F206	Floorboard seam/gap visible near the threshold strip	LOW	Plate 059
F062	Surface detail of the appliance door panel not established with confidence; listed for closer inspection	RE-CHECK	Plate 070
F203	Surface condition of this fitting not established; listed for closer inspection	RE-CHECK	—
F207	Small dark mark on the countertop near the wall junction, cause unclear (could be a chip, stain, or shadow)	RE-CHECK	—
F209	Glassware not inspected individually for chips; listed for closer inspection	RE-CHECK	Plate 055
F211	Wall and sill condition beside the kitchen window not established under the light falling on it; listed for closer inspection	RE-CHECK	Plate 064
F070	Numerous small dark knots and filled nail holes across the kitchen floorboards — inherent to the pine, not damage	SOUND	—
F074	No structural or surface defects visible (drawer interior appears clean, no cracks or damage)	SOUND	Plate 075
F075	No visible dents, rust or damage on pots - appear in used but good condition	SOUND	Plate 076
F208	No visible defects; cabinet interiors and walls appear clean and undamaged	SOUND	Plate 054
F214	No visible defects on stools, table, or counter surfaces; floor and walls appear in good condition	SOUND	Plate 065

26 Kitchen — items and fittings recorded

54 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Fitted overhead wall cabinets, white gloss, including two hydraulic lift-up (flip-up) units, one glass-fronted, with white internal shelving	1	Good - interiors clean and undamaged; small dark mark/dot on one cabinet interior side wall (possibly a screw hole or blemish)	Plate 051, Plate 052, Plate 053, Plate 054, Plate 055

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Fitted base cabinets and drawer units, white laminate carcass and fronts, dark brown/black kickboard strip	1	Good - drawer fronts and carcass show no visible damage; thin exposed particleboard/MDF strip along the front shelf edge where laminate meets underside	Plate 051, Plate 056, Plate 057, Plate 058, Plate 059
Under-sink base cabinet, white melamine interior with chrome hinges, two shelf levels	1	Fair - dark smudge/mark on the white laminate shelf surface; general wear consistent with under-sink storage	Plate 060
Perimeter worktop, cream/white speckled quartz-look engineered stone, glossy finish, with matching light-grey upstand to wall join	1	Good - smooth and largely unmarked; small dark mark on the countertop near the wall junction (chip, stain or shadow - cause unclear)	Plate 051, Plate 061, Plate 059
Kitchen island / breakfast-bar worktop, two-tone butcher-block timber (pale yellow-toned section meeting darker reddish-brown section), on timber supports and black metal L-brackets	1	Fair - clear colour/tone mismatch seam where the pale wood section meets the darker reddish-brown section beside and behind the hob	Plate 062, Plate 058, Plate 063, Plate 064, Plate 065
Painted kitchen walls and splashback, grey/putty finish	1	Fair - faint vertical mark/shadow running down the wall from the corner near the emergency button; otherwise sound	Plate 051, Plate 066
Solid pine plank flooring, knotty honey-toned boards, with metal transition/threshold strip at the change of floor finish	1	Fair - glossy sheen with scuff/wear marks in the high-traffic area near the cabinets; floorboard gap/seam visible near the threshold; metal transition strip slightly raised/uneven where it meets the timber	Plate 058, Plate 059
Recessed ceiling downlights to kitchen (sloped/pitched ceiling section near window)	1	Good - no defects observed	Plate 051
Horizontal venetian blind to kitchen window (recorded as white slats in one view and light wood-tone slats in another), with decorative bead curtain hanging at the window edge	1	Good - no defects observed	Plate 051, Plate 054
Window security guard / burglar bars to kitchen window (seen externally)	1	Good - no defects observed	Plate 051
White wall socket outlets, South African 3-round-pin type, including one double socket; one outlet fitted with a marked cover	4	Good - no damage observed	Plate 051, Plate 056, Plate 067, Plate 054
Wall-mounted device labelled 'EMERGENCY' (panic button / emergency switch)	1	Good - no damage observed	Plate 066
Wall-mounted stainless steel utensil rail with three S-hooks	1	Good - no damage observed	Plate 066

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
SMEG freestanding range cooker, cream/off-white body, stainless steel 5-burner gas hob with black cast-iron pan supports, digital clock/timer display, front control knobs, glass-fronted main oven with long chrome handle and lower drawer/oven compartment	1	Fair - green/dark tarnish or residue build-up around the bases of several control knobs on the right side; dark blackened patina on the cast-iron pan supports; light dust/residue build-up around the chrome 'smeg' badge; general light wear/patina on the stainless hob surface	Plate 068, Plate 069, Plate 062, Plate 058, Plate 063, Plate 064
DEFY dishwasher, stainless/graphite front, built in under the worktop, recessed door handle, control panel with rotary dial selector and indicator lights, green energy-rating sticker on fascia	1	Poor - torn/curled rubber door seal lifting away from the top of the door lining; wire rack tines bent and splayed out of alignment in places; water spot residue and small food debris specks on the interior walls	Plate 051, Plate 070, Plate 071, Plate 059
DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel bar handles, digital 'Cooling+' interior control panel, blue LED interior light strip and clear plastic door bins, set into a wall niche	1	Good - interior clean with no mould, staining or residue; light fingerprint/smudge marks on the stainless steel door surfaces (cosmetic)	Plate 072, Plate 073, Plate 074, Plate 055
DEFY 4-slice stainless steel toaster, two browning dials, buttons labelled DEFROST / REHEAT / CANCEL in maroon, black cord with SA 3-round-pin plug	1	Fair - light dust and crumb residue and fingerprint smudges on the brushed steel body	Plate 067, Plate 051, Plate 056, Plate 061
Stainless steel undermount sink with chrome gooseneck mixer tap and associated plumbing (grey P-trap, braided flexible supply hoses, black woven cable-protector sleeve)	1	Good - no leaks, corrosion or damage observed	Plate 051, Plate 060, Plate 059
Pump-top liquid soap/sanitiser dispenser bottle on the counter	1	Good - no defects observed	Plate 051, Plate 059
Grey dish-drying rack	1	Good - no defects observed	Plate 059
Clear stemmed wine/cocktail glasses, stored upside down on cabinet shelf	10	Good - no chips confirmed; one view is indistinct, so fine chips could not be ruled out on the glassware	Plate 052, Plate 051, Plate 055
Clear glass tumblers - two tall ribbed/fluted tumblers plus a stack of approximately three shorter glasses	5	Good - no chips or cracks observed	Plate 052, Plate 055
Clear fluted glass vase/tumbler	1	Good - no defects observed	Plate 052
White and cream ceramic mugs and cups - one large white mug with handle, one small white espresso/demitasse cup, two tall handleless white cylindrical cups, one taller pale beige/putty mug with handle; three further cream ceramic mugs seen in a second cabinet view	5	Good - no chips observed	Plate 053, Plate 051, Plate 055
Square white ceramic saucers/side plates, stacked	5	Fair - light brown/orange stain or mark near the centre of the top saucer in the stack	Plate 053

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Large white dinner plates, plain, matching set	4	Good - clean, no visible chips from the angle photographed	Plate 056, Plate 051
White side plates, plain, matching set	4	Good - clean, no visible chips	Plate 056, Plate 054
Small white bowls, plain, matching set	4	Good - clean, no visible chips	Plate 056
Medium white/cream bowls, plain, matching set	5	Good - clean, no visible chips	Plate 056, Plate 054
Shallow white pasta/serving bowls	2	Good - no visible chips	Plate 056
Plastic cutlery organiser tray printed 'teaspoons'	1	Good - drawer interior and tray clean, no cracks or damage	Plate 075
Stainless steel dinner/table spoons	5	Good - no damage observed	Plate 075
Stainless steel table forks	4	Good - no damage observed	Plate 075
Stainless steel table knives	5	Good - no damage observed	Plate 075
Small stainless steel teaspoons	2	Good - no damage observed	Plate 075
Black-handled steak/utility knife set standing in a drawer slot	5	Good - no damage observed	Plate 075
Black-handled kitchen knives of varying blade sizes (4) plus one black-handled meat cleaver	5	Good - no damage observed	Plate 075
Black plastic slotted turners/spatulas with stainless steel handles (drawer-stored)	2	Good - no damage observed	Plate 075
Black Y-shaped vegetable peeler	1	Good - no damage observed	Plate 075
Black kitchen scissors/shears	1	Good - no damage observed	Plate 075
Black-handled ladle/scoop with round bowl (drawer-stored)	1	Good - no damage observed	Plate 075
Black plastic measuring spoons on a ring	3	Good - no damage observed	Plate 075
Wooden cooking spoons/turners	3	Fair - spoon heads show dark staining and wear consistent with heavy use	Plate 075
Black-handled utensils hanging on the wall rail/ hooks (observed as a slotted serving spoon, a solid serving spoon and a stainless wire whisk in one view; a ladle and two turners in another)	3	Good - no damage observed	Plate 066, Plate 054
Stainless steel pots/saucepans of varying sizes with glass lids and black/grey silicone-covered handles, in a grey non-slip lined drawer	4	Good - used but sound, no dents or rust; light water spot/residue marks on the glass lid of the front pot	Plate 076
Black enamel oven grill/roasting tray, ridged and flat sections	1	Fair - staining/residue marks across the ridged section of the tray	Plate 057

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Oven mitt with floral/patterned fabric (blue, yellow, orange) and quilted pot-holder/oven glove in pink and green patterned fabric	2	Good - no damage observed	Plate 057
Folded appliance instruction/warranty document printed 'SAFEWAY STOVETOP KETTLE', stored in a kitchen drawer	1	Good - document intact	Plate 057
Under-sink cleaning consumables - Sunlight Platinum dishwashing liquid ('5X GREASE CUTTING POWER'), a green packet of Heavy Duty scourers, a bundle of steel wool scourers in plastic packaging, and a dish brush with red plastic head	4	Good - part-used consumables	Plate 060
Cleaning items in the cabinet beside the dishwasher - green sponge/scourer, green cloth and an amber-coloured dishwashing liquid bottle with red cap	3	Good - part-used consumables	
Backless bar stools, galvanised/raw steel finish with cross-braced legs and square wooden seat tops, at the breakfast bar	2	Good - no visible defects on the stools	Plate 065
White cylindrical ceramic canister with wooden lid, on the island counter	1	Good - no defects observed	Plate 058, Plate 064, Plate 065
Folded blue-and-white striped cloth/napkin on the island counter	1	Good - no staining observed	Plate 064
Refrigerator accessories - ice-cube tray, two blue plastic ice/freezer blocks and white egg-crate style trays	4	Good - clean, no damage observed	Plate 073

27 Kitchen – photographic plates



Plate 051 Fitted overhead wall cabinets



Plate 052 Fitted overhead wall cabinets



Plate 053 Fitted overhead wall cabinets



Plate 054 Fitted overhead wall cabinets



Plate 055 Fitted overhead wall cabinets



Plate 056 Fitted base cabinets and drawer units



Plate 057 Fitted base cabinets and drawer units



Plate 058 Fitted base cabinets and drawer units



Plate 059 Fitted base cabinets and drawer units



Plate 060 Under-sink base cabinet, white melamine interior with chrome hinges, two shelf levels




Plate 061 Perimeter worktop



Plate 062 Kitchen island / breakfast-bar worktop



Plate 063 Kitchen island / breakfast-bar worktop



Plate 064 Kitchen island / breakfast-bar worktop



Plate 065 Kitchen island / breakfast-bar worktop



Plate 066 Painted kitchen walls and splashback, grey/putty finish



Plate 067 White wall socket outlets



Plate 068 SMEG freestanding range cooker



Plate 069 SMEG freestanding range cooker



Plate 070 DEFY dishwasher



Plate 071 DEFY dishwasher



Plate 072 DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel



Plate 073 DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel



Plate 074 DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel



Plate 075 Plastic cutlery organiser tray printed 'teaspoons'



Plate 076 Stainless steel pots/saucepans of varying sizes with glass lids and black/grey silicone

28 Lounge & dining

The open living room with its Jetmaster fireplace, the leather and fabric seating, the media wall, the DSC alarm panel and the dining area.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	FAIR	Clean	Crack and open gap in the plaster where the door architrave meets the ceiling corner; A few small dark specks/marks on the ceiling near the panel seams. (F109, F108)
Walls	FAIR	Clean	Crack and open gap in the plaster where the door architrave meets the ceiling corner; Small chip/notch in plaster step beside the fireplace opening; Small dark marks/scuffs on the wooden console surface. (F109, F031, F104)
Floor	FAIR	Clean	Natural crack/split running across the wood-slab coffee table top; Darker discoloured patch to one floor plank left of centre in the lounge — a stain, a water mark or natural grain variation; not resolved; Noticeable lighter discoloured patch on the wood floor near the armchair, possible sun-fading or rug mark. (F103, F100, F184)
Skirtings, cornices & trim	FAIR	Clean	Crack and open gap in the plaster where the door architrave meets the ceiling corner; A scuff or chip mark is visible on the white skirting board directly in front of the fireplace opening. (F109, F216)
Doors, linings & ironmongery	FAIR	Clean	Crack and open gap in the plaster where the door architrave meets the ceiling corner. (F109)
Windows — sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	FAIR	Clean	Visible splits/cracks in the wood slats of the trunk-table top; One slat on the trunk appears raised or misaligned relative to others. (F039, F040)
Light fittings & ceiling roses	GOOD	Clean	Visible vertical crease/wear marks and light staining on the lower front seat cushion of the grey armchair; Noticeable lighter discoloured patch on the wood floor near the armchair, possible sun-fading or rug mark; Light discoloration/water-mark-like patch on the fabric of the chaise cushion, centre-right of the ottoman section. (F034, F184, F186)
Power points, switches & wiring	ATTENTION	Clean	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone; Small dark specks and marks to the wall beside the alarm panel; A few small dark specks/marks on the ceiling near the panel seams. (F107, F106, F108)

29 Lounge & dining — findings

36 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F107	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone	HIGH	Plate 095
F032	Heavy creasing and wrinkling across all leather cushions consistent with distressed-style leather or wear	MEDIUM	Plate 089
F039	Visible splits/cracks in the wood slats of the trunk-table top	MEDIUM	Plate 081
F101	Dark stain/blotch marks on the seat cushion of the chaise section	MEDIUM	Plate 087
F103	Natural crack/split running across the wood-slab coffee table top	MEDIUM	Plate 082
F109	Crack and open gap in the plaster where the door architrave meets the ceiling corner	MEDIUM	Plate 094
F220	Leather shows extensive creasing/wrinkling and a mottled worn appearance across the visible surface - could be a distressed-style finish or actual wear, not clearly distinguishable	MEDIUM	Plate 090
F221	Leather sofa shows heavy creasing/wrinkling consistent with wear or distressed-style finish across both visible cushions	MEDIUM	Plate 091
F030	Sooty/blackened staining inside the fireplace insert (expected wear from use)	LOW	Plate 077
F031	Small chip/notch in plaster step beside the fireplace opening	LOW	Plate 077
F034	Visible vertical crease/wear marks and light staining on the lower front seat cushion of the grey armchair	LOW	Plate 078
F035	Some fine surface fuzz/pilling texture visible on the armchair fabric	LOW	Plate 078
F036	A round knot-like opening in one floorboard near the centre of the dining floor, possibly an old fixture hole	LOW	Plate 098
F037	A visible seam/gap line running across the floorboards	LOW	Plate 098
F038	Table surface shows some faint watermark/blotch discoloration in the wood	LOW	Plate 098
F040	One slat on the trunk appears raised or misaligned relative to others	LOW	Plate 081
F077	Light reflection glare across the mid-floor area consistent with glossy tile finish, not damage	LOW	Plate 100
F100	Darker discoloured patch to one floor plank left of centre in the lounge – a stain, a water mark or natural grain variation; not resolved	LOW	Plate 096

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F102	Fine dust/lint visible on the sofa armrest fabric	LOW	Plate 087
F104	Small dark marks/scuffs on the wooden console surface	LOW	—
F105	Small dark smudge to the lounge wall, high on the left-hand return	LOW	Plate 093
F106	Small dark specks and marks to the wall beside the alarm panel	LOW	Plate 095
F108	A few small dark specks/marks on the ceiling near the panel seams	LOW	Plate 092
F110	Several small dark specks/spots on the wall to the right of the speaker	LOW	Plate 094
F184	Noticeable lighter discoloured patch on the wood floor near the armchair, possible sun-fading or rug mark	LOW	Plate 084
F185	Small dark mark/spot on wall to left of TV, could be a scuff or nail hole	LOW	Plate 086
F186	Light discoloration/water-mark-like patch on the fabric of the chaise cushion, centre-right of the ottoman section	LOW	Plate 088
F213	Small round metal fitting embedded in floor within the seamed area	LOW	Plate 099
F216	A scuff or chip mark is visible on the white skirting board directly in front of the fireplace opening	LOW	Plate 080
F217	Fireplace interior sooted and darkened, consistent with use; the recess is unlit and the flue was not inspected	LOW	Plate 080
F192	Lounge surface detail not established in fine detail; listed for closer inspection	RE-CHECK	—
F210	Lounge surface condition not established at this position; listed for closer inspection	RE-CHECK	—
F212	Rectangular seam or outline in the dining floor mid-room — possibly a hatch or an old repair; not resolved	RE-CHECK	Plate 099
F033	No obvious tears or stains visible	SOUND	Plate 089
F078	No visible cracks, stains, or chips on the flooring in this view	SOUND	Plate 100
F215	No cracks, staining or damage visible to the lounge walls, floor or fireplace surround; all in good order	SOUND	Plate 079

30 Lounge & dining — items and fittings recorded

46 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Built-in fireplace recess with black metal gas/radiant fire insert, visible ribbed radiant bars and tiled hearth floor, set into a white-trimmed plaster surround	1	Fair - sooty/blackened staining inside the fireplace insert (expected wear from use); small chip/notch in the plaster step beside the fireplace opening; recess interior dark and sooted, limiting close assessment in the s	Plate 077, Plate 078, Plate 079, Plate 080
Fireplace tools - small black hearth brush and a black poker/tool, resting on the tiled hearth and hanging inside the fireplace opening	2	Good - no damage observed; both items in use inside the fireplace recess	Plate 077, Plate 078
Grey woven-fabric wingback armchair, buttoned/tufted back panel with 12 buttons in a 3x4 grid, pale wood tapered legs	1	Fair - visible vertical crease/wear marks and light staining on the lower front seat cushion; fine surface fuzz/pilling texture across the fabric	Plate 077, Plate 078, Plate 081, Plate 082, Plate 083, Plate 084, Plate 085, Plate 086, Plate 079, Plate 080
Grey/charcoal fabric L-shaped sectional sofa with chaise section	1	Fair - dark stain/blotch marks on the seat cushion of the chaise section; a further light discoloured water-mark-like patch on the chaise cushion; fine dust/lint visible on the armrest fabric	Plate 087, Plate 084, Plate 088
Scatter cushions for the grey sectional sofa, matching grey / charcoal-navy velvet-look fabric	5	Good - no defects observed. Count varies between photographs: three counted on the backrest, five counted piled at the armrest; five is the highest verified count and is recorded here	Plate 087, Plate 084, Plate 088
Tan/caramel-brown leather sofa, corner configuration with two sections meeting at a corner, two back and two seat cushions, wooden block legs, top-stitched seams	1	Fair - heavy creasing and wrinkling across all leather cushions with a mottled, variegated worn-in patina over the whole visible surface; the observer could not distinguish an intentional distressed-leather finish from genuine wear; no tears or stains visible	Plate 089, Plate 081, Plate 090, Plate 091
Round live-edge wood-slab coffee table (tree-trunk cross-section, visible growth rings and retained bark edge) on thin black metal hairpin legs	1	Fair - natural crack/split running across the wood-slab table top	Plate 087, Plate 082, Plate 083, Plate 084, Plate 088
Wooden TV console / low media bench with visible knots in the timber top	1	Fair - small dark marks/scuffs on the wooden console top surface	Plate 087, Plate 082, Plate 083, Plate 084, Plate 085, Plate 086

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
SAMSUNG flat-screen television, black, standing on black plastic feet on the TV console; 'SAMSUNG' legible on the lower bezel	1	Good - no defects observed; screen off in every photograph, so display function not verified	Plate 082, Plate 083, Plate 092, Plate 084, Plate 085, Plate 086
SAMSUNG television remote control, black with a red power button, resting on the TV console	1	Good - no damage observed	Plate 082, Plate 086
SAMSUNG wireless satellite speakers, black with chrome/cream bases, wall-mounted high in the room corners ('SAMSUNG' printed on the face of each)	2	Good - no damage observed to the units themselves; both mounted high on opposite walls near the ceiling	Plate 093, Plate 092, Plate 094
Soundbar-style audio unit sitting beneath the television screen on the TV console	1	Fair - observed at distance only; brand and model text not legible and surface condition not resolvable at that resolution	Plate 084
DSC wall-mounted alarm keypad, white, zone numbers 1-16 printed on the fascia	1	Fair - yellow warning-triangle indicator illuminated on the panel, suggesting a fault or unset zone; zones 1 and 2 lit red; small dark specks/marks on the wall below the panel	Plate 095
Chevron-pattern fabric floor poufs / storage cubes - two red-and-cream, one black-and-cream - stored beneath the TV console	3	Good - no defects observed	Plate 096, Plate 082, Plate 083, Plate 084, Plate 085, Plate 088
Organic star/leaf-shaped carved wood side table with a hollowed bowl-like natural-edge top, on three thin black angled metal legs	1	Good - no defects observed on this piece	Plate 081
Rustic reclaimed-wood slatted chest/trunk in use as a coffee table, rough-cut slats of varying tone with visible gaps	1	Fair - visible splits/cracks in the wood slats of the trunk top; one slat raised or misaligned relative to the others	Plate 081
Cowhide-pattern rug, white and brown patches	1	Good - no defects observed	Plate 079
Small round grey rug beneath the tufted armchair	1	Good - no defects observed	Plate 085
Blue/navy upholstered armchair with wooden arm surround and a matching blue scatter cushion (described in one photograph as the corner of another blue upholstered seat; configuration not fully resolved)	1	Good - no defects observed; one of the three views is indistinct, limiting fine surface assessment	Plate 082, Plate 083

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Wishbone-style wooden chair with woven paper-cord seat, standing in the lounge beside the fireplace (matches the dining chairs; may be one of the dining set relocated - not confirmed)	1	Good - no defects observed	Plate 078
Wood-slat / faux-wood venetian blinds to the lounge windows and the sliding balcony door (recorded as one set; the number of individual blinds is not determinable from the photographs)	1	Good - no broken, bent or missing slats observed; blinds shown variously part-open and part-closed	Plate 089, Plate 081, Plate 082, Plate 097, Plate 084, Plate 085, Plate 086, Plate 079, Plate 080, Plate 091
Sliding glass door to the balcony with white metal security grille/gate	1	Good - no damage observed to the glazing or the security grille. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 081
Lounge flooring - wood-look plank tile in a mixed herringbone/ staggered pattern in the main area, transitioning to lighter solid timber strips and to wide-plank grey-brown reclaimed-look boards at the fireplace end	1	Fair - a distinctly darker, almost black-brown discoloured patch/streak running the length of one plank near the centre of the room; a wide lighter discoloured patch on the floor by the armchair consistent with sun-fading or a rug recently removed; no cracks or chips observed elsewhere. Fixed finish: recorded for condition, not as replaceable contents	Plate 077, Plate 078, Plate 096, Plate 084, Plate 088, Plate 079, Plate 080
Lounge wall finishes and paint - recorded variously as pale cream/ off-white, pale grey, greige, sage-green and grey-blue across the different wall planes	1	Fair - small dark smudge/mark on the wall near the ceiling corner; a small dark mark/spot on the wall beside and below the television, possibly a nail hole or scuff; several small dark specks on the wall beside the corner speaker; scattered small dark specks/marks on the wall below the alarm keypad. Fixed finish: recorded for condition, not as replaceable contents	Plate 089, Plate 093, Plate 095, Plate 094, Plate 086
Ceiling - white panelled/coffered ceiling with raised trim lines forming a geometric pattern	1	Fair - a few small dark specks/marks on the ceiling near the panel seams. Fixed finish: recorded for condition, not as replaceable contents	Plate 092
Decorative white cornice/coving to the wall-ceiling junction	1	Fair - visible crack/gap in the plaster or trim where the door architrave meets the ceiling corner, directly beside the wall-mounted Samsung speaker. Fixed finish: recorded for condition, not as replaceable contents	Plate 093, Plate 092, Plate 094
White painted skirting boards throughout the lounge	1	Fair - a scuff or chip mark on the white skirting board directly in front of the fireplace opening; skirting elsewhere shows no damage in the views available. Fixed finish: recorded for condition, not as replaceable contents	Plate 077, Plate 087, Plate 083, Plate 088, Plate 080

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Recessed ceiling downlights (small round fittings; one observed illuminated warm white)	2	Good - one fitting observed lit; no damage to the fittings observed. Count taken from the widest ceiling views available	Plate 092
Ceiling-mounted smoke detector near the lounge corner	1	Fair - observed only indistinctly; make, model and indicator state not legible and function not verified	
Wall-mounted white intercom / entry-phone handset with coiled cord, with an adjacent white single switch and a small round wall-mounted device (doorbell chime or sensor; not identified)	1	Good - no damage observed; coiled cord hanging loose on the wall	Plate 089, Plate 091
Small chrome/silver wall hooks fixed to the lounge wall, both empty	2	Good - securely fixed, no damage observed	Plate 093
Two-gang toggle light switch on the lounge wall beside the doorway	1	Good - plate intact, no cracks or scorching observed. Fixed fitting: recorded for condition, not as replaceable contents	Plate 085
Set of keys hanging on a hook / at the switch plate beside the lounge doorway	1	Good - recorded as observed; the keys themselves are not identified and no value is assigned	Plate 085
Internal door to the lounge - white painted door with silver lever handle and deadbolt/keyhole plate, in a white-painted surround	1	Good - no visible damage to the door, surround or ironmongery in this view. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 085
Wooden dining table with tapered legs (recorded as square and dark-stained in one photograph and as rectangular and medium-brown in another; shape and finish not fully resolved between the two views)	1	Fair - faint watermark/blotch discoloration in the timber of the table top	Plate 098, Plate 099
Wishbone-style wooden dining chairs with woven paper-cord (rush) seats, matching the dining table	4	Good - no fraying, breaks or staining observed in the seat weave or surrounds	Plate 098, Plate 099
Dining area flooring - solid honey-brown pine plank boards with visible knots and grain	1	Fair - a round hole/knot-like opening in one floorboard; a visible seam/gap line running across the boards; a rectangular seam/outline in the floor with a small round metal fitting embedded within it, consistent with an underfloor access hatch or a repair (not confirmed). Fixed finish: recorded for condition, not as replaceable contents	Plate 098, Plate 099
Dining area wall finish (pale grey paint) with a white double round-pin wall socket	1	Good - no cracks, marks or damage observed to the wall or the socket plate. Fixed finish: recorded for condition, not as replaceable contents	Plate 099

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Black cylindrical flue pipe (possibly a wood-burning stove flue) rising at the edge of the dining area	1	Fair - only partially visible at the edge of a single view; type, fixing and condition not confirmed. Recorded for condition, not as replaceable contents	Plate 099
Passage/hallway flooring - wood-look plank tile running from the lounge doorway toward the front door	1	Good - no visible cracks, stains or chips; light glare across the mid-floor is consistent with a glossy tile finish rather than damage. Fixed finish: recorded for condition, not as replaceable contents	Plate 100
Passage/hallway wall finish - grey/light-taupe to cream-beige paint with white skirting	1	Good - no cracks, scuffs or marks observed in the views available. Fixed finish: recorded for condition, not as replaceable contents	Plate 100, Plate 101
Front entrance door - white, with narrow glass side panels	1	Good - no damage observed; photographed at distance down the passage, so ironmongery and seals were not inspected close up. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 100
Internal hinged doors off the passage - white painted, in white surrounds (one on the left of the passage, one standing ajar to the bathroom beyond)	2	Good - no visible damage to leaves, surrounds or hinges. Fixed building fabric: recorded for condition, not as replaceable contents	Plate 100, Plate 101
Two-gang white light switch on the passage wall	1	Good - plate intact, no cracks or marks observed. Fixed fitting: recorded for condition, not as replaceable contents	Plate 101
White console table / shoe rack standing against the passage wall by the front door	1	Good - no damage observed; photographed at distance, so surface detail is not resolvable	Plate 100
White decorative wire/lattice screen or gate, seen from the passage in the room to the right of the front door (position beyond the passage; area assignment provisional)	1	Good - no damage observed; viewed only at distance from the passage	Plate 100

31 Lounge & dining — photographic plates



Plate 077 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 078 Built-in fireplace recess with black metal gas/radiant fire insert




Plate 079 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 080 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 081 Grey woven-fabric wingback armchair



Plate 082 Grey woven-fabric wingback armchair



Plate 083 Grey woven-fabric wingback armchair



Plate 084 Grey woven-fabric wingback armchair



Plate 085 Grey woven-fabric wingback armchair



Plate 086 Grey woven-fabric wingback armchair



Plate 087 Grey/charcoal fabric L-shaped sectional sofa with chaise section



Plate 088 Grey/charcoal fabric L-shaped sectional sofa with chaise section



Plate 089 Tan/caramel-brown leather sofa




Plate 090 Tan/caramel-brown leather sofa



Plate 091 Tan/caramel-brown leather sofa




Plate 092 SAMSUNG flat-screen television




Plate 093 SAMSUNG wireless satellite speakers



Plate 094 SAMSUNG wireless satellite speakers



Plate 095 DSC wall-mounted alarm keypad, white, zone numbers 1-16 printed on the fascia




Plate 096 Chevron-pattern fabric floor poufs / storage cubes



Plate 097 Wood-slat / faux-wood venetian blinds to the lounge windows and the sliding balcony door



Plate 098 Wooden dining table with tapered legs



Plate 099 Wooden dining table with tapered legs



Plate 100 Passage/hallway flooring




Plate 101 Passage/hallway wall finish - grey/ light-taupe to cream-beige paint with white skirting

32 Main bedroom suite & en-suite

The principal bedroom, its fitted wardrobe wall and the en-suite bathroom with double vanity, bath and separate shower.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	FAIR	Clean	Visible pale mineral/water staining on the tiled wall behind the basins. (F047)
Floor	FAIR	Clean	Visible pale mineral/water staining on the tiled wall behind the basins; Visible seam/joint gap in wooden flooring near shower threshold. (F047, F043)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	GOOD	Clean	Inspected; no defect observed.
Windows — sashes, sills & surrounds	FAIR	Clean	Venetian blind slats hang unevenly/crookedly on the lower section of the window; Numerous water spots/droplets on the window glass behind the blinds. (F226, F227)
Blinds & window coverings	FAIR	Clean	One section of the venetian blind slats hangs unevenly/crookedly compared to the rest; Venetian blind slats hang unevenly/crookedly on the lower section of the window; Numerous water spots/droplets on the window glass behind the blinds. (F225, F226, F227)
Light fittings & ceiling roses	GOOD	Clean	Inspected; no defect observed.
Power points, switches & wiring	GOOD	Clean	Inspected; no defect observed.
Built-in wardrobe — carcass, shelving & rails	GOOD	Clean	Inspected; no defect observed.
En-suite — basin & vanity	FAIR	Clean	Visible pale mineral/water staining on the tiled wall behind the basins. (F047)
En-suite — shower & WC	GOOD	Clean	Visible seam/joint gap in wooden flooring near shower threshold. (F043)
Wet-area tiling & grout	FAIR	Clean	Visible pale mineral/water staining on the tiled wall behind the basins; Visible seam/joint gap in wooden flooring near shower threshold. (F047, F043)

33 Main bedroom suite & en-suite — findings

14 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F047	Visible pale mineral/water staining on the tiled wall behind the basins	MEDIUM	Plate 114
F225	One section of the venetian blind slats hangs unevenly/crookedly compared to the rest	MEDIUM	Plate 105
F226	Venetian blind slats hang unevenly/crookedly on the lower section of the window	MEDIUM	Plate 109
F043	Visible seam/joint gap in wooden flooring near shower threshold	LOW	Plate 113
F048	Mattress is bare with no bedding/linen fitted	LOW	Plate 102
F227	Numerous water spots/droplets on the window glass behind the blinds	LOW	Plate 110

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F041	No cracks, staining or mould visible to the tiling or grout at the shower threshold	SOUND	Plate 112
F042	Floor transition from wood to tile at shower threshold appears intact	SOUND	Plate 112
F044	Vanity doors and drawers standing open; no surface defect to the joinery itself	SOUND	Plate 121
F045	Vanity doors and drawers standing open; no other surface defect to the joinery	SOUND	Plate 120
F046	No visible cracks or damage; grout lines appear intact	SOUND	Plate 118
F049	No visible damage; wardrobe and drawers are simply empty	SOUND	Plate 107
F222	No defects visible to the bedroom wall or floor surfaces at this position	SOUND	Plate 106
F223	No defects visible to the bedroom floor, walls or furniture at this position	SOUND	Plate 103

34 Main bedroom suite & en-suite — items and fittings recorded

40 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Double/queen bed — white upholstered divan base with a bare mattress; the mattress ticking is a quilted cream/pink-and-white fabric printed with the repeating brand text "Rest Assured" in red lettering with a blue logo mark. No headboard, no bedding, linen or pillows fitted	1	Fair — mattress is entirely bare with no bedding or linen fitted (property is part-furnished); no tears, sagging or staining visible on the ticking	Plate 102, Plate 103, Plate 104, Plate 105
Pine bedside tables flanking the bed — a taller narrow one at the head end and a lower, wider one with an open lower shelf at the foot side (mismatched pair)	2	Good — natural wood grain and knots visible, varnish sound, no chips or water rings observed	Plate 102, Plate 106, Plate 103
Large white built-in wardrobe spanning the wall — three double-door hanging sections with rails and shelving above a built-in bank of drawers; visible metal cabinet hinges (three per door) and drawer interiors lined in dark grey/charcoal	1	Good — no damage to doors, rails, shelves or drawer boxes; all hanging sections and drawers are EMPTY apart from a single wire clothes hanger left on the rail in the left-hand section	Plate 107, Plate 108, Plate 109
White multi-drawer chest / drawer unit standing in the room (seen directly in one view and in mirror reflection in another; may form part of the fitted wardrobe run — to confirm)	1	Good — no damage observed; partial view only	Plate 107, Plate 105
Wooden desk or side table with visible legs standing at the window end of the room	1	Good — no damage observed; partial view at the edge of the view	Plate 105
Sliding glass door / window unit opening to the garden, glazed and framed	1	Good — glass unbroken, surround straight; greenery visible beyond	Plate 102

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Wooden-slat / faux-wood venetian blinds to the sliding door and the bedroom windows	2	Fair — one section of slats hangs unevenly/ crookedly and is raised higher than the rest, leaving a gap; the lower section of the second window's blind also hangs tilted/ uneven. Remaining slats straight and undamaged	Plate 102, Plate 107, Plate 105, Plate 109, Plate 110
White diamond/square-grid burglar-bar security grilles fitted externally to the glazing	2	Good — grid straight and intact, no rust or distortion visible. Note: numerous water spots/droplets visible on the window glass behind the blinds	Plate 102, Plate 107, Plate 110
Recessed ceiling downlights set into the sloped ceiling (two illuminated in one view with a third dimmer fitting further along)	3	Good — fittings seated flush, no scorching or discolouration observed	Plate 102, Plate 107, Plate 108
Retractable pleated/concertina wooden-slat skylight blind system in light natural timber, with two horizontal tensioning wires threaded through metal clips along the slats, mounted beneath a glass skylight panel	1	Good — slats intact and evenly pleated, tensioning wires and clips in place; glass skylight above sound	Plate 111
Wall-mounted white sensor/detector (alarm PIR or smoke detector) fixed high on the wall at the ceiling junction	1	Good — casing clean and securely mounted	Plate 102
White wall-mounted power sockets, including a double socket beside the bed	2	Good — face plates intact, no scorching or cracking observed	Plate 102, Plate 106, Plate 103
White panelled bedroom door with round silver doorknob and visible keyhole lock	1	Good — paint finish sound, no chipping or scuffing observed	Plate 104
Angled/cathedral white ceiling with white cornice and a grey painted wall band below the cornice — recorded for condition only	1	Good — visible seam/joint lines run diagonally across the ceiling (panel or bulkhead lines); no cracking, staining or damp observed	Plate 102, Plate 108
Grey / pale grey-green painted wall finish with white skirting boards — recorded for condition only	1	Good — no visible defects on the wall surfaces in any view; paint even and skirting sound	Plate 107, Plate 106
Honey-toned pine plank timber flooring with visible knots and a polished/glossy finish — recorded for condition only	1	Good — boards sound with a glossy sheen, no cracks, stains or water damage visible	Plate 104, Plate 109, Plate 103
Paired white ceramic vessel/bowl basins set on the timber vanity countertop — left basin a rounded conical bowl, right basin a more oval/ asymmetric bowl; both with visible overflow holes and chrome pop-up waste fittings	2	Good — no chips or cracks visible on either bowl	Plate 112, Plate 113, Plate 114, Plate 115, Plate 116

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Chrome gooseneck-style single-lever mixer taps serving the paired basins (left tap tall gooseneck, right tap shorter)	2	Good — no corrosion or drip staining observed on the tapware itself	Plate 112, Plate 114, Plate 115, Plate 116
Double vanity unit — white floating cabinet carcass with a reddish-brown/bamboo-look varnished timber countertop, drawers below, partly supported on a single thin metal leg; drawer interior has a cut-out access panel for the plumbing riser	1	Good — drawer left pulled fully open and empty except for a loose grey rubber/plastic fitting (spare basin waste or grommet) lying in the drawer base; no damage to the carcass observed	Plate 114, Plate 116
Rectangular/square white-framed wall mirrors, one above each basin	2	Good — no cracks, chips or de-silvering observed	Plate 112, Plate 113, Plate 115, Plate 117
Chrome wall-mounted cup / toothbrush holder fixed to the wall between the two mirrors	1	Good	Plate 113, Plate 117
Chrome cylindrical wall-mounted dispenser (soap or lotion) fixed beneath the mirror to the right of the basin	1	Good	Plate 115
Large walk-in shower enclosure with frameless glass screen/door separating the shower from the rest of the room	1	Good — glass clean and unbroken, no chipping observed to the screen edges	Plate 112, Plate 113, Plate 118, Plate 119
Chrome shower fittings — rectangular/rose shower head on a rigid angled wall arm, plus a separate chrome round mixer valve with visible tubing running down the tiled wall	1	Good — no visible limescale build-up or corrosion observed	Plate 112, Plate 118, Plate 119
Shower floor and feature wall in beige/brown checkerboard mosaic tiling with a chrome square floor drain grate — recorded for condition only	1	Good — grout lines appear intact, no cracks, staining or mould visible in any view	Plate 112, Plate 118
Large-format beige/taupe rectified wall tiling to the shower and vanity walls — recorded for condition only	1	Fair — pale mineral/water staining visible on the tiled wall behind the basins; grout lines elsewhere appear intact with no cracks or mould	Plate 114, Plate 118
White two-piece close-coupled toilet with cistern and seat	1	Good — no cracks or chips observed to pan, cistern or seat	Plate 112, Plate 115, Plate 116
Wall-mounted toilet-roll holder with one roll loaded; spare toilet rolls stacked on the cistern lid (one spare roll plus another item in one view, two spare rolls in another, three spare rolls in another)	1	Good — holder secure; loose stock counts differ between views and are recorded as observed	Plate 112, Plate 115, Plate 116
Beige / tan-striped bath towels hung over the rail beside the window and over the heater rail	2	Good — no tearing, staining or fraying visible	Plate 112, Plate 116

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Wall-mounted panel heater with a small adjacent thermostat / control panel, and the towel rail/ radiator carrying a beige towel	1	Good — casing intact, no scorching or discolouration observed	Plate 112
Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook, each with hinged double doors, internal hanging rails and shelving	2	Good — no surface defects on the joinery; both units left with doors standing open and interiors entirely EMPTY (bare hanging rails and shelves, no contents)	Plate 113, Plate 120, Plate 121, Plate 122
Built-in white dressing table set in a recessed nook between the wardrobes — knee-hole desk surface, square wall mirror above, and a bank of drawers below (five drawer fronts visible)	1	Good — drawers left half-open and empty; no chips or delamination observed to the fronts	Plate 113, Plate 120, Plate 121, Plate 122
Full-length mirrored sliding wardrobe door with silver/aluminium surround	1	Good — mirror face unbroken, surround straight	Plate 122
Tall white built-in cabinet with hinged door, plus an adjacent built-in white bench/shelf unit with drawers beneath	1	Good — cabinet door observed standing ajar; no damage visible	Plate 117
Window set into the shower wall above head height, fitted with an aluminium venetian blind; a second window with pale blue/white horizontal venetian blinds to the side of the shower	2	Good — slats straight, no bent or missing slats observed	Plate 112, Plate 119
Wide-board pine plank timber flooring throughout the en-suite (unusual for a bathroom) with a tiled threshold into the shower — recorded for condition only	1	Fair — visible seam/joint gap in the wooden flooring near the shower threshold; floor transition from wood to tile at the shower threshold otherwise appears intact; boards show natural knots, no water damage or cupping observed	Plate 113, Plate 120, Plate 114, Plate 116
Grey/taupe painted walls with white coved cornice, white ceiling and white skirting — recorded for condition only	1	Good — paint even, no cracking, damp staining or scuffing observed	Plate 113, Plate 121
Recessed ceiling downlights	1	Good — fittings seated flush, no scorching observed; exact count not determinable from the record (at least one spotlight visible per view)	Plate 112, Plate 120, Plate 121
White shelving unit standing at the far right of the room	1	Good — no damage observed; visible only at the edge of the view	Plate 112
White electrical light-switch plate on the wall beside the mirror	1	Good — plate intact and unmarked	Plate 117

35 Main bedroom suite & en-suite — photographic plates



Plate 102 Double/queen bed



Plate 103 Double/queen bed



Plate 104 Double/queen bed



Plate 105 Double/queen bed



Plate 106 Pine bedside tables flanking the bed



Plate 107 Large white built-in wardrobe spanning the wall



Plate 108 Large white built-in wardrobe spanning the wall



Plate 109 Large white built-in wardrobe spanning the wall



Plate 110 Wooden-slat / faux-wood venetian blinds to the sliding door and the bedroom windows



Plate 111 Retractable pleated/concertina wooden-slat skylight blind system in light natural timber




Plate 112 Paired white ceramic vessel/bowl basins set on the timber vanity countertop



Plate 113 Paired white ceramic vessel/bowl basins set on the timber vanity countertop



Plate 114 Paired white ceramic vessel/bowl basins set on the timber vanity countertop



Plate 115 Paired white ceramic vessel/bowl basins set on the timber vanity countertop



Plate 116 Paired white ceramic vessel/bowl basins set on the timber vanity countertop



Plate 117 Rectangular/square white-framed wall mirrors, one above each basin



Plate 118 Large walk-in shower enclosure with frameless glass screen/door separating the shower



Plate 119 Large walk-in shower enclosure with frameless glass screen/door separating the shower



Plate 120 Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook



Plate 121 Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook



Plate 122 Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook

36 Bedroom 2

The second bedroom with its fitted wardrobe, blinds and floor.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	GOOD	Clean	Varnish shows minor wear/scuff sheen variation on the table top; Faint horizontal smudge mark on right wall at shoulder height; Faint smudge to the bedroom wall at mid height, left of centre. (F087, F157, F161)
Floor	GOOD	Clean	Numerous natural knots across floorboards - inherent to the pine, not damage; Board seam gaps visible where planks meet, normal for this floor type; Mattress resting directly on the floor with no bed base beneath it. (F088, F089, F158)

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	GOOD	Clean	Inspected; no defect observed.
Windows — sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	GOOD	Clean	Light dust settled on the blind slats. (F084)
Light fittings & ceiling roses	GOOD	Clean	Light dust settled on the blind slats. (F084)
Power points, switches & wiring	GOOD	Clean	Inspected; no defect observed.
Built-in wardrobe — carcase, shelving & rails	GOOD	Clean	Inspected; no defect observed.

37 Bedroom 2 — findings

17 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F086	Dark stain/knot mark near the front-left corner of the table top	MEDIUM	Plate 124
F079	Mattress has no bedding - fully bare, exposing printed ticking pattern	LOW	Plate 123
F084	Light dust settled on the blind slats	LOW	Plate 125
F085	Visible wood knots and small round blemish/knot marks on the table top surface	LOW	Plate 124
F087	Varnish shows minor wear/scuff sheen variation on the table top	LOW	Plate 124
F088	Numerous natural knots across floorboards - inherent to the pine, not damage	LOW	Plate 132
F089	Board seam gaps visible where planks meet, normal for this floor type	LOW	Plate 132
F157	Faint horizontal smudge mark on right wall at shoulder height	LOW	Plate 126
F158	Mattress resting directly on the floor with no bed base beneath it	LOW	Plate 126

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F161	Faint smudge to the bedroom wall at mid height, left of centre	LOW	Plate 127
F196	Bedroom surface detail not established in fine detail; listed for closer inspection	RE-CHECK	Plate 129
F197	Bedroom surface condition not established in fine detail; listed for closer inspection	RE-CHECK	Plate 130
F080	Wardrobe doors standing open; interior empty and unused	SOUND	Plate 123
F081	No damage visible on wardrobe interior - shelves and rails appear clean and undamaged	SOUND	Plate 131
F082	Hinges show normal wear, functional	SOUND	Plate 131
F083	Blind slats straight and undamaged	SOUND	Plate 125
F090	No cracks, stains or water damage visible in this section	SOUND	Plate 132

38 Bedroom 2 — items and fittings recorded

13 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Double bed with a natural wood slatted headboard, carrying a bare mattress whose ticking fabric is printed repeatedly with the brand text "REST ASSURED"	1	Fair — mattress fully bare with no bedding or linen fitted, exposing the printed ticking; no tears or staining visible	Plate 123, Plate 124, Plate 125
Second bare mattress bearing the "Rest Assured" brand print in red script with a blue logo mark, resting at floor level — observed in one view lying directly on the floor with no visible bed base, and in another on a low base	1	Poor for use — mattress resting directly on the floor with no visible bed base and no bedding; ticking itself shows no tears or staining	Plate 126, Plate 127
Cream divan-style bed base with a woven honeycomb/ diamond-pattern fabric cover, resting flush on the floor with no visible legs	1	Fair — no legs or base visible, sits directly on the timber floor; fabric cover clean with no tears or marks observed	Plate 128
Small pine bedside tables/stools with an open lower shelf, in unfinished/natural varnished pine — a matching pair, one at the bed head and one across the room	2	Fair — visible wood knots and small round blemish/knot marks across the table top, a dark stain/knot mark near the front-left corner, and minor varnish wear with sheen variation on the top surface	Plate 124, Plate 126, Plate 127, Plate 129, Plate 130

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Built-in white melamine wardrobe run with multiple hinged doors and dark round handles/knobs – one section with a single hanging rail and shelf above, one section of five open adjustable shelves, a narrow vertical column of open cubbies, a further hanging rail section, and a shoe/shelf cubby at the base; dark bronze/black metal cabinet hinges	1	Good – shelves, rails and hinges clean and undamaged, hinges show normal functional wear; the entire interior is EMPTY and unused, with doors left standing open	Plate 123, Plate 131, Plate 129, Plate 130
Empty white plastic clothes hangers left on the wardrobe hanging rail	4	Good – three to four hangers observed, undamaged	Plate 131
Cream/off-white wooden venetian blind to the bedroom window, with two beige/gold braided pull cords ending in wooden acorn-shaped pulls and a separate tilt-cord ladder	1	Good – slats straight and undamaged; slight dust visible on some slats	Plate 125, Plate 123, Plate 131
Recessed ceiling downlights set into the sloped/angled ceiling	2	Good – fittings seated flush, no scorching observed	Plate 123, Plate 131
White double electrical wall sockets (South African 3-pin type) mounted low on the wall near the bed head and beside the bedside table	2	Good – face plates intact, no scorching, cracking or discolouration	Plate 124, Plate 126, Plate 127
White panelled bedroom door to the hallway	1	Good – paint finish sound, no chipping or scuffing observed	Plate 132
Sloped/angled white ceiling – recorded for condition only	1	Good – no cracking, seam separation, staining or damp observed	Plate 123
Sage-grey / sage-green painted wall finish with white skirting boards – recorded for condition only	1	Fair – a faint horizontal smudge mark at roughly shoulder height on one wall, and a faint diffuse smudge/mark at mid-height on another wall with no clear cause; paint otherwise even and skirting sound	Plate 126, Plate 127
Honey-toned pine plank timber flooring with numerous visible knots – recorded for condition only	1	Good – numerous natural knots across the boards (inherent to the pine, not damage) and board seam gaps where planks meet (normal for this floor type); no cracks, stains or water damage visible	Plate 132

39 Bedroom 2 – photographic plates



Plate 123 Double bed with a natural wood slatted headboard



Plate 124 Double bed with a natural wood slatted headboard



Plate 125 Double bed with a natural wood slatted headboard




Plate 126 Second bare mattress bearing the "Rest Assured" brand print in red script with a blue



Plate 127 Second bare mattress bearing the "Rest Assured" brand print in red script with a blue



Plate 128 Cream divan-style bed base with a woven honeycomb/diamond-pattern fabric cover



Plate 129 Small pine bedside tables/stools with an open lower shelf



Plate 130 Small pine bedside tables/stools with an open lower shelf



Plate 131 Built-in white melamine wardrobe run with multiple hinged doors and dark round handles/k




Plate 132 White panelled bedroom door to the hallway

40 Second bathroom

The second full bathroom serving the remainder of the house.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	GOOD	Clean	Inspected; no defect observed.
Walls	GOOD	Clean	Inspected; no defect observed.
Floor	GOOD	Clean	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch; Visible floor trim/transition strip forming an odd raised outline near the corner, could indicate a floor level change or repair. (F187, F188)
Skirtings, cornices & trim	GOOD	Clean	Visible floor trim/transition strip forming an odd raised outline near the corner, could indicate a floor level change or repair. (F188)
Doors, linings & ironmongery	GOOD	Clean	Inspected; no defect observed.
Windows – sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	GOOD	Clean	Inspected; no defect observed.
Power points, switches & wiring	GOOD	Clean	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch. (F187)
Sanitaryware – bath, basin & WC	GOOD	Clean	Small dark mark/residue spot near the drain area inside the basin; Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch. (F097, F187)
Wet-area tiling & grout	GOOD	Clean	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch. (F187)
Vanity, mirror & taps	GOOD	Clean	Small dark mark/residue spot near the drain area inside the basin. (F097)

41 Second bathroom – findings

13 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F091	Cupboard interior appears empty apart from two towels - no visible damage to shelving	LOW	Plate 140
F097	Small dark mark/residue spot near the drain area inside the basin	LOW	Plate 137
F187	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch	LOW	Plate 136

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F188	Visible floor trim/transition strip forming an odd raised outline near the corner, could indicate a floor level change or repair	LOW	Plate 139
F189	Fine surface detail at this position not established; listed for closer inspection	RE-CHECK	—
F224	Interior surface detail of this fitting not established; listed for closer inspection	RE-CHECK	—
F092	Hinges show no visible wear issues	SOUND	Plate 140
F093	No visible cracks or chips on sink, tub, or tiles	SOUND	Plate 133
F094	Tile grout appears intact, no visible staining or mould in view	SOUND	Plate 133
F095	Cupboard shelving shows no visible damage	SOUND	Plate 141
F096	Interior surfaces clean, no stains or marks	SOUND	Plate 141
F098	Otherwise no visible chips or cracks on the basin	SOUND	Plate 137
F099	Empty drawer shows no items and no visible damage inside	SOUND	Plate 137

42 Second bathroom — items and fittings recorded

17 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
White oval built-in bathtub set into a cream/beige large-format tiled surround with tiled deck and front skirt panel	1	Good — tub surface glossy and clean, no cracks or chips visible on the tub or the tiled surround; grout lines intact	Plate 133, Plate 134, Plate 135, Plate 136
Wall-mounted chrome bath mixer tap with a separate hand-held shower attachment on a bracket, plus chrome overflow drain	1	Good — no corrosion or limescale build-up observed	Plate 133, Plate 134
Chrome circular flush-mounted jet/inlet fitting on the inner wall of the bathtub near the overflow drain (spa/jacuzzi-style bath)	1	Good — fitting seated flush, no staining around the collar	Plate 134
Small square access/inspection panel cut into the tiled skirt at the base of the bath (plumbing access)	1	Fair — noted because the square cut-out in the tiled skirt reads as a defect if not an intentional access hatch; edges otherwise clean	Plate 133, Plate 136

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
White round countertop-mounted (vessel) basin with chrome single-lever mixer tap and chrome pop-up waste	1	Fair — small dark mark/residue spot near the drain area inside the basin; no chips or cracks otherwise	Plate 133, Plate 137, Plate 138
Vanity unit beneath the basin — white cabinet surround with a wood-toned, ridged teak-look slatted countertop and a drawer	1	Good — drawer pulled fully open and completely empty with a grey-lined interior; no damage inside or to the carcass	Plate 137, Plate 138
Mirror mounted on the wall above the basin	1	Good — no cracking or de-silvering observed (partial view only)	Plate 133
White close-coupled toilet with cistern, seat and lid, chrome dual-flush button on the cistern lid	1	Good — clean, no visible cracks, chips or staining to pan, cistern or seat	Plate 134, Plate 135, Plate 139
Chrome wall-mounted toilet-roll holder carrying a single partially-used white paper roll	1	Good — holder secure and unmarked	Plate 139
Built-in white melamine linen cupboard with six vertical compartments and hinged doors	1	Good — shelving clean and undamaged, hinges show no wear issues; five of the six compartments are EMPTY	Plate 140, Plate 141
Towel stock held in one compartment of the linen cupboard — two rolled cream/beige towels with a subtle patterned stripe seen in one view; a stack of approximately four to five rolled tan/beige towels with one patterned beige towel folded on top seen in the other	1	Good — no staining, fraying or tearing observed; counts differ between the two views and are recorded exactly as seen	Plate 140, Plate 141
Bath towels in use — a white/cream striped bath towel hung over the tiled bath ledge, and a white towel hanging at the side of the bath	2	Good — no staining or fraying observed	Plate 134, Plate 136
Windows fitted with white venetian blinds — one above the bath and one beside the basin	2	Good — slats appear straight, none bent or missing	Plate 140, Plate 133
Wood-look plank tile flooring in grey-brown/dark brown tones (distinct from the honey-pine timber floors elsewhere in the property) — recorded for condition only	1	Fair — floor trim/transition strip forms an odd raised outline near the corner, which could indicate a floor-level change or a repair; tiles otherwise sound with no cracking	Plate 133, Plate 134, Plate 139
Cream/beige wall tiling to the bath surround and behind the basin, with matching tiled skirting — recorded for condition only	1	Good — grout intact, no visible staining, mould, cracking or chipped tiles	Plate 137, Plate 134
Painted wall finish — two-tone, light grey/blue on one wall and beige/tan on the return corner, with white skirting boards — recorded for condition only	1	Good — paint even, no scuffing, marking or damp staining observed	Plate 139, Plate 138

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Glossy beige/cream large-format tiled wall with a reflective glass screen (likely a shower screen) and an adjacent window with horizontal blinds – recorded for condition only. Detail at this position is not established, so it cannot be tied to a specific bathroom	1	Not assessable – no defects can be confirmed; the detail here is not established	

43 Second bathroom – photographic plates




Plate 133 White oval built-in bathtub set into a cream/beige large-format tiled surround with




Plate 134 White oval built-in bathtub set into a cream/beige large-format tiled surround with




Plate 135 White oval built-in bathtub set into a cream/beige large-format tiled surround with



Plate 136 White oval built-in bathtub set into a cream/beige large-format tiled surround with




Plate 137 White round countertop-mounted




Plate 138 White round countertop-mounted




Plate 139 White close-coupled toilet with cistern



Plate 140 Built-in white melamine linen cupboard with six vertical compartments and hinged doors



Plate 141 Built-in white melamine linen cupboard with six vertical compartments and hinged doors

44 Guest powder room

The guest cloakroom off the circulation space.

Surface schedule

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Ceiling	GOOD	Clean	Inspected; no defect observed.

SURFACE / ELEMENT	CONDITION	CLEANLINESS	OBSERVED
Walls	GOOD	Clean	Inspected; no defect observed.
Floor	GOOD	Clean	Inspected; no defect observed.
Skirtings, cornices & trim	GOOD	Clean	Inspected; no defect observed.
Doors, linings & ironmongery	GOOD	Clean	Inspected; no defect observed.
Windows — sashes, sills & surrounds	GOOD	Clean	Inspected; no defect observed.
Blinds & window coverings	GOOD	Clean	Inspected; no defect observed.
Light fittings & ceiling roses	GOOD	Clean	Inspected; no defect observed.
Power points, switches & wiring	GOOD	Clean	Inspected; no defect observed.
Basin, vanity & taps	GOOD	Clean	Inspected; no defect observed.
WC	GOOD	Clean	Inspected; no defect observed.
Tiling	GOOD	Clean	Inspected; no defect observed.

45 Guest powder room — items and fittings recorded

4 entries. Descriptions are carried in full — the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
Round white ceramic vessel/bowl-style basin mounted on a wood-toned vanity top, with chrome mixer tap and chrome pop-up drain	1	Good — no chips, cracks or staining observed to the bowl or tap	Plate 142
White-framed mirror / frosted-opaque glass panel mounted on the wall above and beside the basin	1	Good — glass intact, surround unmarked	Plate 142
White panelled entrance door with horizontal grooves, chrome round door handle and visible lock mechanism	1	Good — paint finish sound, no chipping or scuffing observed	Plate 142
Warm taupe/greige painted wall finish — recorded for condition only	1	Good — no visible defects in the wall paint from the angle available	Plate 142

46 Guest powder room — photographic plates




Plate 142 Round white ceramic vessel/bowl-style basin mounted on a wood-toned vanity top

47 Rooms whose attribution is not resolved

A single-bed room, an empty wood-look-tiled room and a taupe-walled room are each recorded in full. Which of the named bedrooms they belong to is not established by the record, so they are carried separately rather than filed against a room they may not be.

Surface schedule

These rooms are recorded as a contents and condition schedule only; the surface schedule for the named bedrooms appears under those areas.

48 Rooms whose attribution is not resolved – findings

10 findings recorded in this area.

REF	FINDING AS OBSERVED	SEVERITY	PLATE
F066	Hairline seam/crack lines visible in ceiling bulkhead following the angled step pattern	MEDIUM	Plate 144
F067	Reflective glare patches to the left bedroom wall – paint sheen variation rather than a defect on the balance of what is visible	LOW	Plate 144
F068	Glossy glare/reflection patches on several planks suggesting a sheen inconsistency or wet-look finish	LOW	Plate 145
F069	Visible grout-like seams between planks with slight colour mismatch on some boards	LOW	Plate 145
F193	Diagonal seam/line across ceiling, possibly a board joint	LOW	Plate 148
F195	Visible colour/tone variation between individual floor tiles (patchwork appearance)	LOW	Plate 146
F199	Floor shows scattered lighter scuff marks	LOW	Plate 147
F194	Ceiling and wall detail at this position not established; listed for closer inspection	RE-CHECK	Plate 148
F198	Darker rectangular patches on floor, possibly wear, stains, or shadow (unclear which)	RE-CHECK	Plate 147
F200	Overexposed window obscures view outside/of blind condition	RE-CHECK	Plate 147

49 Rooms whose attribution is not resolved – items and fittings recorded

14 entries. Descriptions are carried in full – the detail is the record.

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
UNATTRIBUTED ROOM A (single-bed room, pale grey/blue walls, casement window) — single bed with a bare mattress covered only by a quilted white mattress protector, no fitted sheet or bedding	1	Fair — mattress is bare apart from a quilted white protector, with no sheet or bedding fitted; no tears or staining visible	Plate 143
UNATTRIBUTED ROOM A — small square two-tier pine side table (top surface plus lower shelf), varnished, with visible knots and natural grain	1	Good — varnish sound, visible wood knots inherent to the timber, no chips or water rings observed	Plate 143
UNATTRIBUTED ROOM A — small wooden stool/table with turned legs, standing near the window	1	Good — no damage observed; seen at distance in the background	Plate 143
UNATTRIBUTED ROOM A — sash/casement window fitted with white venetian blinds, and a white double electrical wall socket with South African plug points	1	Good — blind slats straight and partially open, socket face plate intact and unmarked	Plate 143
UNATTRIBUTED ROOM A — pale grey/blue painted walls, white skirting boards and warm honey-toned pine strip flooring — recorded for condition only	1	Good — walls appear smooth and unmarked, flooring in good condition with no cracks, gaps or staining observed	Plate 143
UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor) — wooden storage trunk/crate approximately knee height (~60cm), built from mixed-tone patchwork wood block tiles/veneer, closed, standing in the corner near the window	1	Good — no splitting, damage or missing blocks observed to the veneer surface	Plate 144, Plate 145, Plate 146, Plate 147
UNATTRIBUTED ROOM B — black cable/adaptor running from the wooden crate to a wall socket, and a small black object (possibly a small bin or speaker) standing beside the crate	1	Fair — loose trailing cable running across the floor from the crate to the socket; object beside the crate not identifiable with certainty	Plate 144, Plate 145
UNATTRIBUTED ROOM B — window with a wooden surround and white venetian blinds, looking out onto a plain grey wall beyond	1	Fair — blinds partially open, slats appear sound; strong light obscures a full view of the blind condition	Plate 144, Plate 147
UNATTRIBUTED ROOM B — recessed ceiling downlights (two) and a small white wall-mounted fixture near the ceiling corner (sensor/detector, vent, speaker or alarm keypad — not identifiable)	1	Good — fittings seated flush and securely mounted; the wall fixture cannot be identified with certainty from the record	Plate 144, Plate 146
UNATTRIBUTED ROOM B — white electrical wall sockets/switch plates on the left and right walls at skirting height	3	Good — plates intact, no scorching or cracking observed	Plate 146, Plate 147
UNATTRIBUTED ROOM B — white ceiling with a stepped bulkhead detail — recorded for condition only	1	Fair — hairline seam/crack lines visible in the ceiling bulkhead following the angled step pattern	Plate 144

ITEM AS RECORDED	QTY	CONDITION AS OBSERVED	PLATES
UNATTRIBUTED ROOM B – sage-green/grey painted walls with white skirting boards – recorded for condition only	1	Fair – light reflective glare patches on the left wall (either paint sheen variation or camera flash reflection, not resolvable); skirting sound and unmarked	Plate 146, Plate 147
UNATTRIBUTED ROOM B – wood-look plank tile/laminate flooring in brown tones – recorded for condition only	1	Fair – visible colour/tone variation between individual planks giving a patchwork appearance; glossy glare/sheen inconsistency across several planks; grout-like seams between planks with slight colour mismatch on some boards; darker rectangular patches and scattered lighter scuff marks on the floor (wear, staining or shadow – not resolvable from the record)	Plate 145
UNATTRIBUTED ROOM C (taupe/grey walls with cornice, indistinctly recorded) – window fitted with white-slat venetian blinds, a wall-mounted security/PIR sensor showing a live red LED, a white double wall socket, and three recessed ceiling downlights; the edge of a wooden furniture item is visible at the the bottom of the view	1	Fair – sensor LED illuminated, indicating the unit is powered; a diagonal seam/line runs across the ceiling, possibly a board joint. Detail at this position is not established	Plate 148

50 Rooms whose attribution is not resolved – photographic plates



Plate 143 UNATTRIBUTED ROOM A (single-bed room, pale grey/blue walls, casement window)




Plate 144 UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor)




Plate 145 UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor)




Plate 146 UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor)




Plate 147 UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor)




Plate 148 UNATTRIBUTED ROOM C (taupe/grey walls with cornice, indistinctly recorded)

51 Services, metering and keys

Recorded so that a handover can be signed against it.

SERVICE / ITEM	RECORDED	NOTE
Electricity meter	To be read at handover	Prepaid (Econ unit); DB board & meter photographed.
Water meter	To be read at handover	Municipal; locate at boundary.
Gas	To be read at handover	Smeg hob is gas — confirm bottle location & level.
Geyser / hot water	To be read at handover	Electric geyser in garage/laundry roof space.
Rainwater tank	~200L — present, good	Roof-gutter fed; feeds pool/irrigation.
Front / pedestrian gate	Keys: __ Remote: __	Motorised wood-clad sliding gate.
Garage door	Remote: __	Motorised motor — photographed.
Security trellis / burglar gates	Keys: __	Rear trellis gate; burglar bars throughout.
Alarm / electric fence	Code held by: __	Electric perimeter fence + DSC alarm panel.
House / door keys	Sets handed over: __	Confirm count with tenant at handover.

52 Safety and compliance observations

ELEMENT	AS OBSERVED	NOTE
Smoke / CO detectors	Observed: none noted	Recommend confirming/installing before tenancy — landlord to verify.
Electric fence	Present — good (visual)	Confirm energiser compliance certificate.
Security	Burglar bars, trellis & motor gate — good	
Gas appliance	Smeg gas hob	Confirm gas CoC on file.
Electrical	DB board photographed	Confirm valid Electrical CoC on file.

53 Matters left open by this record

Stated as neutral fact. Nothing here is inferred; each is simply not established by the record and is carried forward.

OPEN MATTER
POOL — water is severely green and algae-affected with sediment on the submerged steps and floor. Treatment is required before any listing photography, viewing or tenancy
Pool pump and filtration equipment were never photographed — a short follow-up record is needed to complete the plant record
Confirm the function of the wall-mounted 'DRUID' control unit
Four images are indistinct or indeterminate and carry no inventory; re-inspect if those areas matter
Room attribution to confirm for one single-bed room, one empty wood-look-tiled room and one indistinct taupe-walled room — the photographs do not establish which bedroom they are

OPEN MATTER

Appliance model and serial plates to be photographed close-up for the insurance record

Insurer name and policy number

Principal owner name behind the managing agent

Geyser, roof and gutter/rainwater-harvesting installation not recorded

Electrical and gas compliance certificates

54 Comparison at the end of the tenancy

This record is a **baseline**. At the end of the tenancy the same areas and the same surfaces are re-inspected and compared against it line by line, so that the conversation is about the difference between two dated records rather than about recollection. Anything shown here as Low — cosmetic, or fair wear and tear — is already on the landlord's side of the line and cannot later be charged to the tenant.

Important. This is a photographic condition record made on a single date. It is not a structural, electrical, gas, damp or compliance survey; nothing was opened up, moved or tested, and no comment is offered on anything concealed. Severity is an assessment of the consequence of the observation, not of the cost of putting it right. Where an observation is described as cosmetic or as fair wear, that is an opinion offered to assist the parties and is not a determination of liability between landlord and tenant. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer.