

INSURANCE EVIDENCE PACK

Insurance Evidence Pack

What is here, what it is worth, what condition it was in — and what this pack does not prove

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

AREAS RECORDED

15



1 What this pack is

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

An evidence pack assembled so that a household contents claim can be argued from a record rather than from memory. It states what is in the property, where each thing is, what condition it was in on a known date, what it would cost to replace new-for-old, and which photographic plate supports each entry.

It also states plainly what it does **not** establish. No receipts, serial plates, proofs of ownership or prior valuations were available at the date of the record, so every figure here is an opinion of value and a point of departure for discussion with an insurer — not a certified valuation.

2 Asset profile

Asset	Sample Property B — two-bedroom house	Reference	SAMPLE-B
Type	House — 2 bedroom / 2 bathroom, part-furnished	Location	City Bowl, Cape Town
Owner	Private owner — details withheld for publication	Primary use	Residential letting
Public access	No	Insurer	Not on file at the date of the record
Policy number	Not on file at the date of the record	Record date	20 July 2026

3 At a glance

358 ITEMS LOGGED	R1.46m EXPECTED REPLACEMENT	56 ITEMS OVER R8,000	92% RECORD COMPLETE
----------------------------	--	--------------------------------	-------------------------------

4 High-value asset register

Every item carrying an expected replacement estimate of R8,000 or more, in descending order.

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Fitted base cabinets and drawer units, white laminate carcass and fronts, dark brown/black kickboard strip	Kitchen	Photographic	GOOD	55,000	Plate 001, Plate 002, Plate 003, Plate 004, Plate 005
SMEG freestanding range cooker, cream/off-white body, stainless steel 5-burner gas hob with black cast-iron pan supports, digital clock/timer display, front control knobs, glass-fronted main oven with long chrome handle and lower drawer/oven compartment	Kitchen	Photographic — brand legible	FAIR	48,000	Plate 006, Plate 007, Plate 008, Plate 004, Plate 009, Plate 010
Motorised sliding driveway gate - dark-brown horizontal wood-slat panels in a galvanised steel surround, four bays divided by galvanised vertical posts, running on a ground track	Exterior & entrance	Photographic	FAIR	45,000	
Large white built-in wardrobe spanning the wall — three double-door hanging sections with rails and shelving above a built-in bank of drawers; visible metal cabinet hinges (three per door) and drawer interiors lined in dark grey/charcoal	Main bedroom suite	Photographic	GOOD	45,000	Plate 011, Plate 012, Plate 013
Fitted overhead wall cabinets, white gloss, including two hydraulic lift-up (flip-up) units, one glass-fronted, with white internal shelving	Kitchen	Photographic	GOOD	40,000	Plate 001, Plate 014, Plate 015, Plate 016, Plate 017
Built-in white melamine wardrobe run with multiple hinged doors and dark round handles/knobs — one section with a single hanging rail and shelf above, one section of five open adjustable shelves, a narrow vertical column of open cubbies, a further hanging rail section, and a shoe/shelf cubby at the base; dark bronze/black metal cabinet hinges	Bedroom 2	Photographic	GOOD	40,000	Plate 018, Plate 019, Plate 020, Plate 021
Sectional garage door to the double garage, with floor track/threshold	Garage	Photographic	GOOD	30,000	Plate 022
Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook, each with hinged double doors, internal hanging rails and shelving	Main en-suite bathroom	Photographic	GOOD	30,000	Plate 023, Plate 024, Plate 025, Plate 026

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Built-in white cabinetry to the back and side walls of the garage - overhead and floor units with hinged doors	Garage	Photographic	GOOD	28,000	Plate 022, Plate 027, Plate 028, Plate 029, Plate 030
Perimeter worktop, cream/white speckled quartz-look engineered stone, glossy finish, with matching light-grey upstand to wall join	Kitchen	Photographic	GOOD	28,000	Plate 001, Plate 031, Plate 005
Large white melamine built-in storage cupboard system with multiple full-height compartments, doors, and a section of small square/rectangular cubby shelving	Laundry / utility & storage	Photographic	FAIR	28,000	Plate 032, Plate 033
Grey/charcoal fabric L-shaped sectional sofa with chaise section	Lounge	Photographic	FAIR	26,000	Plate 034, Plate 035, Plate 036
Built-in Jetmaster braai - black steel firebox with an oval 'Jetmaster' badge above the opening, black flip-down front cooking surface/shelf, black chimney hood/flue, cast-iron adjustable grate-height hook/lever, and a grey metal ash/wood box drawer embossed 'Jetmaster'	Outdoor courtyard & braai	Photographic – brand legible	FAIR	25,000	Plate 037, Plate 038
Solid pine plank flooring, knotty honey-toned boards, with metal transition/threshold strip at the change of floor finish	Kitchen	Photographic	FAIR	25,000	Plate 004, Plate 005
Tan/caramel-brown leather sofa, corner configuration with two sections meeting at a corner, two back and two seat cushions, wooden block legs, top-stitched seams	Lounge	Photographic	FAIR	25,000	Plate 039, Plate 040, Plate 041, Plate 042
Electric fence system to boundary wall - multiple black strand wires on white/black insulator standoff brackets, running the full length of the wall, with a small yellow warning sign	Exterior & entrance	Photographic	GOOD	22,000	
Sliding glass door from the house onto the courtyard, white aluminium surround	Pool courtyard	Photographic	GOOD	22,000	Plate 043, Plate 044
Kitchen island / breakfast-bar worktop, two-tone butcher-block timber (pale yellow-toned section meeting darker reddish-brown section), on timber supports and black metal L-brackets	Kitchen	Photographic	FAIR	20,000	Plate 008, Plate 004, Plate 009, Plate 010, Plate 045

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Sliding glass door / window unit opening to the garden, glazed and framed	Main bedroom suite	Photographic	GOOD	20,000	Plate 046
DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel bar handles, digital 'Cooling+' interior control panel, blue LED interior light strip and clear plastic door bins, set into a wall niche	Kitchen	Photographic — brand legible	GOOD	19,000	Plate 047, Plate 048, Plate 049, Plate 017
White concertina/trellis security gates across the doors from the patio into the house interior, with diagonal bracing and a door lock/latch mechanism	Outdoor courtyard & braai	Photographic	GOOD	17,000	Plate 038, Plate 050, Plate 051, Plate 052, Plate 053
Built-in white melamine linen cupboard with six vertical compartments and hinged doors	Second bathroom	Photographic	GOOD	16,000	Plate 054, Plate 055
White oval built-in bathtub set into a cream/beige large-format tiled surround with tiled deck and front skirt panel	Second bathroom	Photographic	GOOD	15,000	Plate 056, Plate 057, Plate 058, Plate 059
Double/queen bed — white upholstered divan base with a bare mattress; the mattress ticking is a quilted cream/pink-and-white fabric printed with the repeating brand text "Rest Assured" in red lettering with a blue logo mark. No headboard, no bedding, linen or pillows fitted	Main bedroom suite	Photographic	FAIR	15,000	Plate 046, Plate 060, Plate 061, Plate 062
Double vanity unit — white floating cabinet carcass with a reddish-brown/bamboo-look varnished timber countertop, drawers below, partly supported on a single thin metal leg; drawer interior has a cut-out access panel for the plumbing riser	Main en-suite bathroom	Photographic	GOOD	14,000	Plate 063, Plate 064
Grey synthetic rattan/wicker outdoor three-seat sofa with grey/beige cushions	Outdoor courtyard & braai	Photographic	FAIR	13,000	Plate 050, Plate 051

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Electrical distribution board - white cover panel with two rows of circuit breakers labelled LIGHTS, LIGHTS, LIGHTS, GEYSER, TIMER, STOVE, EARTH LEAKAGE, PLUGS x5 (top row) and MAIN SWITCH, EARTH LEAKAGE, POOL, PLUGS x3, SHAVER (bottom row); Riken RKH-225 breakers; bilingual English/Afrikaans WARNING/WAARSKUWING label	Laundry / utility & storage	Photographic	GOOD	13,000	
Grey synthetic rattan/wicker outdoor armchairs with cream/off-white seat and back cushions and large beige scatter cushions	Outdoor courtyard & braai	Photographic	FAIR	12,000	Plate 065, Plate 052
Built-in fireplace recess with black metal gas/radiant fire insert, visible ribbed radiant bars and tiled hearth floor, set into a white-trimmed plaster surround	Lounge	Photographic	FAIR	12,000	Plate 066, Plate 067, Plate 068, Plate 069
Built-in white dressing table set in a recessed nook between the wardrobes — knee-hole desk surface, square wall mirror above, and a bank of drawers below (five drawer fronts visible)	Main en-suite bathroom	Photographic	GOOD	12,000	Plate 023, Plate 024, Plate 025, Plate 026
Sliding gate motor unit, mounted at the base of the gate at its right end	Exterior & entrance	Photographic	GOOD	11,000	
DEFY front-loading washing machine - dark graphite/anthracite body, round glass porthole door, digital display, single control dial, energy-rating sticker affixed to the door glass	Garage	Photographic — brand legible	GOOD	11,000	Plate 070, Plate 029
Courtyard side door/gate - dark wood-toned vertical planks in a galvanized metal surround, set into the boundary wall	Pool courtyard	Photographic	GOOD	11,000	Plate 043, Plate 071, Plate 072, Plate 073
White-framed window with white-painted expandable concertina security gate on the courtyard elevation	Pool courtyard	Photographic	GOOD	11,000	Plate 074
Grey synthetic rattan/wicker outdoor two-seater sofa with cream/off-white cushions (two back cushions and a long seat cushion split into two sections)	Outdoor courtyard & braai	Photographic	POOR	11,000	Plate 075

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
SAMSUNG flat-screen television, black, standing on black plastic feet on the TV console; 'SAMSUNG' legible on the lower bezel	Lounge	Photographic – brand legible	GOOD	11,000	Plate 076, Plate 077, Plate 078, Plate 035, Plate 079, Plate 080
Large walk-in shower enclosure with frameless glass screen/door separating the shower from the rest of the room	Main en-suite bathroom	Photographic	GOOD	11,000	Plate 081, Plate 023, Plate 082, Plate 083
Double bed with a natural wood slatted headboard, carrying a bare mattress whose ticking fabric is printed repeatedly with the brand text "REST ASSURED"	Bedroom 2	Photographic	FAIR	11,000	Plate 018, Plate 084, Plate 085
DEFY tumble dryer - silver-grey body, round door, dial control, with a yellow sticky note attached to the front panel	Garage	Photographic – brand legible	GOOD	10,000	Plate 070
Utility recess joinery - white floating shelf/wall cabinet unit over a white appliance-height countertop, with a loose thin metal/plastic trim strip lying on the counter	Laundry / utility & storage	Photographic	FAIR	10,000	Plate 086, Plate 033
Alarm and security installation in the service cupboard - beige/cream metal alarm control box with orange and black wiring, a blue circuit board/relay module, a white 'FIDELITY ADT' module with green circuit board and LED indicators, and a vented wall-mounted device plugged into a red-covered socket	Laundry / utility & storage	Photographic	FAIR	10,000	Plate 087
Paired white ceramic vessel/bowl basins set on the timber vanity countertop – left basin a rounded conical bowl, right basin a more oval/asymmetric bowl; both with visible overflow holes and chrome pop-up waste fittings	Main en-suite bathroom	Photographic	GOOD	10,000	Plate 081, Plate 023, Plate 063, Plate 088, Plate 064
DEFY front-loading washing machine, dark grey/black front, round glass door, rotary programme dial (On/Off, Cotton 20/40/60+Prewash/90/Eco, Synthetics 20, Delicate/Hand Wash 40, Downwear 40, Spin+Drain, Rinse, Drum Clean) and small digital display, green 'ENERGY A+++' label on the door glass	Laundry / utility & storage	Photographic – brand legible	POOR	9,500	Plate 089, Plate 090, Plate 033, Plate 091

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Built-in white storage cupboard with three shelves and brown/bronze-toned hinges	Laundry / utility & storage	Photographic	GOOD	9,500	Plate 092
Solid dark wood door at the far right of the covered patio	Outdoor courtyard & braai	Photographic	GOOD	9,000	Plate 038
Tall white built-in cabinet with hinged door, plus an adjacent built-in white bench/shelf unit with drawers beneath	Main en-suite bathroom	Photographic	GOOD	9,000	Plate 093
Vanity unit beneath the basin – white cabinet surround with a wood-toned, ridged teak-look slatted countertop and a drawer	Second bathroom	Photographic	GOOD	9,000	Plate 094, Plate 095
Second bare mattress bearing the "Rest Assured" brand print in red script with a blue logo mark, resting at floor level – observed in one view lying directly on the floor with no visible bed base, and in another on a low base	Bedroom 2	Photographic	POOR	9,000	Plate 096, Plate 097
White-painted expandable concertina security gate covering the sliding glass door onto the courtyard	Pool courtyard	Photographic	FAIR	8,500	Plate 043, Plate 044, Plate 074, Plate 098
DEFY dishwasher, stainless/graphite front, built in under the worktop, recessed door handle, control panel with rotary dial selector and indicator lights, green energy-rating sticker on fascia	Kitchen	Photographic – brand legible	POOR	8,500	Plate 001, Plate 099, Plate 100, Plate 005
Garage door operator - navy-blue plastic motor housing with red LED display mounted on a grey metal rail fixed to the ceiling, red twisted release cord running to a red plastic emergency-release pull toggle on the wall, with a wall-mounted motor control box	Garage	Photographic	GOOD	8,000	Plate 101
Tall white open-shelf cubby storage units	Garage	Photographic	GOOD	8,000	Plate 102, Plate 103
Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio kitchenette unit, with a manufacturer sticker on its lower left corner	Outdoor courtyard & braai	Photographic	GOOD	8,000	Plate 104, Plate 052, Plate 053

ITEM	AREA	PROOF HELD	CONDITION	EXPECTED (R)	PLATES
Wood-slat / faux-wood venetian blinds to the lounge windows and the sliding balcony door (recorded as one set; the number of individual blinds is not determinable from the photographs)	Lounge	Photographic	GOOD	8,000	Plate 039, Plate 040, Plate 076, Plate 105, Plate 035, Plate 079, Plate 080, Plate 068, Plate 069, Plate 042
Wishbone-style wooden dining chairs with woven paper-cord (rush) seats, matching the dining table	Dining	Photographic	GOOD	8,000	Plate 106, Plate 107
Retractable pleated/concertina wooden-slat skylight blind system in light natural timber, with two horizontal tensioning wires threaded through metal clips along the slats, mounted beneath a glass skylight panel	Main bedroom suite	Photographic	GOOD	8,000	Plate 108
Subtotal – items over R8,000				1,008,000	

5 Summary by area

AREA	ITEMS	LOW (R)	EXPECTED (R)	HIGH (R)
Exterior & entrance	28	59,200	112,700	200,100
Pool courtyard	23	37,380	71,600	125,800
Outdoor courtyard & braai	35	61,000	115,750	197,500
Garage	45	84,150	158,270	272,500
Laundry / utility & storage	39	89,300	144,330	228,560
Kitchen	54	188,040	290,530	439,180
Lounge	34	72,800	137,800	256,000
Dining	12	9,500	19,300	38,500
Main bedroom suite	16	63,600	113,100	185,000
Main en-suite bathroom	24	69,750	122,450	203,600
Bedroom 2	13	43,050	78,620	130,350
Second bathroom	16	33,950	62,700	107,200
Guest powder room	4	5,500	9,900	17,000

AREA	ITEMS	LOW (R)	EXPECTED (R)	HIGH (R)
Additional bedroom — attribution not resolved	14	13,600	25,300	44,500
Additional bathroom — attribution not resolved	1	0	0	0
Total	358	830,820	1,462,350	2,445,790

6 Whole-contents replacement

LOW ESTIMATE R0.83m	EXPECTED ESTIMATE R1.46m	HIGH ESTIMATE R2.45m
-------------------------------	------------------------------------	--------------------------------

New-for-old, South African Rand. An opinion of value and a point of departure for discussion with the insurer — not a certified valuation. A certified valuer should sign off the final figure, and should do so item by item for anything disputed.

7 Risk and condition matters relevant to cover

MATTER	SEVERITY	BEARING ON COVER
Pool water severely green and algae-affected, with sediment on the submerged steps and floor	HIGH	A pool in this state is a public-liability and a health matter as well as a maintenance one. It should be cleared and re-inspected before any occupation.
Exposed orange and black cabling around the alarm control box, not fully enclosed	HIGH	Exposed wiring is a live electrical exposure and may bear on an electrical compliance certificate.
Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone	HIGH	Many policies condition theft cover on a functioning alarm. The fault should be cleared and the panel confirmed armed.
No smoke or carbon-monoxide detection observed anywhere in the property	HIGH	Recommend confirming or installing detection before occupation; some policies require it.
Gas hob installed; no gas certificate of compliance on file	MEDIUM	A valid gas CoC is a statutory requirement in South Africa and is commonly a condition of cover.
No electrical certificate of compliance on file	MEDIUM	A valid electrical CoC should be held and produced with any claim.
Damp-like staining and moss/algae discolouration on an unfinished concrete wall section	HIGH	Recorded now so that any later damp claim can be tested against a dated baseline.
Electric perimeter fence, burglar bars, motorised gate and security trellis all present and in good order	SOUND	Physical security is materially better than average and is worth putting to the insurer.

8 Evidence held, and evidence not held

Stated plainly. An evidence pack that overstates what it holds is worse than no pack at all.

CLASS OF EVIDENCE	HELD	NOTE
Photographic record of every area	YES	Every area and every external elevation, on one dated inspection
Dated condition record per item	YES	358 entries, 230 findings
Brand and make legible on major appliances	PARTLY	Smeg, Defy, Samsung, DSC and Jetmaster are legible; full model and serial numbers are not
Serial numbers	NO	Data plates were not recorded close enough to read. A short follow-up inspection would close this.
Purchase receipts	NO	None supplied
Proof of ownership	NO	None supplied
Prior professional valuations	NO	None supplied
Insurer and policy details	NO	Not on file at the date of the record

9 Matters left open by this pack

OPEN MATTER
POOL — water is severely green and algae-affected with sediment on the submerged steps and floor. Treatment is required before any listing photography, viewing or tenancy
Pool pump and filtration equipment were never photographed — a short follow-up record is needed to complete the plant record
Confirm the function of the wall-mounted 'DRUID' control unit
Four images are indistinct or indeterminate and carry no inventory; re-inspect if those areas matter
Room attribution to confirm for one single-bed room, one empty wood-look-tiled room and one indistinct taupe-walled room — the photographs do not establish which bedroom they are
Appliance model and serial plates to be photographed close-up for the insurance record
Insurer name and policy number
Principal owner name behind the managing agent
Geyser, roof and gutter/rainwater-harvesting installation not recorded
Electrical and gas compliance certificates

10 Photographic evidence – the highest-value items



Plate 001 Fitted overhead wall cabinets



Plate 014 Fitted overhead wall cabinets



Plate 015 Fitted overhead wall cabinets



Plate 016 Fitted overhead wall cabinets



Plate 017 Fitted overhead wall cabinets



Plate 002 Fitted base cabinets and drawer units



Plate 003 Fitted base cabinets and drawer units



Plate 004 Fitted base cabinets and drawer units



Plate 005 Fitted base cabinets and drawer units



Plate 109 Under-sink base cabinet




Plate 031 Perimeter worktop



Plate 008 Kitchen island / breakfast-bar worktop

Important. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer. This document is a structured record based on the media and information supplied for the property and on visual assessment of it. Replacement and reinstatement figures are **opinions of value and a point of departure for discussion** – they are estimates, not certified valuations, and a certified valuer should sign off the final figure for any high-value, insured or disputed item. Confirmed facts, owner-supplied information and estimates are distinguished throughout. Condition statements describe what was visible on the recorded date; they are not a structural, electrical, gas, damp or compliance survey, and no part of the fabric was opened up, moved or tested.