



MOVE-IN CONDITION REPORT

Move-In Condition Report

The dated baseline both parties sign — including everything already wrong with the property

PROPERTY

Two-bedroom house, City Bowl, Cape Town

REFERENCE

SAMPLE-B

INSPECTION DATE

20 July 2026

AREAS RECORDED

15





1 What both parties are signing

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

This is the incoming condition report for a long-term let. It records the state of every area and every significant item on the day the property was handed over, so that at the end of the tenancy the argument is about the difference between two dated records rather than about what anybody remembers.

Fair wear and tear is already on the landlord's side of the line. Everything marked below as cosmetic or fair wear is the landlord's, not the tenant's, and cannot later be charged to the tenant. That is the point of writing it down.

2 Inspection details

Property	Sample Property B — two-bedroom house	Reference	SAMPLE-B
Location	City Bowl, Cape Town	Inspection type	Incoming — move-in baseline
Inspection date	20 July 2026	Landlord	Private owner — details withheld for publication
Tenant	To be completed at signature	Managing agent	To be completed at signature
Furnishing	Part-furnished — mattresses bare, most wardrobes and cupboards empty	Inspected by	AssetProof

3 At a glance

15 AREAS INSPECTED	358 ITEMS SCHEDULED	230 CONDITION FINDINGS	13 REQUIRING ACTION BEFORE OCCUPATION
------------------------------	-------------------------------	----------------------------------	--

4 Condition by area

The overall grade for each area, and what drives it.

AREA	CONDITION	FAIR WEAR VS DAMAGE
Exterior & entrance	ATTENTION	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section; Patchy/thin lawn areas
Pool courtyard	ATTENTION	Pool water appears green/algae-affected, not clear; Pool water green/algae-tinted (visible in background)

AREA	CONDITION	FAIR WEAR VS DAMAGE
Outdoor courtyard & braai	FAIR	Patchy/thin grass in lawn area; Weathered, discoloured/algae-stained wood on the step edging below the deck
Garage	FAIR	Crack/joint line across concrete floor near garage door threshold; Weathered/stained driveway paving
Laundry / utility & storage	ATTENTION	Exposed orange and black cabling around the alarm control box, not fully enclosed; Scattered small dark speckled marks (possible dirt or mould) on left interior panel
Kitchen	FAIR	Green/dark tarnish or residue build-up around bases of several control knobs on the right side; Wire rack tines appear bent/splayed out of alignment in places
Lounge	ATTENTION	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone; Heavy creasing and wrinkling across all leather cushions consistent with distressed-style leather or wear
Dining	GOOD	A round knot-like opening in one floorboard near the centre of the dining floor, possibly an old fixture hole; A visible seam/gap line running across the floorboards
Main bedroom suite	FAIR	One section of the venetian blind slats hangs unevenly/crookedly compared to the rest; Venetian blind slats hang unevenly/crookedly on the lower section of the window
Main en-suite bathroom	FAIR	Visible pale mineral/water staining on the tiled wall behind the basins; Visible seam/joint gap in wooden flooring near shower threshold
Bedroom 2	FAIR	Dark stain/knot mark near the front-left corner of the table top; Mattress has no bedding - fully bare, exposing printed ticking pattern
Second bathroom	GOOD	Cupboard interior appears empty apart from two towels - no visible damage to shelving; Small dark mark/residue spot near the drain area inside the basin
Guest powder room	GOOD	Inspected; no adverse finding recorded.
Additional bedroom – attribution not resolved	FAIR	Hairline seam/crack lines visible in ceiling bulkhead following the angled step pattern; Reflective glare patches to the left bedroom wall – paint sheen variation rather than a defect on the balance of what is visible
Additional bathroom – attribution not resolved	GOOD	Interior surface detail of this fitting not established; listed for closer inspection

5 Recorded before occupation, and not the tenant's

Recorded before occupation, and not the tenant's

The plunge pool was severely green and algae-affected with sediment on the submerged steps at the date of this inspection. The leather sofa carries heavy creasing and a worn, mottled surface across every cushion. The dishwasher door seal is torn and lifting at the top of the opening. All three pre-date the tenancy and are recorded here so they cannot be attributed to the tenant at move-out.

6 Existing defects – safety and urgency

To be dealt with by the landlord before or immediately after occupation.

REF	AREA	DEFECT AS OBSERVED	CLASSIFICATION	PLATE
F012	Pool courtyard	Pool water appears green/algae-affected, not clear	LANDLORD – ACT	Plate 001
F014	Pool courtyard	Pool water green/algae-tinted (visible in background)	LANDLORD – ACT	Plate 002
F016	Pool courtyard	Pool water severely green and murky, algae bloom	LANDLORD – ACT	Plate 003
F017	Pool courtyard	Dark sediment/algae buildup visible on submerged pool steps and floor	LANDLORD – ACT	Plate 003
F020	Exterior & entrance	Dark damp-like staining and moss/algae discolouration on unfinished concrete wall section	LANDLORD – ACT	Plate 004
F022	Pool courtyard	Pool water green/algae-tinted	LANDLORD – ACT	Plate 005
F024	Pool courtyard	Pool water is green/algae-affected, not clear	LANDLORD – ACT	Plate 006
F025	Pool courtyard	Dark staining/algae marks on pool wall and floor	LANDLORD – ACT	Plate 006
F107	Lounge	Amber warning indicator illuminated on the alarm panel, indicating a fault or an unset zone	LANDLORD – ACT	Plate 007
F116	Laundry / utility & storage	Exposed orange and black cabling around the alarm control box, not fully enclosed	LANDLORD – ACT	Plate 008
F151	Laundry / utility & storage	Scattered small dark speckled marks (possible dirt or mould) on left interior panel	LANDLORD – ACT	Plate 009
F228	Pool courtyard	Pool water is green and murky, indicating algae growth or neglected water treatment	LANDLORD – ACT	Plate 010
F230	Pool courtyard	Pool water is green/murky, consistent with algae or lack of maintenance	LANDLORD – ACT	Plate 011

7 Existing defects – functional, treat and monitor

REF	AREA	DEFECT AS OBSERVED	CLASSIFICATION	PLATE
F002	Outdoor courtyard & braai	Patchy/thin grass in lawn area	PRE-EXISTING	–
F003	Outdoor courtyard & braai	Weathered, discoloured/algae-stained wood on the step edging below the deck	PRE-EXISTING	Plate 012

REF	AREA	DEFECT AS OBSERVED	CLASSIFICATION	PLATE
F005	Garage	Crack/joint line across concrete floor near garage door threshold	PRE-EXISTING	—
F006	Garage	Weathered/stained driveway paving	PRE-EXISTING	—
F007	Exterior & entrance	Patchy/thin lawn areas	PRE-EXISTING	—
F009	Pool courtyard	Dust/grime buildup on the white security gate bars	PRE-EXISTING	Plate 013
F013	Pool courtyard	Water staining/discolouration on the white pool surround	PRE-EXISTING	Plate 001
F018	Pool courtyard	Hairline cracks in the white pool-surround paving	PRE-EXISTING	Plate 003
F019	Pool courtyard	Grime/staining on paving surface	PRE-EXISTING	Plate 003
F021	Exterior & entrance	Rough, unpainted/unfinished concrete patch contrasting with surrounding painted walls	PRE-EXISTING	Plate 004
F023	Pool courtyard	Hairline crack visible in paved step/platform near water butt	PRE-EXISTING	Plate 005
F032	Lounge	Heavy creasing and wrinkling across all leather cushions consistent with distressed-style leather or wear	PRE-EXISTING	Plate 014
F039	Lounge	Visible splits/cracks in the wood slats of the trunk-table top	PRE-EXISTING	Plate 015
F047	Main en-suite bathroom	Visible pale mineral/water staining on the tiled wall behind the basins	PRE-EXISTING	Plate 016
F054	Kitchen	Green/dark tarnish or residue build-up around bases of several control knobs on the right side	PRE-EXISTING	Plate 017
F063	Kitchen	Wire rack tines appear bent/splayed out of alignment in places	PRE-EXISTING	Plate 018
F064	Kitchen	Torn or lifting rubber door seal/gasket visible at top of door opening	PRE-EXISTING	Plate 018
F066	Additional bedroom – attribution not resolved	Hairline seam/crack lines visible in ceiling bulkhead following the angled step pattern	PRE-EXISTING	Plate 019
F086	Bedroom 2	Dark stain/knot mark near the front-left corner of the table top	PRE-EXISTING	Plate 020
F101	Lounge	Dark stain/blotch marks on the seat cushion of the chaise section	PRE-EXISTING	Plate 021
F103	Lounge	Natural crack/split running across the wood-slab coffee table top	PRE-EXISTING	Plate 022

REF	AREA	DEFECT AS OBSERVED	CLASSIFICATION	PLATE
F109	Lounge	Crack and open gap in the plaster where the door architrave meets the ceiling corner	PRE-EXISTING	Plate 023
F112	Garage	Floor finish appears worn/patchy in places	PRE-EXISTING	—
F113	Laundry / utility & storage	Heavy dark staining/streaking on the washing machine's front panel, especially below and around the door - possibly rust, mould, or detergent residue	PRE-EXISTING	Plate 024
F117	Laundry / utility & storage	Unpainted, unfinished timber strip at the head of the door opening	PRE-EXISTING	Plate 008
F118	Laundry / utility & storage	Bare, unfinished concrete floor with dark staining	PRE-EXISTING	Plate 025
F122	Garage	Hairline crack in wall near floor corner	PRE-EXISTING	Plate 026
F124	Garage	Concrete floor unfinished/bare	PRE-EXISTING	Plate 026
F125	Garage	Moss/algae staining on stone steps and paving	PRE-EXISTING	Plate 027
F126	Garage	Slight water staining at base of wall near garage entrance	PRE-EXISTING	Plate 027
F127	Outdoor courtyard & braai	Patchy, weedy, unmown lawn with bare soil patches	PRE-EXISTING	—
F128	Outdoor courtyard & braai	Visible horizontal crack or joint line in the low boundary wall render	PRE-EXISTING	—
F130	Outdoor courtyard & braai	Dark stain/soiling on seat cushion fabric	PRE-EXISTING	Plate 028
F131	Outdoor courtyard & braai	General soiling and creasing on cushion covers consistent with outdoor weathering	PRE-EXISTING	Plate 028
F136	Outdoor courtyard & braai	Rust on wire grill basket	PRE-EXISTING	Plate 029
F139	Outdoor courtyard & braai	Exposed unconnected plumbing pipe with no fixture attached	PRE-EXISTING	Plate 030
F140	Outdoor courtyard & braai	Interior of wall niches left as bare unpainted cement/plaster, unfinished look	PRE-EXISTING	Plate 030
F142	Outdoor courtyard & braai	Dark stain/weathering at one wooden corner joint of the coffee table	PRE-EXISTING	Plate 031
F144	Exterior & entrance	Dark algae/moisture staining on concrete steps	PRE-EXISTING	Plate 032

REF	AREA	DEFECT AS OBSERVED	CLASSIFICATION	PLATE
F145	Exterior & entrance	Hairline crack in concrete riser near planter	PRE-EXISTING	Plate 032
F150	Laundry / utility & storage	Brownish/tan smear stains on white interior back panel	PRE-EXISTING	Plate 009
F152	Laundry / utility & storage	General grime/dust build-up on interior surfaces	PRE-EXISTING	Plate 009
F162	Exterior & entrance	Driveway paving stained and weathered with dark patches	PRE-EXISTING	—
F166	Garage	Concrete floor has multiple dark stains/patches	PRE-EXISTING	Plate 033
F170	Outdoor courtyard & braai	Concrete paver steps stained and worn	PRE-EXISTING	—
F171	Outdoor courtyard & braai	Patchy lawn with bare/muddy areas	PRE-EXISTING	—
F175	Exterior & entrance	Driveway paving stained/weathered	PRE-EXISTING	—
F176	Exterior & entrance	Driveway paving stained/weathered	PRE-EXISTING	—
F177	Exterior & entrance	Paving stones heavily stained with dark patches/ discolouration throughout	PRE-EXISTING	Plate 034
F181	Garage	Ladder shows heavy paint splatter and surface wear, rust at hinge joints	PRE-EXISTING	Plate 035
F201	Kitchen	Diagonal crack or open seam at the wall corner beside the door architrave	PRE-EXISTING	Plate 036
F204	Kitchen	Metal transition strip on floor at left edge appears slightly raised/uneven	PRE-EXISTING	Plate 037
F205	Kitchen	Metal threshold strip appears slightly raised where it meets the timber floor	PRE-EXISTING	Plate 038
F220	Lounge	Leather shows extensive creasing/wrinkling and a mottled worn appearance across the visible surface - could be a distressed-style finish or actual wear, not clearly distinguishable	PRE-EXISTING	Plate 039
F221	Lounge	Leather sofa shows heavy creasing/wrinkling consistent with wear or distressed-style finish across both visible cushions	PRE-EXISTING	Plate 040
F225	Main bedroom suite	One section of the venetian blind slats hangs unevenly/ crookedly compared to the rest	PRE-EXISTING	Plate 041
F226	Main bedroom suite	Venetian blind slats hang unevenly/crookedly on the lower section of the window	PRE-EXISTING	Plate 042

8 Existing marks — fair wear and tear

Cosmetic. Recorded so that it cannot later be called damage.

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F001	Outdoor courtyard & braai	Dirt/staining in patio slab grout lines	FAIR WEAR	—
F004	Outdoor courtyard & braai	Worn/rough concrete texture on the paving/step base	FAIR WEAR	Plate 012
F008	Garage	Light scuff marks on top surface of the washing machine	FAIR WEAR	Plate 043
F010	Pool courtyard	Dry needles/debris scattered on the artificial turf	FAIR WEAR	Plate 013
F011	Exterior & entrance	Visible plaster/render texture patchiness on wall surface	FAIR WEAR	Plate 044
F015	Pool courtyard	Scuff marks and dirt on white lounge chair surfaces	FAIR WEAR	Plate 002
F026	Pool courtyard	General grime marks on paving stones	FAIR WEAR	Plate 006
F028	Pool courtyard	Small debris/insect nest clump inside one glass pane of the lantern	FAIR WEAR	Plate 045
F029	Pool courtyard	General grime and weathering to the metal body of the exterior wall lantern	FAIR WEAR	Plate 045
F030	Lounge	Sooty/blackened staining inside the fireplace insert (expected wear from use)	FAIR WEAR	Plate 046
F031	Lounge	Small chip/notch in plaster step beside the fireplace opening	FAIR WEAR	Plate 046
F034	Lounge	Visible vertical crease/wear marks and light staining on the lower front seat cushion of the grey armchair	FAIR WEAR	Plate 047
F035	Lounge	Some fine surface fuzz/pilling texture visible on the armchair fabric	FAIR WEAR	Plate 047
F036	Dining	A round knot-like opening in one floorboard near the centre of the dining floor, possibly an old fixture hole	FAIR WEAR	Plate 048
F037	Dining	A visible seam/gap line running across the floorboards	FAIR WEAR	Plate 048
F038	Dining	Table surface shows some faint watermark/blotch discoloration in the wood	FAIR WEAR	Plate 048
F040	Lounge	One slat on the trunk appears raised or misaligned relative to others	FAIR WEAR	Plate 015

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F043	Main en-suite bathroom	Visible seam/joint gap in wooden flooring near shower threshold	FAIR WEAR	Plate 049
F048	Main bedroom suite	Mattress is bare with no bedding/linen fitted	FAIR WEAR	Plate 050
F050	Kitchen	Small dark mark/dot on interior cabinet side wall, possibly a screw hole or blemish	FAIR WEAR	Plate 051
F051	Kitchen	Small brown/orange stain on the top square saucer in the stacked pile	FAIR WEAR	Plate 052
F052	Kitchen	Light dust and fingerprint smudges on toaster's stainless steel body	FAIR WEAR	Plate 053
F053	Kitchen	Faint vertical mark/shadow on painted wall near the emergency button	FAIR WEAR	Plate 054
F055	Kitchen	Light dust/residue build-up around the brand badge	FAIR WEAR	Plate 055
F056	Kitchen	Dark mark/smudge on white laminate shelf surface	FAIR WEAR	Plate 056
F057	Kitchen	Cabinet interior shows general wear consistent with under-sink storage	FAIR WEAR	Plate 056
F058	Kitchen	Staining/residue marks on black oven grill tray surface (ridged section)	FAIR WEAR	Plate 057
F059	Laundry / utility & storage	Small dark speckled marks/residue on the lower countertop surface (left of centre)	FAIR WEAR	Plate 058
F061	Kitchen	Light fingerprint/smudge marks on stainless steel door surface (minor, cosmetic)	FAIR WEAR	Plate 059
F065	Kitchen	Water spot residue and minor food debris specks on interior walls	FAIR WEAR	Plate 018
F067	Additional bedroom – attribution not resolved	Reflective glare patches to the left bedroom wall – paint sheen variation rather than a defect on the balance of what is visible	FAIR WEAR	Plate 019
F068	Additional bedroom – attribution not resolved	Glossy glare/reflection patches on several planks suggesting a sheen inconsistency or wet-look finish	FAIR WEAR	Plate 060
F069	Additional bedroom – attribution not resolved	Visible grout-like seams between planks with slight colour mismatch on some boards	FAIR WEAR	Plate 060
F071	Kitchen	Surface shows glossy sheen with some scuff/wear marks in high-traffic area near cabinets	FAIR WEAR	—

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F072	Kitchen	Floorboard gap and open seam running across the kitchen floor	FAIR WEAR	—
F073	Kitchen	Wooden spoon heads show dark staining and wear consistent with heavy use	FAIR WEAR	Plate 061
F076	Kitchen	Light water spot/residue marks on the glass lid of the front pot	FAIR WEAR	Plate 062
F077	Dining	Light reflection glare across the mid-floor area consistent with glossy tile finish, not damage	FAIR WEAR	Plate 063
F079	Bedroom 2	Mattress has no bedding - fully bare, exposing printed ticking pattern	FAIR WEAR	Plate 064
F084	Bedroom 2	Light dust settled on the blind slats	FAIR WEAR	Plate 065
F085	Bedroom 2	Visible wood knots and small round blemish/knot marks on the table top surface	FAIR WEAR	Plate 020
F087	Bedroom 2	Varnish shows minor wear/scuff sheen variation on the table top	FAIR WEAR	Plate 020
F088	Bedroom 2	Numerous natural knots across floorboards - inherent to the pine, not damage	FAIR WEAR	Plate 066
F089	Bedroom 2	Board seam gaps visible where planks meet, normal for this floor type	FAIR WEAR	Plate 066
F091	Second bathroom	Cupboard interior appears empty apart from two towels - no visible damage to shelving	FAIR WEAR	Plate 067
F097	Second bathroom	Small dark mark/residue spot near the drain area inside the basin	FAIR WEAR	Plate 068
F100	Lounge	Darker discoloured patch to one floor plank left of centre in the lounge — a stain, a water mark or natural grain variation; not resolved	FAIR WEAR	Plate 069
F102	Lounge	Fine dust/lint visible on the sofa armrest fabric	FAIR WEAR	Plate 021
F104	Lounge	Small dark marks/scuffs on the wooden console surface	FAIR WEAR	—
F105	Lounge	Small dark smudge to the lounge wall, high on the left-hand return	FAIR WEAR	Plate 070
F106	Lounge	Small dark specks and marks to the wall beside the alarm panel	FAIR WEAR	Plate 007
F108	Lounge	A few small dark specks/marks on the ceiling near the panel seams	FAIR WEAR	Plate 071

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F110	Lounge	Several small dark specks/spots on the wall to the right of the speaker	FAIR WEAR	Plate 023
F111	Garage	Various stains and scuff marks across the concrete garage floor	FAIR WEAR	—
F114	Laundry / utility & storage	General surface wear/dirt on appliance fronts	FAIR WEAR	Plate 024
F115	Laundry / utility & storage	Light smudging/fingerprints on the mirrored door surface (minor, cosmetic)	FAIR WEAR	Plate 072
F119	Laundry / utility & storage	Washing machine door area shows scuffing/grime around the door surround	FAIR WEAR	Plate 025
F120	Laundry / utility & storage	General scuffing and wear on cabinet interior surfaces	FAIR WEAR	Plate 073
F121	Laundry / utility & storage	Cluttered/disorganised storage typical of utility space	FAIR WEAR	Plate 073
F123	Garage	Scuff/dirt marks at wall base	FAIR WEAR	Plate 026
F129	Outdoor courtyard & braai	Staining on paved tiles	FAIR WEAR	—
F132	Outdoor courtyard & braai	Mild creasing/wrinkling on cushion covers	FAIR WEAR	Plate 074
F133	Outdoor courtyard & braai	Light general wear on wicker weave visible but no breaks	FAIR WEAR	Plate 074
F134	Outdoor courtyard & braai	Distinct circular amber/orange stain (resin or spill residue) on/under the glass table top corner	FAIR WEAR	Plate 075
F135	Outdoor courtyard & braai	Adjacent whitish-green residue patch near the same corner	FAIR WEAR	Plate 075
F137	Outdoor courtyard & braai	Soot and ash residue built up inside firebox and on flip-down shelf	FAIR WEAR	Plate 029
F138	Outdoor courtyard & braai	Dirt/scuff mark on green painted pillar beside braai	FAIR WEAR	Plate 029
F141	Outdoor courtyard & braai	Visible dirt/grime staining on the seat cushion of the central armchair	FAIR WEAR	Plate 031
F143	Outdoor courtyard & braai	Glass tabletop has light dust/smudging	FAIR WEAR	Plate 031
F146	Exterior & entrance	Muddy/bare patches in lawn between stepping stones	FAIR WEAR	Plate 032

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F147	Exterior & entrance	One gate panel section (top-left bay) is a noticeably lighter/different-toned wood than the rest, suggesting a repaired or replaced panel	FAIR WEAR	—
F148	Exterior & entrance	Driveway pavers show uneven weathering/staining across squares	FAIR WEAR	—
F149	Exterior & entrance	Wall paint appears slightly scuffed near gate track	FAIR WEAR	—
F153	Kitchen	Visible colour/tone mismatch seam between two different wood sections of the countertop	FAIR WEAR	Plate 076
F154	Kitchen	Light general wear/patina on hob's stainless surface	FAIR WEAR	Plate 076
F155	Laundry / utility & storage	Scattered small brownish marks/smudges in a rough horizontal band across the wall	FAIR WEAR	—
F157	Bedroom 2	Faint horizontal smudge mark on right wall at shoulder height	FAIR WEAR	Plate 077
F158	Bedroom 2	Mattress resting directly on the floor with no bed base beneath it	FAIR WEAR	Plate 077
F159	Kitchen	Diagonal scuff/scrape mark on wall surface	FAIR WEAR	—
F160	Kitchen	Scattered small dark specks (dirt or insect marks) across the wall	FAIR WEAR	—
F161	Bedroom 2	Faint smudge to the bedroom wall at mid height, left of centre	FAIR WEAR	Plate 078
F163	Exterior & entrance	Gate surface shows scuffed/worn patina	FAIR WEAR	—
F164	Outdoor courtyard & braai	Lawn has visible bare and muddy patches	FAIR WEAR	—
F167	Garage	Wooden ladder shows visible wear on rungs	FAIR WEAR	Plate 033
F169	Outdoor courtyard & braai	Wooden step edging shows heavy weathering/staining, dark patches	FAIR WEAR	—
F172	Outdoor courtyard & braai	Floor tiles appear wet/reflective near doorway	FAIR WEAR	Plate 079
F178	Exterior & entrance	Retaining wall shows surface staining	FAIR WEAR	Plate 034
F179	Exterior & entrance	Paving stained/discoloured with dark patches	FAIR WEAR	—
F180	Garage	Concrete floor shows faint stains/patch marks	FAIR WEAR	Plate 080

REF	AREA	MARK AS OBSERVED	CLASSIFICATION	PLATE
F184	Lounge	Noticeable lighter discoloured patch on the wood floor near the armchair, possible sun-fading or rug mark	FAIR WEAR	Plate 081
F185	Lounge	Small dark mark/spot on wall to left of TV, could be a scuff or nail hole	FAIR WEAR	Plate 082
F186	Lounge	Light discoloration/water-mark-like patch on the fabric of the chaise cushion, centre-right of the ottoman section	FAIR WEAR	Plate 083
F187	Second bathroom	Small square cut/access panel in the tiled tub skirt, lower left, could be read as a defect if not an intentional access hatch	FAIR WEAR	Plate 084
F188	Second bathroom	Visible floor trim/transition strip forming an odd raised outline near the corner, could indicate a floor level change or repair	FAIR WEAR	Plate 085
F190	Laundry / utility & storage	Multiple small dark specks/marks scattered on the interior surfaces of the cabinet, possibly dirt or insect debris	FAIR WEAR	Plate 086
F191	Laundry / utility & storage	Multiple small dark specks/marks on interior cabinet walls across two shelf levels	FAIR WEAR	Plate 087
F193	Additional bedroom – attribution not resolved	Diagonal seam/line across ceiling, possibly a board joint	FAIR WEAR	Plate 088
F195	Additional bedroom – attribution not resolved	Visible colour/tone variation between individual floor tiles (patchwork appearance)	FAIR WEAR	Plate 089
F199	Additional bedroom – attribution not resolved	Floor shows scattered lighter scuff marks	FAIR WEAR	Plate 090
F202	Kitchen	Fridge door surface shows reflected glare and minor smudging	FAIR WEAR	Plate 036
F206	Kitchen	Floorboard seam/gap visible near the threshold strip	FAIR WEAR	Plate 038
F213	Dining	Small round metal fitting embedded in floor within the seamed area	FAIR WEAR	Plate 091
F216	Lounge	A scuff or chip mark is visible on the white skirting board directly in front of the fireplace opening	FAIR WEAR	Plate 092
F217	Lounge	Fireplace interior sooted and darkened, consistent with use; the recess is unlit and the flue was not inspected	FAIR WEAR	Plate 092
F227	Main bedroom suite	Numerous water spots/droplets on the window glass behind the blinds	FAIR WEAR	Plate 093

9 Furnished inventory handed over

The tenant takes responsibility for these. Quantities and condition as at the date of inspection.

AREA	ITEM	QTY	CONDITION
Exterior & entrance	Electric fence system to boundary wall - multiple black strand wires on white/black insulator standoff brackets, running the full length of the wall, with a small yellow warning sign	1	GOOD
Exterior & entrance	White satellite dish mounted on roof pillar	1	GOOD
Exterior & entrance	Motorised sliding driveway gate - dark-brown horizontal wood-slat panels in a galvanised steel surround, four bays divided by galvanised vertical posts, running on a ground track	1	FAIR
Exterior & entrance	Sliding gate motor unit, mounted at the base of the gate at its right end	1	GOOD
Exterior & entrance	Driveway planter display - terracotta and plastic pots holding aeonium/echeveria-type succulents and aloes, with driftwood/root decor pieces	1	GOOD
Exterior & entrance	Prickly-pear (Opuntia) cactus and a small green succulent in metal/ceramic pots on the low wall beside the steps, with loose driftwood pieces set in beside them	2	GOOD
Exterior & entrance	Small teal-blue plant pots with seedlings, placed on the edges of the concrete steps	2	GOOD
Exterior & entrance	Teal-green wheelie-bin-style container standing beside the front garden planter	1	GOOD
Exterior & entrance	Dark grey plastic wheelie bins standing on the driveway paving, the right-hand one hand-painted in white lettering 'the property [locality redacted]'	2	GOOD
Exterior & entrance	Green plastic cylindrical rainwater/water storage tank standing in the side passage against the wall	1	GOOD
Exterior & entrance	White PVC downpipes and surface plumbing running down the side passage wall	1	GOOD
Exterior & entrance	Black wrought-iron side gate in the side passage	1	GOOD
Exterior & entrance	Small white wall-mounted sensor/box on the side passage wall	1	GOOD
Exterior & entrance	Roof-level pipe manifold - cluster of blue and copper-coloured pipes with valves and fittings mounted at the ceiling/wall junction under the overhang	1	GOOD
Exterior & entrance	Black wall-mounted light fixture and adjacent electrical junction/inspection cover on the roof terrace	1	GOOD
Exterior & entrance	Pale-green access hatch/door in the roof-terrace wall, standing open over a recessed water meter or valve assembly	1	GOOD

AREA	ITEM	QTY	CONDITION
Exterior & entrance	Folding clothes-drying rack standing on the roof terrace	1	GOOD
Exterior & entrance	Washing-line wires strung across the roof terrace, with a TV aerial/satellite mount alongside	1	GOOD
Exterior & entrance	Black burglar bars to the window in the cream/beige wall at roof-terrace level	1	GOOD
Exterior & entrance	Boundary outlook from the roof terrace – mature planting and rooflines beyond the boundary wall, recorded for context	1	GOOD
Pool courtyard	White plastic sun-lounger chairs with adjustable slatted backrests, one fitted with caster wheels on its front legs	2	FAIR
Pool courtyard	Courtyard side door/gate - dark wood-toned vertical planks in a galvanized metal surround, set into the boundary wall	1	GOOD
Pool courtyard	Dark grey wall-mounted post box/mailbox beside the courtyard gate	1	GOOD
Pool courtyard	Electric fence strand wires running along the top of the courtyard boundary wall	1	GOOD
Pool courtyard	Black wrought-iron lantern wall lights on the courtyard-facing house wall - square frosted-glass shades divided into a 3x3 grid by black metal muntins, on curled scroll brackets, one larger and one smaller	2	FAIR
Pool courtyard	White-painted expandable concertina security gate covering the sliding glass door onto the courtyard	1	FAIR
Pool courtyard	Sliding glass door from the house onto the courtyard, white aluminium surround	1	GOOD
Pool courtyard	Black plastic water butt/rainwater container standing on the raised paved step beneath the downpipe	1	GOOD
Pool courtyard	Rainwater downpipe serving the courtyard - black plastic hopper box on the wall feeding a white PVC pipe run	1	GOOD
Pool courtyard	Dark ceramic/stone garden ornaments standing on the paving at the base of the courtyard wall - one vase and one lantern-shaped ornament	2	GOOD
Pool courtyard	White PVC pool pipe (skimmer/equipment line) lying across the corner of the pool surround	1	FAIR
Pool courtyard	Small yellow plastic pool test-kit vial floating at the pool edge	1	GOOD
Pool courtyard	White security/burglar bars to the courtyard-facing windows - vertical bars and a white diamond-pattern panel	1	GOOD
Pool courtyard	White-framed window with white-painted expandable concertina security gate on the courtyard elevation	1	GOOD
Pool courtyard	Small rectangular grey wall-mounted light fixture above the courtyard door	1	GOOD

AREA	ITEM	QTY	CONDITION
Outdoor courtyard & braai	Built-in Jetmaster braai - black steel firebox with an oval 'Jetmaster' badge above the opening, black flip-down front cooking surface/shelf, black chimney hood/flue, cast-iron adjustable grate-height hook/lever, and a grey metal ash/wood box drawer embossed 'Jetmaster'	1	FAIR
Outdoor courtyard & braai	Wire mesh grill basket with folding handle, sitting on the braai grate	1	POOR
Outdoor courtyard & braai	Round stainless-steel undermount bar sink in the braai counter, with a single chrome wall-mounted tap and chrome U-bend plumbing beneath	1	GOOD
Outdoor courtyard & braai	Grey synthetic rattan/wicker outdoor two-seater sofa with cream/off-white cushions (two back cushions and a long seat cushion split into two sections)	1	POOR
Outdoor courtyard & braai	Grey synthetic rattan/wicker outdoor three-seat sofa with grey/beige cushions	1	FAIR
Outdoor courtyard & braai	Grey synthetic rattan/wicker outdoor armchairs with cream/off-white seat and back cushions and large beige scatter cushions	2	FAIR
Outdoor courtyard & braai	Grey synthetic rattan/wicker coffee table with a tempered glass top set into a rattan-wrapped surround with exposed circular wooden corner joints	1	POOR
Outdoor courtyard & braai	Green woven fabric cover or cushion laid over the patio coffee table	1	GOOD
Outdoor courtyard & braai	Wall-mounted black flat-screen TV/monitor set into the upper alcove of the patio kitchenette unit, with a manufacturer sticker on its lower left corner	1	GOOD
Outdoor courtyard & braai	Exposed copper/brass plumbing pipe with a P-trap bend and isolation valve protruding from the lower kitchenette niche	1	POOR
Outdoor courtyard & braai	Cream-coloured electrical socket/switch plates on the patio and kitchenette walls	1	GOOD
Outdoor courtyard & braai	White concertina/trellis security gates across the doors from the patio into the house interior, with diagonal bracing and a door lock/latch mechanism	2	GOOD
Outdoor courtyard & braai	Solid dark wood door at the far right of the covered patio	1	GOOD

AREA	ITEM	QTY	CONDITION
Outdoor courtyard & braai	Wall-mounted lantern-style light fixture centred above the patio opening	1	GOOD
Outdoor courtyard & braai	Wooden venetian blinds/shutters behind the glazed patio doors	1	GOOD
Outdoor courtyard & braai	Potted plants in terracotta, concrete and metal planters through the rear garden and patio bed - including a large potted aloe, agave, cactus and a small cactus/succulent in a metal planter box	1	GOOD
Outdoor courtyard & braai	Weathered grey driftwood/root decor - a sculpture piece on the patio and a large driftwood log used as a planter display, plus a driftwood piece at the base of the patio wall	1	GOOD
Outdoor courtyard & braai	Garden hose, coiled and lying across the rear lawn	1	GOOD
Outdoor courtyard & braai	Small teal/turquoise planter with greenery on the patio	1	GOOD
Garage	Sectional garage door to the double garage, with floor track/threshold	1	GOOD
Garage	Garage door operator - navy-blue plastic motor housing with red LED display mounted on a grey metal rail fixed to the ceiling, red twisted release cord running to a red plastic emergency-release pull toggle on the wall, with a wall-mounted motor control box	1	GOOD
Garage	Wall-mounted control unit branded 'DRUID', black housing with digital display and multiple labelled buttons	1	GOOD
Garage	Grey electrical distribution box mounted on the garage wall below the DRUID control unit	1	GOOD
Garage	Built-in white cabinetry to the back and side walls of the garage - overhead and floor units with hinged doors	1	GOOD
Garage	Tall white open-shelf cubby storage units	1	GOOD
Garage	DEFY front-loading washing machine - dark graphite/anthracite body, round glass porthole door, digital display, single control dial, energy-rating sticker affixed to the door glass	1	GOOD
Garage	DEFY tumble dryer - silver-grey body, round door, dial control, with a yellow sticky note attached to the front panel	1	GOOD
Garage	Stainless-steel microwave oven standing at floor level beside the laundry appliances	1	FAIR
Garage	Laundry sink/basin with two taps, set beside the washer and dryer	1	GOOD
Garage	Laundry basket on a small rolling stand	1	GOOD

AREA	ITEM	QTY	CONDITION
Garage	White fold-up ironing board	1	GOOD
Garage	Manual push reel lawnmower, black body with red wheels	1	GOOD
Garage	Electric push lawnmower, orange and black, with black grass-catcher box and a red coiled extension cord wrapped around the handle	1	GOOD
Garage	Black plastic bucket	1	GOOD
Garage	Wooden ladder (extension type) leaning against the garage wall	1	POOR
Garage	Aluminium step ladder leaning against the garage back wall	1	GOOD
Garage	Wall-mounted fire extinguisher	1	GOOD
Garage	Folded wooden clothes airer/drying rack leaning against the garage wall	1	GOOD
Garage	Wooden slatted bed base and headboard stored upright against the garage wall, with two grey/beige bath mats or rugs draped over the top rail	1	GOOD
Garage	Long-handled garden and cleaning tools stored upright in the shelving - broom with red-and-silver handle, mop, red-headed garden rake, orange-tined leaf rake, spade and a black extendable pole	1	GOOD
Garage	Red-and-black vacuum cleaner or steam mop stored in the garage cupboard	1	GOOD
Garage	Cleaning supplies in a grey plastic basin on the cupboard shelf - white spray bottle, part-used yellow-labelled bottle, blue washing-up liquid bottle and other containers	1	GOOD
Garage	Capsule coffee machine, black body with white/chrome accent ring and stainless steel drip tray, stored on a cupboard shelf	1	GOOD
Garage	Orbital/disc sander power tool stored on the cupboard shelf	1	GOOD
Garage	Blue strap/tie-down stored on the cupboard shelf	1	GOOD
Garage	Small red-and-blue boxes stacked at the front of the cupboard shelf	1	GOOD
Garage	Grey plastic wheelie/pedal bin marked 'C.C.C.' standing inside the garage	1	GOOD
Garage	Mop bucket with mop handle, and dustpan	1	GOOD
Garage	Small white waste/pedal bin standing near the garage side door	1	GOOD
Garage	White side door with round knob, leading from the garage into the house	1	GOOD
Garage	Wall-mounted key hook	1	GOOD
Garage	White wall-mounted electrical box/socket with surface cable run	1	GOOD
Garage	Small trolley/hand-truck	1	GOOD
Garage	Wooden-framed panel or mirror leaning against the garage wall	1	GOOD
Garage	Wooden workbench top in the garage cupboard run	1	GOOD

AREA	ITEM	QTY	CONDITION
Garage	Aluminium folding table stored beside the laundry appliances	1	GOOD
Garage	Yellow-handled long tool and stacked grey/black plastic buckets	1	GOOD
Garage	Assorted stored goods on the garage shelving - shoes, storage boxes, tins and cans, a plastic bowl, a small plant pot and a brown paper bag	1	GOOD
Garage	Stored cardboard boxes and flattened cardboard on the garage floor	1	FAIR
Garage	Black lantern-style wall light fixture mounted on the exterior wall above the garage opening	1	GOOD
Laundry / utility & storage	DEFY front-loading washing machine, dark grey/black front, round glass door, rotary programme dial (On/Off, Cotton 20/40/60+Prewash/90/Eco, Synthetics 20, Delicate/Hand Wash 40, Downwear 40, Spin+Drain, Rinse, Drum Clean) and small digital display, green 'ENERGY A+++' label on the door glass	1	POOR
Laundry / utility & storage	DEFY tumble dryer, silver front-loader with round porthole door and timer dial, carrying a yellow 'Autodryer Operations' instruction sticker, a red/white 'DO NOT OVERLOAD THE DRUM - RECOMMENDED LOAD' warning sticker and a green energy-rating sticker	1	FAIR
Laundry / utility & storage	DEFY microwave oven, silver/mirrored finish, standing on the timber shelf above the laundry appliances; labelled preset panel (BAKED POTATO, POPCORN, PIZZA, BEVERAGE, FROZEN DINNER, REHEAT, POWER, TIMER, CLOCK, RESET, COOK, COOK BY WEIGHT, START/STOP, DEFROST BY WEIGHT, SPEED DEFROST) and numeric keypad	1	GOOD
Laundry / utility & storage	Chrome double wall hook, utility recess side wall	1	GOOD
Laundry / utility & storage	Wooden venetian blind to the utility area window	1	GOOD
Laundry / utility & storage	Laundry sink/trough with two exposed chrome tap fittings above and visible P-trap plumbing beneath (recorded as a white plastic rectangular basin in one view and a stainless-steel wall-mounted trough in another)	1	FAIR
Laundry / utility & storage	Ironing board with green-and-cream / green-and-blue checked patterned cover	1	GOOD
Laundry / utility & storage	Black dustpan and brush set	1	GOOD
Laundry / utility & storage	Yellow-handled mop with grey plastic mop bucket	2	FAIR
Laundry / utility & storage	Black plastic bucket containing small metal fittings/hardware	1	FAIR
Laundry / utility & storage	Genesis CycloVac cyclonic vacuum cleaner (Verimark), boxed - 'The ideal compact & powerful cyclonic vacuum'	1	EXCELLENT

AREA	ITEM	QTY	CONDITION
Laundry / utility & storage	Red canister-style handheld cleaning appliance (vacuum or steam cleaner), stored in the utility cupboard	1	FAIR
Laundry / utility & storage	Steam iron, blue and white, with woven/braided cord	1	GOOD
Laundry / utility & storage	Boxed DEFY-branded item (black box, appears to be a small appliance), stored on a cupboard shelf	1	GOOD
Laundry / utility & storage	White plastic multi-hook organiser	1	GOOD
Laundry / utility & storage	Clear plastic bag containing folded white/blue fabric items with blue text (possibly aprons or linens)	1	GOOD
Laundry / utility & storage	Brown plastic 'Coconut Oil' toiletry bottles (shampoo/conditioner pair)	2	GOOD
Laundry / utility & storage	Cleaning consumables on the lower cupboard shelf - purple spray bottle, green/white bottle, blue-capped spray bottle, an aerosol can with red cap, a clear bottle with black cap, an orange bottle, and a pack labelled 'DRY CARPET & FABRIC CLEANER'	7	GOOD
Laundry / utility & storage	Assorted stored items on the cupboard middle shelf - black shoe stretcher/boot form, round grey lid/pan, and navy and brown/tan fabric belts or straps	3	FAIR
Laundry / utility & storage	Black pod-style (Nespresso-type) coffee machine, stored on a utility cupboard shelf	1	FAIR
Laundry / utility & storage	Long-handled cleaning and garden tools stored in the cupboard - black wet/dry mop system with red handle, orange plastic leaf rake, and further mop and broom handles	4	FAIR
Laundry / utility & storage	Utility cupboard contents - grey plastic basin, cleaning spray bottles and bottles of liquid on the lower shelf, a brown paper bag, a coiled blue cable/strap and a black drawstring bag	1	FAIR
Laundry / utility & storage	Red toolbox stored on the shelf above the laundry counter	1	FAIR
Laundry / utility & storage	Clear plastic laundry basket	1	GOOD
Laundry / utility & storage	Metal-legged side table in the laundry nook	1	GOOD
Laundry / utility & storage	Beige stone/marble-look stool or side table	1	GOOD
Laundry / utility & storage	Glade Secrets 'Ocean Escape' air freshener can and a HellermannTyton TOP Tronic instruction leaflet stored at the distribution board	2	GOOD
Kitchen	Painted kitchen walls and splashback, grey/putty finish	1	FAIR

AREA	ITEM	QTY	CONDITION
Kitchen	Horizontal venetian blind to kitchen window (recorded as white slats in one view and light wood-tone slats in another), with decorative bead curtain hanging at the window edge	1	GOOD
Kitchen	Wall-mounted stainless steel utensil rail with three S-hooks	1	GOOD
Kitchen	SMEG freestanding range cooker, cream/off-white body, stainless steel 5-burner gas hob with black cast-iron pan supports, digital clock/timer display, front control knobs, glass-fronted main oven with long chrome handle and lower drawer/oven compartment	1	FAIR
Kitchen	DEFY dishwasher, stainless/graphite front, built in under the worktop, recessed door handle, control panel with rotary dial selector and indicator lights, green energy-rating sticker on fascia	1	POOR
Kitchen	DEFY side-by-side double-door stainless steel fridge/freezer with paired brushed-steel bar handles, digital 'Cooling+' interior control panel, blue LED interior light strip and clear plastic door bins, set into a wall niche	1	GOOD
Kitchen	DEFY 4-slice stainless steel toaster, two browning dials, buttons labelled DEFROST / REHEAT / CANCEL in maroon, black cord with SA 3-round-pin plug	1	FAIR
Kitchen	Stainless steel undermount sink with chrome gooseneck mixer tap and associated plumbing (grey P-trap, braided flexible supply hoses, black woven cable-protector sleeve)	1	GOOD
Kitchen	Pump-top liquid soap/sanitiser dispenser bottle on the counter	1	GOOD
Kitchen	Grey dish-drying rack	1	GOOD
Kitchen	Clear stemmed wine/cocktail glasses, stored upside down on cabinet shelf	10	GOOD
Kitchen	Clear glass tumblers - two tall ribbed/fluted tumblers plus a stack of approximately three shorter glasses	5	GOOD
Kitchen	Clear fluted glass vase/tumbler	1	GOOD
Kitchen	White and cream ceramic mugs and cups - one large white mug with handle, one small white espresso/demitasse cup, two tall handleless white cylindrical cups, one taller pale beige/putty mug with handle; three further cream ceramic mugs seen in a second cabinet view	5	GOOD
Kitchen	Square white ceramic saucers/side plates, stacked	5	FAIR
Kitchen	Large white dinner plates, plain, matching set	4	GOOD
Kitchen	White side plates, plain, matching set	4	GOOD
Kitchen	Small white bowls, plain, matching set	4	GOOD
Kitchen	Medium white/cream bowls, plain, matching set	5	GOOD
Kitchen	Shallow white pasta/serving bowls	2	GOOD

AREA	ITEM	QTY	CONDITION
Kitchen	Plastic cutlery organiser tray printed 'teaspoons'	1	GOOD
Kitchen	Stainless steel dinner/table spoons	5	GOOD
Kitchen	Stainless steel table forks	4	GOOD
Kitchen	Stainless steel table knives	5	GOOD
Kitchen	Small stainless steel teaspoons	2	GOOD
Kitchen	Black-handled steak/utility knife set standing in a drawer slot	5	GOOD
Kitchen	Black-handled kitchen knives of varying blade sizes (4) plus one black-handled meat cleaver	5	GOOD
Kitchen	Black plastic slotted turners/spatulas with stainless steel handles (drawer-stored)	2	GOOD
Kitchen	Black Y-shaped vegetable peeler	1	GOOD
Kitchen	Black kitchen scissors/shears	1	GOOD
Kitchen	Black-handled ladle/scoop with round bowl (drawer-stored)	1	GOOD
Kitchen	Black plastic measuring spoons on a ring	3	GOOD
Kitchen	Wooden cooking spoons/turners	3	FAIR
Kitchen	Black-handled utensils hanging on the wall rail/hooks (observed as a slotted serving spoon, a solid serving spoon and a stainless wire whisk in one view; a ladle and two turners in another)	3	GOOD
Kitchen	Stainless steel pots/saucepans of varying sizes with glass lids and black/grey silicone-covered handles, in a grey non-slip lined drawer	4	GOOD
Kitchen	Black enamel oven grill/roasting tray, ridged and flat sections	1	FAIR
Kitchen	Oven mitt with floral/patterned fabric (blue, yellow, orange) and quilted pot-holder/oven glove in pink and green patterned fabric	2	GOOD
Kitchen	Folded appliance instruction/warranty document printed 'SAFEWAY STOVETOP KETTLE', stored in a kitchen drawer	1	GOOD
Kitchen	Under-sink cleaning consumables - Sunlight Platinum dishwashing liquid ('5X GREASE CUTTING POWER'), a green packet of Heavy Duty scourers, a bundle of steel wool scourers in plastic packaging, and a dish brush with red plastic head	4	GOOD
Kitchen	Cleaning items in the cabinet beside the dishwasher - green sponge/scourer, green cloth and an amber-coloured dishwashing liquid bottle with red cap	3	GOOD
Kitchen	Backless bar stools, galvanised/raw steel finish with cross-braced legs and square wooden seat tops, at the breakfast bar	2	GOOD
Kitchen	White cylindrical ceramic canister with wooden lid, on the island counter	1	GOOD

AREA	ITEM	QTY	CONDITION
Kitchen	Folded blue-and-white striped cloth/napkin on the island counter	1	GOOD
Kitchen	Refrigerator accessories - ice-cube tray, two blue plastic ice/freezer blocks and white egg-crate style trays	4	GOOD
Lounge	Built-in fireplace recess with black metal gas/radiant fire insert, visible ribbed radiant bars and tiled hearth floor, set into a white-trimmed plaster surround	1	FAIR
Lounge	Fireplace tools - small black hearth brush and a black poker/tool, resting on the tiled hearth and hanging inside the fireplace opening	2	GOOD
Lounge	Grey woven-fabric wingback armchair, buttoned/tufted back panel with 12 buttons in a 3x4 grid, pale wood tapered legs	1	FAIR
Lounge	Grey/charcoal fabric L-shaped sectional sofa with chaise section	1	FAIR
Lounge	Scatter cushions for the grey sectional sofa, matching grey / charcoal-navy velvet-look fabric	5	GOOD
Lounge	Tan/caramel-brown leather sofa, corner configuration with two sections meeting at a corner, two back and two seat cushions, wooden block legs, top-stitched seams	1	FAIR
Lounge	Round live-edge wood-slab coffee table (tree-trunk cross-section, visible growth rings and retained bark edge) on thin black metal hairpin legs	1	FAIR
Lounge	Wooden TV console / low media bench with visible knots in the timber top	1	FAIR
Lounge	SAMSUNG flat-screen television, black, standing on black plastic feet on the TV console; 'SAMSUNG' legible on the lower bezel	1	GOOD
Lounge	SAMSUNG television remote control, black with a red power button, resting on the TV console	1	GOOD
Lounge	SAMSUNG wireless satellite speakers, black with chrome/cream bases, wall-mounted high in the room corners ('SAMSUNG' printed on the face of each)	2	GOOD
Lounge	Soundbar-style audio unit sitting beneath the television screen on the TV console	1	FAIR
Lounge	DSC wall-mounted alarm keypad, white, zone numbers 1-16 printed on the fascia	1	FAIR
Lounge	Chevron-pattern fabric floor poufs / storage cubes - two red-and-cream, one black-and-cream - stored beneath the TV console	3	GOOD
Lounge	Organic star/leaf-shaped carved wood side table with a hollowed bowl-like natural-edge top, on three thin black angled metal legs	1	GOOD
Lounge	Rustic reclaimed-wood slatted chest/trunk in use as a coffee table, rough-cut slats of varying tone with visible gaps	1	FAIR
Lounge	Cowhide-pattern rug, white and brown patches	1	GOOD
Lounge	Small round grey rug beneath the tufted armchair	1	GOOD

AREA	ITEM	QTY	CONDITION
Lounge	Blue/navy upholstered armchair with wooden arm surround and a matching blue scatter cushion (described in one photograph as the corner of another blue upholstered seat; configuration not fully resolved)	1	GOOD
Lounge	Wishbone-style wooden chair with woven paper-cord seat, standing in the lounge beside the fireplace (matches the dining chairs; may be one of the dining set relocated - not confirmed)	1	GOOD
Lounge	Wood-slat / faux-wood venetian blinds to the lounge windows and the sliding balcony door (recorded as one set; the number of individual blinds is not determinable from the photographs)	1	GOOD
Lounge	Sliding glass door to the balcony with white metal security grille/gate	1	GOOD
Lounge	Lounge flooring - wood-look plank tile in a mixed herringbone/staggered pattern in the main area, transitioning to lighter solid timber strips and to wide-plank grey-brown reclaimed-look boards at the fireplace end	1	FAIR
Lounge	Lounge wall finishes and paint - recorded variously as pale cream/off-white, pale grey, greige, sage-green and grey-blue across the different wall planes	1	FAIR
Lounge	Ceiling - white panelled/coffered ceiling with raised trim lines forming a geometric pattern	1	FAIR
Lounge	Decorative white cornice/coving to the wall-ceiling junction	1	FAIR
Lounge	White painted skirting boards throughout the lounge	1	FAIR
Lounge	Recessed ceiling downlights (small round fittings; one observed illuminated warm white)	2	GOOD
Lounge	Ceiling-mounted smoke detector near the lounge corner	1	FAIR
Lounge	Wall-mounted white intercom / entry-phone handset with coiled cord, with an adjacent white single switch and a small round wall-mounted device (doorbell chime or sensor; not identified)	1	GOOD
Lounge	Small chrome/silver wall hooks fixed to the lounge wall, both empty	2	GOOD
Lounge	Two-gang toggle light switch on the lounge wall beside the doorway	1	GOOD
Lounge	Set of keys hanging on a hook / at the switch plate beside the lounge doorway	1	GOOD
Lounge	Internal door to the lounge - white painted door with silver lever handle and deadbolt/keyhole plate, in a white-painted surround	1	GOOD
Dining	Wooden dining table with tapered legs (recorded as square and dark-stained in one photograph and as rectangular and medium-brown in another; shape and finish not fully resolved between the two views)	1	FAIR
Dining	Wishbone-style wooden dining chairs with woven paper-cord (rush) seats, matching the dining table	4	GOOD

AREA	ITEM	QTY	CONDITION
Dining	Dining area flooring - solid honey-brown pine plank boards with visible knots and grain	1	FAIR
Dining	Dining area wall finish (pale grey paint) with a white double round-pin wall socket	1	GOOD
Dining	Black cylindrical flue pipe (possibly a wood-burning stove flue) rising at the edge of the dining area	1	FAIR
Dining	Passage/hallway flooring - wood-look plank tile running from the lounge doorway toward the front door	1	GOOD
Dining	Passage/hallway wall finish - grey/light-taupe to cream-beige paint with white skirting	1	GOOD
Dining	Front entrance door - white, with narrow glass side panels	1	GOOD
Dining	Internal hinged doors off the passage - white painted, in white surrounds (one on the left of the passage, one standing ajar to the bathroom beyond)	2	GOOD
Dining	Two-gang white light switch on the passage wall	1	GOOD
Dining	White console table / shoe rack standing against the passage wall by the front door	1	GOOD
Dining	White decorative wire/lattice screen or gate, seen from the passage in the room to the right of the front door (position beyond the passage; area assignment provisional)	1	GOOD
Main bedroom suite	Double/queen bed — white upholstered divan base with a bare mattress; the mattress ticking is a quilted cream/pink-and-white fabric printed with the repeating brand text "Rest Assured" in red lettering with a blue logo mark. No headboard, no bedding, linen or pillows fitted	1	FAIR
Main bedroom suite	Pine bedside tables flanking the bed — a taller narrow one at the head end and a lower, wider one with an open lower shelf at the foot side (mismatched pair)	2	GOOD
Main bedroom suite	Large white built-in wardrobe spanning the wall — three double-door hanging sections with rails and shelving above a built-in bank of drawers; visible metal cabinet hinges (three per door) and drawer interiors lined in dark grey/charcoal	1	GOOD
Main bedroom suite	White multi-drawer chest / drawer unit standing in the room (seen directly in one view and in mirror reflection in another; may form part of the fitted wardrobe run — to confirm)	1	GOOD
Main bedroom suite	Wooden desk or side table with visible legs standing at the window end of the room	1	GOOD
Main bedroom suite	Sliding glass door / window unit opening to the garden, glazed and framed	1	GOOD
Main bedroom suite	Wooden-slat / faux-wood venetian blinds to the sliding door and the bedroom windows	2	FAIR

AREA	ITEM	QTY	CONDITION
Main bedroom suite	White diamond/square-grid burglar-bar security grilles fitted externally to the glazing	2	GOOD
Main bedroom suite	Recessed ceiling downlights set into the sloped ceiling (two illuminated in one view with a third dimmer fitting further along)	3	GOOD
Main bedroom suite	Retractable pleated/concertina wooden-slat skylight blind system in light natural timber, with two horizontal tensioning wires threaded through metal clips along the slats, mounted beneath a glass skylight panel	1	GOOD
Main bedroom suite	Wall-mounted white sensor/detector (alarm PIR or smoke detector) fixed high on the wall at the ceiling junction	1	GOOD
Main bedroom suite	White wall-mounted power sockets, including a double socket beside the bed	2	GOOD
Main bedroom suite	White panelled bedroom door with round silver doorknob and visible keyhole lock	1	GOOD
Main bedroom suite	Angled/cathedral white ceiling with white cornice and a grey painted wall band below the cornice – recorded for condition only	1	GOOD
Main bedroom suite	Grey / pale grey-green painted wall finish with white skirting boards – recorded for condition only	1	GOOD
Main bedroom suite	Honey-toned pine plank timber flooring with visible knots and a polished/glossy finish – recorded for condition only	1	GOOD
Main en-suite bathroom	Paired white ceramic vessel/bowl basins set on the timber vanity countertop – left basin a rounded conical bowl, right basin a more oval/asymmetric bowl; both with visible overflow holes and chrome pop-up waste fittings	2	GOOD
Main en-suite bathroom	Chrome gooseneck-style single-lever mixer taps serving the paired basins (left tap tall gooseneck, right tap shorter)	2	GOOD
Main en-suite bathroom	Double vanity unit – white floating cabinet carcass with a reddish-brown/bamboo-look varnished timber countertop, drawers below, partly supported on a single thin metal leg; drawer interior has a cut-out access panel for the plumbing riser	1	GOOD
Main en-suite bathroom	Rectangular/square white-framed wall mirrors, one above each basin	2	GOOD
Main en-suite bathroom	Chrome wall-mounted cup / toothbrush holder fixed to the wall between the two mirrors	1	GOOD
Main en-suite bathroom	Chrome cylindrical wall-mounted dispenser (soap or lotion) fixed beneath the mirror to the right of the basin	1	GOOD
Main en-suite bathroom	Large walk-in shower enclosure with frameless glass screen/door separating the shower from the rest of the room	1	GOOD
Main en-suite bathroom	Chrome shower fittings – rectangular/rose shower head on a rigid angled wall arm, plus a separate chrome round mixer valve with visible tubing running down the tiled wall	1	GOOD

AREA	ITEM	QTY	CONDITION
Main en-suite bathroom	Shower floor and feature wall in beige/brown checkerboard mosaic tiling with a chrome square floor drain grate — recorded for condition only	1	GOOD
Main en-suite bathroom	Large-format beige/taupe rectified wall tiling to the shower and vanity walls — recorded for condition only	1	FAIR
Main en-suite bathroom	White two-piece close-coupled toilet with cistern and seat	1	GOOD
Main en-suite bathroom	Wall-mounted toilet-roll holder with one roll loaded; spare toilet rolls stacked on the cistern lid (one spare roll plus another item in one view, two spare rolls in another, three spare rolls in another)	1	GOOD
Main en-suite bathroom	Beige / tan-striped bath towels hung over the rail beside the window and over the heater rail	2	GOOD
Main en-suite bathroom	Wall-mounted panel heater with a small adjacent thermostat / control panel, and the towel rail/radiator carrying a beige towel	1	GOOD
Main en-suite bathroom	Built-in white gloss wardrobe/cabinet units flanking the dressing-table nook, each with hinged double doors, internal hanging rails and shelving	2	GOOD
Main en-suite bathroom	Built-in white dressing table set in a recessed nook between the wardrobes — knee-hole desk surface, square wall mirror above, and a bank of drawers below (five drawer fronts visible)	1	GOOD
Main en-suite bathroom	Full-length mirrored sliding wardrobe door with silver/aluminium surround	1	GOOD
Main en-suite bathroom	Tall white built-in cabinet with hinged door, plus an adjacent built-in white bench/shelf unit with drawers beneath	1	GOOD
Main en-suite bathroom	Window set into the shower wall above head height, fitted with an aluminium venetian blind; a second window with pale blue/white horizontal venetian blinds to the side of the shower	2	GOOD
Main en-suite bathroom	Wide-board pine plank timber flooring throughout the en-suite (unusual for a bathroom) with a tiled threshold into the shower — recorded for condition only	1	FAIR
Main en-suite bathroom	Grey/taupe painted walls with white coved cornice, white ceiling and white skirting — recorded for condition only	1	GOOD
Main en-suite bathroom	Recessed ceiling downlights	1	GOOD
Main en-suite bathroom	White shelving unit standing at the far right of the room	1	GOOD
Main en-suite bathroom	White electrical light-switch plate on the wall beside the mirror	1	GOOD
Bedroom 2	Double bed with a natural wood slatted headboard, carrying a bare mattress whose ticking fabric is printed repeatedly with the brand text "REST ASSURED"	1	FAIR

AREA	ITEM	QTY	CONDITION
Bedroom 2	Second bare mattress bearing the "Rest Assured" brand print in red script with a blue logo mark, resting at floor level — observed in one view lying directly on the floor with no visible bed base, and in another on a low base	1	POOR
Bedroom 2	Cream divan-style bed base with a woven honeycomb/diamond-pattern fabric cover, resting flush on the floor with no visible legs	1	FAIR
Bedroom 2	Small pine bedside tables/stools with an open lower shelf, in unfinished/natural varnished pine — a matching pair, one at the bed head and one across the room	2	FAIR
Bedroom 2	Built-in white melamine wardrobe run with multiple hinged doors and dark round handles/knobs — one section with a single hanging rail and shelf above, one section of five open adjustable shelves, a narrow vertical column of open cubbies, a further hanging rail section, and a shoe/shelf cubby at the base; dark bronze/black metal cabinet hinges	1	GOOD
Bedroom 2	Empty white plastic clothes hangers left on the wardrobe hanging rail	4	GOOD
Bedroom 2	Cream/off-white wooden venetian blind to the bedroom window, with two beige/gold braided pull cords ending in wooden acorn-shaped pulls and a separate tilt-cord ladder	1	GOOD
Bedroom 2	Recessed ceiling downlights set into the sloped/angled ceiling	2	GOOD
Bedroom 2	White double electrical wall sockets (South African 3-pin type) mounted low on the wall near the bed head and beside the bedside table	2	GOOD
Bedroom 2	White panelled bedroom door to the hallway	1	GOOD
Bedroom 2	Sloped/angled white ceiling — recorded for condition only	1	GOOD
Bedroom 2	Sage-grey / sage-green painted wall finish with white skirting boards — recorded for condition only	1	FAIR
Bedroom 2	Honey-toned pine plank timber flooring with numerous visible knots — recorded for condition only	1	GOOD
Second bathroom	White oval built-in bathtub set into a cream/beige large-format tiled surround with tiled deck and front skirt panel	1	GOOD
Second bathroom	Wall-mounted chrome bath mixer tap with a separate hand-held shower attachment on a bracket, plus chrome overflow drain	1	GOOD
Second bathroom	Chrome circular flush-mounted jet/inlet fitting on the inner wall of the bathtub near the overflow drain (spa/jacuzzi-style bath)	1	GOOD
Second bathroom	Small square access/inspection panel cut into the tiled skirt at the base of the bath (plumbing access)	1	FAIR
Second bathroom	White round countertop-mounted (vessel) basin with chrome single-lever mixer tap and chrome pop-up waste	1	FAIR
Second bathroom	Vanity unit beneath the basin — white cabinet surround with a wood-toned, ridged teak-look slatted countertop and a drawer	1	GOOD

AREA	ITEM	QTY	CONDITION
Second bathroom	Mirror mounted on the wall above the basin	1	GOOD
Second bathroom	White close-coupled toilet with cistern, seat and lid, chrome dual-flush button on the cistern lid	1	GOOD
Second bathroom	Chrome wall-mounted toilet-roll holder carrying a single partially-used white paper roll	1	GOOD
Second bathroom	Built-in white melamine linen cupboard with six vertical compartments and hinged doors	1	GOOD
Second bathroom	Towel stock held in one compartment of the linen cupboard — two rolled cream/beige towels with a subtle patterned stripe seen in one view; a stack of approximately four to five rolled tan/beige towels with one patterned beige towel folded on top seen in the other	1	GOOD
Second bathroom	Bath towels in use — a white/cream striped bath towel hung over the tiled bath ledge, and a white towel hanging at the side of the bath	2	GOOD
Second bathroom	Windows fitted with white venetian blinds — one above the bath and one beside the basin	2	GOOD
Second bathroom	Wood-look plank tile flooring in grey-brown/dark brown tones (distinct from the honey-pine timber floors elsewhere in the property) — recorded for condition only	1	FAIR
Second bathroom	Cream/beige wall tiling to the bath surround and behind the basin, with matching tiled skirting — recorded for condition only	1	GOOD
Second bathroom	Painted wall finish — two-tone, light grey/blue on one wall and beige/tan on the return corner, with white skirting boards — recorded for condition only	1	GOOD
Guest powder room	Round white ceramic vessel/bowl-style basin mounted on a wood-toned vanity top, with chrome mixer tap and chrome pop-up drain	1	GOOD
Guest powder room	White-framed mirror / frosted-opaque glass panel mounted on the wall above and beside the basin	1	GOOD
Guest powder room	White panelled entrance door with horizontal grooves, chrome round door handle and visible lock mechanism	1	GOOD
Guest powder room	Warm taupe/greige painted wall finish — recorded for condition only	1	GOOD
Additional bedroom — attribution not resolved	UNATTRIBUTED ROOM A (single-bed room, pale grey/blue walls, casement window) — single bed with a bare mattress covered only by a quilted white mattress protector, no fitted sheet or bedding	1	FAIR
Additional bedroom — attribution not resolved	UNATTRIBUTED ROOM A — small square two-tier pine side table (top surface plus lower shelf), varnished, with visible knots and natural grain	1	GOOD

AREA	ITEM	QTY	CONDITION
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM A – small wooden stool/table with turned legs, standing near the window	1	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM A – sash/casement window fitted with white venetian blinds, and a white double electrical wall socket with South African plug points	1	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM A – pale grey/blue painted walls, white skirting boards and warm honey-toned pine strip flooring – recorded for condition only	1	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B (empty room, sage-green walls, wood-look plank tile/laminate floor) – wooden storage trunk/crate approximately knee height (~60cm), built from mixed-tone patchwork wood block tiles/veneer, closed, standing in the corner near the window	1	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – black cable/adaptor running from the wooden crate to a wall socket, and a small black object (possibly a small bin or speaker) standing beside the crate	1	FAIR
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – window with a wooden surround and white venetian blinds, looking out onto a plain grey wall beyond	1	FAIR
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – recessed ceiling downlights (two) and a small white wall-mounted fixture near the ceiling corner (sensor/detector, vent, speaker or alarm keypad – not identifiable)	1	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – white electrical wall sockets/switch plates on the left and right walls at skirting height	3	GOOD
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – white ceiling with a stepped bulkhead detail – recorded for condition only	1	FAIR
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – sage-green/grey painted walls with white skirting boards – recorded for condition only	1	FAIR
Additional bedroom – attribution not resolved	UNATTRIBUTED ROOM B – wood-look plank tile/laminate flooring in brown tones – recorded for condition only	1	FAIR

AREA	ITEM	QTY	CONDITION
Additional bedroom — attribution not resolved	UNATTRIBUTED ROOM C (taupe/grey walls with cornice, indistinctly recorded) — window fitted with white-slat venetian blinds, a wall-mounted security/PIR sensor showing a live red LED, a white double wall socket, and three recessed ceiling downlights; the edge of a wooden furniture item is visible at the the bottom of the view	1	FAIR
Additional bathroom — attribution not resolved	Glossy beige/cream large-format tiled wall with a reflective glass screen (likely a shower screen) and an adjacent window with horizontal blinds — recorded for condition only. Detail at this position is not established, so it cannot be tied to a specific bathroom	1	NOT

10 Services, meters and keys handed over

ITEM	READING / COUNT AT HANDOVER	NOTE
Electricity meter	-----	Prepaid (Econ unit); DB board & meter photographed.
Water meter	-----	Municipal; locate at boundary.
Gas	-----	Smeg hob is gas — confirm bottle location & level.
Geyser / hot water	-----	Electric geyser in garage/laundry roof space.
Rainwater tank	~200L — present, good	Roof-gutter fed; feeds pool/irrigation.
Front / pedestrian gate	Keys: __ Remote: __	Motorised wood-clad sliding gate.
Garage door	Remote: __	Motorised motor — photographed.
Security trellis / burglar gates	Keys: __	Rear trellis gate; burglar bars throughout.
Alarm / electric fence	Code held by: __	Electric perimeter fence + DSC alarm panel.
House / door keys	Sets handed over: __	Confirm count with tenant at handover.

11 Safety items to be confirmed by the landlord

ELEMENT	AS OBSERVED	ACTION
Smoke / CO detectors	Observed: none noted	Recommend confirming/installing before tenancy — landlord to verify.
Electric fence	Present — good (visual)	Confirm energiser compliance certificate.
Security	Burglar bars, trellis & motor gate — good	
Gas appliance	Smeg gas hob	Confirm gas CoC on file.
Electrical	DB board photographed	Confirm valid Electrical CoC on file.

12 The photographic record at handover



Plate 046 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 047 Built-in fireplace recess with black metal gas/radiant fire insert




Plate 094 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 092 Built-in fireplace recess with black metal gas/radiant fire insert



Plate 015 Grey woven-fabric wingback armchair



Plate 022 Grey woven-fabric wingback armchair



Plate 095 Grey woven-fabric wingback armchair



Plate 081 Grey woven-fabric wingback armchair



Plate 096 Grey woven-fabric wingback armchair



Plate 082 Grey woven-fabric wingback armchair



Plate 021 Grey/charcoal fabric L-shaped sectional sofa with chaise section



Plate 083 Grey/charcoal fabric L-shaped sectional sofa with chaise section



Plate 014 Tan/caramel-brown leather sofa




Plate 039 Tan/caramel-brown leather sofa



Plate 040 Tan/caramel-brown leather sofa




Plate 071 SAMSUNG flat-screen television




Plate 070 SAMSUNG wireless satellite speakers



Plate 023 SAMSUNG wireless satellite speakers

13 Acknowledgement

Each party confirms they have read this report, inspected the property against it, and agree it records the condition of the property at the start of the tenancy.

PARTY	NAME	SIGNATURE	DATE
Tenant			
Managing agent			
Landlord			

14 At the end of the tenancy

The outgoing inspection re-walks the same fifteen areas and the same surfaces and compares each one against this baseline, line by line. Anything recorded here as fair wear and tear is excluded from the comparison. Anything that has moved from Good to Fair, or from Fair to Poor, is set out with the matching plate from both dates, so the difference is visible rather than argued.

Important. This is a photographic condition record made on a single date. It is not a structural, electrical, gas, damp or compliance survey; nothing was opened up, moved or tested, and no comment is offered on anything concealed. Severity is an assessment of the consequence of the observation, not of the cost of putting it right. Where an observation is described as cosmetic or as fair wear, that is an opinion offered to assist the parties and is not a determination of liability between landlord and tenant. AssetProof is not an insurer, loss adjuster, assessor, broker or certified valuer. This is a condition record, not a valuation or a compliance survey. The outgoing report compares each area against this baseline at move-out.