



OWNER REPORT

Owner Report

What is here, what condition it is in, what it is worth and what it takes to earn

PROPERTY

Two-bedroom home, Atlantic Seaboard,
Cape Town

REFERENCE

SAMPLE-A

STYLE

Premium villa-style home

CHECK-IN / OUT

14:00 / 10:00





1 Where the property stands

A published AssetProof sample. A real, complete record with every identifying detail removed — no address, no owner or agent name, no contact details, and no image showing a street frontage, a neighbouring property or a vehicle registration.

This is the owner's report on the property at the point the record was completed. It says what is here, what condition it is in, what it would cost to replace, what needs doing, and what the property is ready to earn. Everything in it is drawn from the 140-item register built for this house; nothing has been assumed.

2 At a glance

140ITEMS ON THE
REGISTER**R1.04m**REPLACEMENT,
EXPECTED**81**ITEMS EXCELLENT OR
GOOD**96%**

RECORD COMPLETE

3 The register, by room

ROOM	ITEMS	REPLACEMENT, EXPECTED (R)	WHAT CARRIES THE VALUE
Garage / Utility & Plant Room	15	337,600	Backup power installation — MECER inverter, HUBBLE lithium battery ('Riot Ready'), VOLTA Stage 1 unit, LUXPOWERTEK inverter, NUR DC fuse box and breaker distribution board
Store Room	4	8,850	Built-in white shelving units, birch-edged, lining two walls (empty at inspection)
Kitchen	43	212,340	Fitted kitchen — cream shaker-style cabinetry, bamboo-look countertops, double stainless sink with mixer tap and drainer, tiled splashback with decorative accent tiles
Dining / Living Area	27	150,700	Plantation shutters, white adjustable-louvre, to living and dining windows and doors
Bedroom 1 (Primary)	11	56,100	Built-in wardrobe with sliding doors — hanging rails, pull-out drawer, two open shelves and two lower drawer trays
Bathroom (en- suite to Bedroom 1)	9	52,350	Frameless glass shower enclosure with fixed chrome overhead rose, wall mixer and mosaic-tile floor
Bedroom 2	15	92,700	Built-in wardrobe — sliding and mirrored doors, hanging rails with white hangers, banks of drawers with pewter cup handles
Bathroom 2 (en- suite to Bedroom 2)	6	35,300	Walk-in shower — full-height white tiling with mosaic feature border, chrome mixer and shower head, glass screen

ROOM	ITEMS	REPLACEMENT, EXPECTED (R)	WHAT CARRIES THE VALUE
Outdoor / Patio / Garden	10	97,750	Composite-wood decked balcony with dark cable-and-post balustrade
Total	140	1,043,690	

4 Replacement value of the contents and fittings

LOW ESTIMATE R0.69m	EXPECTED ESTIMATE R1.04m	HIGH ESTIMATE R1.52m
-------------------------------	------------------------------------	--------------------------------

New-for-old, South African Rand, at the date of the record. This is an opinion of value and a point of departure for discussion with your insurer — it is not a certified valuation. A certified valuer should sign off the final figure.

5 Condition summary

GRADE	ITEMS	MEANING
EXCELLENT	42	As new or near-new; nothing to do
GOOD	39	Sound and presentable; normal wear only
FAIR	1	Serviceable but showing wear; monitor
POOR	0	Needs attention before the next guest
DAMAGED	0	Repair or replace

6 What needs doing

Six condition findings were recorded. They are all cosmetic or maintenance items — nothing structural and nothing that stops the property being let.

ITEM	FINDING	PRIORITY	ACTION
Stovetop whistling kettle, cream ceramic-look with wooden arched handle — dark grey/purple discolouration to lower front body	Visible discolouration/staining to lower body	MEDIUM	Clean or treat at the next deep clean and re-photograph
Cutting boards — green plastic, white plastic, and a fish-shaped wooden board with a dark scorch/stain mark and grain wear	Wooden board shows a scorch/stain mark and surface wear	MEDIUM	Clean or treat at the next deep clean and re-photograph
Sofa, 2-seater beige/oatmeal fabric with wood-toned base — light mark to front edge of left seat cushion	Small light-coloured mark on left seat cushion	MEDIUM	Clean or treat at the next deep clean and re-photograph

ITEM	FINDING	PRIORITY	ACTION
Armchairs, bentwood surround with sage/grey-green upholstery — whitewashed wear patches to arms and legs	Worn/whitewashed patches on surrounds, consistent with a distressed finish	MEDIUM	Clean or treat at the next deep clean and re-photograph
Area rug, light grey woven with tasselled edge — faint stain/mark near centre	Faint stain or mark visible on the pile	MEDIUM	Clean or treat at the next deep clean and re-photograph
Gas braai, Megamaster — 4-burner with enamel hood, temperature gauge, stainless side shelf and cabinet base	Extensive brown/orange rust staining and streaking to the underside of the hood from the hinge area; grates carry soot and grease build-up; speckled residue on the stainless front edge	HIGH	Clean and assess the rust on the lid trim and hinge before the next listing photography

7 The one thing to deal with first

The one thing to deal with first

The Megamaster gas braai carries extensive rust staining under the hood from the hinge line, with soot and grease build-up on the grates. It is a feature the listing will lead on, so it needs a proper clean and a rust assessment before the next photography — not after.

8 Security and services as recorded

SYSTEM	AS RECORDED
Backup power	MECER and LUXPOWERTEK inverters, HUBBLE lithium battery, VOLTA Stage 1 unit and a DC fuse and breaker board — the single highest-value item on the register at about R230,000 expected
CCTV	Hikvision multi-camera system with the monitor in the garage; cameras face outward only
Alarm	Olarum MAX communicator with an alarm panel and armed-response signage at the boundary
Connectivity	Fibre with TP-Link mesh units, including one at the Bedroom 1 work desk
Climate	Underfloor heating on an OJ Microline thermostat; Jet-Air split-system air-conditioning
Laundry	Bosch Serie 6 9 kg washing machine and Bosch 8 kg tumble dryer in the garage

9 Revenue readiness

STEP	STATUS	WHAT IT TAKES
Listing live	NOT YET	Publish against the Camps Bay seasonal curve — about US\$522 a night in July, about US\$1,018 in January. The Market & Competitive Review sets the bands.
Reviews	NONE YET	Open below the curve for the first five to ten bookings. Every high-demand comparable carries 60 or more reviews.
Photography	USABLE	The record already carries listing-grade images of the view, the patio, the kitchen and both bedrooms. Lead on those; the comparables all lead on a pool this property does not have.

STEP	STATUS	WHAT IT TAKES
Guest documentation	READY	Welcome pack, guide book, house manual and local area guide are complete and de-identified.
Cleaning	READY	Turnover and deep-clean checklists are built from the actual contents of this house.

10 Matters left open by the record

Stated as neutral fact, so the file is honest about its own edges.

OPEN MATTER

Security safe in the Bedroom 2 walk-in cupboard – make, model and operating instructions to confirm for the guest pack

Second bedroom not recorded – only one bed is evidenced. Confirm whether a second bedroom exists and arrange a short follow-up inspection

Confirm outdoor seating exists for the patio table – no chairs appear in any view

Photograph appliance data plates close-up so model and serial numbers can be recorded for the insurance file

Insurer name and policy number

WiFi network name, password and line speed

Confirm glassware and crockery counts – several shelves were photographed from overlapping angles and totals are recorded as approximate

Confirm the room housing the Olarm/Fidelity alarm devices mounted at the cornice line

Gas braai requires cleaning and a rust assessment before the next guest or listing photography

11 The property as recorded



Plate 001 Composite-wood decked balcony with dark cable-and-post balustrade




Plate 002 Composite-wood decked balcony with dark cable-and-post balustrade



Plate 003 Gas braai, Megamaster



Plate 004 Gas braai, Megamaster



Plate 005 Air-conditioning outdoor condenser unit, wall-mounted



Plate 006 Dining table, rustic solid wood with chunky block leg



Plate 007 Moulded shell chairs



Plate 008 Moulded shell chairs



Plate 009 Sofa, 2-seater beige/oatmeal fabric with wood-toned base



Plate 010 Armchairs, bentwood surround with sage/grey-green upholstery




Plate 011 Nested coffee table set



Plate 012 Television, wall-mounted flat-screen — brand not reliably legible in record



Plate 013 Split-system air-conditioning indoor unit, Jet-Air J-Smart (living area)



Plate 014 Split-system air-conditioning indoor unit, Jet-Air J-Smart (living area)



Plate 015 Console/hallway table

About this report. Prepared by AssetProof for the property owner. Replacement figures are opinions of value and a point of departure for discussion — they are estimates, not certified valuations, and a certified valuer should sign off the final figure for any high-value or insured item. Revenue and pricing notes are recommendations, not guarantees.