




I. Observed Film Property



II. K-M Coefficient (mm^{-1})



III. Observed Film Reflectance



[B13]
Burnt Sienna
Calcined Natural Iron Oxide (PBr 7)
13.4% PVC
{iron oxide brown}

1:4 tint
(volume B13:volume W03 = 1:4)

1:9 tint
(volume B13:volume W03 = 1:9)

[W03]
Titanium White (i)
Titanium Dioxide (PW 6)
22.8% PVC
{titanium dioxide white}