


CV Public Transport Accessibility Assessment Report

DSAPT Compliance Evaluation

Project Name	CV Accessibility of Public Transport
Product Name	Accessibility Audit Transport
Team Name	Research in Computer Knowledge

Accessibility Assessment Details

Date	10/05/2026
Input Image	 shutterstock.com · 2613984261
Accessibility Feature Detected	Accessibility Feature Detected: Tactile flooring
Output Image	 shutterstock.com · 2613984261
DSAPT Compatibility	0%
Notes	Tactile flooring was detected, but the estimated luminance contrast is 25.20%. This is below the minimum selected DSAPT contrast level of 30%, so it is not considered compatible based on contrast.