Noise Identification Diagnostics: Bullialdus Crater

Detected Noise Summary

Scene: Bullialdus Crater

Gaussian severe bands: 0


Striped bands: 57

Spiked bands: 0


Thermal detected: True

Smile detected: True


Gaussian Noise Bands




Stripe Detection



Spectral Spike Detection



Thermal Flag: gradient=0.0008



Spectral Smile Detection

