

Termite Inspection Report

Client: Demo data - privacy protected · Residential timber pest inspection
Visit Date: 28 September 2026, 1:00 PM – 1:50 PM
Generated by: AI report assistant, from a Preserver field export

Summary

A termite inspection was carried out at the property, covering the rear deck post bases, a bathroom wall moisture check, and a full-property conducive-conditions walkthrough. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

Active mud termite tubes were found on one deck post base and flagged for treatment, elevated moisture was recorded on a bathroom skirting board consistent with a conducive condition, and the property probe and visual check found no further evidence of live activity elsewhere.

Inspection Summary

Category	Observation	Status	Action Required
Deck Post Base	Active mud termite tubes on one post	High Priority	Schedule treatment
Bathroom Wall	Elevated moisture reading, conducive condition	Attention	Investigate moisture source
Property-Wide Probe	No further live activity found	On Track	Annual recheck recommended

Field Evidence


The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Rear deck — termite mud tubes

-27.4602, 153.0087 · 28 Sep 2026, 1:08 PM

Active mud termite tubes observed running up a deck post base from the soil.



Bathroom wall — moisture check

-27.4602, 153.0087 · 28 Sep 2026, 1:22 PM

Elevated moisture meter reading on the bathroom skirting board, a conducive condition for termite activity.



Exterior — probe and report sign-off

-27.4601, 153.0086 · 28 Sep 2026, 1:42 PM

Timber probe and inspection report completed on the rear deck railing at the end of the visit.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
1:08 PM	Voice	"Got active mud tubes on the back deck post, that's live termite activity — needs treatment booked in."
1:22 PM	Voice	"Moisture meter's reading high on the bathroom skirting, that's a conducive condition worth flagging to the owner."
1:42 PM	Text	Full property probe complete, no further live activity found elsewhere.

Site Visit Log

1:00 PM	Activity started on-site — GPS lock confirmed, property address
1:08 PM	Deck post inspection — photo + voice observation logged
1:22 PM	Bathroom moisture check — photo + voice observation logged
1:42 PM	Property-wide probe — photo + text observation logged
1:50 PM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a client-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me