

Plumbing Job Report

Client: Demo data - privacy protected · Residential leak callout

Visit Date: 28 September 2026, 1:15 PM – 1:52 PM

Generated by: AI report assistant, from a Preserver field export

Summary

An on-site callout was carried out to investigate a reported leak under the kitchen sink, covering a pipe joint inspection, a hot water system check, and a review of overall fixture condition. All observations were captured on-site using the Preserver app, with GPS location and timestamp data recorded automatically alongside supporting photos and voice notes converted to text.

The inspection found a slow drip at the kitchen sink supply joint, consistent with a worn compression fitting, and the hot water heater showed early corrosion at a fitting that will need monitoring. Neither issue is urgent, but both have been flagged with recommended next steps and logged against the job checklist.

Job Summary

Category	Observation	Status	Action Required
Kitchen Sink	Slow drip at supply pipe joint, worn compression fitting	Attention	Replace fitting
Hot Water System	Early corrosion at heater fitting	Monitor	Recheck next service
General Condition	Fixtures otherwise in good working order	OK	No action required

Field Evidence

The following images and captions were captured directly through the Preserver app during the visit. Each entry retains its original GPS coordinates and capture timestamp. Demo data - privacy protected.



Kitchen sink — pipe joint leak

-27.4560, 153.0031 · 28 Sep 2026, 1:19 PM


Slow drip visible at the supply pipe joint under the kitchen sink, consistent with a worn compression fitting.



Hot water heater — fitting condition

-27.4561, 153.0032 · 28 Sep 2026, 1:33 PM

Pressure gauge and fitting on the hot water unit show early-stage corrosion, flagged for monitoring.



Field tablet — job checklist

-27.4560, 153.0030 · 28 Sep 2026, 1:46 PM

On-device checklist confirming the leak repair recommendation and heater fitting follow-up.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
1:19 PM	Voice	"Got a slow drip here at the supply joint under the sink, looks like the compression fitting's worn out. Simple fix, going to note it for replacement."
1:33 PM	Voice	"Hot water unit's fitting has got a bit of early corrosion starting, nothing urgent but worth keeping an eye on at the next service."
1:46 PM	Text	Leak repair recommended for kitchen sink fitting. Hot water heater fitting flagged for monitoring at next scheduled visit.

Site Visit Log

1:15 PM	Activity started on-site — GPS lock confirmed, client residence
1:19 PM	Kitchen sink — photo + voice observation logged
1:33 PM	Hot water system — photo + voice observation logged
1:46 PM	Job checklist — photo + text observation logged
1:52 PM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the job, turned into a client-ready plumbing report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me