

Property Mould Assessment Report

Site: 14 Narel Street, Albion QLD 4010
Inspection Date: 28 September 2026, 12:14 PM – 12:21 PM
Generated by: AI report assistant, from a Preserver field export

Summary

A site inspection was carried out at the above address in response to a tenant report of a musty odour and visible staining. Three areas of concern were documented using the Preserver app: a bathroom ceiling corner near the extractor fan, a bedroom closet interior, and a window-frame wall corner. All observations were captured on-site with GPS location and timestamp data recorded automatically, alongside supporting photos and voice notes converted to text.

Overall, active mould growth was confirmed in two of the three areas, consistent with a moisture-ingress and poor-ventilation pattern rather than a single isolated cause. Remediation is recommended before the growth extends further into adjoining wall cavities.

Severity Overview

Location	Finding	Severity	Est. Affected Area
Bathroom ceiling (fan)	Active mould, water staining	High	~0.3 sq m
Bedroom closet	Mould on baseboard, musty odour	Moderate	~0.15 sq m
Window corner (living)	Surface mould, condensation marks	Low–Moderate	~0.1 sq m

Field Evidence

The following images and captions were captured directly through the Preserver app during the site visit. Each entry retains its original GPS coordinates and capture timestamp.



Bathroom ceiling — extractor fan surround

-27.4225, 153.0430 · 28 Sep 2026, 12:15 PM


Visible water staining and dark mould spotting around the extractor fan housing, consistent with inadequate ventilation during showering.



Bedroom closet — baseboard

-27.4225, 153.0431 · 28 Sep 2026, 12:18 PM

Musty odour noted on entry. Mould staining visible along the lower baseboard, extending approximately 40cm along the rear wall.



Living area — window frame corner

-27.4224, 153.0429 · 28 Sep 2026, 12:21 PM

Surface-level mould at the wall/window junction with condensation marks, likely linked to a thermal bridge at the frame.

Voice & Text Observations

Observations below were recorded on-site as voice notes and automatically transcribed, or entered directly as text, through the Preserver app.

Time	Type	Transcript / Note
12:15 PM	Voice	"Ceiling above the shower, right where the fan is — you can see the staining spread out from the housing, and it's damp to touch."
12:18 PM	Voice	"Closet smells musty as soon as you open it. Mould along the bottom of the wall, looks like it's been sitting a while."
12:21 PM	Text	Window corner — condensation build-up most mornings per tenant. Surface mould only at this stage.

Site Visit Log

12:14 PM	Activity started on-site — GPS lock confirmed, Nariel St, Albion
12:15 PM	Bathroom ceiling — photo + voice observation logged
12:18 PM	Bedroom closet — photo + voice observation logged
12:21 PM	Living area window — photo + text observation logged
12:21 PM	Activity ended and locked — record sealed, tamper-evident

How This Report Was Produced

This report was generated from a single Preserver export — no re-typing, no separate note-taking app, and no manual GPS lookups. During the site visit, every photo, voice note and text entry was captured in one place, each automatically stamped with the time and exact location it was recorded.

At the end of the visit, the activity was locked directly in the app, sealing the record so nothing could be altered after the fact. The full activity — photos, transcripts, GPS log and metadata — was then exported in one step (JSON + Photos) and handed to an AI assistant, which produced the structured report above in a matter of minutes.

The result: a defensible, timestamped, location-verified record of the inspection, turned into a client-ready report the same day it was captured.

Preserver

Free to capture. Record your observations — photo, video, voice or text — with GPS and timestamp on every entry. Export anywhere, including straight to AI. preserver.me