
An actual instrument, built around actual geometry

NIST/MTC Plate · AP242 · 261 faces · three radius-1.5 mm cylindrical surfaces highlighted



QIF definition 99 → nominal 100 → characteristic 101 → feature 97 → actual 102

3.017 mm satisfies the local interval. The containing inspection still records overall FAIL.