

RESIDENTIAL PROPERTY INSPECTION REPORT

Minneapolis Home

4567 Lyndale Ave S, Minneapolis, MN

BASEMENT & MOISTURE

Basement area shows no signs of moisture intrusion or water damage. Walls are dry with no evidence of staining.




Photo: BASEMENT & MOISTURE

SUMMARY

Overall property condition is acceptable. Recommend standard monitoring and maintenance.