

Smoke test: Acceptance test: Found issues:

Unaccept able Low 32

### Top severity issues

ID QATC-878313 QATC-878328

QATC-877472 QATC-878387 QATC-878322 Severity

- Major
- Major
- Major
- Major
- Major Major

# Testing environment

Operating system:

Windows 10, 64 bits

#### QA team

Company:

QA manager:

QA engineers:



Shabbir Hossain Mridha

28 hours

#### Additional information

Testing dates:

17.10.2024 - 25.10.2024 Time spent:


# Version 2.0.

#### Product version: 2.0

General quality analysis The overall quality of the application can be estimated as Low. The main functionality of application which creat the zip file and compress image only functions partially. Additionally, several significant issues are present within the application. Specifically, Auto- Optimize function is non-operational, the size of big picture does not meet the requirment, and no path can be selected while creating gallery. The total number of defects are 32. Functional defects prevail, 17 of them have are Major and 11 defects gain the Average severity. A detailed quality analysis is presented below.


# Detailed quality analysis

# The total number of defects by severity



The chart shows the statistics of defects by the degree of the negative impact they have on the application. Almost **88%** of issues have Major and Average severity.

# The total number of defects by components



<u>877485</u>).

The chart represents defects quantity on separate modules. The majority of issues actual in "File" module (10), and in "Optimize" module (7).

#### Quality of separate modules

Module	Quality	Comments
Files	• Low	The quality of this section can be estimated as Low as the main functionality of the moudle which is create gallery does not function Properly. Some other noticable bugs for example Gallery folder directory selection (QATC-874770) and Zip file creation (QATC-875311) are present.
Edit	<ul><li>Medium</li></ul>	The quality of this section can be estimated as Medium, as some functionality of this module works as intended. The most important problems are the following: Order by random function does not work (QATC-877234) and some function of Set as cover does not work (QATC-877217).
Options	• Low	The quality estimation for this module is Low due most of the functionality of this module does not work properly. The most important defects are that the language does not change (QATC-878377) and External logo is not added to big picture (QATC-878373).
Help	<ul><li>High</li></ul>	In general, the quality of the module can be estimated as High.NO noticable defect is present here.
Optimize	• Low	The quality of this section is estimated as Low due to most of the function not working. The most noticable one are that, Auto optimize function does not work (QATC-877482). Also the sliders are not functional (QATC