


LOG OF BORING No. OW-36

PROJECT : MRT Orange Line Project : Bang Khun Non -

LOCATION : Bangkok

Min Buri (Suwinthawong) Section



BORING STARTED : 14/02/25

RIG. ACKER

WL. -2.50 m 24 Hrs. After Boring

BORING FINISHED : 18/02/25

FOREMAN : WN.


JOB No. : 1167287

LOG OF BORING No. OW-36

PROJECT : MRT Orange Line Project : Bang Khun Non -

LOCATION : Bangkok

Min Buri (Suwinthawong) Section



BORING STARTED : 14/02/25

RIG. ACKER

WL. -2.50 m 24 Hrs. After Boring

BORING FINISHED : 18/02/25

FOREMAN : WN.


JOB No. : 1167287

LOG OF BORING No. OW-36

PROJECT : MRT Orange Line Project : Bang Khun Non -

LOCATION : Bangkok

Min Buri (Suwinthawong) Section



BORING STARTED : 14/02/25

RIG. ACKER

WL. -2.50 m 24 Hrs. After Boring

BORING FINISHED : 18/02/25

FOREMAN : WN.

JOB No. : 1167287

LOG OF BORING No. OW-36

PROJECT : MRT Orange Line Project : Bang Khun Non -

LOCATION : Bangkok

Min Buri (Suwinthawong) Section

DEPTH, m.	SAMPLE No.	TYPE OF SAMPLE	SAMPLE DIST. RECOVERY	DESCRIPTION OF MATERIAL	GRAPHIC LOG	○ <i>Natural Water Content</i> × <i>Plastic Limit</i> △ <i>Liquid Limit (%)</i>	○ Su (UC) ● Su' (UC) △ Su (FV) ▲ Su' (FV) × Qp/2 ▽ Su (UU) (t/m ²) 2.5 5 7.5 □ SPT, N (Blow/ft) 20 40 60
75							
	49	SS					
	50	SS		Silty clay, trace fine sand, light greyish brown, hard. (CH)			97 □
	51	SS					67 □
	52	SS					74 □
80				79.95 m.			96 □
				END OF BORING			
				(A) Silty clay, trace to some crushed stone, with decayed wood, greyish brown. (Fill)			
85							



BORING STARTED : 14/02/25

RIG. ACKER

WL. -2.50 m 24 Hrs. After Boring

BORING FINISHED : 18/02/25

FOREMAN : WN.

JOB No. : 1167287