



No: 12323234585

DATE: 2020-06-14

LOCATION: **KEEMK**

INWARD EQUIPMENT INTERCHANGE

CONTAINER NO :sadf2345677

20P0

SEAL -

DEST KERNA

SHIPPING LINE : UNION LOGISTICS LTD

1/01/11/0

VESSEL : asdf

VOY NO:asdf

TRANSPORTER : asdf


TRUCK NO: KGH 423L

B\L NO: 12323234585

DRIVER : Barbara McClintock

DELIVERY NOTE:

PARTY DELIVERING CONTAINER: asdf



Tally Report

MINOR DENTS AND SCRATCHES SEEN

Repair Code	Description of Damage/Repair Qty	Hours Labour Cost\$	Material Cost Total Cost
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
BSRF ST/1	Straighten Bottom Side Rail Flange upto first 15 cm	0.15	96
			384

Prepared by : AUGUSTINE AUGUSTINE

Repair Estimated by: AUGUSTINE AUGUSTINE

Distribution: 1, Transporter: 2, Shpg Line 3 BBL