
DKspring material - picture showing one depressed spring (normal usage) and how it does not return to un-depressed state, contact material or part supplier.

5/20/2016 - TBE



dor.