
1. Stim Space-Time DEM
Gross BB Code [[72,12,6]]
Bravyi Depth-7 Circuit
Noise p in [10^-3, 5x10^-3]
10,260 Fault Mechanisms
Bipartite Tanner Graph
Extract DEM
2. Torus Automorphism
Group G = Z_l x Z_m (36 shifts)
Exact Symmetries (Thm 1)
10,260 -> 285 Orbits (36x)
Equivariance Enforced
Window Boundary Classes
Orbit Tying
3. 6-Bit Integer QNBP
T=15 Unfolded Iterations
Dyadic Step Delta = 0.25
Dynamic Range [-7.75, +7.75]
CSD Shift-and-Add (DSP=0)
Soft Syndrome Parity Loss
Posterior L_v
4. Margin Gate G3
Syndrome Matched?
M_min = min |L_v| >= tau
Zero False Flips
Log-Depth Evaluator
Pass (>= tau)
Fail (< tau)
Fast-Path FPGA
Accept Rate: 75.6%
Latency: 240 ns (T=15)
LER: 0.0000 (0 Err)
Immediate Commit
Fallback Pool
Fallback: 24.4%
C++ BP+OSD-CS-10
P_pipe = 1.9e-4
Buffered D/G/c Queue
Continuous Streaming Sliding Window (Width W = 3 rounds, Commit Stride F = 1 round, Cycle = 1000 ns)