



www.shemca.co.za

WE DELIVER COMPLIANCE ANYTIME, ANYWHERE
OCCUPATIONAL HEALTH & SAFETY MANAGEMENT

SITE NAME: ENGEN FOURWAYS GARDENS

PROJECT NAME: MINOR BUILDING WORKS

CONTRACTOR: ORANGE CIRCLE CONSTRUCTION



09 December 2025

Engen Petroleum
Cnr. Riebeeck & Long Street
Cape Town
8001

To whom it may concern:

This legal compliance audit report serves the purpose of ensuring continuous improvement of HSEQ Management on site.

As per Construction Regulations 5 the Duties of the client; the client shall ensure that periodic health and safety audits and document verification are conducted at intervals mutually agreed upon, but at least once every 30 days and to ensure that the health and safety audit report is provided to the contractor within 7 days after the audit.

The appointed agent performing the health and safety audit shall be registered with a statutory body (SACPCMP) approved by the Chief Inspector as qualified to perform the required functions.


CONTENTS

SECTION 1: Communication	3
SECTION 2: Audit Score	3
SECTION 3: Visual Support & Comment	4
SECTION 4: Non-Compliance Items	5
SECTION 5: Comments/Observations	5

SECTION 1: COMMUNICATION

Name	E-Mail
Kylen Naidu	Kylen.naidu@engenoil.com
Faldiel Gafieldien	faldiel@qscoprojects.co.za
Junanna Labuschagne	Junanna@24hsafety.co.za
Anna Fourie	Anna@24hsafety.co.za
Bev Wagner	Bev@24hsafety.co.za
Vernon Steenberg	Vernon@orange-circle.co.za
Shemca Group	Info@shemca.co.za
Ruan Botes	Ruan@shemca.co.za
Wayne Thompson	Wayne@shemca.co.za

SECTION 2: AUDIT SCORE



www.shemca.co.za

Shop 15, Bonaero Park Shopping Centre
Atlas road, Kempton Park, Gauteng, 1619



info@shemca.co.za



071 628 5974
079 970 7296



Members of:






Business Reg: 2022/471853/07 | TAX Ref: IT - 9756503182


B-BBEE Level 2 Contributor

Disclaimer: The information transmitted is intended only for the person or entity to which it is addressed and contains confidential information. Any review, retransmission, dissemination or other use of, or taking of action in reliance upon this information by persons or entities other than the intended recipients is prohibited. If you have received this information in error, please contact the sender and delete the material from your systems.

SECTION 3: VISUAL SUPPORT & COMMENTS

VISUAL COMPLIANCE ITEM	DESCRIPTION OF COMPLIANCE ITEM
	All ladders on site were in good condition. GENERAL SAFETY REGULATIONS 13 – LADDERS: 13A (1) An employee shall ensure that every ladder is constructed of sound material and is suitable for the purpose for which it is used, and – (a) is fitted with non-skid devices at the bottom ends and hooks or similar devices at the upper ends of the stiles which shall ensure the stability of the ladder during normal use;
	Drop sheets was used by the contractor to ensure no paint spillage on site.
	All completed checklists, registers, toolbox talks & DSTI's was available in the safety file.

VISUAL NON-COMPLIANCE ITEM



DESCRIPTION OF NON-COMPLIANCE ITEM

Not all employees on site were complying with the PPE requirements set out by Engen.

ENGEN RETAIL SPECIFICATIONS – 4.12 PERSONAL PROTECTIVE EQUIPMENT (PPE) AND CLOTHING:

All Contractors shall ensure PPE needs are analysed and that all workers are issued and wear hard hats. All contractor employees are to wear yellow, high-visibility vests while on site.

VISUAL NON-COMPLIANCE ITEM



DESCRIPTION OF NON-COMPLIANCE ITEM

Danger Tape has been used as barricading on site.

SPECIFICATION FOR TEMPORARY HOARDING & BARRICADING AT RETAIL SITES 3.1 - HOARDING AND BARRICADE TYPES:

The hoarding is to be a minimum 1,8 metres high with a maximum 50mm gap and may be in the form of wire mesh fencing, corrugated iron, structurally supported shade cloth, solid steel interlocking panels, steel fencing, plywood or suitable alternatives.

Note: Orange road cones, hazard tape or flashing lights are considered a form of signage and do not constitute barricading.



www.shemca.co.za

Shop 15, Bonaero Park Shopping Centre
Atlas road, Kempton Park, Gauteng, 1619



info@shemca.co.za



071 628 5974
079 970 7296

Business Reg: 2022/471853/07 | TAX Ref: IT - 9756503182



B-BBEE Level 2 Contributor

Members of:



Disclaimer: The information transmitted is intended only for the person or entity to which it is addressed and contains confidential information. Any review, retransmission, dissemination or other use of, or taking of action in reliance upon this information by persons or entities other than the intended recipients is prohibited. If you have received this information in error, please contact the sender and delete the material from your systems.

SECTION 4: NON-COMPLIANCE ITEMS

1. RESPONSIBILITIES OF THE PRINCIPAL CONTRACTOR AND CONTRACTOR:
 - The team on site has changed & the organogram must be aligned with the appointees & employees on site.
 - The incident / accident reporting procedure has been included in the safety file but there is no proof of communication attached.
2. THE FOLLOWING DESIGNATIONS MUST BE IN PLACE:
 - First Aider - The appointed employee was not on site at the time of the audit.
 - Construction Manager - The appointed employee was not on site at the time of the audit.
 - Emergency Evacuation Controller - The appointed employee was not on site at the time of the audit.
3. PERMIT TO WORK:
 - Electronic copies of the permit receiver's competency was available on site, the competency must be printed and included in the safety file.
4. PUBLIC SAFETY:
 - Sufficient safeguarding must be in place to prohibit the public from entering the site (Fencing off.) - Sections of the site barricading has been done with danger tape and danger tape does not comply with the Engen requirements.
5. PERSONAL PROTECTIVE EQUIPMENT (PPE):
 - All persons (including visitors) on site must wear hard hats.
 - Reflective vests are to be worn when working in the vicinity of traffic.
6. GENERAL HOUSEKEEPING:
 - Loose material required for use on site must not obstruct any means of access or egress from workplaces and passageways as this could lead to tripping hazards.
 - Storage areas must be demarcated.

SECTION 5: COMMENTS/OBSERVATIONS

To note: All compliance audit reports must be closed out with an action/close out report. This must be submitted within 72 hours of receiving this audit report. Copies of the audit reports must be printed and available in the HSE.

Kind Regards,



Ruan Botes
HSEQ Auditor
082 779 9452

CONTACT US

- 📍 JHB Head Office
- 📍 KZN Regional Office
- 📍 Western Cape Regional Office
- ☎ +27 71 628 5974
- ✉ info@shemca.co.za
- 🌐 www.shemca.co.za

