



RESUMO DE MATERIAIS

Material	Un	Qtd
Tubo PVC DN200mm	barra	3
Luva correr PVC DN200mm	pç	2
Anel borracha DN200mm	pç	4
Pasta lubrificante	kg	0.12
Areia lastro	m³	1.31
Areia envoltória	m³	3.94
Brita dreno	m³	2.63
PV concreto DN1200	pç	1
Ramal esgoto DN100	pç	1
Caixa inspeção	pç	1
Junção Y PVC DN200x100mm	pç	1
PV Montante: N_001		
PV Jusante: PI_03		



Estaca	CT(m)	CF(m)	Prof(m)	Dist(m)	DN/Mat	Decl(%)
N_001	0.000	0.000	0.000			
PI_03	13.445	12.845	0.600	16.43	DN200 Tubo PV	0.01%

NS001

Rua: RUA SEBASTIAO BRASIL C RIOS

N_001 ao PI_03

DN200 Tubo PVC | 16.4m

Decl: 0.011%

V=3.53m/s | Tau=56.0Pa

Custo: R\$ 14,951.30

SE LIGA NA REDE

23/03/2026