
Colibri Scan Report



Licence Plate
0742 GCK

VIN

Date
29.10.2026 9:48

Car Brand

Car Model


Calculation Method
GERMANY

Language
ENGLISH GB

Customer
Chapa y Pintura Carmonauto S

Total Dents
All: 84 Ø: 30mm

Notes



Colibri Parameters

Colibri Location
Talavera de la Reina
Colibri ID: COLIBRI-028
Speed: 0.153602
Dent Detection Version
HoloEdgeDetection_20250704_0024_
Build
Software version: 29-09-2026Snapsho
Last Commit: c19519f6402d92bb78c5
Date: 09/29/2026 12:53:03
Dent Scale Calibrated: : 102%
Dent Scale: : 102%
Dent Scale Backend: : 102%
Dent Confidence: : 32
Confidence Calibrated: : 32

Colibri Scan Report

Left


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Fender Front Left										
Door Front Left		2							2	20
Door Rear Left										
Fender Rear Left										
Roof Spar Left		3							3	20

Horizontal


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Bonnet		13	10	5		1	1	1	31	31
Roof		25	9	4				1	39	26
Trunk Top		1							1	20
Trunk Bottom	-	-	-	-	-	-	-	-	-	-

Right


	10mm	20mm	30mm	40mm	50mm	60mm	70mm	80mm	Total	Φ
Fender Front Right		1		1					2	30
Door Front Right				2					2	40
Door Rear Right										
Fender Rear Right										
Roof Spar Right		4							4	20




Colibri Scan Report




Fender Front Left Left



Fender Front Right Right




Door Front Left Left



Door Front Right Right


Colibri Scan Report



Door Rear Left Left



Door Rear Right Right




Fender Rear Left Left



Fender Rear Right Right

Colibri Scan Report




Roof

Colibri Scan Report




Roof Spar Left Left



Roof Spar Right Right

Colibri Scan Report



Bonnet



Trunk Top

No Image

Trunk Bottom