

VEHICLE INSPECTION

TATA NEXON CREATIVE PLUS

2024

Report generated on: 03 Jul 2026, 20:49

Comprehensive Car Inspection Report

Thorough inspection with 178+ quality checks

Precise insights backed by AI-assisted damage detection

178+

Quality checks

AI + Manual

Damage detection

Offline-first

Secure & private

Contents of report

01 Your report at a glance

Overview of your overall car condition

02 Inspection summary

Category-wise ratings and condition

03 Detailed evaluation of each category

- Documents Verification
- Exterior Inspection

04 Photos & damage evidence

Captured images with highlighted damage marks

At a glance

TATA NEXON CREATIVE PLUS

2024

3/5

Good

Details

Inspection date	03 Jul 2026, 20:49	VIN	2564336677
Registration	FYHFEARG5544	Color	White
Odometer	13000 km	Category	OLD

Inspection summary

This section provides a comprehensive evaluation of the inspection, divided into key categories to offer an in-depth and accurate overview.

Exterior

3/5 Good

The Exterior is in good condition compared to other similar cars.

Interior

3/5 Good

The Interior is in good condition compared to other similar cars.

Engine

3/5 Good

The Engine is in good condition compared to other similar cars.

Electrical

3/5 Good

The Electrical is in good condition compared to other similar cars.

Tyres

4/5 Very good

The Tyres is in great condition compared to other similar cars.

Suspension

3/5 Good

The Suspension is in good condition compared to other similar cars.

Safety

4/5 Very good

The Safety is in great condition compared to other similar cars.

Documentation

3/5 Good

The Documentation is in good condition compared to other similar cars.


Vehicle images




Documents Verification → Documents → Registration Certificate (RC)




Documents Verification → Documents → Insurance Valid




Documents Verification → Documents → Pollution Certificate




Documents Verification → Documents → Road Tax Paid




Documents Verification → Documents → Service Book Available



Documents Verification → Documents → Spare Key Available



Documents Verification → Documents → Owner Manual



Exterior Inspection → Front → Front Bumper

01. Documents Verification

4/5 Very good

Perfect: 5 Imperfect: 2

PARAMETER	RESULT
Registration Certificate (RC)	 Yes
Insurance Valid	 No
Pollution Certificate	 Yes
Road Tax Paid	 Yes
Service Book Available	 Yes
Spare Key Available	 No
Owner Manual	 Yes

02. Exterior Inspection


1/5 Poor

Perfect: 0 Imperfect: 2

PARAMETER	RESULT
Front Bumper	Minor scratches
Tailgate	Minor scratches

Exterior Inspection → Front → Front Bumper

Green box = AI-detected damage • Blue pin = manual annotation



Manual annotations (1)

- Scratch • CRITICAL • Note: need repair

Exterior Inspection → Front → Front Bumper

Green box = AI-detected damage • Blue pin = manual annotation



AI-detected damage (3)

- Scratch • MEDIUM • 85% confidence — Repair: Localized repair or repaint of the bumper corner.
- Scratch • MEDIUM • 80% confidence — Repair: Localized repair or repaint of the bumper corner.
- Scratch • HIGH • 90% confidence — Repair: Refinish or replace the front bumper guard.

Thank you

We truly appreciate your decision to prioritize the safety and maintenance of your vehicle. By opting for a thorough inspection, you're ensuring not only the longevity of your car but also peace of mind for you and your loved ones.

Final recommendation

Mechanical service

Inspector remarks

thhct

Inspected by test

Disclaimer: This inspection is conducted to the best of our ability and knowledge at the time of inspection. Findings reflect the vehicle's observable condition and do not constitute a warranty.