


DENTAL X-RAY ANALYSIS REPORT

Report ID: 19896e11-5147-4da7
Date Generated: 2025-12-16 01:00:38
Image: 5f1acbcafc1243b193d742e73a966631_54.png
Total Detections: 35

OVERVIEW

Total Teeth Detected	35
Disease Distribution	
• Healthy	31
• Periapical lesion	3
• Filling	1
Severity Distribution	
• None	35

ANNOTATED X-RAY IMAGE



DETAILED FINDINGS

Tooth #	Disease	Severity	Area	Confidence	Urgency
8	Periapical lesion	None	Root	48%	URGENT
9	Healthy	None	Entire Tooth	84%	LOW
9	Healthy	None	Entire Tooth	66%	LOW
10	Healthy	None	Entire Tooth	77%	LOW
10	Periapical lesion	None	Root	48%	URGENT
11	Healthy	None	Entire Tooth	76%	LOW
11	Healthy	None	Entire Tooth	72%	LOW
12	Healthy	None	Entire Tooth	77%	LOW
12	Healthy	None	Entire Tooth	71%	LOW
12	Healthy	None	Entire Tooth	58%	LOW
13	Healthy	None	Entire Tooth	84%	LOW
13	Healthy	None	Entire Tooth	68%	LOW

14	Healthy	None	Entire Tooth	87%	LOW
14	Healthy	None	Entire Tooth	86%	LOW
15	Healthy	None	Entire Tooth	91%	LOW
15	Healthy	None	Entire Tooth	80%	LOW
16	Healthy	None	Entire Tooth	83%	LOW
16	Healthy	None	Entire Tooth	82%	LOW
17	Healthy	None	Entire Tooth	92%	LOW
17	Healthy	None	Entire Tooth	88%	LOW
18	Healthy	None	Entire Tooth	82%	LOW
18	Healthy	None	Entire Tooth	81%	LOW
19	Healthy	None	Entire Tooth	88%	LOW
19	Healthy	None	Entire Tooth	82%	LOW
20	Healthy	None	Entire Tooth	81%	LOW
20	Healthy	None	Entire Tooth	78%	LOW
21	Healthy	None	Entire Tooth	83%	LOW
21	Healthy	None	Entire Tooth	82%	LOW
22	Healthy	None	Entire Tooth	77%	LOW
22	Healthy	None	Entire Tooth	66%	LOW
23	Healthy	None	Entire Tooth	76%	LOW
23	Healthy	None	Entire Tooth	65%	LOW
24	Healthy	None	Entire Tooth	72%	LOW
24	Periapical lesion	None	Root	48%	URGENT
25	Filling	None	Crown	30%	LOW

TREATMENT RECOMMENDATIONS

■ URGENT - Immediate Attention Required:

Tooth #8 (Periapical lesion):

- Endodontic evaluation needed
- Possible root canal treatment
- Monitor lesion size

Tooth #10 (Periapical lesion):

- Endodontic evaluation needed
- Possible root canal treatment
- Monitor lesion size

Tooth #24 (Periapical lesion):

- Endodontic evaluation needed
- Possible root canal treatment
- Monitor lesion size

DISCLAIMER: This report is generated by an AI-assisted diagnostic tool and should be used for informational purposes only. It is NOT a substitute for professional dental examination and diagnosis. Please consult with a licensed dentist for proper evaluation and treatment.