

EVENT  
Hurricane / TS Lala — Central Pacific

RESEARCH CUTOFF  
Aug 17, 2026 · 08:00 HST

REPORT  
Operations & business development

DISTRIBUTION  
NorthStar leadership · Executive General Adjusters

— STORM RESPONSE BRIEFING — HAWAIIAN ISLANDS

# Lala spared the coastline a landfall. It did not spare the grid, the highways, or Kaʻū.

A four-county assessment of structural damage, high-voltage grid failure, transport isolation, and life-safety response — with the claims outlook and the recovery workload it implies. Every figure carries its source and confidence rating.

PEAK CUSTOMERS OUT

**250.9<sub>k</sub>**

HECO peak · Aug 16, 11:00 — confirmed

TRANSMISSION LINES DOWN

**25**

16 Hawaiʻi Island · 9 Oʻahu — corroborated

HOMES DAMAGED / DESTROYED

**100<sub>+</sub>**

Southern Big Island — preliminary, Gov. Green

MAX REPORTED RAINFALL

**33<sub>+</sub> in**

Laupāhoehoe, since Friday — obs windows differ

PEAK REPORTED GUST

**140<sub>mph</sub>**

Mauna Kea summit obs — carried 100+ to 140

CONFIRMED STORM DEATHS

**0**

2 determinations pending — do not attribute

01 THE SIXTY-SECOND READ   02 STORM & TIMELINE   03 STATEWIDE IMPACT   04 ISLAND ASSESSMENT   05 IMPACT MAP   06 CLAIMS OUTLOOK   07 RESPONSE POSTURE  
08 ACTION MATRIX   09 RISK WATCHLIST   A CHART DATA   10 SOURCES & METHOD

COVER VISUAL: ILLUSTRATIVE RENDERING — NOT SATELLITE IMAGERY

# What happened, what it costs, and where the work is.

- No landfall, hurricane-grade hit.** Lala peaked as a Category 1 (80 mph, 985 mb) passing about 30 miles south of Ka Lae on Saturday evening, brushed the southern Big Island with its eyewall, and was downgraded to a tropical storm at 2:00 a.m. Sunday. It was a hurricane for roughly 17 hours — all of them next to Hawai'i Island.
- Water on Hawai'i Island, wind on O'ahu and Maui.** 33 inches of rain fell at Laupāhoehoe; a flash-flood emergency in Ka'ū swept two homes away (confirmed) and damaged or destroyed 100+ (preliminary, Gov. Green). O'ahu logged 39–66 reported roof-damage incidents and 147 downed trees — a full day after closest approach.
- The grid took the structural hit.** HECO peaked at 250,900 customers out — about half its base — with 25 high-voltage transmission lines down; a 42-mile Hāmākua span lost multiple poles. HECO projects days for urban O'ahu and Maui, and **weeks to months** for rural Big Island.
- Ka'ū is cut off.** Highway 11 collapsed near Nā'ālehu, 6–8 bridges are damaged or destroyed, and Pāhala — home of the district's only hospital — had no ground access Sunday. The Kona side is the only way in until an emergency bypass opens.
- Recovery machinery is moving.** Hilo and Kona airports reopened Sunday; all commercial ports were reopened by Monday. About 100 mainland mutual-aid line workers arrive Tuesday and work Wednesday. Joint preliminary damage assessment is underway; no Stafford Act request had been filed as of Sunday.
- Early money signals.** Statewide damage "in the hundreds of millions" and agriculture losses of \$50M+ — both preliminary. The state unlocked a \$100M emergency fund on August 13, before the storm arrived.
- No confirmed storm deaths.** One Big Island traffic death is disputed as to storm attribution; one recovered body is under determination. No casualty figure belongs in any client-facing material.

## BOTTOM LINE — EXECUTIVE GENERAL ADJUSTERS

**Severity sits in Ka'ū, frequency sits on O'ahu.** Ka'ū's swept and washed-out homes are flood-causation files inside a simultaneous eyewall wind field — expect wind-versus-water disputes on every partial loss. Only Hawai'i County was hurricane-warned, and most neighbor-island damage accrued Sunday, after the downgrade: hurricane-deductible applicability turns on trigger wording. Power, civil-authority, and ingress/egress interruption claims will outnumber structure claims. The 72-hour mold threshold lands Tuesday–Wednesday.

## BOTTOM LINE — NORTHSTAR OPERATIONS

**Stage Kona for Ka'ū, Hilo for the windward corridor.** Ka'ū movements are convoy-with-road-confirmation, self-sufficient in fuel, water, and comms. Tarping O'ahu's 39–66 reported roof-damage incidents is the highest-leverage 72-hour action. The rural outage plateau creates weeks of temporary-power and drying demand that grid restoration cannot shortcut. The Highway 11 bypass decides whether Ka'ū presents as mitigable water losses or demolition, rebuild, and mold files — track it daily.

**Held apart — figures still in conflict at cutoff**

Kaua'i outages: ~863 (KIUC, Sun 7 p.m.) vs 36,000+ (Civil Beat, Sun a.m.). O'ahu roofs: 66 (HFD joint briefing) vs 39 (AP/Civil Beat). Ka'ū bridges: 6 (mayor's aerial survey) vs 8 (Civil Beat). Carried as ranges or held apart — never averaged.

# Seventeen hours as a hurricane. Four counties of consequence.

Tropical Cyclone Lala (CP012026) never made landfall. Terrain did the damage: the eyewall's rain trained onto Mauna Loa's southern slopes while tropical-storm wind fields worked the whole chain for another full day.

**80**<sub>mph</sub>**Peak intensity — Category 1**

985 mb · Sat Aug 15, ~5–7 p.m. HST · CPHC  
— confirmed

**~30**<sub>mi</sub>**Closest pass, south of Ka Lae**

Sat Aug 15, ~5 p.m. HST — eyewall brushed  
the southern Big Island

**17**<sub>hrs</sub>**Total time at hurricane strength**

Sat 9 a.m. → Sun 2 a.m. HST — all within  
~150 mi of Hawai'i Island

**305**<sub>mi W</sub>**Last advisory position**

Of Honolulu · Sun 11 p.m., 60 mph — all  
warnings discontinued · CPHC Adv. 20

# Event sequence — HST

- Aug 13

**Advisories begin; state moves first**  
CPHC opens advisories on Lala. Governor Green signs an emergency proclamation and unlocks a \$100M emergency fund — before the first band arrives.
- Aug 14

**Pre-staging**  
Hawaiian Electric activates its incident response plan and stages 500+ workers. Hawai'i County issues its own proclamation. USCG port condition Zulu sequence begins Friday evening.
- Aug 15 • 09:00

**Hurricane Lala — Category 1**  
Hurricane Warning for Hawai'i County; tropical-storm warnings for Maui County, O'ahu, and Kaua'i. That distinction matters to deductibles later.
- Aug 15 • morning-evening


**Windward rivers leave their banks**  
The Wailuku River in Hilo rises 3.4 → 16.2 ft in 12 hours. Hilo Bayfront floods. Highway 11 begins closing segment by segment, MM 54–69.
- Aug 15 • ~17:00

**Closest approach — peak intensity**  
Eyewall passes ~30 mi south of Ka Lae at 80 mph. Mauna Kea summit records a 140-mph gust. Ka'u takes 3–5 in/hr rain — flash-flood emergency, and two Nā'ālehu homes are confirmed swept away Saturday evening. Big Island outages hit 63,270 by 7 p.m.
- Aug 16 • 02:00

**Downgrade — rescues through the night**  
Lala weakens to a tropical storm. National Guard rescues continue in Nā'ālehu and Wai'ōhinu, including two paramedics whose vehicle was taken by the water.

## Customers without power — Hawaiian Electric territories

Aug 15–17 · HECO published snapshots, HST



**Read:** the peak came a full day after closest approach — transmission failures, not the storm's proximity, drove the curve. The Monday point is an American Red Cross cross-check on a different customer universe, shown hollow and never averaged with HECO's series. Kaua'i (KIUC, a separate co-op) is excluded here: its Sunday figures conflict by ~40× between sources (~863 vs 36,000+) and are held apart until KIUC publishes its own tally.

## Why rural restoration takes weeks, not days

Damage is vegetation-driven and concentrated in transmission — the backbone between generation and neighborhoods. Sixteen high-voltage lines are down on Hawai'i Island, and a 42-mile Hāmākua span lost multiple poles and structures — which is also what keeps four independent power producers — Puna Geothermal, Hāmākua Energy, Hāwī Renewable, Pakini Nui — disconnected. Distribution crews cannot re-energize what the backbone cannot feed. Section 05 diagrams this.



Aug 16 • morning

### **O'ahu transmission failures; Ka'ū confirmed severed**

Statewide outages surge to 197,400 by 7 a.m. as nine O'ahu transmission lines fail. Highway 11's collapse is reported; Pāhala is cut off. Hilo and Kona airports reopen after inspections.



Aug 16 • 11:00

### **Grid nadir — 250,900 out**

HECO's peak: roughly half its customer base, O'ahu alone at 173,900. Mutual aid is requested from mainland utilities.



Aug 16 • evening

### **Restoration gains; first damage totals**

178,400 still out by 7 p.m. — Maui down to 7,000. Governor: 100+ homes damaged or destroyed and damage "in the hundreds of millions" (both preliminary). Bridge tally 6–8 — mayor's aerial survey vs Civil Beat. Shelters drop from 426 to ~100 people. JPDA begins.



Aug 16 • 23:00

### **All warnings discontinued**

CPHC Advisory 20: Lala 305 mi west of Honolulu at 60 mph. Forecast to re-intensify well west of the state midweek — a surf problem now, not a wind problem.



Aug 17 • 08:00

### **Research cutoff**

116,000+ customers still out (Red Cross). ~100 mainland line workers arrive Tuesday, work Wednesday. Highway 11 bypass decision pending. Next full refresh: Aug 18, 08:00 HST.


# The damage, measured.

Utility telemetry, agency tallies, and gauge observations as of the cutoff. Every figure keeps its timestamp — snapshots from different hours are compared cautiously or not at all.

## Outages by island — peak vs still out

HECO territories · customers

■ Peak (island's own peak hour) ■ Still out — Sun Aug 16, 7 p.m.



**Read:** O'ahu carried the volume; Hawai'i Island carries the duration. Maui's curve bent fastest — 28,700 to 7,000 in a day. Peaks occurred at different hours (Big Island Saturday evening, O'ahu Sunday morning) and are labeled as such. Kaua'i (KIUC) is held apart pending resolution of a ~40× source conflict.

## High-voltage transmission lines down — one square, one line


HECO telemetry via Aug 16 releases · corroborated



**Why it matters:** these 25 lines are the restoration bottleneck. Separately, a 42-mile Hāmākua corridor span lost multiple poles and structures. Together they are what keep four independent power producers off the grid. Mainland mutual-aid crews go to these lines first.

### Maximum reported rainfall by island


Observation windows differ — do not rank precisely



**Caution:** figures mix 12-, 24-, and multi-day windows; the NWS post-storm rainfall table was unpublished at cutoff. The scale of the gap is real — the ranking beyond that is provisional. Lighter segment shows the range carried across sources.

### Restoration outlook by area

HECO / KIUC statements, Aug 16 · qualitative horizons



**The operative sentence:** HECO warns of "weeks or even months" for rural Hawai'i Island — Puna, Ka'ū, the Kona districts, South Kohala. That plateau is the demand signal for temporary power, fuel logistics, and mitigation that cannot wait for the grid. Wednesday's mutual-aid work start produces the first credible duration estimates.

### Life safety & response volume

59

Ocean rescues — O'ahu, Saturday

Honolulu Ocean Safety; 7,700 preventative actions — synthesis-carried

12<sub>4</sub>

Residents rescued / flooded homes

Waiāhole-Waikāne, windward O'ahu · confirmed (synthesis)

147

Downed-tree incidents — O'ahu

HFD, with 29 downed-line and 16 water calls · confirmed

39<sub>-66</sub>

Roof-damage incidents — O'ahu

Conflicting official tallies — carried as a range

426<sub>→~100</sub>

People sheltered, Sat → Sun night

Red Cross; Ka'ū shelters staying open · confirmed

226

National Guard deployed

Including swift-water rescues in Nā'ālehu and Wai'ōhinu · confirmed

6<sub>-8</sub>

Ka'ū bridges damaged or destroyed

Mayor's aerial survey vs Civil Beat — engineering tally pending

30<sub>+</sub>


County roads closed — Hawai'i Island

Plus Hwy 11 MM 54-69, Hwy 19, 250, 270 segments · corroborated

# Four counties, four different storms.

Hawai'i Island

CATASTROPHIC — KA'Ū



ILLUSTRATIVE RELIEF

63.3k

PEAK OUT • SAT 7 P.M.

33 in

RAIN • LAUPĀHOEHOE

140 mph

GUST • MAUNA KEA


- Ka'ū flash-flood emergency at 3–5 in/hr: 2 homes confirmed swept away in Nā'ālehu on Saturday evening; 100+ damaged or destroyed across the southern districts (preliminary, Gov. Green)
- Highway 11 severed — collapse near Nā'ālehu/Kāwā Flats; 6–8 bridges damaged or destroyed; Pāhala and Ka'ū Hospital without ground access Sunday
- 16 transmission lines down; the 42-mi Hāmākua span lost multiple poles; 4 independent producers disconnected; rural restoration "weeks or even months" (HECO)
- 3 hospitals on backup diesel; 2 Liberty Dialysis centers closed; island-wide "Essential Needs Only" water notice; Nā'ālehu/Wai'ōhinu municipal water offline
- Cemetery washout near Nā'ālehu; ag losses concentrated in Ka'ū coffee and macadamia — statewide ag estimate \$50M+ (preliminary)

CONFIDENCE: CONFIRMED CORE • PRELIMINARY TOTALS

HECO • Gov. Green • Mayor Alameda • NWS

O'ahu

SEVERE — WIND FREQUENCY



ILLUSTRATIVE RELIEF

173.9k

PEAK OUT • SUN 11 A.M.

39–66

ROOF INCIDENTS

147

TREES DOWN • HFD


- Nine transmission lines down drove the state's largest urban outage — a full day after closest approach; conservation requested Salt Lake to East Honolulu
- Mānoa Stream record 14-ft flow; H-1 flooding near Makiki and School St; 12 residents rescued from 4 flooded homes in Waiāhole-Waikāne
- Sheraton Princess Kaiulani roof debris partially closed Kalākaua Ave; Mapunapuna commercial district flooded, vehicles stranded on Āhua St
- Tantalus Drive partial collapse; Pali Hwy Kailua-bound lanes closed at last report; BWS 8-inch main break opened a sinkhole in Niu Valley
- City targets normal operations Tuesday; Monday closures for non-essential offices, parks, and licensing

CONFIDENCE: CONFIRMED • ROOF TALLY IN CONFLICT

HFD • HECO • BWS • City & County

Maui County

MODERATE — FAST RECOVERY

ILLUSTRATIVE RELIEF

28.7k

PEAK OUT

>80 mph

GUSTS · WEST MAUI

6–14 in

RAIN · NWS + WINDWARD OBS


- Mala Ocean Tavern (Lahaina) lost a roof section to wind — the county's largest named commercial loss
- Makawao: eucalyptus onto buildings and poles, businesses damaged including Ohana Island Grindz, simultaneous power and water outage
- North Kihei commercial lots under alluvial mud; Hāna Hwy and Pi'ilani Hwy fragile, local-traffic corridors
- Moloka'i East End access limited by flooding at Kamalō; Lāna'i landfill closed Saturday for unsafe winds
- Fastest restoration curve in the state — 28,700 to ~7,000 out by Sunday 7 p.m.; Kahului port and airport functional throughout

CONFIDENCE: CONFIRMED / CORROBORATED

HECO · MauiNow · Maui County · Civil Beat

Kaua'i & Ni'ihau

ALERT — NORTH SHORE WATCH

ILLUSTRATIVE RELIEF

~863\*

KIUC OUT · SUN 7 P.M.

1

WATER SERVICE AREA DOWN

None

STRUCTURE LOSSES VERIFIED

- \*Outage conflict held open: ~863 members (KIUC via county, Sun 7 p.m.) vs 36,000+ (Civil Beat, Sun a.m.) — a ~40× gap; awaiting KIUC's own release
- Kūhiō Hwy closed near Manoa Stream; Hanalei Bridge segment reopened as passable by Sunday evening (county update — supersedes earlier "closed" reports)
- Hā'ena–Wainiha water service out, DOW crews awaiting access; restoration pockets at Kōke'e, Mt. Kahili, Kīpū, Wainiha
- DLNR closed Kalalau Trail, Nāpali Coast, Polihale, and all forest reserves; county refuse, landfill, and bus services ran normally Monday
- Ni'ihau: zero verified reporting at cutoff — a coverage gap, not an all-clear

CONFIDENCE: CONFIRMED COUNTY DATA · OUTAGE DISPUTED

County of Kaua'i · KIUC · DLNR

Severity matrix — domain by island

| ISLAND         | WIND                                                                            | FLOOD / RAIN                                                    | POWER                                                              | STRUCTURES                                                              | TRANSPORT                                                      | WATER SYSTEMS                                                           |
|----------------|---------------------------------------------------------------------------------|-----------------------------------------------------------------|--------------------------------------------------------------------|-------------------------------------------------------------------------|----------------------------------------------------------------|-------------------------------------------------------------------------|
| Hawai'i Island | <div>SEVERE</div> <div>Eyewall brush; 140-mph summit gust (high-elev obs)</div> | <div>CATASTROPHIC</div> <div>33 in; flash-flood emergency</div> | <div>CATASTROPHIC</div> <div>16 HV lines; weeks-months rural</div> | <div>CATASTROPHIC</div> <div>100+ homes prelim; 2 swept confirmed</div> | <div>CATASTROPHIC</div> <div>Hwy 11 severed; 6–8 bridges</div> | <div>SEVERE</div> <div>Island-wide restriction; 2 systems offline</div> |
|                |                                                                                 |                                                                 |                                                                    |                                                                         |                                                                |                                                                         |

| ISLAND                          | WIND                                       | FLOOD / RAIN                                             | POWER                                                                        | STRUCTURES                                              | TRANSPORT                                    | WATER SYSTEMS                                 |
|---------------------------------|--------------------------------------------|----------------------------------------------------------|------------------------------------------------------------------------------|---------------------------------------------------------|----------------------------------------------|-----------------------------------------------|
| O'ahu                           | SEVERE<br>39–66 roofs; 147 trees           | MODERATE<br>Record Mānoa flow;<br>valley pockets         | SEVERE<br>173.9k peak; 9 HV lines                                            | MODERATE<br>Roof/debris pattern, no<br>losses of record | MODERATE<br>H-1, Pali, Tantalus,<br>Kalākaua | LIMITED<br>Niu Valley main break              |
| Maui County                     | SEVERE<br>>80 mph West Maui                | MODERATE<br>6–10 in NWS, up to 14<br>windward; Kīhei mud | MODERATE<br>28.7k peak, fast recovery                                        | MODERATE<br>Mala Tavern; Makawao<br>businesses          | MODERATE<br>Upcountry trees;<br>Hāna fragile | MODERATE<br>Makawao disruption                |
| Kaua'i                          | LIMITED<br>TS-force; branch strikes        | MODERATE<br>Trailing bands; Hanalei<br>Valley ag         | DISPUTED<br>~863 vs 36,000+ — unresolved                                     | LIMITED<br>Minimal direct loss<br>(synthesis)           | LIMITED<br>Kūhiō at Manoa<br>Stream          | SEVERE<br>Hā'ena–Wainiha out,<br>access-gated |
| Moloka'i·<br>Lāna'i·<br>Ni'ihau | LIMITED<br>Lāna'i landfill wind<br>closure | MODERATE<br>Kamalō overtopping                           | LIMITED<br>Moloka'i/Lāna'i in Maui<br>County counts; Ni'ihau no<br>reporting | UNASSESSED<br>Thin reporting                            | MODERATE<br>East End access<br>limited       | UNASSESSED<br>Ni'ihau: no reporting           |

Severity classes reflect documented impact at cutoff, not final assessment. "Unassessed" marks reporting gaps — treat as unknown, never as unaffected. Island relief tiles are illustrative renderings, not survey imagery.




# One pass, four counties — mapped.

Schematic plot from CPHC advisory positions and incident reporting. Positions are approximate and not for navigation.


**Lala — track, closest approach, and hardest-hit locations**

CPHC advisories CP012026 · incident reports through Aug 17, 08:00 HST



## The Ka'ū problem — one road, now severed


Highway 11 corridor status, Sun Aug 16



**Why this one segment matters:** everything mitigable in Ka'ū — extraction, drying, tarping, hospital resupply — queues behind this bypass. Every day it stays closed converts water losses into demolition and mold files.

## Anatomy of a weeks-long outage

Why rural Hawai'i Island waits while Honolulu relights



**Operational consequence:** facilities in the rural plateau cannot plan around a restoration date that does not exist yet. Generator fuel cycles, temporary power, and climate control are the bridge — for weeks, not days.

# Where the files will come from, and where they will be contested.

No filed-claim counts exist yet — county damage portals opened Aug 16–17 and the joint preliminary damage assessment is underway. What follows are the verified damage facts that will generate claims, the causation map, and the deployment conditions on the ground.

## Dominant peril by geography — the causation map

| AREA                                                    | DOMINANT PERIL                             | DOCUMENTED BASIS                                                                                                                                                                                            | COVERAGE IMPLICATION                                                                                                                                                                                                             |
|---------------------------------------------------------|--------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Kaʻū — Nāʻālehu, Waiʻōhinu, Pāhala, Ocean View          | <div>WATER</div> <div>+ WIND OVERLAP</div> | 3–5 in/hr rates, flash-flood emergency; homes swept by flooding; bridges destroyed — while the eyewall sat overhead (51 mph sustained; gusts 71–73 at South Point, county reports above 80, HECO cited ~90) | <b>The concurrent-causation dispute zone.</b> Swept homes point to flood/NFIP; expect wind-vs-water disputes on every partial loss and anti-concurrent-causation disputes on totals. Sequence documentation decides these files. |
| Hilo / Hāmākua / Laupāhoehoe                            | <div>WATER + EARTH MOVEMENT</div>          | 33 in at Laupāhoehoe; Wailuku River 3.4 → 16.2 ft in 12 hrs; active SR-19 landslide                                                                                                                         | Flood plus landslide/mudflow — exclusion versus NFIP mudflow coverage will be contested on slope properties                                                                                                                      |
| West Maui + Upcountry                                   | <div>WIND</div>                            | Gusts >80 mph West Maui; Mala Ocean Tavern roof; eucalyptus onto buildings and poles in Makawao                                                                                                             | Clean wind-causation territory — property policies. North Kīhei mud-over-lots is the water exception                                                                                                                             |
| Oʻahu — valleys & flood pockets                         | <div>WATER</div>                           | Record 14-ft Mānoa Stream flow; H-1 flooding; 4 flooded homes Waiāhole-Waikāne; Mapunapuna commercial flooding                                                                                              | Flood claims inside an otherwise wind event — verify NFIP penetration; Mapunapuna commercial losses likely flood-coded                                                                                                           |
| Oʻahu — wind belt (Kalihi, Waiʻanae, windward, Waikīkī) | <div>WIND</div>                            | 39–66 roof incidents; 147 trees down; Sheraton Princess Kaiulani debris; 67-mph gust at Kāneʻohe MCAS                                                                                                       | Property-policy wind claims at volume — roof, debris, and tree-impact pattern                                                                                                                                                    |
| Kauaʻi North Shore · Molokaʻi East End                  | <div>WATER</div> <div>ACCESS</div>         | Kūhiō closure at Manoa Stream; Hāʻena-Wainiha water outage; Kamalō overtopping                                                                                                                              | Low structural volume — utility, service-interruption, and access issues dominate                                                                                                                                                |

### The hurricane-deductible question

Lala was a hurricane for roughly **17 hours** — all of it near the Big Island. **Only Hawai'i County carried a Hurricane Warning**; Maui County, O'ahu, and Kaua'i were under tropical-storm warnings. Most neighbor-island damage accrued Sunday, *after* the 2:00 a.m. downgrade — O'ahu's outage peak came a full day after closest approach.

Whether percentage hurricane or named-storm deductibles apply outside Hawai'i County turns on each policy's trigger wording — warning issued, hurricane-force conditions, or named-storm. The warning map by county and the downgrade timestamp above are the evidence base. This report states the facts; it does not adjudicate wording.

### Interruption claims will outnumber structure claims

- + **Service interruption:** 250,900 out at peak; weeks-to-months rural Big Island — spoilage and BI in outage-only zones
- + **Civil authority:** USCG port Zulu closures Fri-Sat; Hilo and Kona airports closed, reopened Sunday (HNL never closed); Honolulu's Monday municipal closures — all dated, all documentable
- + **Ingress/egress:** Pāhala businesses have access claims independent of physical damage; ~190-200 Saturday flight cancellations anchor hospitality BI
- + **Contamination:** brown-water advisories and a DOH leptospirosis caution make floodwater Category 3 from day one — scope accordingly

### Large-loss watchlist — key named properties in the record

| PROPERTY / ASSET              | LOCATION        | WHAT IS KNOWN                                                                                                  | CONFIDENCE        |
|-------------------------------|-----------------|----------------------------------------------------------------------------------------------------------------|-------------------|
| Mala Ocean Tavern             | Lahaina, Maui   | Roof section torn off by wind — time-sensitive hospitality BI                                                  | CONFIRMED · SYNTH |
| Sheraton Princess Kaiulani    | Waikīkī, O'ahu  | Falling roof debris; Kalākaua Ave partially closed — only named hotel damage in the record                     | CONFIRMED · SYNTH |
| Ka'ū Hospital                 | Pāhala, Hawai'i | Not damaged — but road-isolated; the district's only hospital; access is the county's top priority             | CONFIRMED         |
| 3 hospitals (unnamed)         | Hawai'i Island  | On backup diesel generators; fuel logistics flagged critical — names not public yet                            | CONFIRMED         |
| Liberty Dialysis ×2           | Hilo, Hawai'i   | Both centers closed Saturday; damage status unstated                                                           | CONFIRMED         |
| 4 independent power producers | Hawai'i Island  | Puna Geothermal, Hāmākua Energy, Hāwī Renewable, Pakini Nui — off-grid since Sat 4 p.m.; damaged interconnects | CONFIRMED         |
| Nā'ālehu Elementary           | Ka'ū, Hawai'i   | Classroom floor damage; closed through Thu Aug 20; also serving as shelter                                     | CONFIRMED         |
|                               |                 |                                                                                                                |                   |

| PROPERTY / ASSET                         | LOCATION          | WHAT IS KNOWN                                                                                                                            | CONFIDENCE          |
|------------------------------------------|-------------------|------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| Kaʻū High & Pāhala Elementary            | Pāhala, Hawaiʻi   | Possibly closed longer; damage detail unpublished                                                                                        | CONFIRMED • CLOSURE |
| Niu Valley Middle School                 | Oʻahu             | Emergency roof repairs by DOE                                                                                                            | CONFIRMED           |
| Ohana Island Grindz + Makawao businesses | Makawao, Maui     | Building damage from fallen trees; simultaneous power and water outage                                                                   | CORROBORATED        |
| Highway 11 + 6–8 Kaʻū bridges            | Kaʻū, Hawaiʻi     | Collapse near Kāwā Flats; bridges damaged/destroyed per aerial survey; engineering pending — future FEMA PA workstream                   | CORROBORATED        |
| BWS main, Hawaii Loa St                  | Niu Valley, Oʻahu | 8-inch main break opened a sinkhole                                                                                                      | CORROBORATED        |
| Mapunapuna commercial district           | Oʻahu             | Minor structural damage, flooding, stranded vehicles on Āhua St — likely flood-coded commercial losses                                   | PRELIMINARY         |
| Miranda's Farms + Kaʻū ag belt           | Kaʻū / S. Kona    | Coffee and macadamia losses; statewide ag \$50M+ (Farm Bureau) — mostly crop-insurance channels, but farm structures are property claims | PRELIMINARY         |


Corpus rule carried forward: nothing in the record assesses any other specific private facility — do not infer a named property's condition from community-level reporting. Mauna Kea summit facilities reported a 140-mph gust with no facility damage reported.

## Deployment conditions — CAT logistics

- ✦ **Air:** Hilo, Kona reopened Sunday; HNL never closed. Residual schedule disruption into early week
- ✦ **Sea:** all commercial ports reopened after condition Zulu — barge shipping for vehicles and equipment is viable
- ✦ **Ka'ū:** base operations Kona-side; Pāhala unreachable by road at last report; confirm route status before every movement
- ✦ **Lodging:** no availability data published — but ~100 mainland line workers (Tue), 226 Guard, and agency field teams compress Hilo/Kona rooms. Book early
- ✦ **Power & comms:** assume no grid power in rural Big Island work zones for weeks; carry satellite comms for Ka'ū; potable water and floodwater PPE required
- ✦ **Intake signals:** damage portals live in all four counties; JPDA numbers plausible within 24–48 hrs; watch for the Stafford Act request

## The mitigation clock — wet-out was Aug 15–16

Industry-standard water-loss timeline (IICRC-class guidance), applied to this event — not corpus data



**Applied to Lala:** Ka'ū and Hilo structures wetted Saturday night reach the 72-hour mark **Tuesday night Aug 18**; O'ahu and Maui Sunday wet-outs reach it **Wednesday Aug 19**. August humidity plus no grid power — no air conditioning, no dehumidification — in exactly the wettest districts compresses the window. Structures in the weeks-long outage plateau cannot passively dry. Tarping O'ahu's 39–66 reported roof-damage incidents is the highest-leverage 72-hour action; trailing rain lands on every roof still open, and midweek surf from re-intensification works exposed shorelines.

## Two cautions for client-facing work

**Casualties:** no storm-attributed death is officially confirmed — one traffic death is disputed, one recovered body is under determination. Use no casualty figures. **Pre-existing damage:** Ka'ū and rural Hawai'i parcels may carry unrepaired March 2026 Kona-low flood damage (separate federal declaration) — a causation and valuation overlap on the same properties.

# Where the work is, and what we put against it.

Each row ties a service line to a district and to the specific fact that justifies deploying it. Nothing here is speculative — if the record does not support a deployment, it is not on this table.

| DISTRICT                                                               | JUSTIFYING FACT                                                                                                              | NORTHSTAR SERVICE LINE                                                                                                                                                                                                       |
|------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Ka'ū — Nā'ālehu, Wai'ōhinu, Pāhala, Ocean View</b>                  | 100+ homes damaged/destroyed (prelim); 2 confirmed swept; flash flooding at 3–5 in/hr; community isolation; cemetery washout | <b>CAT command and emergency response</b> · water mitigation and structural drying on the flooded-not-destroyed inventory · muck-out and debris · contents · total-loss rebuild pipeline · sensitive-scope biohazard support |
| <b>Ka'ū corridor — Hwy 11 and bridges</b>                              | Roadway collapse at Kāwā Flats; 6–8 bridges damaged/destroyed; boulder and tree blockage MM 54–69                            | Heavy debris removal · emergency access support · <b>public-entity reconstruction</b> — bridge and roadway packages under the FEMA PA workstream once declared                                                               |
| <b>Hilo / Hāmākua / Laupāhoehoe</b>                                    | Wailuku River flood; 33-in rainfall; Bayfront flooding; SR-19 active landslide; 42-mi transmission span down                 | Commercial dry-out on the Bayfront corridor · slope and landslide debris removal · temporary power for facilities inside the outage plateau                                                                                  |
| <b>Rural outage plateau — Puna, Kona districts, S. Kohala, Ka'ū</b>    | HECO's "weeks or even months"; 4 IPPs off-grid; island-wide water restriction; 3 hospitals on generators                     | <b>Temporary power and fuel logistics</b> — hospital generator support is a named immediate action · temporary climate control to stop secondary mold in closed buildings                                                    |
| <b>O'ahu wind belt — Kalihi, Wai'anae, windward, Waikīkī</b>           | 39–66 roof incidents; 147 downed trees; Sheraton Princess Kaiulani debris; Niu Valley school roof                            | <b>Roof tarping and shrink wrap at volume</b> · tree removal from structures · hospitality make-safe and façade debris work · institutional repairs                                                                          |
| <b>Urban O'ahu flood pockets — Mānoa, Makiki, Mapunapuna, Waiāhole</b> | Record Mānoa Stream flow; commercial flooding in Mapunapuna; 4 flooded homes; BWS main break and sinkhole                    | Category 3 water mitigation and structural drying — brown-water and leptospirosis advisories govern scope · commercial dry-out in the industrial belt                                                                        |
| <b>Maui — Lahaina, Makawao, N. Kīhei</b>                               | Mala Ocean Tavern roof loss; Makawao tree-struck businesses; commercial lots under alluvial mud                              | Roof tarping on time-sensitive hospitality BI · tree and debris removal · mud-out and drainage clearing for commercial lots                                                                                                  |

| DISTRICT           | JUSTIFYING FACT                                                                    | NORTHSTAR SERVICE LINE                                                                    |
|--------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|
| Kaua'i North Shore | Hā'ena-Wainiha water outage; access-gated KIUC pockets; DOW crews waiting on roads | Temporary water and power support · standby mitigation staged for the moment access opens |

### Staging — where we sit while the picture firms

**Kona** is the Ka'ū gateway — the only verified ground approach. **Hilo** (airport and harbor both open) bases windward and transmission-corridor work, with the Hwy 19 (MM 28) slide constraining the northern link. **Kawaihae** serves Kohala by sea. **Kahului** is Maui's working hub. Deconflict laydown with HECO's own mutual-aid staging from Tuesday. Do not stage in Ka'ū flood zones, near saturated slopes, or across unassessed bridges.

### Safety posture for field crews

Treat every downed line as energized and hold a 30-foot standoff — tree work near lines is this event's signature injury mechanism. Floodwater is Category 3: leptospirosis caution, no wading, cover cuts, decontaminate. Stay out of stream corridors and gulches 48–72 hours — landslides need no new rain. Dark signals are 4-way stops. Generators run outside, 20 feet from openings. Stop-work authority applies to every person on every site.

— PREMIER RESPONSE

# One call mobilizes assessment, mitigation, and reconstruction under a single accountable command.

NorthStar deploys emergency response, water mitigation, temporary power, debris, environmental remediation, and rebuild crews statewide — with the documentation discipline adjusters need on contested-causation files.



# What gets done, by whom, checked when.

Consolidated from every recommended action in the record, deduplicated. Status is as of the Aug 17, 08:00 HST cutoff.

| ISSUE                                         | LOCATION                              | STATUS AT CUTOFF | WHY IT MATTERS                                                                    | ACTION                                                                                  | OWNER / CONFIRM WITH                       | CHECKPOINT                |
|-----------------------------------------------|---------------------------------------|------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------|---------------------------|
| Hwy 11 severed; 6–8 bridges damaged/destroyed | Ka‘ū                                  | BLOCKED          | Sole road lifeline to Ka‘ū communities, hospital, freight                         | Obtain HDOT/DPW timeline; verify single-lane bypass build; pre-plan Kona-side logistics | Ops lead Hawai‘i Is. · HDOT, County DPW    | 12 hr, then daily 08:00   |
| Ka‘ū Hospital access + fuel                   | Pāhala + 3 island hospitals           | CRITICAL         | Region's only hospital road-isolated; 3 hospitals on backup diesel                | Confirm patient/staff status, medevac contingency; priority fuel-tanker escorts         | Health liaison · County CD, DOH, State EOC | Immediate – 6 hr          |
| Rural outages, weeks–months                   | Puna, Kona districts, S. Kohala, Ka‘ū | DEGRADED         | Multi-week life-support, water pumping, comms risk; core mitigation demand signal | Map affected sites; generator and fuel plan; track HECO transmission repair schedule    | Utilities coordinator · HECO/HELCO         | HECO twice-daily releases |
|                                               |                                       |                  |                                                                                   |                                                                                         |                                            |                           |

| ISSUE                                   | LOCATION                                                    | STATUS AT CUTOFF      | WHY IT MATTERS                                                                   | ACTION                                                                                           | OWNER / CONFIRM WITH                    | CHECKPOINT               |
|-----------------------------------------|-------------------------------------------------------------|-----------------------|----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|-----------------------------------------|--------------------------|
| <b>Mutual-aid reception</b>             | Statewide; staging TBD                                      | INBOUND TUE           | ~100 WRMAG line workers arrive Tue, work Wed; lodging and laydown tighten        | Complete staging, equipment, and housing plan; deconflict NorthStar laydown with utility staging | Logistics · HECO, WRMAG                 | By 06:00 Aug 18          |
| <b>Water systems</b>                    | Hawai'i Is. · Nā'ālehu/Wai'ōhinu · Makawao · Hā'ena-Wainiha | RESTRICTED            | Potable water and sanitation constraint for crews and clients                    | Track DWS/DOW notices; monitor bowser deployments; preposition water for partner sites           | Logistics · county water depts, Guard   | 12 hr, then twice daily  |
| <b>Landslide / flash-flood residual</b> | Windward Hawai'i, E. Maui, O'ahu valleys                    | ACTIVE – HWY 19 MM 28 | Hazard persists without new rain on 15–35 in totals                              | Restrict work near streams and slopes 48–72 hrs; stage slope-stabilization capability            | Safety officer · NWS, HDOT engineers    | Each NWS cycle           |
| <b>Bridge engineering status</b>        | Ka'ū structures                                             | PENDING               | Heavy-equipment routing depends on load ratings; high water delaying inspections | Obtain HDOT tallies; no heavy assets across unassessed structures                                | Ops lead Hawai'i Is. · HDOT engineering | 16:00 Aug 17, then daily |
|                                         |                                                             |                       |                                                                                  |                                                                                                  |                                         |                          |

| ISSUE                     | LOCATION                   | STATUS AT CUTOFF   | WHY IT MATTERS                                                       | ACTION                                                                        | OWNER / CONFIRM WITH                       | CHECKPOINT            |
|---------------------------|----------------------------|--------------------|----------------------------------------------------------------------|-------------------------------------------------------------------------------|--------------------------------------------|-----------------------|
| Damage-data pipelines     | All four counties          | PORTALS LIVE       | JPDA gateway to federal aid defines recovery scope and claim volume  | Track JPDA releases; route partner damage data through official portals       | Recovery coordinator · HI-EMA, county EMAs | HI-EMA 08:00 updates  |
| Sheltering & displacement | Kaʻū primarily             | 426 → ~100         | Multi-night need if homes uninhabitable; housing-repair scope signal | Coordinate with Red Cross and Vibrant Hawaiʻi on transition and feeding       | Community liaison · Red Cross, county EMAs | Daily shelter census  |
| Casualty communications   | Ocean View · Kalihi Stream | DISPUTED / PENDING | Public-messaging accuracy; family sensitivity                        | Publish no casualty numbers; await medical examiner and police determinations | Comms lead · HPD, Hawaiʻi PD, ME           | Next briefings ~14:00 |

Operational checkpoints from cutoff

**BY 14:00 AUG 17**

Kaʻū Hospital access and medevac contingency confirmed. Hospital generator fuel reserves and tanker escorts verified. Casualty determination update expected.

**BY 18:00 AUG 17**

HECO aerial assessments complete on Oʻahu and Maui corridors. Hwy 11 bypass decision. Water bowzers checked at Nāʻālehu, Waiʻōhinu, Makawao. County portal tallies begin to firm.

**BY 06:00 AUG 18**

~100 mainland line workers and equipment arrive; deployment against the 16 Hawaiʻi Island transmission lines. First JPDA numbers plausible. Full intelligence refresh at 08:00.

**BY 06:00 AUG 19**

Rural restoration timelines firm after Wednesday's mutual-aid work start. Pāhala access resolved or confirmed long-duration. Lala re-intensification and surf watch. School reopening decisions.

# What could still move — and what we simply do not know.

## Re-intensification — a surf problem, not a wind problem

Lala is forecast to regain hurricane strength well west of the state by midweek. The operational effect is renewed high surf on west- and south-facing shores through about Aug 19 — coastal facilities, shoreline roads, and any marine staging. Keep crews off exposed shorelines until advisories lift.

## Saturated slopes — the dominant post-storm hazard

15–35 inches fell across Big Island catchments — observation windows vary and are not yet comparable. Landslides need no new rain: the Hwy 19 slide is active, Tantalus Drive partially collapsed, and the governor warned that rains of this class bring widespread slides. Watch corridors: windward Big Island, East Maui, O’ahu valleys, Pali Hwy, H-3, Farrington Hwy, Hawai’i Belt Road.

## Figures most likely to move

The Ka’ū destroyed-vs-damaged split (JPDA will supersede the 100+ figure). The bridge count (6 vs 8). The O’ahu roof tally (39 vs 66). The KIUC outage scale (~863 vs 36,000+). Casualty determinations. The NWS post-storm rainfall table, which will finally make gauge values comparable.

## Coverage gaps are not all-clears

Ni’ihau has zero verified reporting. Moloka’i’s East End, Lāna’i’s interior, the Hāna–Kīpahulu structural picture, and Kona-side damage detail are all thin. No sewage, fuel, or hazmat release was confirmed at cutoff — DOH environmental findings are pending, and absence of evidence is not evidence of absence.

# Every plotted figure, in one table.

The values behind each chart, with the detail carried in the on-screen tooltips. Printed and PDF copies lose hover, so the series are reproduced here in full.

## A1 · Customers without power — published snapshots

| TIME (HST)          | CUSTOMERS OUT | ISLAND SPLIT WHERE PUBLISHED                                                     | SOURCE & CONFIDENCE                                   |
|---------------------|---------------|----------------------------------------------------------------------------------|-------------------------------------------------------|
| Sat Aug 15 · ~19:00 | 63,270        | Hawai'i Island only — statewide total not published at this hour                 | HECO via Star-Advertiser · confirmed                  |
| Sun Aug 16 · 07:00  | 197,400       | Statewide — O'ahu transmission failures driving the surge                        | HECO 8 a.m. release, carried in synthesis · confirmed |
| Sun Aug 16 · 11:00  | 250,900       | Statewide peak — O'ahu alone 173,900; about half of HECO's base                  | HECO via Star-Advertiser · confirmed                  |
| Sun Aug 16 · 14:30  | 191,800       | 130,100 O'ahu · 45,900 Hawai'i · 15,800 Maui                                     | HECO noon/4 p.m. releases · confirmed                 |
| Sun Aug 16 · 19:00  | 178,400       | 126,500 O'ahu · 44,900 Hawai'i · 7,000 Maui                                      | HECO via Star-Advertiser · confirmed                  |
| Mon Aug 17          | ≥116,000      | Cross-check on a different customer universe — not comparable to the HECO series | American Red Cross · corroborated                     |

## A2 · Outages by island — peak vs still out

| ISLAND         | PEAK    | PEAK HOUR          | STILL OUT | NOTE                                                                            |
|----------------|---------|--------------------|-----------|---------------------------------------------------------------------------------|
| O'ahu          | 173,900 | Sun Aug 16 · 11:00 | 126,500   | Nine transmission lines lost; conservation requested Salt Lake to East Honolulu |
| Hawai'i Island | 63,270  | Sat Aug 15 · 19:00 | 44,900    | Eyewall pass; rural districts face weeks to months                              |
| Maui County    | 28,700  | Sun Aug 16         | 7,000     | Fastest recovery curve in the state                                             |

| ISLAND        | PEAK     | PEAK HOUR  | STILL OUT | NOTE                                                                                              |
|---------------|----------|------------|-----------|---------------------------------------------------------------------------------------------------|
| Kauaʻi (KIUC) | disputed | Sun Aug 16 | disputed  | ~863 (KIUC via county, Sun 7 p.m.) vs 36,000+ (Civil Beat, Sun a.m.) — held apart, never averaged |

### A3 · Rainfall and wind observations

| ISLAND         | RAINFALL       | BASIS & WINDOW                                                                                            | PEAK WIND                                                    |
|----------------|----------------|-----------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|
| Hawaiʻi Island | 33 in +        | Laupāhoehoe, since Friday (corroborated); synthesis carries 30–35 in for high catchments                  | 140 mph summit (100+ carried elsewhere) — high-elevation obs |
| Maui County    | 6–14 in        | NWS official 6–10 in/24 hr (confirmed); 13–14 in windward slopes by Sat night (Civil Beat, single source) | >80 mph gusts, West Maui                                     |
| Oʻahu          | 12.55 in       | Kawainui Stream gauge, since Friday (corroborated); synthesis carried 8+ in localized totals              | 67 mph, Kāneʻohe MCAS; 35–50 mph general                     |
| Kauaʻi         | Not quantified | Heavy trailing rainbands Sunday; storm total unpublished at cutoff                                        | Tropical-storm force                                         |

Observation windows differ across these figures — 12-hour, 24-hour, and multi-day totals are mixed because the NWS post-storm rainfall table was unpublished at cutoff. Do not rank gauge values against each other until it publishes.

### A4 · Grid damage and restoration horizons

| ITEM                                 | VALUE | DETAIL                                                                                             |
|--------------------------------------|-------|----------------------------------------------------------------------------------------------------|
| Transmission lines down              | 25    | 16 Hawaiʻi Island · 9 Oʻahu — HECO telemetry, corroborated                                         |
| Hāmākua corridor span                | 42 mi | Lost multiple poles and structures to wind-toppled trees — reported separately from the line count |
| Independent power producers off-grid | 4     | Puna Geothermal · Hāmākua Energy · Hāwī Renewable · Pakini Nui — disconnected Sat ~4 p.m.          |
| Oʻahu urban grid                     | Days  | "Within days" — HECO projection, Aug 16                                                            |
| Maui County                          | Days  | "Within days" — HECO projection, Aug 16                                                            |

| ITEM                  | VALUE        | DETAIL                                                                                            |
|-----------------------|--------------|---------------------------------------------------------------------------------------------------|
| Kaua'i — KIUC pockets | Days         | Kōke'e, Mt. Kahili, Kīpū, Wainiha: no restoration Sunday night, work resuming as conditions allow |
| Rural Hawai'i Island  | Weeks–months | Puna, Ka'ū, South and North Kona, South Kohala — "weeks or even months" (HECO, confirmed)         |
| Mainland mutual aid   | ~100         | Western Region Mutual Assistance line workers — arrive Tue Aug 18, begin work Wed Aug 19          |

# How to read this report — and what you may republish.

## Confidence labels, as used throughout

- CONFIRMED

Primary agency or utility release, or multiple independent primary sources
- CORROBORATED

Multiple secondary sources agree; primary confirmation pending
- PRELIMINARY

Early official estimate expected to be superseded — the 100+ homes figure is the example
- SINGLE-SOURCE

One outlet only; treat as unverified until matched
- DISPUTED

Sources actively conflict — carried as a range or held apart, never averaged

Figures keep their as-of timestamps. Snapshots from different hours are never merged; conflicting tallies are shown side by side. Where the record is silent, the report says so instead of filling the gap.

## Media & imagery clearance for republication

- CLASS A — CLEARED

HDOT / Hawai'i County Civil Defense official imagery (road clearing, flood response). Public domain government work. Credit: "Photo courtesy of the Hawai'i Department of Transportation / Hawai'i County Civil Defense"
- CLASS C — RESTRICTED

Wire-agency photography (AFP/Getty and similar). Commercial license required — do not republish on LinkedIn or client materials
- CLASS D — LINK ONLY

Editorial and community photos (Civil Beat staff and courtesy images). Link to the story; do not re-host the asset

No third-party photography is embedded in this report. The cover visual and island relief tiles are NorthStar-produced illustrative renderings — not satellite, survey, or event imagery — and are cleared for distribution with the file, which remains clearance-safe to forward.

## Verified damage imagery registry — geo-verified assets with direct links

| ASSET   | WHAT IT SHOWS                                                                                                                             | LOCATION                             | CREDIT                                   | CLASS | PERMITTED USE                                                                                                              |
|---------|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|------------------------------------------|-------|----------------------------------------------------------------------------------------------------------------------------|
| VIS-005 | <b>HDOT road-clearing operations</b> — heavy machinery clearing mud and downed trees from a state route · <a href="#">HDOT · coverage</a> | State route corridor, Hawai'i Island | Hawai'i Dept. of Transportation          | A     | Public domain government work — cleared for LinkedIn and client materials with the HDOT / County Civil Defense credit line |
| VIS-002 | <b>Flood debris across Highway 11</b> — courtesy photo cross-referenced with HDOT closures · <a href="#">story</a>                        | Nā'ālehu, Hawai'i Island             | Sandy Sturbaum / courtesy via Civil Beat | D     | Link only — permission required to re-host                                                                                 |

| ASSET   | WHAT IT SHOWS                                                                                                             | LOCATION                      | CREDIT                              | CLASS | PERMITTED USE                                                           |
|---------|---------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------|-------|-------------------------------------------------------------------------|
| VIS-003 | <b>Fallen tree crushing a pickup</b> — geo-located at Pualei Circle near Kapiʻolani Park · <a href="#">story</a>          | Waikīkī, Oʻahu                | Jessica Terrell / Civil Beat        | D     | Link only — editorial news rights                                       |
| VIS-004 | <b>Splintered plumeria trees at the law library</b> · <a href="#">story</a>                                               | UH Mānoa campus, Oʻahu        | Stewart Yerton / Civil Beat         | D     | Link only — editorial news rights                                       |
| VIS-006 | <b>Boarded and sandbagged storefront</b> — commercial storm readiness · <a href="#">story</a>                             | North Kīhei, Maui             | Erin Nolan / Civil Beat             | D     | Link only — editorial news rights                                       |
| VIS-001 | <b>Toppled tree resting on a residential roof</b> — wire-service still, matched to press metadata · <a href="#">story</a> | Mountain View, Hawaiʻi Island | Jill K. Briggs / AFP / Getty Images | C     | Do not republish — commercial license required; view via the story link |

Registry carries the geo-verified assets documented in the source corpus at cutoff. Restricted assets (Classes C and D) are linked to their original publication rather than embedded — the report file itself stays clearance-safe to forward. Only the Class A HDOT imagery may be dropped into client-facing material, with its credit line.

Standing verification rule

This document reflects the record as of Aug 17, 2026, 08:00 HST and is superseded by any later official release. It is situational intelligence, not a coverage determination, engineering assessment, or legal advice. Verify figures against current CPHC, HECO/KIUC, county, and HI-EMA releases before external use. Next scheduled refresh: Aug 18, 08:00 HST.



Emergency response, disaster recovery, environmental remediation, and specialty contracting. Prepared by NorthStar market intelligence for leadership, operations, and Executive General Adjuster partners working the Lala event.

PRIMARY SOURCES

- 1. CPHC / NWS Honolulu — advisories CP012026
- 2. Hawaiian Electric — Aug 14-16 releases
- 3. KIUC & County of Kauaʻi updates
- 4. HI-EMA · HDOT · county civil defense
- 5. Office of the Governor · Hawaiʻi County mayor
- 6. USCG port condition notices · Red Cross

REPORTING REVIEWED

- 1. Honolulu Civil Beat · Star-Advertiser
- 2. Hawaii News Now · KHON2 · HPR
- 3. Big Island Now · MauiNow · Kauaʻi Now
- 4. AP · NYT · Guardian · CNN · ABC · NBC

