

NEWRRO AI & MST BLOCKCHAIN

SATELLITE AUDIT CERTIFICATE — PARAMETRIC CROP INSURANCE

CERT ID: CERT-81EFB289AA77 | 2026-09-25 16:51:35 UTC

1. FARM PLOT & DISASTER IDENTIFICATION

Plot ID:	BIHAR_DARBHANGA_01
Farmer Name:	Ram Singh
Location:	Darbhanga, Bihar
Crop Type:	RICE Acreage: 3.0 acres
Phone:	N/A
Disaster Type:	Monsoon Kosi Flood
Assessment Date:	2026-09-25 16:51:35 UTC


2. SATELLITE TELEMETRY METRICS

Sentinel-2 NDVI (Pre-event):	0.7500 (Healthy crop baseline)
Sentinel-2 NDVI (Post-event):	0.1800 (Post-disaster measurement)
NDVI Vegetation Loss:	76.0% ■ CRITICAL
Sentinel-1 SAR Mean:	-17.50 dB (Flood threshold: -15.0 dB)
SAR Flood Duration:	6 consecutive days below -15 dB
NDWI Moisture Index:	-0.4200 ■ DROUGHT
IMD/OWM Rainfall (48h):	185.0 mm

3. NEWRRO AI 2-OF-3 MULTI-SOURCE CONSENSUS RESULT

Oracle Consensus Score:	1.00 (3/3 feeds voted YES)
Verdict:	■ APPROVED — 3/3 feeds confirmed disaster event
Verified Damage:	76.0%
Payout Authorized:	0.75 MST (≈ ■25,000)

4. SATELLITE TELEMETRY TIME-SERIES GRAPH



5. CRYPTOGRAPHIC BLOCKCHAIN PROOF

EIP-191 AI Proof Hash:	0x4f8a91bc76de203918a994ef7162bca98164392019ab921c1029384756abcdef
MST Blockchain TX Hash:	0x8f3a91bc24ef10c79184aa2758129e8dcD48A6461082f48392019ab921c102938
Signing Standard:	EIP-191 Personal Sign (Ethereum keccak256)
ECDSA Recovery:	OpenZeppelin ECDSA.recover() verified on MST Layer 1

■ VERIFIED & DIGITALLY SIGNED BY NEWRRO AI ORACLE AGENT
Cryptographically anchored to MST Blockchain Layer 1. Tamper-evident EIP-191 proof.