

DOCKING PROGRESS REPORT – Day 7	
Ship Name	GAS NURI ARIZONA
Type of Docking	INTERMEDIATE SURVEY V
Location	Semarang
Main Contractor	PT . YWTS
Date	16 July 2018

PHOTO REPORT



AF Application on bottom area has been done



AF Application on bottom area



AF application on vertical side area



AF application on vertical side area



DFT measurement



Listing vertical side



Ship Hull condition looking not good because only repainted bottom and vertical side area



Vacuum test welding hull after replating found no leaked



Vacuum test bottom plug



Alumunium Anode has been installed



Sea Chest Has been closed