Total NDT
Non-Destructive Specialist

Address: 1747 Willow Lake Dr. White Oak, TX 75693 Phone: 430-201-2070

Ultrasonic Examination Report

Client:	SAChem	**Location:**	**2311 Pipeline Rd. Cleburne, Tx 76033**	**Report No.**	1 OF 1
Procedure:	TNDT-UT-003 Rev. 3			**Date:**	11/4/2025
Code/Specification:	ASME Sec. V			**P/O No.**	OilPro003
Item Description:	Vessel			**Total NDT SC #**	200-25-487
Scope of Examination:	UT Thickness on Specified Areas			**Dwg:**	54-11-002 Methylchloride Storage

Testing Parameters

Instrument Mfg.	Olympus	Model:	38DL Plus			S/N:	130715308		Calibration Date		3/3/2026		
Longitudinal Frequency 0°	5MHz	MHz	Size	.375"	Type:	Echo to Echo	S/N:	812283	Ref. dB	65	Scan dB	0	
Angle Beam 70°	N/A	MHz	Size	N/A	Type:	N/A	S/N:	N/A	Ref. dB	N/A	Scan dB	N/A	
Angle Beam 60°	N/A	MHz	Size	N/A	Type:	N/A	S/N:	N/A	Ref. dB	N/A	Scan dB	N/A	
Angle Beam 45°	N/A	MHz	Size	N/A	Type:	N/A	S/N:	N/A	Ref. dB	N/A	Scan dB	N/A	
Calibration Standards:	Type:	Steel	Material:	CS	Mfg.	3E	S/N:	24-2910	Temp.	80°			
Surface Condition:	Painted	Range:	5 Inch	Couplant:	UTX-FE								

Part Details

Location/Type of Joint:	N/A		
Material/Dimensions:	OD: 131.875"		
Welding Process:	N/A		
Part Number:	NB# 51113	Heat Number:	N/A
Serial Number:	140435-01-9	Surface Temp.	80°

Results

Performed Ultrasonic Thickness Test on preset areas
Readings on vessel were taken clockwise faceing North
Readings on Nozzels were taken on top of pipe
going clockwise, or on North side working clockwise.
0° on 24 Could not be accessed due to catwalk.
N1 Readings were unavalible due to not getting a redaing.
N5 is a Threaded Pipe
N10 is a Blank Flange

Drawing

Additional Pages ☐







Start Time:	N/A	am / pm	End Time:	N/A	am / pm	Consumables	N/A	Gal/Gel	Number of People		1
Travel Hours	N/A	Perdiem	Yes ☐	No ☑	Number of Vehicles	N/A	Total Mileage	N/A	Total Hours	See Billing Sheet	

Customer Name: OilPro Consulting

Examiner Name/Level: Damon Crain Lvl. II

Customer Signature:

Examiner Signature: Damon Crain Lvl. II